

ASS. REC. BY:

REF: CS/MSG17019052 / R1662

Special Instructions:

SURVEYOR

Rosal

ASSIGNMENT (Office)

From (Person):

menimen

Clara milah yeeh

of

MSIG

Date/Time:

04/10/17 @ 3.40pm

Estimated Cost:

Bill to

①

TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGM717

Insured:

at Workshop m/s

Performance

Tel:

81214600

of

303 Alexandra Road

Policy No

28951307 QMY

Claim No:

531735

Sum Insured

Excess:

\$1000.00

Make of Veh:

D.O.A

02/10/17

(Client's Record)

CA / (REV) / REP. / REV 24 HRS

5/10/17

H.O.D. Endorsement:

Date/Time:

4/17 3.51pm

Person Contacted

Inthiran

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SGM717-X

6/10-

Revert via menimen.

6/10 @ 14:44 authorise repair by Lui Siew wei

6/10 @ 4:05pm email authorise repair excess \$1000/-

Confirm \$14,171.80, 6 days. (Red: 5415.04 : 27%)

Rasul

REF: MS19

ASSIGNMENT

From _____ Date: 5/10/17
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SGM71T
 at Workshop/mis: Performance
 of: 303 Alexandra Road
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: \$1000.00
 (Client's Record)
 Make of Veh: _____
 * Inthiran
 (Policy Condition): _____
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: 206K
 DAC Accident Rpt. Consistent? Yes or No
 GIA PR Seen Consistent? Yes or No
 Est. Repairs _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / ☒ REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT
 Date / Time Action / Instruction

Veh No: SGM71T Yr Regn: 2017 / APR
 Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: B.M.W 530I LEONARD cc 1998
 Colour: WHITE A/C Insured / Std / NI / NA
 Sp Reading: 18153 T Radio Insured / Std / NI / NA
 Eng No: _____
 C No: WBA JAS205 06885019
 Gen. Cond: Good ☒ / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / SRim / STD A/Rim or
 Tyre Size: F: 245/40 R19
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R Bal: 6 mm R Bal: 6 mm
 L Bal: 6 mm L Bal: 6 mm
 D.O.A: 02/10/17 D.O.I: 05/10/17
 Survey held at: PERFORMANCE
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRT N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 01 FEB 2018

Date/Time: File Pass to?

112 Typist

Date/Time: File Return to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Report Format: OD

Lump Sum / I.B.I: (\$) 14,171.80

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

Survey Fee

Transportation

S + RS (\$)

Photos

Others

TOTAL

300
10
310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17019052/R1tb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-10-2017



Code : MSG

1.

Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SGM 71T
Policy No.	28951307QMY	Coverage (\$)	0.00
Claim No.	531735	Excess (\$)	1,000.00
Assign From	MERIMEN (CLARA MILAH YEO)	Assign Date	04/10/2017

2.

Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

--	--

5.

General Information

Accident Date	02/10/2017	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a.

Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2017		04 Oct 2017 15:40 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SIME DARBY SERVICES PTE LTD, Co. Reg. No.: 197501065W		
Vehicle Reg. No.:	SGM71T	Date of Loss:	02/10/2017 16:00 - :59
Claim Type:	OD / 531735	Policy/Cover Note No.:	28951307QMY (Comprehensive) Coverage: 28/04/2017 - 27/04/2018
		Excess:	S\$1,000.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/10/2017]		
Driver/Custodian:	KWEK JIN NGEE VERNON (45 / Male), NRIC: S7145417G, Tel: +6582221159		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 6 October, 2017 4:05 PM
To: Inthiran Thurasamy
Cc: SUR
Subject: SGM 71T OD MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGM 71T (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SGM71T (531735)**

OD

Oct 2 2017 4:00PM

[SIME DARBY SERVICES PTE LTD]

Performance Motors Limited

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 06/10/2017 14:44 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11678.65) - SGM71T - Claim Handler: Clara Milah Yeo

Approved;11678.65:a if c; check items to be confirmed

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/10/2017 17:29
Date Of Accident	02/10/2017 16:30
Exact Location Of Accident	WOODLANDS AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM71T
Insured/Policyholder	
Name Of Registered Owner	SIME DARBY SERVICES PTE LTD
Co Reg No	197501065W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82221159

Vehicle Particulars

Manufacturer	BMW
Model	530
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	13202414

Driver

Name of Driver	KWEK JIN NGEE VERNON
NRIC No	S7145417G
Date Of Birth	20/11/1971
Occupation	INDOOR
Date Of Driving Pass	17/08/2007
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82221159
Fax Number	
Contact Number	
Email Address	VKWEK@HOTMAIL.COM

Address	60 PUNGGOL WALK #16-23
Postcode	828780
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	NA
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Woodland Ave 4

SGM71T

Sketch Plan Pg. 2

Describe Circumstances of the Accident

On 2-10-2017 at about 4:30pm when I was trying to make a U-turn at Woodlands Ave 4, I hit a column wall and bumper & right headlamp dented & cracked.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44356
Date Estimated : 04/10/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre
Singapore 159942

- ACCOUNT -

66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGM71T	G885019	28/04/2017	530iA	0

DESCRIPTION

To replace front bumper, fender left, repair bonnet and
attachements including knock out dent area cause by
accident.

VALUE
1700 3,400.00

Painting front bumper, fender left and bonnet.

1730 3,221.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

To replace left headlight including conduct
tests for proper function.

450 531.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries.

new ? 80 150.00

Total Labour 1: 7,774.00

DESCRIPTION

FRT LH SIDE PANEL BRACKET 1
FRT LH SIDE PANEL ALUMINIUM
GRILLE AIR INLET OPEN LH (LINES)
LH PROTECTIVE STRIP LINES (LUXURY)
LH FOG LAMP SUPPORT
GUIDE TOP LH
GUIDE BUMPER LH
FRT BUMPER PANEL PRIMED (PMA/PDC)
SET MOUNTING PDC/PMA SENSOR FRT
LH TRIM AIR DUCT SIDE PANEL (CHROM)
LETTERING (LUXURY LINE)

QTY	PRIC
1	52.20
1	884.40
1	87.35
1	63.00
1	76.85
1	34.55
1	16.15
1	1,258.85
1	62.50
1	61.50
1	44.10

VALUE

new 52.20
Bf 884.40
with 87.35
with 63.00
PDC 76.85
new 34.55
new 16.15
new 1,258.85
new 62.50
new 61.50
new 44.10

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190328 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44356
Date Estimated : 04/10/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGM71T	G885019	28/04/2017	530iA	0

DESCRIPTION	QTY	PRIC	VALUE
PLAQUE 82MM	1	67.80	67.80
FRT LH WHEEL ARCH FRT SECTION COVER	1	125.25	125.25
FRT LH WHEEL ARCH RR SECTION COVER	1	125.25	125.25
LH COVER BOTTOM	1	66.70	66.70
LH HEADLIGHT LED AHL HIGH (ICON LIG	1	4,589.25	4,589.25
DECOUPING RING PDC TORQUE CONVERTER	4	4.95	19.80
ULTRASONIC SENSOR MINERALWEISS(WA96	1	363.05	363.05
ULTRASONIC SENSOR MINERALWEISS(WA96	1	363.05	363.05

Total Parts : 8,361.60

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date/Time 05/10/17 01520 Excess S\$ 1000

Surveyor's Name Rabul Sign R

Surveyor's Tel 90010068 Authorised Yes/No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 6 days

REVERT

Remy 6K point

18457.35

Labour 1	:	7,774.00
Parts	:	8,361.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,129.49
Grand Total	:	17,265.09

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44356
Date Estimated : 04/10/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 159942

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SGM71T	G885019	28/04/2017	530iA	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace front bumper and attachments, front LH fender and attachments, LH foglamp support include knocking out dents caused by the accident	1700.00		1,700.00			
To spray paint front bumper and front LH fender	1730.00		1,730.00			
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00			
To replace LH LED AHL headlight include programming and conducting tests for proper function	451.00		451.00			
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00			
To carry out body cavity preservation. (Per panel).	100.00		100.00			
# To diagnose and replace LH LED daytime driving light module, LH LED direction indicator module, front electronics light control unit include conducting checks for proper function	451.00		451.00			
Sundries	150.00		150.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLIND RIVET *	3.15	2.00		6.30
FRT LH SIDE PANEL BRACKET 1	52.20	1.00		52.20
FRT LH SIDE PANEL ALUMINIUM	884.40	1.00		884.40
GRILLE AIR INLET OPEN LH (LINES)	87.35	1.00		87.35
LH PROTECTIVE STRIP LINES (LUXURY)	63.00	1.00		63.00
LH FOG LAMP SUPPORT	76.85	1.00		76.85
FRT BUMPER PANEL PRIMED (PMA/PDC)	1,258.85	1.00		1,258.85
LETTERING (LUXURY LINE)	44.10	1.00		44.10
# RIVET *	0.45	3.00		1.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

# LH LED MODULE DAYTIME DRIVING LIGHT *	223.55	1.00	223.55
# LH LED MODULE DIRECTION INDICATOR *	767.45	1.00	767.45
LH HEADLIGHT LED AHL HIGH (ICON LIG	4,589.25	1.00	4,589.25
# CONTROL UNIT FRT LIGHT ELECTRONICS *	872.10	1.00	872.10
ULTRASONIC SENSOR MINERALWEISS(WA96	363.05	1.00	363.05

SUPPLEMENTARY ITEMS

Total Labour :	4,882.00
Total Parts :	9,289.80
Total Labour & Parts :	14,171.80
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	13,171.80
GST @7%:	922.03
Grand Total :	14,093.83

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44356
Date Estimated : 04/10/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 159942

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SGM71T	G885019	28/04/2017	530iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To diagnose and replace LH LED daytime driving light module, LH LED direction indicator module, front electronics light control unit include conducting checks for proper function	451.00		451.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLIND RIVET *	3.15	2.00		6.30
# RIVET *	0.45	3.00		1.35
# LH LED MODULE DAYTIME DRIVING LIGHT *	223.55	1.00		223.55
# LH LED MODULE DIRECTION INDICATOR *	767.45	1.00		767.45
# CONTROL UNIT FRT LIGHT ELECTRONICS *	872.10	1.00		872.10

Total Labour :	451.00
Total Parts :	1,870.75
Total Labour & Parts :	2,321.75

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17019052/R1TBN2

Date: 02/02/2018

REFERENCE

Insured/Claimant: SIME DARBY SERVICES PTE LTD

Policy No: 28951307QMY

Date of Loss: 02/10/2017

Nature of Claim: OD

Claim No: 531735

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM71T	Engine No:	16569883B48B20B
Make & Model:	BMW 530i, 2.0 LED NAV (A)	Chassis No:	WBAJA52050G885019
Reg. Date:	28/04/2017 (Man. Year: 2017)	Odometer:	18153 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$206,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R19	Rear Tyre Size:	245/40R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,382.35	9,439.80	942.55	9.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,075.00	4,732.00	3,343.00	41.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,457.35	14,171.80	4,285.55	23.22
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	17,457.35	13,171.80	4,285.55	24.55
+ GST 7.00/7.00% (S\$)	1,222.01	922.03	299.98	24.55
Nett Amount (S\$)	18,679.36	14,093.83	4,585.53	24.55

INSPECTION

Date of Assignment: 04/10/2017

Date Inspected: 06/10/2017 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Feb 2018)
Parts:	143	BMW 530I 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM71T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT LH SIDE PANEL BRACKET 1	Necessary	52.20 FS	*52.20 FS
2	1	*FRT LH SIDE PANEL ALUMINIUM	Bent	884.40 FS	*884.40 FS
3	1	*GRILLE AIR INLET OPEN LH (LINES)	Cut	87.35 FS	*87.35 FS
4	1	*LH PROTECTIVE STRIP LINES (LUXURY)	Cut	63.00 FS	*63.00 FS
5	1	*LH FOG LAMP SUPPORT	Cracked	76.85 FS	*76.85 FS
6	1	*GUIDE TOP LH	Not Necessary	34.55 FS	*- FS
7	1	*GUIDE BUMPER LH	Not Necessary	16.15 FS	*- FS
8	1	*FRT BUMPER PANEL PRIMED (PMA/PDC)	Deformed	1,258.85 FS	*1,258.85 FS
9	1	*SET MOUNTING PDC/PMA SENSOR FRT	Not Necessary	62.50 FS	*- FS
10	1	*LH TRIM AIR DUCT SIDE PANEL (CHROM)	Not Necessary	61.50 FS	*- FS
11	1	*LETTERING (LUXURY LINE)	Necessary	44.10 FS	*44.10 FS
12	1	*PLAQUE 82MM	Serviceable	67.80 FS	*- FS
13	1	*FRT LH WHEEL ARCH FRT SECTION COVER	Serviceable	125.25 FS	*- FS
14	1	*FRT LH WHEEL ARCH RR SECTION COVER	Serviceable	125.25 FS	*- FS
15	1	*LH COVER BOTTOM	Serviceable	66.70 FS	*- FS
16	1	*LH HEADLIGHT LED AHL HIGH (ICON LIG)	Broken	4,589.25 FS	*4,589.25 FS
17	4	*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	19.80 FS	*- FS
18	1	*ULTRASONIC SENSOR MINERAL WEISS (WA96)	Scratched	363.05 FS	*363.05 FS
19	1	*ULTRASONIC SENSOR MINERAL WEISS (WA96)	Serviceable	363.05 FS	*- FS
20	2	*ADJUSTABLE BLIND RIVET	Necessary	6.30 FS	*6.30 FS
21	3	*RIVET	Necessary	1.35 FS	*1.35 FS
22	1	*LH LED MODULE DAYTIME DRIVING LIGHT	Not Working	223.55 FS	*223.55 FS
23	1	*LH LED MODULE DIRECTION INDICATOR	Not Working	767.45 FS	*767.45 FS
24	1	*CONTROL UNIT FRT LIGHT ELECTRONICS	Not Working	872.10 FS	*872.10 FS
25	1	*SUNDRIES	Necessary	150.00 FS	*150.00 FS
				Total Parts (S\$)	10,382.35 9,439.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER,FENDER LEFT,REPAIR BONNET AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT	New	3,400.00	1,700.00
2	PAINTING FRONT BUMPER,FENDER LEFT AND BONNET	New	3,221.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO REPLACE LEFT HEADLIGHT INCLUDING CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	451.00
5	TO REMOVE OLD PDC ASSEMBLY,REPKACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
7	TO DIAGNOSE AND REPLACE LH LED DAYTIME DRIVING LIGHT MODULE,LH LED DIRECTION INDICATOR MODULE,FRONT ELECTRONICS LIGHT CONTROL UNIT INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION	New	451.00	451.00
Gross Labour Cost (\$\$)			8,075.00	4,732.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >