



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 3069T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR NUMBER PLATE LAMP (CONSISTENT)	SERVICEABLE	61.60	-
1	N/S TAILLAMP ASSY (CONSISTENT)	SERVICEABLE	174.33	-
	LESS 20% DISCOUNT		-47.19	-
			188.74	-
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	40.00	20.00
1	N/S REAR WOODEN CARRIAGE CHASSIS MEMBER (SN) (CONSISTENT)	CRACKED	650.00	650.00
1	REAR WOODEN STEP MEMBER (SN) (CONSISTENT)	CRACKED	150.00	150.00
1	REAR WOODEN CROSS MEMBER (SN) (CONSISTENT)	SERVICEABLE	580.00	-
1	REAR CROSS MEMBER (SN) (CONSISTENT)	SERVICEABLE	300.00	-
1	REAR LOWER REINFORCEMENT BEAM (SN) (CONSISTENT)	BENT	700.00	700.00
			2,420.00	1,520.00
<b>LABOUR</b>				
	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.		200.00	120.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		250.00	150.00
	TO FOCUS TAILLAMPS .TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	10.00
	TO REMOVE REAR WOODEN CARRIAGE & RENEW AFFECT PART IN ORDER TO FACILITATE REPAIRING WORKS.		900.00	600.00
			1,400.00	880.00
<b>GRAND TOTAL</b>			<b>4,008.74</b>	<b>2,400.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,900.00</b>

Report Ref No. CC6/AXA15004834/Kpa3q2-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.