



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC6/AXA15004834/Kpa3q2-1

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 21-10-2020



ATTN:STACEY NG

Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 2716G	Veh. Inspected	YM 3069T
Policy No.	P1440118	Coverage (\$)	0.00
Claim No.	C0332578	Excess (\$)	0.00
Assign From		Assign Date	18/03/2015

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FE83P	c.c	3908
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	FE83PEA00696	Colour	WHITE
Odometer	284383	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	700 R16X10	BRIDGESTONE	9 mm
L/H Front Tyre	700 R16X10	BRIDGESTONE	9 mm
R/H Rear Tyre	185 R14X10 (D)	UE168	7/7 mm
L/H Rear Tyre	185 R14X10 (D)	UE168	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/03/2015	Inspection Date	18/03/2015
Survey held at	K KIM HIN AUTO PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------