

YM 30697
 TP AXA
 LKK@kennet1
 18/3/2015 @ 11:Am



CO. REG. NO: 199402370D
 GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號
 Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895
 Email: service@kkinhin.com.sg

7N-27930

Vehicle Insurance 16 G
 Accident Date : 06-Mar-2015

Not Authorized

No. : 26774

Date : 09-Mar-2015

Our Ref : 150155 (AXA) / XW

- LKK Auto Consultants Pte Ltd
- Resurvey before/after Spray Painting.
 - Damaged parts to Display when Re-inspection.
 - Parts prices subject to confirmation.
 - Third Party Survey without prejudice.
 - No illegal modification is allowed.

PAGE : 1

RICHARDS CAR RENTAL PTE LTD
 Singapore

1/1/2015

ESTIMATED COST OF REPAIR FOR MITSUBISHI FE83PEOSRDEA (2006) YM3069T
 =====

1 pc rear number plate lamp	61.60 X	
1 pc n/s taillamp assy	174.33 X	
	235.93	
	Less 20% :	-47.19
		188.74
1 pc rear number plate	40.00 sn	20sn
1 pc n/s rear wooden carriage chassis member	650.00 sn	
1 pc rear wooden step member	150.00 sn	
1 pc rear wooden cross member	580.00 sn X	
1 pc rear cross member	300.00 sn X	
1 pc rear lower reinforcement beam	700.00 sn	
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.		
To putty and respray on affected portions.		
To focus taillamps. To check rear wiring and lighting operation.		
To remove rear wooden carriage & renew affect part in order to facilitate repairing works.		

1520.00
 + 880.00

 2400.00
 - 20%

 \$1920

20sn
 40.00 sn
 650.00 sn
 150.00 sn
 580.00 sn X
 300.00 sn X
 (Bt) 700.00 sn
 200.00 1201
 150 250.00 150L
 Reinforcement
 50.00 101

900.00 6001

Total : S\$ 4,008.74
 =====

Singapore Dollars Four Thousand and Eight and Cents Seventy Four Only

4/Sum \$1900/-

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.