



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003241
INV Date 17/04/2020
Reference CC6/CTI17019138/Uda3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. XD 9670B
Insured Veh. GBG 4313K
Claim No. SNM17D05780C02
Policy No. DMCVSN1754131700
Accident Date 04/10/2017
Inspection Date 06/10/2017

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17019138/Uda3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 4313K	Veh. Inspected	XD 9670B
Policy No.	DMCVSN1754131700	Coverage (\$)	0.00
Claim No.	SNM17D05780C02	Excess (\$)	0.00
Assign From		Assign Date	06/10/2017

2. Vehicle Particulars & Condition

Make & Model	mitsubishi fuso fv51 (M)	c.c	11967
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	FV51SJA10141	Colour	WHITE
Odometer	225774	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	TRANSTONE	6 mm
L/H Front Tyre	295/80 R22.5	TRANSTONE	6 mm
R/H Rear Tyre	295/80 R22.5 (D/D)	TRANSTONE	6/6/6/6 mm
L/H Rear Tyre	295/80 R22.5 (D/D)	TRANSTONE	6/6/6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/10/2017	Inspection Date	06/10/2017
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 9670B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BENT / TWISTED	3,530.70	2,200.83
2	FRONT BUMPER END GARNISH LH	TWISTED (1 PC ONLY)	225.00	120.00
1	BUMPER GARNISH LH CENTRE	MISSING / CRACKED	258.30	258.30
1	OUTSIDE TEMP SENSOR	TORN	233.00	233.00
1	SENSOR BOX	DAMAGED	218.00	218.00
1	ADDITIONAL TOP BUMPER CENTER	DISTORTED	663.00	663.00
1	ADDITIONAL TOP BUMPER LH	DISTORTED	523.00	381.12
1	ADDITIONAL TOP BUMPER REINFORCEMENT	DISTORTED	720.00	720.00
1	HEADLAMP RIM LH	TWISTED	335.00	118.18
1	FOG LAMP RH	NOT NECESSARY	1,008.00	-
1	FOG LAMP RIM LH	TWISTED	325.00	136.42
1	FRONT DOOR LAMP LH	TWISTED	352.00	352.00
1	STEP BOARD (MIDDLE) GARNISH	TO REPAIR SEE LABOUR	485.00	-
	LESS 10% DISCOUNT		-887.60	-
	LESS 25% DISCOUNT		-	-1,350.21
			7,988.40	4,050.64
<u>LABOUR</u>				
	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS/ATTACHMENTS APPLY HOT -WORKS WHERE NECESSARY REPAIR/RESHAPE DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ATTACHMENTS.INCLUSIVE OF THE REPAIR OF STEP BOARD (MIDDLE)GARNISH.		1,200.00	600.00
	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS COMPONENTS/ATTACHMENTS.		1,200.00	600.00
			2,400.00	1,200.00
GRAND TOTAL			10,388.40	5,250.64



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00
---	--	--	-----------------

Report Ref No. CC6/CTI17019138/Uda3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.