



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2011 MERCEDES SLK200 KOMPRESSOR CONV (SKX4017U)

Date of Loss

3 October 2017

Time of Loss

9.05

Loss Description

SKX4017U-Vehicle skidded and collided with object.

Comment

Workshop Details

Total Rebate Amount

67286

Nett Loss Amount

\$32,714.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

20/08/2018



Days of work completion *

318



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKX4017U

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

11/01/2012



Mileage

38144

Age of Vehicle

5

Driver Details

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2011

CATEGORY

Driver Name

ASSESSMENT INFO...

2011

FNOL INFORMATI...

CHIA-LI PANG

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... MERCEDES

ASSESSMENT INFO... MERCEDES BENZ

CATEGORY Model

POLICY INFORMAT... SLK200 KOMPRESSOR CONV

ASSESSMENT INFO... SLK 200

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO... ▼

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WDD1724482F029093

CATEGORY Date of Birth

FNOL INFORMATI... 15 September 1969

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 48

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... WDD1724482F029093

CATEGORY Engine No

POLICY INFORMAT... 27186130369650

ASSESSMENT INFO... 27186130369650

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1796

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 100000

FNOL INFORMATI... 31

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI... S6932451G

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI... 3

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 6 June 1987

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI... 31 December 9999

POST SURVEY INF... dd/mm/yyyy

CATEGORY

Address

FNOL INFORMATI...

Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI... S6932451G

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

09/10/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/45R17

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

225/45R17

Front left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts				
Add Approve Deny Submit All															
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/J BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			BONNET			Cracked	1200				1200	Review
		2	1			ENGINE UNDER COVER			Damaged	238				238	Review
		3	1			FRONT BUMPER			Deformed	830				830	Review
		4	1			FRONT BUMPER GRILLE COVER LH			Cut	30				30	Review
		5	1			FRONT BUMPER SPONGE CENTER			Cracked	113				113	Review
		6	1			FRONT BUMPER SPONGE LH (NPA)			Serviceable	0	0	0	0	0	Deny
		7	1			FRONT BUMPER SPONGE RH (NPA)			Serviceable	0	0	0	0	0	Deny
		8	1			FRONT BUMPER WASHER COVER LH			Deformed	86				86	Review
		9	1			FRONT BUMPER WASHER JET LH (NPA)			Serviceable	0	0	0	0	0	Deny
		10	1			FRONT COVER LED DAY LIGHT LH			Damaged	48				48	Review
		11	1			FRONT DOOR MIRROR LH (WITH LED) (NPA)			Repair	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		12	1			FRONT FENDER COWLING LH			Damaged	82				82	Review
		13	1			FRONT FENDER LH			Repair	0	0	0	0	0	Deny
		14	1			FRONT GRILLE BASE			Cracked	124				124	Review
		15	1			FRONT GRILLE LOGO			Missing	95				95	Review
		16	1			FRONT GRILLE LOGO HOLDER			Damaged	48				48	Review
		17	1			FRONT GRILLE OUTER			Cracked	105				105	Review
		18	1			FRONT KNUCKLE BEARING LH			Serviceable	0	0	0	0	0	Deny
		19	1			FRONT KNUCKLE LH			Bent	498				498	Review
		20	1			FRONT LED DAY LIGHT LH			Serviceable	298				298	Review
		21	1			FRONT PANEL TOP GARNISH (NPA)			Serviceable	0	0	0	0	0	Deny
		22	1			FRONT PARKING SENSOR LH			Serviceable	0	0	0	0	0	Deny
		23	2			FRONT PARKING SENSOR RING			Necessary	8				16	Review
		24	1			FRONT SHOCK ABSORBER LH			Bent	865				865	Review
		25	1			FRONT SIDE PARKING SENSOR LH			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		26	1			FRONT STABILIZER BAR LINK ROD LH			Bent	54				54	Reviewi
		27	1			FRONT STEERING RACK			Cracked	3450				3450	Reviewi
		28	1			FRONT SUSPENSION LOWER ARM LH			Bent	295				295	Reviewi
		29	1			FRONT SUSPENSION UPPER ARM LH			Bent	247				247	Reviewi
		30	1			FRONT WHEEL HUB LH			Bent	275				275	Reviewi
		31	1			FRONT WHEEL RIM ALLOY			Cracked	780				780	Reviewi
		32	1			HEADLAMP LH			Cut	1932				1932	Reviewi
		33	1			REAR CAMBER STRUT LH			Bent	128				128	Reviewi
		34	1			REAR CROSSMEMBER			Bent	1290				1290	Reviewi
		35	1			REAR DRIVESHAFT LH			Bent	1450				1450	Reviewi
		36	1			REAR KNUCKLE LH			Bent	855				855	Reviewi
		37	1			REAR SHOCK ABSORBER LH			Bent	865				865	Reviewi
		38	1			REAR STABILIZER BAR LINK ROD LH			Bent	35				35	Reviewi

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		39	1			REAR SUSPENSION LOWER ARM COVER LH			Bent	22				22	Review
		40	1			REAR THRUST ARM LH			Bent	105				105	Review
		41	1			REAR TIE ROD LH			Bent	112				112	Review
		42	1			REAR TOWING STRUT LH			Bent	83				83	Review
		43	1			REAR WHEEL BEARING LH			Bent	215				215	Review
		44	1			REAR WHEEL HUB LH			Bent	238				238	Review
		45	1			REAR WHEEL RIM ALLOY LH			Cracked	780				780	Review

Labour

Add		Approve		Deny		Submit All				
EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REN
		1		TOWING CHARGE	85	0	0	Reviewing		
		2		TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT DOOR MIRROR LH, FRONT DOOR LH, REAR FENDER LH, LH ROCKER PANEL	1000	0	0	Reviewing		
		3		TO KNOCK AND STRAIGHTEN FRONT FENDER RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. TO REALIGN ALL CONNECTION	500	0	0	Reviewing		
		4		TO REMOVE AND REPLACE UNDERCARRIAGE FRONT SUSPENSION LH AND REAR SUSPENSION LH	300	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMARKS
		5		TO COMPUTER WHEEL ALIGNMENT	80	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 8 DAYS	Reviewing			
☐		2	FRONT NUMBER PLATE	Deny	0	NOT NECESSARY	
☐		3	FRONT TYRE LH (\$350) (80%)	Reviewing	280	PUNCTURED	
☐		4	FRONT TYRE RH (\$350) (80%)	Reviewing	280	PUNCTURED	
☐		5	REAR SUSPENSION LOWER ARM LH	Reviewing	160	BENT (SUPPLEMENTARY)	
☐		6	SPOILER RUNNING BOARD PANEL LH	Reviewing	630	DEFORMED (SUPPLEMENTARY)	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		7	FRONT SUSPENSION LOWER ARM SCREW LH	Reviewing	13	BENT (SUPPLEMENTARY)	
		8	CENTER FLOOR PANEL CLIPS (10PCS)	Reviewing	60	NECESSARY (SUPPLEMENTARY)	
		9	CENTER FLOOR PANEL CLAMPS (10PCS)	Reviewing	60	DISTORTED (SUPPLEMENTARY)	
		10	CENTER FLOOR PANEL COVER	Reviewing	102	DEFORMED (SUPPLEMENTARY)	
		11	REAR FLOOR PANEL TORSION BAR LH	Reviewing	55	BENT (SUPPLEMENTARY)	
		12	FRONT SUSPENSION ARM BUSH LH	Reviewing	38	BENT (SUPPLEMENTARY)	
		13	ENGINE CENTER UNDER COVER	Reviewing	115	DEFORMED (SUPPLEMENTARY)	
		14	LINKAGE FRONT LH	Reviewing	304	BENT (SUPPLEMENTARY)	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		15	FRONT CROSS MEMBER	Reviewing	1458	BENT (SUPPLEMENTARY)	
☐		16	FRONT SUSPENSION ARM UPPER SCREW LH	Reviewing	23	BENT (SUPPLEMENTARY)	
☐		17	REAR SUSPENSION ARM LOWER SCREW LH	Reviewing	23	BENT (SUPPLEMENTARY)	
☐		18	FRONT ENGINE MOUNTING LH	Reviewing	195	BENT (SUPPLEMENTARY)	
☐		19	FRONT ENGINE MOUNTING RH	Reviewing	195	BENT (SUPPLEMENTARY)	
☐		20	GEAR BOX MOUNTING	Reviewing	95	BENT (SUPPLEMENTARY)	
☐		21	REAR SUSPENSION COVER THRUST ARM LH	Reviewing	12	DEFORMED (SUPPLEMENTARY)	
☐		22	FRONT SHOCK ABSORBER TOP MOUNT LH	Reviewing	205	BENT (SUPPLEMENTARY)	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐ 	23	FRONT CROSSMEMBER SCREW	Reviewing	15	BENT (SUPPLEMENTARY)	
☐ 	24	REAR FLOOR PANEL COVER	Reviewing	50	DEFORMED (SUPPLEMENTARY)	
☐ 	25	BONNET SPRING (2PCS)	Reviewing	60	BENT (SUPPLEMENTARY)	
☐ 	26	FRONT SPEED WHEEL SENSOR LH	Reviewing	155	DISTORTED (SUPPLEMENTARY)	
☐ 	27	REAR GEAR DIFFERENTIAL	Reviewing	5000	CRACKED (SUPPLEMENTARY)	
☐ 	28	TO REMOVE & REPLACE REAR GEAR DIFFERENTIAL	Reviewing	200	(SUPPLEMENTARY)	
☐ 	29	TO REMOVE & REFIX EXHAUST SILENCER	Reviewing	80	(SUPPLEMENTARY)	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$29,315.00

Claim Amount

\$29,315.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,965.00	\$1,965.00
Miscellaneous	\$9,863.00	\$9,863.00
Excess	-\$400.00	-\$400.00
Spare Parts	\$17,887.00	\$17,887.00

Submit for Review