

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17019244/APA3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant

Vehicle No : SJC2129R

Insured Vehicle No :

SHD826T

Date of Loss: 06/10/2017

Nature of Claim:

TP

Claim No: C0454809

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJC2129R

Make & Model:

HONDA AIRWAVE, 1.5 (A)

Engine No:

HIDDEN

Reg. Date:

(Man. Year: 1900)

Chassis No:

GJ11205530

Colour:

Black

Odometer:

135659 km

Engine Capacity:

0 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

185/65 R14

Rear Tyre Size:

185/65 R14

Front Left Side:

Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side:

Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,064.80	450.00	2,614.80	85.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	880.00	670.00	43.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,614.80	1,330.00	3,284.80	71.18
Approved Total (Overridden) (\$\$)		1,000.00		
Nett Amount (\$\$)	4,614.80	1,000.00	3,614.80	78.33
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 09/10/2017

Date Inspected: 09/10/2017 Inspected At:

Ho Beng Trading (HQ)

Blk 3020A #01-33, Ubi Road 1

Singapore 408714

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2020)
Parts:	M1-MPV	HONDA AIRWAVE 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC2129R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (CONSISTENT)	Repair	1,078.50 F	*- F
2	1		*REAR BUMPER CLIPS (CONSISTENT)	Not Necessary	30.00 F	*- F
3	1		*REAR RH DOOR (CONSISTENT)	Repair	996.30 F	*- F
4	1		*REAR RH WHEEL RIM (CONSISTENT)	Cut	680.00 FS	*450.00 FS
5	1		*REAR RH TYRE (CONSISTENT)	Not Necessary	280.00 FS	*- FS
					Total Parts (S\$)	3,064.80 450.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	200.00
2	SPRAY PAINTING	New	700.00	600.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER DOOR FITTING	New	150.00	0.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	50.00
Gross Labour Cost (\$\$)			1,550.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >