

ASS. REC BY:

REF CS3 / MS617019552 / Ti 627

menimen Taufik

ASSIGNMENT (Office)

From (Person): Lionel Tan

of MS19

Date/Time 10/10/17 @ 4.51pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 7665 B

Insured: SFX 861J

at Workshop m/s

One Zone Autocare @ yehoo.mn

Tel: 62520118

or 7 Soon Lee Street # 01-05 ispace Building, 627608

192308294 EAC

Policy No: A2879573.9 TMP

Claim No: 532168

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/10/2017

CA / REV / REP. / REV 24 HRS

wp

Date/Time: 11/10/17 @ 10:34am

Person Contacted

Mr. Hoo

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJV 7665B - x

SFX 861J - CS / A28030100002 / Rd

Dof: 291308

After repair: 16.10.2017

11.12.17 532pm Email to Lionel Tan thru menimen

Taughlin

REF:

MSTG

mslg

ASSIGNMENT

From

Date

9/10/17

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

SLP6121X

at Workshop in

Performance

at

303 Alexandra Road

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Ven

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value

DAC Accident Report

Consistent? Yes or No

GIA PR Seen

Consistent? Yes or No

Est. Repairs

days

Res

Yes or No

Lump Sum

%

3 Val

Yes or No

CA / REV / REP / 24 HRS 'up'

Date

Person Contacted

Vehicle IN / OUT

Date / Time

Action / Instruction

\$3500 - \$4500

6 days

NO GIA report.

Veh No

SSV7665B

Regd

2010 / Feb 08

Type ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Nissan Syphy

CC 1498

Colour

White

Insured / Std / NI / NA

Sp Reading

T Read Insured / Std / NI / NA

Eng No

C No

JN1BDA611701045Y

Gen Cond Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Mod Nil / SRM / STD AIRim or

Tyre Size

195/65R15

R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R Ba

6

mm

R Ba

6

mm

L Ba

6

mm

L Ba

6

mm

D.O.A

D.O.I

4/1/17 @ 3.21pm

Survey held at

One Zone 7 Sun Lee St

Des of Damages: Frt / Rear / OS / NIS / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision

of OS

URGENT

Date/Time File Pass to:

11.12.2017

Date/Time File Return to:



Prel. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

S - RS

Photo

Others

TOTAL

Report Format:

PRS

Lump Sum / I.B.I.: (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech Insp (\$



Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17019552/T1gb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 11-10-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFX 861J	Veh. Inspected	SVJ 7665B	
Policy No.	A28795937TMP	Coverage (\$)	0.00	
Claim No.	532168	Excess (\$)	0.00	
Assign From	MERIMEN (LIONEL TAN)	Assign Date	10/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/10/2017	Inspection Date	11/10/2017	
Survey held at	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Oct 2017		10 Oct 2017 16:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:		TEO HAK BAK, ID: S0050643E, Tel: +6590089913		[Created by insurer]
Main Claimant:		CHRISPL TRANSPORT SERVICE, Co. Reg. No.: 53356676B		
Vehicle Reg. No.:		SJV7665B	Date of Loss:	06/10/2017 09:00 - :59
Claim Type:		TP / 532168	Policy/Cover Note No.:	A28795739TMP (Third Party Only) Coverage: 27/07/2017 - 26/07/2018
Vehicle Reg. No. (Insured):		SFX861J	Policy No. (Claimant):	
		Excess:	S\$0.00	
Repairer:		One Zone Autocare LLP (HQ) 7 Soon Lee Street #01-05 ISpace Building, 627608 Pioneer - Tel: 62520118		
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/10/2017]		
Driver/Custodian (Insured):		TEO HAK BAK (66 / Male), NRIC: S0050643E, Tel: +6590089913		
Adj Asg. Remarks:		Please contact Mr ERIS @ 9230 8294 OR 6252 0118 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP-RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A.
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

View Sent Message

This mail is associated with :

*SJV7665B (532168)
[SFX861J]

TP

CHRISPL TRANSPORT SERVICE

Oct 6 2017 9:00AM

[TEO HAK BAK]

One Zone Autocare LLP

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 11/12/2017 17:32 PM.
To MSIG_LTPP
Subject Pre-repair Inspection

Dear Lionel,

Refer to your assignment on 10.10.2017 at 4.51PM.

Please be informed that we have inspected the vehicle SJV 7665B on 11.10.2017 at 3.21PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Oct 2017		10 Oct 2017 16:51 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		TEO HAK BAK , ID: S0050643E, Tel: +6590089913 [Created by insurer]							
Main Claimant:		CHRISPL TRANSPORT SERVICE , Co. Reg. No.: 53356676B							
Vehicle Reg. No.:		SJV7665B	Date of Loss:	06/10/2017 09:00 - :59					
Claim Type:		TP / 532168	Policy/Cover Note No.:	A28795739TMP (Third Party Only) Coverage: 27/07/2017 - 26/07/2018					
Vehicle Reg. No. (Insured):		SFX861J	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer:		One Zone Autocare LLP (HQ) 7 Soon Lee Street #01-05 ISpace Building, 627608 Pioneer - Tel: 62520118							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Imm.Advice due 11/10/2017]							
Driver/Custodian (Insured):		TEO HAK BAK (66 / Male), NRIC: S0050643E, Tel: +6590089913							
Adj Asg. Remarks:		Please contact Mr ERIS @ 9230 8294 OR 6252 0118 to arrange for survey .							
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
• MSIG_LTPP (27/11/2017): Upload final report - SJV7665B									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV7665B (532168)
[SFX861J]
TP
CHRISPL TRANSPORT SERVICE
Oct 6 2017 9:00AM
[TEO HAK BAK]
One Zone Autocare LLP

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/10/17 16:24	Accident Statement From: SC - Reg. No: SFX861J, Claimant: TEO HAK BAK		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/10/17 10:04	General View		Load JPG	☒
2	13/10/17 10:04	General View		Load JPG	☒
3	13/10/17 10:04	General View		Load JPG	☒
4	13/10/17 10:04	General View		Load JPG	☒
5	13/10/17 10:04	General View		Load JPG	☒
6	13/10/17 10:04	General View		Load JPG	☒
7	13/10/17 10:04	General View		Load JPG	☒
8	13/10/17 10:04	General View		Load JPG	☒
9	13/10/17 10:04	General View		Load JPG	☒
10	13/10/17 10:04	General View		Load JPG	☒
11	13/10/17 10:04	General View		Load JPG	☒
12	13/10/17 10:04	General View		Load JPG	☒
13	13/10/17 10:04	General View		Load JPG	☒
14	13/10/17 10:04	General View		Load JPG	☒
15	13/10/17 10:04	General View		Load JPG	☒
16	13/10/17 10:04	General View		Load JPG	☒
17	13/10/17 10:04	General View		Load JPG	☒
18	13/10/17 10:04	General View		Load JPG	☒
19	13/10/17 10:04	General View		Load JPG	☒
20	13/10/17 10:04	General View		Load JPG	☒
21	13/10/17 10:04	General View		Load JPG	☒
22	13/10/17 10:04	General View		Load JPG	☒
23	13/10/17 10:04	General View		Load JPG	☒
24	13/10/17 10:04	General View		Load JPG	☒
25	13/10/17 10:04	General View		Load JPG	☒
26	13/10/17 10:04	General View		Load JPG	☒
27	13/10/17 10:04	General View		Load JPG	☒
28	13/10/17 10:04	General View		Load JPG	☒
29	13/10/17 10:04	General View		Load JPG	☒
30	13/10/17 10:04	General View		Load JPG	☒
31	13/10/17 10:04	General View		Load JPG	☒
32	13/10/17 10:04	General View		Load JPG	☒
33	13/10/17 10:04	General View		Load JPG	☒
34	13/10/17 10:04	General View		Load JPG	☒

35	13/10/17 10:04	General View		Load JPG	☒
36	11/12/17 17:30	Photo After Spray		Load JPG	☒
37	11/12/17 17:30	Photo After Spray		Load JPG	☒
38	11/12/17 17:30	Photo After Spray		Load JPG	☒
39	11/12/17 17:30	Photo After Spray		Load JPG	☒
40	11/12/17 17:30	Photo After Spray		Load JPG	☒
41	11/12/17 17:30	Photo After Spray		Load JPG	☒
42	11/12/17 17:30	Photo After Spray		Load JPG	☒
Documentation					
			1 per page ▼		☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail		Print
1	08/12/17 14:11	Repairers Bill		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17019552/T1BE2

Date: 12/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28795739TMP
Claimant Vehicle No :	SJV7665B	Insured Vehicle No :	SFX861J
Date of Loss:	06/10/2017	Nature of Claim:	TP
		Claim No:	532168

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV7665B	Engine No:	HR15267149B
Make & Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Chassis No:	JN1BAAG11Z0110454
Reg. Date:	08/02/2010 (Man. Year: 2009)	Odometer:	136711 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	10/10/2017	
Date Inspected:	11/10/2017 Inspected At:	One Zone Autocare LLP (HQ) 7 Soon Lee Street #01-05 ISpace Building Singapore 627608
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD TAUFIKH

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2017)
Parts:	143	NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV7665B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >