

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17019732/R1GBN2
Date: 31/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80428177QMX
Claimant Vehicle No :	SLB8325H	Insured Vehicle No :	SJR6114C
Date of Loss:	11/10/2017	Nature of Claim:	TP
		Claim No:	532827

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB8325H		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Classic (A)	Engine No:	1ZRY219471
Reg. Date:	25/04/2016 (Man. Year: 2015)	Chassis No:	MR053REH104540298
Colour:	Grey	Odometer:	107753 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,840.70	905.90	2,934.80	76.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,290.00	1,700.00	1,590.00	48.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,130.70	2,605.90	4,524.80	63.46
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	7,130.70	2,050.00	5,080.70	71.25
+ GST 7.00/7.00% (S\$)	499.15	143.50	355.65	71.25
Nett Amount (S\$)	7,629.85	2,193.50	5,436.35	71.25

INSPECTION

Date of Assignment:	13/10/2017 Present Location:	-
Date Inspected:	13/10/2017 Inspected At:	249 Jalan Boon Lay Repairer: Ding Auto Pte Ltd Blk 10 #01-20 Sin Ming Ind Est Sec C Singapore 575645
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 Classic (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SLB8325H/31/01/2018 09:03	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	200.00 F	*200.00 F
2	1		*REAR BUMPER SIDE RETAINER LONG LHS	Cracked	25.00 F	*25.00 F
3	1		*REAR BUMPER SIDE RETAINER LONG RHS	Serviceable	25.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER SHORT RHS	Serviceable	20.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER SHORT LHS	Cracked	20.00 F	*20.00 F
6	1		*REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
7	1		*REAR BUMPER SIDE REFLECTOR LHS	Cracked	36.00 F	*36.00 F
8	1		*REAR BUMPER SIDE REFLECTOR RHS	Not Necessary	36.00 F	*- F
9	1		*REVERSER SENSOR	Necessary	160.00 F	*160.00 F
10	1		*REAR BOOT	Repair	350.00 F	*- F
11	1		*REAR BOOT EMBLEM-LOGO	Necessary	25.00 F	*25.00 F
12	1		*REAR BOOT EMBLEM-COROLLA	Necessary	25.00 F	*25.00 F
13	1		*REAR BOOT EMBLEM-ALTIS	Necessary	25.00 F	*25.00 F
14	1		*REAR BOOT NUMBER PLATE LAMP LHS	Serviceable	40.00 F	*- F
15	1		*REAR BOOT NUMBER PLATE LAMP RHS	Not Necessary	40.00 F	*- F
16	1		*REAR BOOT CHROME	Serviceable	150.00 F	*- F
17	1		*REAR BOOT LOCK	Serviceable	185.00 F	*- F
18	1		*REAR BOOT LOCK CATCH	Serviceable	25.00 F	*- F
19	1		*REAR END PANEL	Repair	180.00 F	*- F
20	1		*REAR END PANEL TOP GARNISH	Serviceable	125.00 F	*- F
21	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	35.00 FS	*35.00 FS
22	1		*SPARE TYRE PANEL	Repair	180.00 F	*- F
23	1		*SPARE TYRE PANEL BOARD	Serviceable	145.00 F	*- F
24	1		*REAR END WEATNERSTRIP	Serviceable	65.00 F	*- F
25	1		*REAR END PANEL BRACKET LHS	Serviceable	35.00 F	*- F
26	1		*REAR END PANEL BRACKET RHS	Serviceable	35.00 F	*- F
27	1		*TAIL LAMP OUTER LHS	Cracked	150.00 F	*150.00 F
28	1		*TAIL LAMP OUTER RHS	Serviceable	150.00 F	*- F
29	1		*TAIL LAMP INNER RHS	Not Necessary	140.00 F	*- F
30	1		*TAIL LAMP INNER LHS	Serviceable	140.00 F	*- F
31	1		*REAR BOOT INNER LINING CLIP	Necessary	35.00 FS	*35.00 FS
32	1		*REAR FENDER LHS	Repair	450.00 F	*- F
33	1		*REAR FENDER INNER SHIELD LHS CLIP	Necessary	35.00 FS	*35.00 FS
34	1		*REAR FENDER INNER SHIELD LHS	Not Necessary	36.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,358.00	806.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	482.70	99.90
Total Parts (\$\$)	3,840.70	905.90

LKK Auto Consultants Pte Ltd/SLB8325H/31/01/2018 09:03. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	1,400.00	700.00
2	R&R BOOTLID COMPONENTS	New	80.00	40.00
3	R&R REAR WINDSCREEN	New	150.00	-
4	R&R SPARETYRE BOARD/CARPET/TRIM	New	100.00	60.00
5	R&R REAR REVERSE SENSOR	New	50.00	40.00
6	SPRAY REAR BUMPER	New	250.00	200.00
7	SPRAY REAR END PANEL	New	250.00	200.00
8	SPRAY REAR BOOT	New	250.00	200.00
9	SPRAY REAR FENDER LHS	New	250.00	200.00
10	SPRAY REAR FENDER RHS	New	250.00	-
11	CHECK WIRING	New	80.00	20.00
12	RUSH PROOFING	New	80.00	40.00
13	SPRAY REVERSE SENSOR	New	100.00	-
Gross Labour Cost (\$\$)			3,290.00	1,700.00

LKK Auto Consultants Pte Ltd/SLB8325H/31/01/2018 09:03. Not valid without Reference section.

< END OF ESTIMATES >