

ASS. REC. BY:

REF: CS/EG1/7019785/Aqbm2

Special Instruction:

Submitted for

Adrian

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

16/10/17 @ 9:14am

Estimated Cost:

Bill to:

OD: (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 6182 G

Insured:

XD 9314 E

at Workshop m/s

MG solution

Tel:

6744 4165

of

23 kaki Bukit Ave 4 (South Wing), #02-03B, 415933

Policy No:

Claim No:

XD9314E / SE / PT D.SNF P1702473

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

12/10/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

16/10/17 @ 9:14am

Person Contacted:

Ms. Heng

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKF6182G-X

XD 9314 E-X

17/10/17 @ 5.07pm Informed Pei Li, we are pending estimate from repairer.

28/11/17 @ 5.05pm revised to Pei Li by email.

vs \$4700, 8 days (led \$9633, 67%)

Surveyor

REF: EGI

ASSIGNMENT

From: _____ Date: 16/10/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKF 6182 G

at Workshop m/s MG solution

of 23 kaki Bukit Ave 4 # 02-03 / 415933

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wpl

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKF6182 G. Yr Regn: 2012 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Scirocco c.c 1390

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 142124

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WVW22213ZCV028633.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235 / 40 R18

R: 235 / 40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 16/10/17.

Survey held at MG solution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S, O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Ego.

RECEIVED 29 NOV 2017

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / L.B.I: (\$ 4700)

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG117019785/Aqb		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 16-10-2017		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 9314E	Veh. Inspected	SKF 6182G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	YEE PEI LEE	Assign Date	16/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/10/2017	Inspection Date	16/10/2017	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No.: 4/EG17019785/Agb
Policy Type: OD / TP / TP RES / TL / EVA

SKF 61829

Case Handler

Typist

Admin (Cath): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

Cath 28/11/17

Case Handler

Date

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 16 October, 2017 9:14 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XD9314E / TP : SKF6182G/LKK / DOA : 12.10.2017
Attachments: XD9314E - SAS.pdf; SKF6182G - SAS.pdf; SKF6182G - PRS FORM.pdf; SKF 6182G - (PRE-INSPECTION) (595 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD – Adrian Ling** to be the "Single Joint Expert".

Please assist to conduct this survey from **MG SOLUTION PTE LTD**,

ADDRESS : 23 KAKI BUKIT AVE 4 (SOUTH WING)
#02-03B VICOM INSPECTION CENTRE
SINGAPORE 415933

PERSON TO CONTACT : MS HENG @ 6744 4165

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most
affordable prices available in the market.

ERGO
TravelProtect

Your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Plc. Ltd

 **BUY NOW**

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 28 November, 2017 5:05 PM
To: Survey Report (ERGO Insurance Pte. Ltd.); assignments
Cc: SUR
Subject: RE: XD9314E / TP : SKF6182G/LKK / DOA : 12.10.2017
Attachments: CSEGI17019785Aqb.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SKF 6182G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 19 October, 2017 10:04 AM
To: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: XD9314E / TP : SKF6182G/LKK / DOA : 12.10.2017

Dear Pei Li,

Noted with thanks.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 18 October, 2017 3:44 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: XD9314E / TP : SKF6182G/LKK / DOA : 12.10.2017

Dear Shiau Chan,

Claim no is DSMFP1702473.

Appreciate for all future ERGO survey email, do not cc email to peili.yee@ergo.com.sg

Thanks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XD9314E/SE/pl

Date: 28th November 2017

Our Ref: CS/EG117019785/Aqb

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SKF 6182G

We thank you for the instruction on 16/10/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/10/2017 at the premises of M/s MG SOLUTION and have the following to report:-

Workshop Estimate Amount	: S\$ <u>14,333.00</u>
Revised Estimate Amount	: S\$ <u>4,700.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages at the rear n/s, o/s portion.



Comments/ Present Status:
Damages consistent.
Days of repair: 8 days.
We have NOT authorise repair.

Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 17 October, 2017 5:02 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments
Cc: 'Yee Pei Li'; SUR
Subject: RE: XD9314E / TP : SKF6182G/LKK / DOA : 12.10.2017

Dear Pei Li,

Please be informed that we have inspected the vehicle SKF 6182G on 16/10/2017.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 16 October, 2017 9:26 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments
<assignments@lkkauto.com>
Cc: 'Yee Pei Li' <pei.li.yee@ergo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: XD9314E / TP : SKF6182G/LKK / DOA : 12.10.2017

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 16 October, 2017 9:14 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XD9314E / TP : SKF6182G/LKK / DOA : 12.10.2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD – Adrian Ling** to be the "Single Joint Expert".

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO : ERGO INSURANCE PTE LTD DATE : 13/10/2017
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SKF6182G
MODEL : VOLKSWAGEN SCIROCCO 1.4A
CHASSIS NO

ACCIDENT DETAILS

DATE : 12-Oct-17
TIME : 14:45HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FENDER RH <i>Dented</i>	1	\$ 1,050.00	\$ 1,050.00 ✓
2	FRONT DOOR RH <i>Repair</i>	1	\$ 1,288.30	\$ 1,288.30 +
3	BOOTLID <i>Repair</i>	1	\$ 1,422.20	\$ 1,422.20 +
4	BOOTLID LOGO <i>New</i>	1	\$ 89.20	\$ 89.20 ✓
5	BOOTLID WINDSCREEN MOULDING <i>New</i>	1	\$ 181.30	\$ 181.30 +
6	REAR BUMPER <i>Dented</i>	1	\$ 1,125.90	\$ 1,125.90 ✓
7	REAR BUMPER SIDE RETAINER <i>n</i>	1	\$ 92.10	\$ 92.10 ✓
8	TAILLAMP LH <i>Dented</i>	1	\$ 412.00	\$ 412.00 ✓
9	TAILLAMP LOWER BRACKET LH <i>New</i>	1	\$ 88.20	\$ 88.20 +
10	REAR FENDER LH <i>Repair</i>	1	\$ 966.20	\$ 966.20 +
11	REAR FENDER INNER COWLING LH <i>Repair</i>	1	\$ 162.50	\$ 162.50 ✓
12	REAR END PANEL <i>n</i>	1	\$ 892.10	\$ 892.10 +

2768.20
2492.28

TOTAL PRICE \$ 7,770.00
LESS 10% \$ 777.00
SUB TOTAL PRICE \$ 6,993.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT WHEEL RIM <i>Wt</i>	1	\$ 850.00	\$ 850.00 550
2	WHOLE CAR STICKER <i>Rec.</i>	1	\$ 1,800.00	\$ 1,800.00 1000.

3	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
4	REAR FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	x.
5	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	x
6	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	x

1570

TOTAL \$ 3,030.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	1000	
3	TUFF COAT	\$ 250.00	40	
4	WIRING CHECK	\$ 80.00	30	
5	UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 150.00	x	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	60	
7	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x.	
9	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO <i>Specification</i> <i>ETC</i>	\$ 350.00	x.	
7	REMOVE AND REFIX FRONT DOOR RH	\$ 100.00	x.	
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 400.00	x.	

to check diagnostic of vehicle

TOTAL

\$4,310.00

1930

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,023.00
TOTAL LABOUR COST : \$ 4,310.00
TOTAL REPAIR COST : \$ 14,333.00

Adrian Lj total: 5882.28

16/10/17.

1/5 08 Days

f/s: 4 TK.

APPROVED DETAILS

EXCESS
NO. OF WORKING DAYS
RE-SURVEY
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI17019785/Aqbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 30-11-2017	
Code : EGI			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 9314E	Veh. Inspected	SKF 6182G
Policy No.		Coverage (\$)	0.00
Claim No.	DSMFP1702473	Excess (\$)	0.00
Assign From	YEE PEI LEE	Assign Date	16/10/2017
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN SCIROCCO	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WWWZZZ13ZCV028633	Colour	GREY
Odometer	142104	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/40 R18	GOODYEAR	6 mm
L/H Front Tyre	235/40 R18	GOODYEAR	6 mm
R/H Rear Tyre	235/40 R18	GOODYEAR	6 mm
L/H Rear Tyre	235/40 R18	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/10/2017	Inspection Date	16/10/2017
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 6182G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER RH	DENTED	1,050.00	1,050.00
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,288.30	-
1	BOOTLID	TO REPAIR SEE LABOUR	1,422.20	-
1	BOOTLID LOGO	NECESSARY	89.20	89.20
1	BOOTLID WINDSCREEN MOULDING	NOT NECESSARY	181.30	-
1	REAR BUMPER	DEFORMED	1,125.90	1,125.90
1	REAR BUMPER SIDE RETAINER	NECESSARY	92.10	92.10
1	TAILLAMP LH	CRACKED	412.00	412.00
1	TAILLAMP LOWER BRACKET LH	NOT NECESSARY	88.20	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	966.20	-
1	REAR FENDER INNER COWLING LH	NOT NECESSARY	162.50	-
1	REAR END PANEL	NOT NECESSARY	892.10	-
	LESS 10% DISCOUNT		-777.00	-276.92
			6,993.00	2,492.28
SPECIAL NETT ITEMS				
1	FRONT WHEEL RIM (SN)	CUT	850.00	550.00
1	WHOLE CAR STICKER (SN)	NECESSARY	1,800.00	1,000.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	SET REAR FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	220.00	-
			3,030.00	1,570.00
LABOUR				
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH, BOOTLID AND REAR FENDER LH.		1,400.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	1,000.00
	TUFF COAT.		250.00	40.00
	WIRING CHECK.		80.00	30.00

Report Ref No. CS/EG17019785/Aqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	60.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	100.00	-
	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	350.00	-
	REMOVE AND REFIX FRONT DOOR RH.	NOT NECESSARY	100.00	-
	REMOVE AND REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	400.00	-
			4,310.00	1,930.00
GRAND TOTAL			14,333.00	5,992.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,700.00

Report Ref No. CS/EGI17019785/Aqbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.