

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17019862/T1FA3Q2

Date: 06/08/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P0594183

Claimant

Vehicle No : GBE9280Z

Insured Vehicle No :

XE132S

Date of Loss: 12/10/2017

Nature of Claim:

TP

Claim No: C0455524

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE9280Z**

Make & Model: TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)

Engine No: 1KD2601976

Reg. Date: 26/04/2016 (Man. Year: 2016)

Chassis No: KDY2318024140

Colour: Silver

Odometer: 59997 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

145 R13

Front Left Side: OHTSU 4 mm

Rear Left Side:

OHTSU 2 mm

Front Right Side: OHTSU 4 mm

Rear Right Side:

OHTSU 2 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 4,484.50 | 2,048.27 | 2,436.23 | 54.33 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,140.00 | 820.00 | 320.00 | 28.07 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,624.50 | 2,868.27 | 2,756.23 | 49.00 |
| Approved Total (Overridden) (S\$) | | 2,300.00 | | |
| (S\$) | 5,624.50 | 2,300.00 | 3,324.50 | 59.11 |
| + GST 7.00/7.00% (S\$) | 393.72 | 161.00 | 232.72 | 59.11 |
| Nett Amount (S\$) | 6,018.22 | 2,461.00 | 3,557.22 | 59.11 |
| + Loss of Use (3.0 x S\$100.00/day) (S\$) | | 300.00 | | |
| + Doc/Search Fee (S\$) | | 5.35 | | |
| Nett Liability (S\$) | | 2,766.35 | | |
| Global Sum Settlement (S\$) | | 2,750.00 | | |

INSPECTION

Date of Assignment: 16/10/2017

Date Inspected: 24/10/2017 Inspected At:

William's Auto Pte Ltd (HQ)
BLK 3 WOODLANDS ROAD 391-B
YEW TEE INDUSTRIAL ESTATE
Singapore 677965

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 03 Aug 2020) | |
| Parts: | N/A | TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBE9280Z) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|---|--------------------------|
| 1 | 1 | | *FRONT DOOR PANEL ADDRESS STICKER -RH (CONSISTENT) | Necessary | 25.00 FS | *25.00 FS |
| 2 | 1 | | *BODY LETTERING AND LOGO (CONSISTENT) | Not Necessary | 180.00 FS | *- FS |
| 3 | 1 | | *FRONT DOOR -RH (CONSISTENT) | Bent | 985.20 F | *985.20 FL |
| 4 | 1 | | *FRONT DOORS SIGNA LAMP -RH (CONSISTENT) | Missing | 145.30 F | *145.30 FL |
| 5 | 1 | | *FRONT DOOR SIGNAL HARNESS -RH (CONSISTENT) | Not Necessary | 179.20 F | *- FL |
| 6 | 1 | | *FRONT DOOR SIDE MIRROR ASSY -RH (CONSISTENT) | Cut | 384.70 F | *384.70 FL |
| 7 | 2 | | *FRONT DOOR HINGE -RH (CONSISTENT) | Repair | 166.20 F | *- FL |
| 8 | 1 | | *FRONT DOOR LOCK -RH (CONSISTENT) | Not Necessary | 257.30 F | *- FL |
| 9 | 1 | | *FRONT DOOR GLASS REGULATOR -RH (CONSISTENT) | Not Necessary | 289.70 F | *- FL |
| 10 | 1 | | *FRONT HEADLAMP -RH (P 1) (CONSISTENT) | Cut | 1,589.50 F | *900.10 FL |
| 11 | 1 | | *FRONT DOOR LOWER STEP GARNISH -RH (CONSISTENT) | Cut | 282.40 F | *282.40 FL |
| | | | | | Sub Total (\$\$) | 4,484.50 2,722.70 |
| | | | | | - List Item Discount on L Items 0.00/25.00% (\$\$) | 0.00 674.43 |
| | | | | | Total Parts (\$\$) | 4,484.50 2,048.27 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | LABOUR TO REMOVE NECESSARY DAMAGED PARTS ENABLE TO STRAIGHTEN PANEL ,PANEL BEAT & REPAIR AFFECTED PILLAR ,PANEL TO THE SAME | New | 450.00 | 350.00 |
| 2 | TO SPRAY PAINT ON REPLACEMENT PARTS AND AFFECTED AREAS | New | 500.00 | 350.00 |
| 3 | LABOUR TO TRANSFER FRONT DAMAGED DOOR -RH ATTACHMENTS TO NEW DOOR | New | 80.00 | 60.00 |
| 4 | WIRING JOB | New | 30.00 | 30.00 |
| 5 | LABOUR TO APPLY /SPRAY PAINT RUST PROOFING WHERE IS NECESSARY | New | 80.00 | 30.00 |
| Gross Labour Cost (\$\$) | | | 1,140.00 | 820.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >