

22/03/2002

ASS. REC. BY:

REF:

CS/AWA17019867/midp02

Special Instruction:

Surveyor:

Ma.

ASSIGNMENT (Office)

From (Person):

Tan Kah Leng

of

AWA

Date/Time:

16-10-2017 423pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SHC 106T

Insured:

EN 16Y

at Workshop m/s

Soon Hock Motor

Tel:

65425119

of

Blk 10 Amk. Ind Park A #01-05

Policy No:

BVPPSB0549051700

Claim No:

NSV1701169/BT

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14-10-2017

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

16-10-2017 5pm

Person Contacted:

Lynn

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 106T - PS3 / F7 (150115) / Uthall

2017-06-21B

EN 16Y. x

Surveyor:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s CHUNNI.

of

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 13 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SAC106T Yr Regn: APR 2002

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TEY N BONKHA c.c 1991

Colour: Yellow A/C: Insured / Std / NI / NA

Sp.Reading: No Reading T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMAHET4IXMCA 822525

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: — L

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 14/10/2012 D.O.I. 19/10/2012

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Chad 10/05/30, 55%

9k 13w/1 days

RECEIVED 27 FEB 2011

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 13

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) S + RS. SI

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$)

TOTAL

Report Format : TP

Lump Sum / I.B.I. (\$) 9000

250
250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17019867/M1qb

(SINGAPORE BRANCH)
60 ANSON ROAD, #08-01 (9th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 16-10-2017



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EN 16Y	Veh. Inspected	SHC 106T
Policy No.	BVPPSB0549051700	Coverage (\$)	0.00
Claim No.	NSV170116/BT	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	16/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/10/2017	Inspection Date	16/10/2017
Survey held at	SOON HOCK MOTOR PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PK 2A #01-05/06 AMK AUTOPOINT . SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No.: CS/AWA170198677 Mugb
Policy Type: OD / TP / TP RES / TL / EVA

SHC 1067

Case Handler

Typist

Admin (Cath): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA /REV/REP)	✓			
C Report Type	✓			
C Weekend Charges	✓			
N Survey held at/Repairer	✓			
C Excess				

Surveyor (Ma C.F.): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	✓		
--	---	--	--


(3) Workshop Estimate/Assignment Form

N ALL Parts condition	✓		
C Market Value for OD cases			
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)			
C Days of repair	✓		
C Finalised Amount			
C Re-inspection Cases to Finalize within 5 Days			

(4) System - (Views/Merimen)

C Resurvey photo Uploaded			
---------------------------	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

Catherine Chong (LKK Auto)

From: Tan, KahLeong <KahLeong.Tan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Monday, 16 October, 2017 4:23 PM
To: LKK (assignments@lkkauto.com)
Cc: SUR (sur@lkkauto.com); chunnimotor@gmail.com
Subject: TP Survey assignment for SHC 106T - DOA: 14.10.2017 Our ref: NSV1701169/BT

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of Mr Ma Chin Fook, as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SHC 106 T
Insured Vehicle	:	EN 16 Y
Policy Number	:	BVPPSB0549051700
Name of Workshop	:	Soon Hock Motor
Contact Number	:	6483 6016 / 6542 5119 / 6542 7162
Person to Contact	:	Ms Lynn / Ms Irene
Estimated Cost of repairs	:	\$ 19,805.30

Regards,
Claims Division

Copy to Soon Hock Motor via Email

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group
Global Market

MCD817136860 / ConforDelGro Engineering Pte Ltd - Loyang
ENTRY DATE & TIME: 16/10/2017 09:34

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2017 09:34
Date Of Accident	14/10/2017 13:35
Exact Location Of Accident	PIE TWDS CHANGI AIRPORT B4 LOR 6 TOA PAYOH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC106T
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	SONATA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-15072702MFSH
Cover Note Number	
Driver	
Name of Driver	CHIN WEI SHENG EDMUND
NRIC No	S8201578G
Date Of Birth	22/02/1982
Occupation	OUTDOOR
Date Of Driving Pass	29/06/2010
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	EWEISHENG22@GMAIL.COM

Address BLK 219C BEDOK CENTRAL
#02-118
Postcode 463219
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number EN16Y
Vehicle Make/Model/Colour LAND ROVER
Details Of Properties
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT AND REAR
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLS5167C
 Vehicle Make/Model/Colour BMW
 Details Of Properties
 Name of Driver R GUNASEGARAN
 NRIC/Passport Number S7244676C
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage REAR
 No. Of Passenger (Including Driver)
 Details of Witness
 Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJF1128P
 Vehicle Make/Model/Colour SUBARU
 Details Of Properties
 Name of Driver UNKNOWN
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage FRONT
 No. Of Passenger (Including Driver)
 Details of Witness
 Name
 Phone Number
 Email Address

DETAILS OF INJURED PERSON 1

Name CHIN WEI SHENG EDMUND
 Approximate Age
 Injuries Sustain BACK, NECK AND BODY
 Injured person in which vehicle? SHC106T
 Were seat belts worn? YES
 Was injured conveyed to hospital by ambulance? NO
 Address BLK 219C BEDOK CENTRAL
 #02-118
 Postcode 463219

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


CITYCAB PTE LTD
CO. REG. NO. 199502838G

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 15/10/2017@11:00hrs


Reporting Centre Personnel's Signature
Name: Lisa Diong
NRIC/FIN No.: -

SKETCH PLAN



Along PIE Twds Changi Airport B/4 Lor 6 Toa Payoh Exit

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/10/2017@ 13:35hrs,My taxi (A) was travelling along PIE twds Changi Airport B/4 Lor 6 Toa Payoh Exit.With 1 male 1 female passenger on board.
I was on the extreme right lane 1,I saw infront of me vehicle slow down and stopped,so I follow too.Out of sudden,there was a loud impact coming from the rear portion and caused my taxi (A) to lose control and surge forward,and hit onto the veh (C) rear portion.My taxi (A) front and rear portion was damaged.
I assessed the damages to my taxi (A) and come to know that were 4 vehicles involved in the chain accident.
A-SHC 106T
B-EN 16Y male driver
C-SLS 5167C Mr Gunasegaran,S 7244676C.
D-SJF 1126P male driver
After the accident,I felt pain back,neck and body,will consult doctor later on.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15/10/2017@11:00hrs

Reporting Centre Personnel's Signature
Name: Lisa Diong
NRIC/FIN No.: -

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE****To survey by ULC (Ma)*

VEHICLE NO : SHC 106T (CITYCAB)

DATE : 16.10.2017

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

Allied

- Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille		X \$ 282.10		ave
	Radiator Grille U Moulding		X \$ 108.90		da.
	Front Bumper Cover		X \$ 538.80		det
	Front Bumper Sponge		X \$ 136.30		ove
	Front Bumper Reinforcement		X \$ 504.10		ave
	Front Bumper Bracket Top (LH/RH)	\$	22.40	\$ 44.80	} dis
	Front Bumper Protector (LH/RH)	\$	29.20	\$ 58.40	
	Front Bumper Bracket (LH/RH)	\$	20.10	\$ 40.20	
	Front Bumper Side Bracket	\$	14.30	\$ 28.60	
	Headlamp Support Panel Assy		X \$ 1,023.00		ove
	Headlamp (LH/RH)	\$	797.90	\$ 1,595.80	ave.
	Radiator		X \$ 814.80		ove
	Radiator Fan Blade,Cowling,Motor Assy		X \$ 651.30		ove
	Radiator Bracket	\$	6.20	X \$ 12.40	ove
	Aircon Condenser		X \$ 1,089.90		ove
	Inter Cooler		X \$ 771.50		ave
	Inter Cooler Mounting (2 PCS)		X \$ 24.80		ove
	Wiring-ECM		X \$ 3,107.80		dis
				\$ 10,833.50	
				\$ 2,166.70	
				\$ 8,666.80	
	Front Number Plate		\$ 25.00		Nett
	Front No Plate Trim Cover		\$ 30.00		Nett
				\$ 55.00	
	Labour Charge				
	Panel Beating		\$ 1,000.00		500
	Spray Painting Charge		\$ 200.00		180
	Wiring Charge		\$ 50.00		30
	Towing Charge		\$ 50.00		/
	Remove/Refix Aircon & Refill Gas		\$ 150.00		100
	Remove/Refix Dashboard		\$ 450.00		200?
	Remove/Refix Fuse Box		\$ 180.00		X
				\$ 2,080.00	

SHC 106T

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid			\$ 1,349.50	da
	Boot Lid Rubber			\$ 110.90	dis
	Boot Lid Lock Upper			\$ 132.10	da
	Boot Lid Lock Lower			\$ 30.30	da
	Boot Lid Sonata Plate			\$ 43.60	na
	Boot Lid Hyundai Plate			\$ 24.20	na
	Boot Lid 'H' Emblem			\$ 26.10	na
	Boot Lid CRDI Plate			\$ 22.70	na
	Boot Lid Lamp (LH/RH)		\$ 230.00	\$ 460.00	avg
	Boot Lid Trimboard			\$ 165.40	turn
	Boot Lid Trimboard Clips (11pcs)			\$ 11.00	na
	Rear Bumper			\$ 578.40	da
	Rear Bumper Reinforcement			\$ 483.30	turn
	Rear Bumper Clip			\$ 22.00	na
	Rear Bumper Bracket			\$ 49.00	dis
	Rear Bumper Sponge			\$ 137.40	turn
	Rear Bumper Under Cover			\$ 185.80	na
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00	avg
	Tail Lamp (LH/RH)		\$ 344.00	\$ 688.00	avg
	Rear Panel			\$ 391.80	da
	Rear Panel Garnish			\$ 95.80	dis
	Spare Tyre Holder			\$ 27.60	na
	Spare Tyre Panel			\$ 863.00	na
	Spare Tyre Panel Cushion			\$ 200.30	da
	Rear Towing Hook			\$ 135.30	na
	Member Assy- Rear Floor Centre			\$ 163.60	na
	Panel Assy-Rear Floor Side (RH)			\$ 88.55	na
	Exhaust Pipe Insulator			\$ 56.10	na
	Exhaust Silencer			\$ 723.00	da
	Exhaust Pipe Hanger			\$ 56.10	na
	SUB TOTAL			\$ 7,397.25	
	LESS 20%			\$ 1,479.45	
	DISCOUNTED TOTAL			\$ 5,917.80	
	Boot Lid City Cab Logo & Tel No Sticker			\$ 30.00	Nett na
	Rear Bumper Reverse Sensor			\$ 135.70	Nett na
	Rear Bumper Rubber Mat			\$ 50.00	Nett na
	Labour Charge			\$ 215.70	
	Panel Beating			\$ 1,500.00	1500
	Spray Painting Charge			\$ 1,000.00	900
	Wiring Charge			\$ 50.00	30
	Tuff Kote			\$ 50.00	40
	Remove/Refix Reverse Sensor			\$ 120.00	60
	Remove/Refix Exhaust Pipe			\$ 150.00	207
	TOTAL LABOUR			\$ 2,870.00	
	ESTIMATE TOTAL			\$ 19,805.30	

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

19/10/2017
10w Jang
20/10/17




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD			Ref : CS/AWA17019867/M1qbe2	
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (9th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Date : 05-03-2018	
			Code : AWA	
1. Policy Particulars : THIRD PARTY CLAIM				
Insured Veh.	EN 16Y	Veh. Inspected	SHC 106T	
Policy No.	BVPPSB0549051700	Coverage (\$)	0.00	
Claim No.	NSV170116/BT	Excess (\$)	0.00	
Assign From	TAN KAH LEONG	Assign Date	16/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KMHET41VMCA822525	Colour	YELLOW	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MAXXIS	7 mm	
L/H Front Tyre	215/60 R16	MAXXIS	7 mm	
R/H Rear Tyre	215/60 R16	MAXXIS	7 mm	
L/H Rear Tyre	215/60 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/10/2017	Inspection Date	19/10/2017	
Survey held at	SOON HOCK MOTOR PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PK 2A #01-05/06 AMK AUTOPOINT . SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 106T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Out Adjusted (\$)
REPLACEMENT OF PARTS				
1	RADIATOR GRILLE	SERVICEABLE	282.10	-
1	RADIATOR GRILLE U MOULDING	DENTED	108.90	108.90
1	FRONT BUMPER COVER	DEFORMED	538.80	538.80
1	FRONT BUMPER SPONGE	SERVICEABLE	136.30	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	504.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	DISTORTED	44.80	44.80
2	FRONT BUMPER PROTECTOR (LH/RH) @\$29.20	DISTORTED	58.40	58.40
2	FRONT BUMPER BRACKET (LH/RH) @\$20.10	DISTORTED	40.20	40.20
2	FRONT BUMPER SIDE BRACKET @\$14.30	DISTORTED	28.60	28.60
1	HEADLAMP SUPPORT PANEL ASSY	SERVICEABLE	1,023.00	-
2	HEADLAMP (LH/RH) @\$797.90	CRACKED	1,595.80	1,595.80
1	RADIATOR	SERVICEABLE	814.80	-
1	RADIATOR FAN BLADE, COWLING, MOTOR ASSY	SERVICEABLE	651.30	-
2	RADIATOR BRACKET @\$6.20	SERVICEABLE	12.40	-
1	AIRCON CONDENSER	SERVICEABLE	1,089.90	-
1	INTER COOLER	SERVICEABLE	771.50	-
2	INTER COOLER MOUNTING	SERVICEABLE	24.80	-
1	WIRING - ECM	DISTORTED	3,107.80	3,107.80
1	BOOT LID	DENTED	1,349.50	1,349.50
1	BOOT LID RUBBER	DISTORTED	110.90	110.90
1	BOOT LID LOCK UPPER	BENT	132.10	132.10
1	BOOT LID LOCK LOWER	BENT	30.30	30.30
1	BOOT LID SONATA PLATE	NECESSARY	43.60	43.60
1	BOOT LID HYUNDAI PLATE	NECESSARY	24.20	24.20
1	BOOT LID 'H' EMBLEM	NECESSARY	26.10	26.10
1	BOOT LID CRDI PLATE	NECESSARY	22.70	22.70
2	BOOT LID LAMP (LH/RH) @\$230.20	CRACKED	460.40	460.40
1	BOOT LID TRIMBOARD	TORN	165.40	165.40
11	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	REAR BUMPER	DEFORMED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	TORN	483.30	483.30
1	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET	DISTORTED	49.00	49.00
1	REAR BUMPER SPONGE	TORN	137.40	137.40

Report Ref No. CS/AWA17019867/M1qbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate (Before Workshop) (\$)	Quoted Adjusted (\$)
1	REAR BUMPER UNDER COVER	SERVICEABLE	185.80	-
2	REAR BUMPER PROTECTOR (LH/RH) @\$38.00	N/S DISTORTED / O/S SERVICEABLE	76.00	38.00
2	TAIL LAMP (LH/RH) @\$344.00	CRACKED	688.00	688.00
1	REAR PANEL	DENTED	391.80	391.80
1	REAR PANEL GARNISH	DISTORTED	95.80	95.80
1	SPARE TYRE HOLDER	SERVICEABLE	27.60	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	863.00	-
1	SPARE TYRE PANEL CUSHION	DEFORMED	200.30	200.30
1	REAR TOWING HOOK	TO REPAIR SEE LABOUR	135.30	-
1	MEMBER ASSY - REAR FLOOR CENTRE	TO REPAIR SEE LABOUR	163.60	-
1	PANEL ASSY - REAR FLOOR SIDE (RH)	TO REPAIR SEE LABOUR	88.55	-
1	EXHAUST PIPE INSULATOR	SERVICEABLE	56.10	-
1	EXHAUST SILENCER	BENT	723.00	723.00
1	EXHAUST PIPE HANGER	TO REPAIR SEE LABOUR	56.10	-
	LESS 20% DISCOUNT		-3,646.15	-2,261.30
			14,584.60	9,045.20
	SPECIAL NETT ITEMS			
1	BOOT LID CITY CAB LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	FRONT NUMBER PLATE (SN) }	BENT	25.00	40.00
1	FRONT NO PLATE TRIM COVER (SN) }		30.00	-
			270.70	255.70
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL, REAR TOWING HOOK, MEMBER ASSY - REAR FLOOR CENTRE, PANEL ASSY - REAR FLOOR SIDE (RH) AND EXHAUST PIPE HANGER.		2,500.00	1,500.00
	SPRAY PAINTING CHARGE.		1,200.00	1,080.00
	WIRING CHARGE.		100.00	60.00
	TOWING CHARGE.		50.00	50.00
	REMOVE / REFILL AIRCON & REFILL GAS.		150.00	100.00

Report Ref No. CS/AWA17019867/M1qbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX DASHBOARD.	NOT NECESSARY	450.00	280.00
	REMOVE / REFIX FUSE BOX.		180.00	-
	TUFF KOTE.		50.00	40.00
	REMOVE/ REFIX REVERSE SENSOR.		120.00	60.00
	REMOVE/REFIX EXHAUST PIPE.		150.00	20.00
			4,950.00	3,190.00
GRAND TOTAL			19,805.30	12,490.90

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,000.00
---	--	--	----------

Report Ref No. CS/AWA17019867/M1qbe2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.