


- Picture -

Mode	MD mode	Mod. des. overview	PANEL VAN WHEELBASE 3200 MM, LONG OVERHANG
FIN/MD	WDF 44760323272799	Catalog	60V
VIN	WDF44760323272799	Major assembly:	
Sales designation	109KA/ L 4X2 3200	Major assembly MD	
Assortment class	Van	Group	50 - RADIATOR
Market	Europe	Subgroup	030 - RADIATOR
Picture number	B50030000044.170321		





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR GBF9602Z*M

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #08-16
AIG BUILDING
SINGAPORE 079120
64191000

Vehicle & Document Information

WIP No 34049
Reg No/Reg Date GBF9602Z*M / 02/05/2017
Date In/Mileage 07/08/2017 / 6285
Chassis No WDF44760323272799
Engine No R9MA503C016413
Make/Model MBCV/Vito 109KA/ L 4X2 3200 Ma
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator				
WA00000/	Credit	16/11/2017/ 12:42	WS	122 / Ng Wei Siang				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z. Complaint								
GEAR CANNOT ENGAGE WHEN START								120.00
S SUB								
VEHICLE TOWING FROM 4 WOOLLERTON PARK TO 188 PANDAN LOOP								60.00
A 26100501								
CHECK TRANSMISSION OPERATION								
VEHICLE AFTER WARM UP, AFTER ENGAGE GEAR, PRESS ACCELERATE BUT								
VEHICLE CANNOT MOVE								
A 00000099						0.79		100.00
Add job to remove front bumper								
A 20400002						16.66		200.00
REPLACE RADIATOR								
A 20114001						28.57		60.00
REPLACE COOLANT INCLUDING ANTIFREEZE, CHECK FOR LEAKS								
A 88115701						16.66		100.00
BUMPER WITH INTEGRATED FRONT RADIATOR GRILLE REPLACE								
A 88185801								36.00
BRACKET FOR FRONT BUMPER REPLACE (BUMPER REMOVED)								
A 88193601						28.57		60.00
UPPER CROSSMEMBER REMOVE/ INSTALL (BUMPER REMOVED)								
A 09881001						0.79		100.00
REPLACE AIR DUCT								
A 83176201						33.33		40.00
EXTRACT REFRIGERANT, CHECK FOR LEAKS, REFILL (WHEN WORKING ON AIR								
CONDITIONING)								
A 83654303						16.66		100.00
CONDENSER REMOVE/INSTALL AND, IF NECESSARY, REPLACE (WITH SYSTEM								
DRAINED) ALL AIR CONDITIONERS								
A 83662201						33.33		40.00
DRIER CARTRIDGE REPLACE								
M FREON GAS								100.00
FREON GAS								

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6771 4389
Fax: 6775 6310
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR GBF9602Z*M

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #08-16
AIG BUILDING
SINGAPORE 079120
64191000

Vehicle & Document Information

WIP No 34049
Reg No/Reg Date GBF9602Z*M / 02/05/2017
Date In/Mileage 07/08/2017/ 6285
Chassis No WDF44760323272799
Engine No R9MA503C016413
Make/Model NBCV/Vito 109KA/ L 4X2 3200 Ma
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000007	Credit	16/11/2017/ 12:42	WS	122 / Ng Wei Siang				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S SUBADJ. SUB-COST ADJUSTMENT REFER PO: 272716 (adjust cost price)								-1200.00
X BPNEXC INSURANCE EXCESS								
X BRACKET					1.00	23.59	10.00	21.23
X BRACKET					1.00	23.59	10.00	21.23
X COOLANT RADIATOR					1.00	408.11	10.00	367.30
X CROSS MEMBER					1.00	216.44	10.00	194.80
X SUPPORT					1.00	90.12	10.00	81.11
X SCREW					3.00	1.49	10.00	4.02
X RIVET					4.00	4.16	10.00	14.98
X AIR DUCT					1.00	53.85	10.00	48.46
X AIR DUCT					1.00	53.56	10.00	48.20
X AIR DUCT					1.00	97.59	10.00	87.83
X MOUNTING FRAME					1.00	90.31	10.00	81.28
X REFRIGERANT CONDENSER					1.00	540.36	10.00	486.32
X TRIM BUMPER					1.00	651.08	10.00	585.97
X TRIM PANEL WHEEL HOUSING					1.00	129.47	10.00	116.52
X TRIM PANEL WHEEL HOUSING					1.00	129.47	10.00	116.52
X RADIATOR ANTIFREEZE					2.00	45.18	10.00	81.32
X COVER HOOD					1.00	398.81	10.00	358.93
X STUD					1.00	3.08	10.00	2.77
X *P NUT					8.00	1.91	10.00	13.75
X BRACKET					1.00	16.78	10.00	15.10
X *P NUT					4.00	1.21	10.00	4.36
X BRACKET					1.00	20.19	10.00	18.17
X LOCK					2.00	1.30	10.00	2.34
X NUT					3.00	2.23	10.00	6.02
X REFRIGERANT DRIER					1.00	88.88	10.00	79.99
X LINK BLOCK					1.00	8.36	10.00	7.52
X ELASTOMER BEARING					2.00	1.97	10.00	3.55 (17)

Confirmed & accepted by

Nett 2,785.59
7% GST on 2785.59 194.99

Total Payable 2,980.58

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6771 4389
Fax: 6775 6310
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Daimler Fleet Management Singap Reg No/Reg Date GBF9602Z*M / 02/05/2017 Date In/Mileage 07/08/2017/ 6285 Chassis No WDF44760323272799 Engine No R9MA503C016413 Make/Model MBCV/Vito 109KA/ L 4X2 3200 Ma Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
WA000007	Credit	23/11/2017/ 12:03	WS	122 / Ng Wei Siang	34049	25302084
Description of Goods / Services				Qty	Unit Price S\$	Amount S\$
Z Complaint						
GEAR CANNOT ENGAGE WHEN START						
S SUB						120.00
VEHICLE TOWING FROM 4 WOOLLERTON PARK TO 188 PANDAN LOOP						
A 26100501						60.00
CHECK TRANSMISSION OPERATION						
VEHICLE AFTER WARM UP, AFTER ENGAGE GEAR, PRESS ACCELERATE BUT						
VEHICLE CANNOT MOVE						
A 00000099					0.79	100.00
Add job to remove front bumper						
A 20400002					16.66	200.00
REPLACE RADIATOR						
A 20114001					28.57	60.00
REPLACE COOLANT INCLUDING ANTIFREEZE, CHECK FOR LEAKS						
A 88115701					16.66	100.00
BUMPER WITH INTEGRATED FRONT RADIATOR GRILLE REPLACE						
A 88185801						36.00
BRACKET FOR FRONT BUMPER REPLACE (BUMPER REMOVED)						
A 88193601					28.57	60.00
UPPER CROSSMEMBER REMOVE/ INSTALL (BUMPER REMOVED)						
A 09881001					0.79	100.00
REPLACE AIR DUCT						
A 83176201					33.33	40.00
EXTRACT REFRIGERANT, CHECK FOR LEAKS, REFILL (WHEN WORKING ON AIR						
CONDITIONING)						
A 83654303					16.66	100.00
CONDENSER REMOVE/INSTALL AND, IF NECESSARY, REPLACE (WITH SYSTEM						
DRAINED) ALL AIR CONDITIONERS						
A 83662201					33.33	40.00
DRIER CARTRIDGE REPLACE						
M FREON GAS						100.00
FREON GAS						
S SUBADJ						F.O.C.

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6771 4389
Fax: 6775 6310
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Daimler Fleet Management Singap Reg No/Reg Date GBF9602Z*M / 02/05/2017 Date In/Mileage 07/08/2017/ 6285 Chassis No WDF44760323272799 Engine No R9MA503C016413 Make/Model MBCV/Vito 109KA/ L 4X2 3200 Ma Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
WA000007	Credit	23/11/2017/ 12:03	WS	122 / Ng Wei Siang	34049	25302084

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
SUB COST ADJUSTMENT REFER PO:272716 WIPLINE:6 (adjust cost price)			-1200.00
X BPNEXC			
INSURANCE EXCESS			
X BRACKET	1.00	23.59 10.00	21.23
X BRACKET	1.00	23.59 10.00	21.23
X COOLANT RADIATOR	1.00	408.11 10.00	367.30
X CROSS MEMBER	1.00	216.44 10.00	194.80
X SUPPORT	1.00	90.12 10.00	81.11
X SCREW	3.00	1.49 10.00	4.02
X RIVET	4.00	4.16 10.00	14.98
X AIR DUCT	1.00	53.85 10.00	48.46
X AIR DUCT	1.00	53.56 10.00	48.20
X AIR DUCT	1.00	97.59 10.00	87.83
X MOUNTING FRAME	1.00	90.31 10.00	81.28
X REFRIGERANT CONDENSER	1.00	540.36 10.00	486.32
X TRIM BUMPER	1.00	651.08 10.00	585.97
X TRIM PANEL WHEEL HOUSING	1.00	129.47 10.00	116.52
X TRIM PANEL WHEEL HOUSING	1.00	129.47 10.00	116.52
X RADIATOR ANTIFREEZE	2.00	45.18 10.00	81.32
X COVER HOOD	1.00	398.81 10.00	358.93
X STUD	1.00	3.08 10.00	2.77
X *P NUT	8.00	1.91 10.00	13.75
X BRACKET	1.00	16.78 10.00	15.10
X *P NUT	4.00	1.21 10.00	4.36
X BRACKET	1.00	20.19 10.00	18.17
X LOCK	2.00	1.30 10.00	2.34
X NUT	3.00	2.23 10.00	6.02
X REFRIGERANT DRIER	1.00	88.88 10.00	79.99
X LINK BLOCK	1.00	8.36 10.00	7.52
X ELASTOMER BEARING	2.00	1.97 10.00	3.55

Parts	2,869.59	Nett	2,785.59
Labour	896.00	7% GST on	194.99
Standard Menu	0.00		
Specialist Job	120.00	Total Payable	2,980.58
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	-1,100.00	Total Due	2,980.58
Total (w/o GST)	2,785.59		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6771 4389
Fax: 6775 6310
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2017		24 Oct 2017 11:23 Edit Adj Rpt	S\$3,985.59 Edit Estimates	S\$3,985.59 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z		
Vehicle Reg. No.:	GBF9602Z	Date of Loss:	05/08/2017 14:00 - :59
Claim Type:	OD / 5683268885SG	Policy/Cover Note No.:	999995580 (Comprehensive)
		Excess:	S\$1,200.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/11/2017]		
Driver/Custodian:	MUHAMMAD IBNU'ATTAILLAH BIN JOHARI (30 / Male), NRIC: S8704009G, Tel: +6590086240		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
AIG_SG (24/10/2017): GBF9602Z / OD / 05/08/2017 / Coverage & Excess update			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*GBF9602Z (568326885SG)

OD

Aug 5 2017 2:30PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Cycle & Carriage Industries Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer	
Photos/Images								3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	23/11/17 11:41	Chassis Number							Load JPG	☒	
2	23/11/17 11:41	General View							Load JPG	☒	
3	23/11/17 11:41	General View							Load JPG	☒	
4	23/11/17 11:41	General View							Load JPG	☒	
5	23/11/17 11:41	General View							Load JPG	☒	
6	23/11/17 11:41	General View							Load JPG	☒	
7	23/11/17 11:41	General View							Load JPG	☒	
8	23/11/17 11:41	General View							Load JPG	☒	
9	23/11/17 11:41	General View							Load JPG	☒	
10	23/11/17 11:41	General View							Load JPG	☒	
11	23/11/17 11:41	General View							Load JPG	☒	
12	23/11/17 11:41	General View							Load JPG	☒	
13	23/11/17 11:41	General View							Load JPG	☒	
14	23/11/17 11:41	General View							Load JPG	☒	
15	23/11/17 11:41	General View							Load JPG	☒	
16	23/11/17 11:41	General View							Load JPG	☒	
17	23/11/17 11:41	General View							Load JPG	☒	
18	23/11/17 11:41	General View							Load JPG	☒	
19	23/11/17 11:41	General View							Load JPG	☒	
20	23/11/17 11:41	General View							Load JPG	☒	
21	23/11/17 11:41	General View							Load JPG	☒	
22	23/11/17 11:41	General View							Load JPG	☒	
23	23/11/17 11:41	General View							Load JPG	☒	
24	23/11/17 11:41	General View							Load JPG	☒	
25	23/11/17 11:41	General View							Load JPG	☒	
26	23/11/17 11:41	General View							Load JPG	☒	
27	23/11/17 11:41	General View							Load JPG	☒	
28	23/11/17 11:41	General View							Load JPG	☒	
29	23/11/17 11:41	General View							Load JPG	☒	
30	23/11/17 11:41	General View							Load JPG	☒	
31	23/11/17 11:41	General View							Load JPG	☒	
32	23/11/17 11:41	General View							Load JPG	☒	
33	23/11/17 11:41	General View							Load JPG	☒	
34	23/11/17 11:41	General View							Load JPG	☒	
35	23/11/17 11:41	General View							Load JPG	☒	
36	23/11/17 11:41	General View							Load JPG	☒	
37	23/11/17 11:41	General View							Load JPG	☒	
38	23/11/17 11:41	General View							Load JPG	☒	
39	23/11/17 11:41	General View							Load JPG	☒	
40	23/11/17 11:41	General View							Load JPG	☒	

41	23/11/17 11:41	General View		Load JPG	☒
42	23/11/17 11:41	General View		Load JPG	☒
43	23/11/17 11:41	General View		Load JPG	☒
44	23/11/17 11:41	Reinspection Photo		Load JPG	☒
45	23/11/17 11:41	Reinspection Photo		Load JPG	☒
46	23/11/17 11:41	Reinspection Photo		Load JPG	☒
47	23/11/17 11:41	Reinspection Photo		Load JPG	☒
48	23/11/17 11:41	Reinspection Photo		Load JPG	☒
49	23/11/17 11:41	Reinspection Photo		Load JPG	☒
50	23/11/17 11:41	Reinspection Photo		Load JPG	☒
51	23/11/17 11:41	Reinspection Photo		Load JPG	☒
52	23/11/17 11:41	Reinspection Photo		Load JPG	☒
53	23/11/17 11:41	Reinspection Photo		Load JPG	☒
54	23/11/17 11:41	Reinspection Photo		Load JPG	☒
55	23/11/17 11:41	Reinspection Photo		Load JPG	☒
56	23/11/17 11:41	Reinspection Photo		Load JPG	☒
57	23/11/17 11:41	Reinspection Photo		Load JPG	☒
58	23/11/17 11:41	Reinspection Photo		Load JPG	☒
59	23/11/17 11:41	Reinspection Photo		Load JPG	☒
60	23/11/17 11:41	Reinspection Photo		Load JPG	☒
61	23/11/17 11:41	Reinspection Photo		Load JPG	☒
62	23/11/17 11:42	Reinspection Photo		Load JPG	☒
63	23/11/17 11:42	Reinspection Photo		Load JPG	☒
64	23/11/17 11:42	Reinspection Photo		Load JPG	☒
65	23/11/17 11:42	Reinspection Photo		Load JPG	☒
66	23/11/17 11:42	Reinspection Photo		Load JPG	☒
67	23/11/17 11:42	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/10/17 11:58	Certificate of Insurance		Load PDF	
2	24/10/17 11:58	WORKSHOP ESTIMATE		Load PDF	
3	28/11/17 10:18	Discharge Voucher		Load PDF	

Linked Accident Report Documents

				View	Use Viewer
Assessment Reports				1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	07/10/17 17:13	Accident Statement		Load HTM	
2	10/10/17 16:21	Accident Statement Addm. #1		Load HTM	
3	11/10/17 17:17	Addendum Sheet		Load JPG	☒
4	11/10/17 17:17	Accident Statement Addm. #2		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	10/10/17 16:20	Accident Photo		Load JPG	☒
2	10/10/17 16:20	Accident Photo		Load JPG	☒
3	10/10/17 16:20	Accident Photo		Load JPG	☒
4	10/10/17 16:20	Accident Photo		Load JPG	☒
5	10/10/17 16:20	Accident Photo		Load JPG	☒
6	10/10/17 16:20	Accident Photo		Load JPG	☒
7	10/10/17 16:20	Accident Photo		Load JPG	☒
8	10/10/17 16:20	Accident Photo		Load JPG	☒
9	10/10/17 16:20	Accident Photo		Load JPG	☒

10	10/10/17 16:20	Driving License		Load JPG	☒
11	10/10/17 16:20	Driving License		Load JPG	☒
Documentation			1 per page		☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail		
1	07/10/17 17:11	Sketch Plan		Load JPG	☒
2	07/10/17 17:11	Common Statement		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG17019996/R1QBE2

Date: 28/11/2017

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Policy No: 999995580

Date of Loss: 05/08/2017

Nature of Claim:

OD

Claim No:

5683268885SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF9602Z

Make & Model: MERCEDES-BENZ VITO 109, 1.6 CDI LONG (M)

Engine No: R9MA503C016413

Reg. Date: 02/05/2017 (Man. Year: 2017)

Chassis No: WDF44760323272799

Colour: Red

Odometer: 0 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$108,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16C

Rear Tyre Size:

205/65 R16C

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,869.59	2,869.59	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,336.00	1,116.00	220.00	16.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,205.59	3,985.59	220.00	5.23
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	3,005.59	2,785.59	220.00	7.32
+ GST 7.00/7.00% (S\$)	210.39	194.99	15.40	7.32
Nett Amount (S\$)	3,215.98	2,980.58	235.40	7.32

INSPECTION

Date of Assignment: 24/10/2017

Date Inspected: 19/10/2017 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET	Necessary	21.23 FS	*21.23 FS
2	1		*BRACKET	Necessary	21.23 FS	*21.23 FS
3	1		*COOLANT RADIATOR	Necessary	367.30 FS	*367.30 FS
4	1		*CROSS MEMBER	Bent	194.80 FS	*194.80 FS
5	1		*SUPPORT	Necessary	81.11 FS	*81.11 FS
6	3		*SCREW	Necessary	4.02 FS	*4.02 FS
7	1		*RIVET	Necessary	14.98 FS	*14.98 FS
			(4 PCS)			
8	1		*AIR DUCT	Cracked	48.46 FS	*48.46 FS
9	1		*AIR DUCT	Cracked	48.20 FS	*48.20 FS
10	1		*AIR DUCT	Cracked	87.83 FS	*87.83 FS
11	1		*MOUNTING FRAME	Cracked	81.28 FS	*81.28 FS
12	1		*REFRIGERANT CONDENSER	Bent	486.32 FS	*486.32 FS
13	1		*TRIM BUMPER	Cut	585.97 FS	*585.97 FS
14	1		*TRIM PANEL WHEEL HOUSING	Torn	116.52 FS	*116.52 FS
15	1		*TRIM PANEL WHEEL HOUSING	Torn	116.52 FS	*116.52 FS
16	2		*RADIATOR ANTIFREEZE	Necessary	81.32 FS	*81.32 FS
17	1		*COVER HOOD	Cracked	358.93 FS	*358.93 FS
18	1		*STUD	Necessary	2.77 FS	*2.77 FS
19	1		**P NUT	Necessary	13.75 FS	*13.75 FS
			(8 PCS)			
20	1		*BRACKET	Necessary	15.10 FS	*15.10 FS
21	4		**P NUT	Necessary	4.36 FS	*4.36 FS
22	1		*BRACKET	Necessary	18.17 FS	*18.17 FS
23	2		*LOCK	Necessary	2.34 FS	*2.34 FS
24	1		*NUT	Necessary	6.02 FS	*6.02 FS
			(3 PCS)			
25	1		*REFRIGERANT DRIER	Necessary	79.99 FS	*79.99 FS
26	1		*LINK BLOCK	Missing	7.52 FS	*7.52 FS
27	1		*ELASTOMER BEARING	Necessary	3.55 FS	*3.55 FS
			(2 PCS)			

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,869.59	2,869.59
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	VEHICLE TOWING FROM 4 WOOLLERTON PARK TO 188 PANDAN LOOP	New	120.00	120.00
2	CHECK TRANSMISSION OPERATION VEHICLE AFTER WARM UP, AFTER ENGAGE GEAR, PRESS ACCELERATE BUT VEHICLE CANNOT MOVE	New	60.00	60.00
3	ADD JOB TO REMOVE FRONT BUMPER	New	120.00	100.00
4	REPLACE RADIATOR	New	240.00	200.00
5	REPLACE COOLANT INCLUDING ANTIFREEZE, CHECK FOR LEAKS	New	84.00	60.00
6	BUMPER WITH INTEGRATED FRONT RADIATOR GRILLE REPLACE	New	120.00	100.00
7	BRACKET FOR FRONT BUMPER REPLACE (BUMPER REMOVED)	New	36.00	36.00
8	UPPER CROSSMEMBER REMOVE / INSTALL (BUMPER REMOVED)	New	84.00	60.00
9	ENGINE AIR INTAKE DUCT UPSTREAM OF AIR FILTER REPLACE	New	12.00	0.00
10	REPLACE AIR DUCT	New	120.00	100.00
11	EXTRACT REFRIGERANT, CHECK FOR LEAKS, REFILL (WHEN WORKING ON AIR CONDITIONING)	New	60.00	40.00
12	DRIER CARTRIDGE REPLACE	New	60.00	40.00
13	FREON GAS	New	100.00	100.00
14	CONDENSER REMOVE/INSTALL AND, IF NECESSARY, REPLACE (WITH SYSTEM DRAINED) ALL AIR CONDITIONERS	New	120.00	100.00
Gross Labour Cost (S\$)			1,336.00	1,116.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >