REF	050F1)NJ/en:			
Smalle.	ASSI	GNMENT		16/1/2015
3			14 (46343.	Yr Rogn: 14/1/2013
Dato:	-	Type: M.Car / M.	Cycle / Bue / Van	
From:		Truck/T	raller or	co 1798
OD / TP / WS / TP RES / OD RES / EYA / IN	VIMV		gota Prins.	
OD/TP/WS/12				4 100.
To Inspect Vehicle No:		_ 000000	VINDEN	T/Radio: Insured Std NI NA
at Workshop m/s		Sp.Reading	No Display	
		Eng/No:		0.40
Insured: SLP 3233 Z	3140F0- CLYES		J70KN36119	tor 75550
Insured: SLP 3233.7 Policy No. 5091080953	050617 002	Gon. Cond; C	Bood / Fair / Poor / I	aked / Burnt or
Claims No. MT10901	00-1-		order / Jammed / Le	paked / Burnt or
Sum Insured:	ress:	Brake: Inc	ISIRim I STD AJE	Rim or
(Client's Record)			1757	(skis
Make of Veh:		Tyre Stze:	2 5 5	
			IG	/ LIZA / MIC / OHTSU / PIR / SUM! /
(Policy Condition)	N/S C	DIS BS I DUN	EXNUVATORIO	Fallan
Remark: The veh had commenced its repair at the time of inspecti	ion.	TOYOTY	OKO or	Rear
tepair at the		Front	/ mr	R/Bal.
Bal, or Markot Value:	sistent? ; Yes or No	R/Bal.		L/Bel.
IDAC Accident report	sistent? : Yes or No	L/Bal.	17/10/pol7.	. D'OT 10 10 July
GIA / PR Seen:	Res.: Yes or No	0.00	Sini	IT "
Est. Repairs:%	3 Val.: Yes or No	Stilvey	namen · Ert / Rea	ar I OIS I NIS I UIC I Rooftop or
Lum Sum:	10	Des. of	Fr+ 0/s	t in
CA I REV I REP. 1 24 HRS	Vohiclo: I	ed TUO18	U/C / Chassis fran	ne / Body Structure affected dun to o
Dale: Person Conta	cled:		5.6 JES	315 TAX/10/7/2101
Dale / Time Action / Instruction	OR AGIBUS	42/Klh0362	007 (40 nly- 131	19 14 CKK.
3HC HOSH J	NA/INC) 7(11924 /1	3	PWI C	. NTuc.
	stian confirm	ed IS\$	1600	
OUINT	giot. 70, 85	599		
CRed	9107.10	ni/ on47		
RE	CEMER & A	O1 (U1)		
				A American Marie Company of the Comp
	n peret	Days	Of Repair:	Survey Fee: 160
	Prell. Report	Days Rest	Of Repair: irvey No. of Trip	Transportation; 3
Datofilmo, FRa Passe to7	Preli. Report Final Report	Rest	irvey No. of Trip	Transportation: 3
Date/Time, File Pass to?	Prell. Report Final Report	Add Fee:	rvey No. of Trip	Transportation: 3
Datafilms, File Pass In7	Preli. Report Final Report	Rest	rvey No. of Trip	Transportation:)_S+RS_SI) Photos); Outsiers

Survey Department Check List (Case Handler)

6	ce No.: NS INC 17020102 STB Type: OD / TP / TP RES / TL / EVA	Case H	Typist		
Admin	(): Case handler to make sure all In	formation created	by the assi	gnment tea	m are A
1) Offic	e Assign Form	Y-Date	N-Date	Y-Date	N-Date
С	Reference No.	V			
С	Customer Code				
N	Assign From				
C	Assign Date	~			
С	Veh No (Inspected)	-			
С	Veh No (Insured)	~			
С	D.O.A	~			
С	Policy No	~			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
С	Report Type				
С	Weekend Charges				
N	Survey held at/Repairer	1			
С	Excess				Alexander de la companya della companya de la companya de la companya della compa

С	Policy No	~		
С	Claim No	_		
C	Insurance Authorisation (CA /REV/REP)			
С	Report Type	-		
С	Weekend Charges			
N	Survey held at/Repairer	1		
С	Excess			
Survey	or (): Case handler to make sure t	he surveryor compl	eted all requir	ed information
(1) Assig	gnment Form			
С	Vehicle No	~		
С	Regn Month/Year	~		
N	Vehicle Type			
N	Make & Model	~		
C	Engine Capacity. (C.C)	~		
N	Colour	~		
С	Odometer. (Sp.Reading)	~		
С	Chassis No	~		
N	General Condition	_		
N	Steering	~		
N	Brake	/	$\neg \vdash$	
N	Modification (Modi)	~		
C	Tyre Size	~		
N	Tyre Make	~		
С	Tyre Balance	~		
C	Date of Inspection	~		
N	Survey held	~		
Ν	Des.of Damages	/		
(2) Syste	em - (Views/Merimen)			
С	Damaged Vehicle Photographs Uploaded	~		
(3) Worl	kshop Estimate/Assignment Form			
N	ALL Parts condition	~		
С	Market Value for OD cases			
С	Estimate Repair Cost for PRI (RSI, TMI, MSIG)			
С	Days of repair	~		
С	Finalised Amount	~		
С	Re-inspection Cases to Finalize within 5 Days			
	em - (Views/Merimen)			
С	Resurvey photo Uploaded			

Check By:	VERON)>	11	17	
	Case Handler		9	Date	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTU	IC INCOME INSUF	RANCE CO-OPERATIVE LTD	Ref:	NS/INC1702010	02/Srb
4		D UNION HOUSESINGAPORE	Date:	20-10-2017 INC4	
١.		Policy Particulars	:- THIR	D PARTY CLAIM	THE STREET
	Insured Veh.	SLP 3233Z	Veh. li	nspected	SHC 4634J
	Policy No.	5091086953	Cover	age (\$)	0.00
	Claim No.		Exces	s (\$)	0.00
	Assign From		Assig	n Date	19/10/2017
2.		Vehicle Parti	culars &	& Condition	A CONTRACTOR
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year o	of Reg.	
	Chassis No.		Colou	r	
	Odometer	•	Steeri	ng	
	Brakes		Modifi	ication	
	General				
3.		Condit	ions of	Tyres	
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	o marine realin	Descripti	on of Da	amages	
5.		Genera	l Inform	nation	
	Accident Date	17/10/2017	Inspe	ction Date	19/10/2017
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD	V3
		60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 757	705
5a.	Contamel VIII	R	emarks		
		ON WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, V			

TP Claims against NTUC Income: Follow-Through Survey

ON	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Estimate	Tentative renair cost
1	MT/0958426-002	SMRT BUSES LTD	SMB 1474U	SJQ 5234B	20/8/2017	\$6.133.90	\$1 700 00
2	MT/0958554-002	SMRT TAXIS PTE LTD	SHB 167Y	SJR 8588E	21/8/2017	\$2 933.00	200000
m	MT/0962276-001	SMRT BUSES LTD	SMB 5037Y	FT 9907Z	3/10/2016	\$1 588 00	\$1.241.00
4	MT/0909389-002	SMRT BUSES LTD	SMB 31648	\$G\$ 4739T	26/7/2016	\$1,068,00	\$415.00
2	MT/0967270-002	SMRT TAXIS PTE LTD	SHD 6454T	SKW 70411	27/10/2017	\$0.000,00	¢2 250.00
9	MT/0966048-002	SMRT TAXIS PTE LTD	SHC 46341	SI D 37337	17/10/2017	\$10.707.015	\$4,530,00
7	MT/0965873-002	SMRT TAXIS PTE LTD	SHF 377L	SLH 7836A	13/10/2017	\$10,701,73	\$2,600.00

Claim received from LKK Auto

	BaoTech						HOSSEL		ralClaim
1						Change Lar	guage '	Change Passwor	d + Log Ou
Polic	y Query								
Policy No	s.				Date of Acci	dent	17/10/	2017 12:11	
Vehicle t	No.(For Motor)	SLP3233Z							
					Search				
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
0	5091086953	QCD TECHNOLOGY PTE LTD	199505774W	GPC	drivo CLASSIC	SLP3233Z	SLP3233Z	08/06/2017	07/06/2018
-	Policy No Vehicle No Select	Policy Query Policy No. Vehicle No.(For Motor) Select Policy No.	Policy Query Policy No. Vehicle No. (For Motor) SLP3233Z Select Policy No. Policyholder Name QCD S091086953 TECHNOLOGY	Policy Query Policy No. Vehicle No. (For Motor) SLP3233Z Select Policy No. Policyholder Name NRIC QCD S091086953 TECHNOLOGY 199505774W	Policy Query Policy No. Vehicle No. (For Motor) SLP3233Z Select Policy No. Policyholder Policyholder NRIC QCD QCD S091086953 TECHNOLOGY 199505774W GPC	Policy Query Policy No. Date of Acci Vehicle No. (For Motor) SLP32332 Search Select Policy No. Policyholder Name NRIC Product Cover Type QCD S091086953 TECHNOLOGY 199505774W GPC drivo CLASSIC	Policy Query Policy No. Date of Accident Vehicle No. (For Motor) SLP3233Z Search Select Policy No. Policyholder NRIC Product Cover Type No. QCD S091085953 TECHNOLOGY 199505774W GPC drivo CLASSIC SLP3233Z	Policy Query Policy No. Date of Accident 17/10/ Vehicle No. (For Motor) SLP3233Z Search Select Policy No. Policyholder Name NRIC Product Cover Type Vehicle No. Object QCD S091086953 TECHNOLOGY 199505774W GPC drivo CLASSIC SLP3233Z SLP3233Z	Policy Query Policy No. Date of Accident 17/10/2017 12:11 Vehicle No. (For Motor) SLP3233Z Search Select Policy No. Policyholder NRIC Product Cover Type Vehicle Insured Commence Name NRIC Product Cover Type No. Object Date 9 5091085953 TECHNOLOGY 199505774W GPC drivo CLASSIC SLP3233Z SLP3233Z 08/06/2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACC			- 0.0	-0.7
ACC		11.41	CIVI	-141

17/10/2017 17:39 Date Of Report 17/10/2017 11:30 Date Of Accident

THOMSON PLAZA ENTRANCE Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC4634J

Insured/Policyholder

SMRT TAXIS PTE LTD Name Of Registered Owner

198905369K Co Reg No NOEMAIL Email Address

Mobile Phone No

Alternative Phone No OFFICE-80000000

Vehicle Particulars

TOYOTA Manufacturer

PRIUS TAXI-1.8 (A) Model

Exact Purpose for which vehicle was being used at HIRE AND REWARD

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

TAXI

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

Insurance Company

Name of Insurance Company

FIRST CAPITAL INSURANCE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

D-17087562MFSH

Cover Note Number

Driver

TOH ZHI WAI RAYMOND Name of Driver

S7805309G NRIC No 21/02/1978 Date Of Birth OUTDOOR Occupation 22/01/1998 Date Of Driving Pass

19 YEARS AND 8 MONTHS **Driving Experience**

Gender MALE

Mobile Number Fax Number

Contact Number

NOEMAIL EMail Address

- Linksynthesenses

- SA - SERVICE

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

Vehicle

General Information of the Accident

SIDE SWIPE Type Of Accident

CLEAR Weather Conditions DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police?

YES

NO

If Yes, Please state which Police Station

PUNGGOL N.P.C Police Station Name

ROAD: 21A TEBING LANE, POSTCODE: 828837, COUNTRY: Police Station Address

SINGAPORE

TEL NO: - FAX NO: Police Station Contact

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20171017/2079 On 17/10/2017 at about 1130hrs, I was driving along Upper Thomson Road in my Taxi bearing registration plate SHC4634J. I then turn left into the left lane of Thomson plaza. There was a small slope after turning left and bushes on the right, slightly obstructing the view to my right. As I was about to complete the turn, a MPV bearing SLP3233Z came from another path on my right side and the side of our cars collided against each other. We then exit the vehicle and exchange particulars. The below mentioned is the particulars of the driver of the MPV. Afendy Bin Abu Bakar S6828769C. I felt pain on my right shoulder as such I went to see a doctor at Sin Min Clinic. I was then given 5 days of medical leave. I had an in-car camera installed inside my taxi and it captured the moment of the incident. After viewing the clip, I noticed that the MPV (SLP3233Z) which was driving towards the same path as me had actually drove straight through a stop line without stopping. On my side, I was concentrating on turning to the left side as such I did not detect the MPV coming straight from my right side. I had the footage inside my phone. The damages in my car consist of a dent on the front right side of my car and the other party had dent on the left side of his MPV.

Attachment(s)

Are accident photos available for attachment? YES

YES Was there any video captured by Car Camera?

FILE TOO LARGE Remarks/ Reasons:

NO Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLP3233Z

Vehicle Make/Model/Colour

Details Of Properties

AFENDY BIN ABU BAKAR

Name of Driver

S6828769C

NRIC/Passport Number Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

TOH ZHI WAI RAYMOND

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHC4634J

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Sur1 30

Policyholder's Signature / Date &

Driver's Signature (# driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

du 19/10/217

Sketch Plan

A-SHC 46343 B-SLP 32332 and the second

RECKO TO PART	PRMAT - 7/2017 1012/2 29	
201045 10 LOGIC	: REPORT - 7/2017 1017/2079	
With the same of t		
14		
		- The second of
		- Committee - Comm
		A STATE OF THE STA
part of the second seco	lars are true in every respect.	
011 319	/.	ah 18/10
	The	W

- I de la reconstante

- according

- Charlestones

- The offer of the control of the co

- Shirt engrands





Police Station Of Origin: Punggol N.P.C

21A Tebing Lane SINGAPORE 828837

Tel No: 1800-6049999

T/20171017/2079

1 of 3 Report No. T/2017* 3*7/2079

	e Report M	ACCIDENT ade:	Vide Report No.:	Station Division 38		
Informar	nt's Particu	lars -	() 全面解析基本的主动	等。在原用是由其工作等等的		
Name of	Informant: WAI, RAY		Address: APT BLK 122A EDGEDALE P 821122	LAINS #14-179 SINGAPORE		
ID Type	/ ID No.: D / S780530	9G	Contact No.: Home/Office:	Mobile: 90068411		
National			Email:			
Sex: Male	Age:	Date of Birth: 21/02/1978	Type of Informant: Driver			
Race: Chinese			Language:	Institution / School Name:		
Occupati Taxi driv	tion:		Driving Licence Information: Class: 2B,2A,3 Date of Expiry:			

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/10/2017 11:30	Type of Longtion: Bend
	I MSON ROAD or turning left into The	omson Plaza Road Surface:		Road Speed Limit:
Clear		Dry		Traffic Volume:
Traffic Flow:		Traffic Control: Not Controlled		No Traffic
One Way	sion:	1401 001100		Anyone conveyed by ambulance:

The second second second	ehicle Involved	Make	Model	Color	Condition	No of Passenge
Vehicle No.	Туре	Iviano	IWOOCI	1 2 2 2	Slightly	0
SHC4634J	Taxi				Damaged	
			-		Slightly	1
SLP3233Z	Car				Damaged	7. 581

75. (2:5:21

12:00 21 21 1 and an arrival





Police Station Of Origin:

Report No. T/20171017/2079

2 of 3

** rgol N.P.C ** Tobing Lane SINGAPORE 828837 ** 1800-6049999

CONTINUATION OF REPORT

Brist Details.

14 h. U. + . = - 1 . J

On 17/10/2017 at about 1130hrs, I was driving along Upper Thomson Road in my Taxi bearing registration plate SHC4634J. I then turn left into the left lane of Thomson Plaza. There was a small slope after turning left and bushes on the right, slightly obstructing the view to my right.

As I was about to complete the turn, a MPV bearing SLP 3233Z came from another path on my right side and the side of our cars collided against each other. We then exit the vehicle and exchange particulars. The below mentioned is the particulars of the driver of the MVP.

Afendy bin Abu Bakar S6828769C

I felt pain on my right shoulder as such I went to see a doctor at Sin Min Clinic. I was then given 5 days of medical leave.

I had an in-car camera installed inside my taxi and it captured the moment of the incident. After viewing the clip, I noticed that the MPV (SLP 3233Z) which was driving towards the same path as me had actually drove straight through a stop line without stopping. On my side, I was concentrating on turning to the left side as such I did not detect the MPV coming straight from my right side. I had the footage inside my phone. The damages in my car consist of a dent on the front right side of my car and the other party had a sont on the left side of his MPV.

A CONTRACTOR OF THE PARTY OF TH

and the constitution has been

this offer of developing \$6

Sketch Plan Pg. 5





Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999 3 of 3 Report No. T/2017****17/2079

.01

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 WANG SHILING, ELVIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 17/10/2017 14:52
Officer In Charge Of Case:	Classification Of Case:
SSI GOH GEOK LYE Contact No.: 65476148	SH 085
	State Harce

Enquire Transfer Fee

Vehicle Details	
Vehicle No.	SHC4634J
Vehicle Type	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1	Air-Con (Taxi)
Vehicle Scheme	Taxi (Company)
Vehicle Make	TOYOTA
Vehicle Model	PRIUS TAXI (SMRT)
Chassis No.	JTDKN36U405755550
Propellant	Petrol-Electric
Engine No.	2ZR6259547
Motor No.	3JM6259547
Engine Capacity	1798 cc
Power Rating	60.0 kW
Maximum Power Output	100.0 kW (134 bhp)
Maximum Laden Weight	1805 kg
Unladen Weight	1370 kg
Year Of Manufacture	2014
Original Registration Date	14 Jan 2015
Lifespan Expiry Date	13 Jan 2023
COE Category	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid	\$52,486.00
COE Expiry Date	13 Jan 2023
Road Tax Expiry Date	13 Jan 2018
PARF Eligibility Expiry Date	13 Jan 2023
Inspection Due Date	13 Jul 2018
Intended Transfer Date	23 Nov 2017
CO2 Emission	92.00 (g/km)
CEVS Rebate Utilised Amount	\$30,000.00

The current road tax expiry is 13 Jan 2018. You may renew the road tax from 14 Oct 2017 with all prerequisite(s) fulfilled. If the road tax is renewed after 13 Jan 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	~ 2	11.00
Sub Total			11.00
Nett Road Tax Amount (After Offsetting Over Payment)	510.00	20	510.00
Total Amount Payable			521.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK Print



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

NTHE

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHC4634J

Ref. No

TAX/10/17/2101

Reg. Date

: 14/01/2015

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS

Name of Driver

TOH ZHI WAI RAYMOND

Type of Accident

SIDE SWIPE

Date / Time of Accident

17/10/2017 11:30:00 AM

Accident Reported Date / Time :

17/10/2017 12:00:00 AM

Surveyor is Required?

Yes

Survey by

200

Vehicle is Towed Back?

Yes

Towed Back Date/Time

17/10/2017

Replacement Vehicle issued? :

No

Accident Repair Job Card No :


000024092606


Special Instruction to ARC, if any

TOWED \$40 / SLP3233Z

Prepared Date

17/10/2017 05:19:50 PM





LKK Auto Consultants hence notify

- the Repairer of the following:
 To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page:

Section B - To be Completed by Service Advisor, Accident Repair Centre 0 Chassis No: JTDKN36U405755550 Mileage Repair Completed Date / Time : Work Shop Summary of Repair Estimates Adjusted by Surveyor, if applicable Quotation from ARC 0.00 845.00 Total Labout Charges 0.00 1,116.00 Total Spray Painting Charges 7,159.15 7,159.15 Total Material Charges 0.00 910.00 Other Charges 0.00 10,030.15 TOTAL 0.00 0.00 **Lum Sum Total** 0.00 5.00 No. of Repair Days 3 days Prepared / Adjusted By 01/01/1900 12:00:00 AM : 19/10/2017 10:20:16 AM Arc / Surveyor Sing Off Date Prepared / Adjusted Date Remarks 19/10/2017 10:20:16 AM Prepared Date : Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair Invoice No Quotation No Invoice Date : Quotation Date Prepared Date: Invoice Amount :

Section D - Details of Repair Estimates

Part 1 - Labour Works

TO REPAIR RH FRONT PORTION Total Labour	845.00 845.00	0.00	
Job Scope	170 115 115 115 115 115 115 115 115 115 11	0.00 500 -	
L. C.	Quotation from ARC	Adjusted by Surveyo	r, if applicable

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
(C174)	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 🗸
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	2 0.00
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, it	f applicable
TOWING CHARGE	80.00	0.00 ×	i i meriminaliti
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0:00 30	consta
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00-30.	
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 🗶	-
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00 > >	
TO TOP UP A/C GAS	120.00	0.00 🔀	
TO CONDUCT RADIATOR PRESSURE CHECK	100.00	0.00 ×	
TO REPLACE SUNDRY PARTS	100.00	0:00 20	
TO WASH AND VACUUM	60.00	0.00 ×	
Total Other Costs	910.00	0.00	

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
3801-		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace	No
7050 5374-			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
7051 3875- 7030		6505553	FENDER LINER	1	171.70	25.00	128.77	Replace	Replace	No
3851- 7040			FENDER LINER PAD, FR WHEEL. RH	1	49.30	25.00	36.97	Replace	Replace	No.
2611 7140		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace	No
Frt) 2119-		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace V	No.
7930 52116-		6505516	BUMPER SUPPORT	1	76.40	25.00	57.30	Replace	Replace	No
7040 52115- 47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace	No
52021- 47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace	No.
52611- 47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace 7	No
57014- 47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace	No
57013- 47030			ARM SUB-ASSY, FR BUMPER RH		250.40	25.00	187.80	Replace	Replace	No.
81511- 47050			LENS & BODY, FR TURN RH		1 511.80	10.00	460.62	Replace	Replace	No
81519- 47060			BRACKET, FR TURN UPPER RH	3	1 24.40	25.00	18.30	Replace	Replace	No
81519- 47050			BRACKET, FR TURN LOWER RH		1 26.00	25.00	19.50	Replace	Replace /	No.
81519- 47060			BRACKET, FR TURN		1 58.20	25.00	43.65	Replace	Replace	No
88710- 47150			TUBE & ACCESSORY		1 631.90	25.00	473.92	Replace	Replace	No selection
85315- 47140			WIPER WASHER JAR		1 180.10	25.00	135.07	Replace	Replace	No
85330 47010			MOTOR NO:1, WIPER WASHER JAR	3	1 239.00	10.00	215.10	Replace	Replace 7	No
85330 60180			MOTOR NO:2, WIPER WASHER JAR	2	1 240.00	10.00	216.00	Replace	Replace	No
82113- 47180			WIRE, ENGINE ROOM, NO.3		1 242.00	10.00	217.80	Replace	Replace	No
52127- 47903			COVER, FR BUMPER HOLE RH		1 18.50	25.00	13.87	Replace	Replace	in the cases
53102- 47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER		1 311.10	25.00	233.32	Replace	Replace	— modelmost test
81210- 12230		6505439			1 295.20	10.00	265.68	Replace	Replace /	No
81130- 47500		6505437	STATEMENT MESSON OF MESSON		1 945.20	10.00	850.68		51 6,308.47	CA Market Assess
			TOTAL MATERIALS					10.7	15 7,159.15	

Added Spare Parts / Material Usage After Surveyor Signed off


Discount Final Price ARC Check Surveyor Check List Price Qty Part Name Check **Portion** Part (\$) (%) (\$) Number TOTAL SUPPLEMENTARY MATERIALS - - time-investi ------------- also via - index-pos - interpretation 1 - managed Balletin --------- commendator-si ---------tourselberry -------- ------------------ Administration of the

- instantani

Acres (Kigorola)

and a second

5



TOWED \$40 / SLP3233Z AND AFTER PAINT PHOTO , FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL BEFORE PAINT PHOTO AND AFTER PAINT PHOTO , FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email :sebastianyeang @lkkauto.com HP:90036121

UMPSUM REPAIR Prepared Date	: 17/10/2017 05:19:50 PM 23/10/12 PUSS
Recording Camera Radio Antenna	Date 23/10/17 Ways Job Mu: 13/627 10
E (1) 1	Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicle sont to \$25 / Data In 23/0 4 Towning 1509 Vehicl

4X/10/17/2101

Page:

1.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405755550

Mileage

Work Shop :

Repair Completed Date / Time :

10,707.70

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

845.00

500.00

Total Spray Painting Charges

1,116.00

400.00

Total Material Charges

1,018.37

Other Charges

1,018.37

830.00

-318.37

TOTAL

3,809.37

1,600.00

Lum Sum Total

0.00

0.00

No. of Repair Days

4.00 /

Prepared / Adjusted By

5.00

Arc / Surveyor Sing Off Date

: 19/10/2017 10:20:16 AM

SEBASTIAN (LKK) 19/10/2017 12:32:42 PM

Prepared / Adjusted Date

Remarks

Prepared Date : 19/10/2017 10:20:16 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

: QN-1710-0551

Invoice No

Quotation Date : 23 10

Invoice Date

Invoice Amount :

Prepared Date:

+ 480.00/

1598.69

LIS \$1600/-

2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR RH FRONT PORTION	845.00	500.00		
Total Labour	845.00	500.00		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378.00	200.00 /
TO RESPRAY RIM	180.00	0.00
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0.00
Total Spray Painting & Panel Beating	1,116.00	400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00
TO TOP UP A/C GAS	120.00	0.00
TO CONDUCT RADIATOR PRESSURE CHECK	100.00	0.00
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
Lump Surn Adjustment by Surveyor	0.00	-398.37
Total Other Costs	830.00	-318.37

. 1

Part 4 - Spare Parts / Material Usage

3801- 7050 5374- 7051 3875- 7030 3851- 7040 2611- 7140 Frt) 52119- 7930 52116- 17040		6505557 6505553 6505658	FENDER FRT/RH NAME PLATE (HYBRID) FENDER LINER FRT/RH FENDER LINER PAD, FR WHEEL RH WHEEL DISC. FRONT	1	723.40 51.90 171.70 49.30	100.00 25.00 25.00	0.00 38.92 128.77	Replace	Repair Replace	No R
7051 3875- 7030 3851- 7040 2611 7140 Frt) 2119- 7930 2116- 7040		6505658	(HYBRID) FENDER LINER FRT/RH FENDER LINER PAD, FR WHEEL. RH	1	171.70		H347/08/70/	Replace	Replace	No
3875- 7030 3851- 7040 2611 7140 Frt) 52119- 57930 52116- 47040		6505658	FRT/RH FENDER LINER PAD, FR WHEEL, RH	0		25.00	128 77	-		
3851- 7040 2611- 7140 Frt) 52119- 52116- 47040			FR WHEEL, RH	To .	49.30		120.11	Replace	Replace	No /
2611 17140 Frt) 52119- 17930 52116- 17040			WHEEL DISC. FRONT	0	Line and the second	25.00	0.00	Replace	Not given	No X
2119- 7930 2116- 7040		6505517		U	1,484.20	25.00	0.00	Replace	Not given	No X
52116- 17040			BUMPER FRT	1	482.00	100.00	0.00	Replace	Repair	No /L
		6505516	BUMPER SUPPORT	0	76.40	25.00	0.00	Replace	Not given	No X
52115- 17040	e e l	6505515	BUMPER SUPPORT	0	76.40	25.00	0.00	Replace	Not given	No X
52021- 47023		6505539	BUMPER REINFORCEMENT FRT	0	498.40	25.00	0.00	Replace	Not given	No
52611- 47080		6505518	BUMPER ENERGY ABSORBER FRT	0	78.80	25.00	0.00	Replace	Not given	No X
57014- 47030			ARM SUB-ASSY, FR BUMPER LH	C	250.40	25.00	0.00	Replace	Not given	No X
57013- 47030			ARM SUB-ASSY, FR BUMPER RH	C	250.40	25.00	0.00	Replace	Not given	No X
31511- 47050			LENS & BODY, FR TURN RH	C	511.80	10.00	0.00	Replace	Not given	No X
81519- 47060			BRACKET, FR TURN UPPER RH	(24.40	25.00	0.00	Replace	Not given	No X
81519- 47050			BRACKET, FR TURN LOWER RH	(26.00	25.00	0.00	Replace	Not given	No X
81519- 47060			BRACKET, FR TURN	(58.20	25.00	0.00	Replace	Not given	No X
88710- 47150			TUBE & ACCESSORY	(0 631.90	25.00	0.00	Replace	Not given	No X
85315- 47140			WIPER WASHER JAR		0 180.10	25.00	0.00	Replace	Not given	No X
85330 47010			MOTOR NO:1, WIPER WASHER JAR		0 239.00	10.00	0.00	Replace	Not given	No X
85330 60180			MOTOR NO:2, WIPER WASHER JAR		0 240.00	10.00	0.00	Replace	Not given	No ×
82113- 47180			WIRE, ENGINE ROOM, NO.3		0 242.00	10.00	0.00	Replace	Not given	No X
52127- 47903			COVER, FR BUMPER HOLE RH		0 18.50	25.00	0.00	Replace	Not given	No X
53102- 47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER		0 311.10	25.00	0.00	Replace	Not given	No X
81210- 12230		6505439	FOG LAMP RH		0 295.20	10.00	0.00	Replace	Not given	No X
81130- 47500		6505437	HEAD LAMP RH		1 945.20	10.00	850.68	Replace	Replace	No
			TOTAL MATERIALS						38 1,018.37 37 1,018.37	

Added Spare Parts / Material Usage After Surveyor Signed off



Thatcham escribe

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ITUC INCOME INSUR	ANCE CO-OPERATIVE LTD	Ref:	NS/INC1702010	2/Srbn2		
3 BRAS BASAH ROAI		Date:	28-11-2017 INC4			
	Policy Particulars	:- THIRI	D PARTY CLAIM			
Insured Veh.	SLP 3233Z	_	nspected	SHC 4634J		
Policy No.	5091086953	Cover	age (\$)	0.00		
Claim No.	MT/0966048-002	Exces	s (\$)	0.00		
Assign From		Assig	n Date	19/10/2017		
2.	Vehicle Parti	iculars 8	& Condition			
Make & Model	TOYOTA PRIUS	c.c		1798		
Engine No.	HIDDEN	Year o	of Reg.	2015		
Chassis No.	JTDKN36U405755550	Colou	ır	MAROON		
Odometer	(*)	Steeri	ing	IN ORDER		
Brakes	IN ORDER	Modif	fication	NIL		
General	FAIR					
3.	Condit	tions of	Tyres			
	Size	Make		Balance		
R/H Front Tyre	195/65 R15	FALKE	EN	6 mm		
L/H Front Tyre	195/65 R15	FALKE	EN	6 mm		
R/H Rear Tyre	195/65 R15	FALKE	EN	6 mm		
L/H Rear Tyre	195/65 R15	FALKE	EN	6 mm		
4.	Description of Damages					
THE VEHICLE SU	ISTAINED DAMAGES AT THE F	RONT O	S PORTION.			
DAMAGES SEE I	DETAILS					
5.		al Inform	mation			
Accident Date	17/10/2017	Inspe	ection Date	19/10/2017		
Survey held at	SMRT AUTOMOTIVE SERVICE					
	60 WOODLANDS INDUSTRIA			57705		
5a.		Remark				
TANKE INCOME	ION WAS CONDUCTED ON A"W NCE TO YOUR INSTRUCTIONS,	WE HAV	E NOT AUTHORIS	IS. ED REPAIRS.		
5b.			of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4634J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NAME PLATE (HYBRID)(DISC 25%)	NECESSARY	51.90	38.92
1		TORN	171.70	128.77
1	HEAD LAMP RH (DISC 10%)	CUT	945.20	850.68
1		NOT NECESSARY	49.30	-
1	WHEEL DISC, FRONT	NOT NECESSARY	1,484.20	-
4	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	-
- 31	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	-
1	THE PART OF THE PA	NOT NECESSARY	250.40)
	ARM SUB-ASSY,FR BUMPER RH	NOT NECESSARY	250.40	-
	LENS & BODY, FR TURN RH	NOT NECESSARY	511.80) -
	BRACKET,FR TURN UPPER RH	NOT NECESSARY	24.40	
	BRACKET, FR TURN LOWER RH	NOT NECESSARY	26.00) -
139	BRACKET, FR TURN	NOT NECESSARY	58.20	
	TUBE & ACCESSORY	NOT NECESSARY	631.90	0
	WIPER WASHER JAR	NOT NECESSARY	180.10	o .
	MOTOR NO.1 WIPER WASHER JAR	NOT NECESSARY	239.0	0
	MOTOR NO.2 WIPER WASHER JAR	NOT NECESSARY	240.0	0
	WIRE, ENGINE ROOM, NO 3	NOT NECESSARY	242.0	0
	COVER,FR BUMPER HOLE RH	NOT NECESSARY	18.5	0
	BUMPER GRILLE SUB-ASSY,LOWER	NOT NECESSARY	311.1	0
	1 FOG LAMP RH	NOT NECESSARY	295.2	0
	1 FENDER FRT/RH	TO REPAIR	723.4	0
	1 BUMPER FRT	TO REPAIR	482.0	0
	BOWFERTKI		7,916.7	0 1,018.3
	LABOUR		557380252	
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,415.0	
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,216.0	430.0

Report Ref No. NS/INC17020102/Srbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE SUNDRY PARTS. TO WASH AND VACUUM.	NOT NECESSARY	100.00 60.00	
			2,791.00	980.00
	GRAND TOTAL		10,707.70	1,998.37

	1,600.00
RECOMMENDED COST OF LUMP SUM REPAIRS	1,000.00
(TO ITS PRE-ACCIDENT CONDITION)	
(CONFIRMED)	

Report Ref No. NS/INC17020102/Srbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tord, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.