

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020197/R1TBE2

Date: 20/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28677733MKF

Claimant Vehicle No : XD4500S

Insured Vehicle No : YP5908T

Date of Loss: 17/10/2017

Nature of Claim: TP

Claim No: 533620

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD4500S**

Make & Model: IVECO ML190EL25, 5.9 D (M)

Engine No: 778770

Reg. Date: 31/03/2011 (Man. Year: 2010)

Chassis No: ZCFA1VJ0402574162

Colour: White

Odometer: 161114 km

Engine Capacity: 5880 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Hankook 8 mm

Rear Left Side: Hankook 8/8 mm

Front Right Side: Hankook 8 mm

Rear Right Side: Hankook 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,561.13	6,531.13	30.00	0.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	2,880.00	750.00	20.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,191.13	9,411.13	780.00	7.65
+ GST 7.00/7.00% (S\$)	713.38	658.78	54.60	7.65
Nett Amount (S\$)	10,904.51	10,069.91	834.60	7.65

INSPECTION

Date of Assignment: 23/10/2017

Date Inspected: 23/10/2017 Inspected At:

18 TUAS AVE 10

Repairer : Motorviva Pte Ltd (HQ)

Estimated Period of Repair: 1.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Apr 2018)	
Parts:	N/A	IVECO ML190EL25 5.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD4500S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR VIEW MIRROR LHS	Broken	2,103.89 FL	*2,103.89 FL
2	1		*REAR VIEW MIRROR TOP GASKET LHS	Necessary	24.10 FL	*24.10 FL
3	1		*SUNDRIES	Necessary	60.00 FS	*30.00 FS
4	1		*FRONT CORNER PANEL LHS	Broken	1,033.77 FL	*1,033.77 FL
5	1		*FRONT CORNER PANEL SEAL LHS	Necessary	63.13 FL	*63.13 FL
6	1		*FRONT CORNER PANEL RETAINER LHS	Necessary	21.72 FL	*21.72 FL
7	1		*FRONT SIDE FENDER LHS	Cracked	1,652.98 FL	*1,652.98 FL
8	1		*FRONT STEP GARNISH LHS	Cracked	1,105.87 FL	*1,105.87 FL
9	1		*SUNVISOR	Cracked	2,571.32 FL	*2,571.32 FL
10	1		*SUNVISOR SIDE LAMP LHS	Cracked	91.40 FL	*91.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,728.18	8,698.18
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,167.05	2,167.05
Total Parts (\$\$)	6,561.13	6,531.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOW VEHICLE BACK TO WORKSHOP	New	200.00	200.00
2	TO REMOVE & REFIX REAR VIEW MIRROR ASSY	New	600.00	380.00
3	TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK	New	280.00	200.00
4	TO REMOVE & REFIX FRONT CORNER PANEL, FRONT SIDE FENDER, FRONT STEP GARNISH AND SUNVISOR ASSY	New	1,500.00	1,200.00
5	TO CARRY OUT SPRAY PAINTING ON FRONT CORNER PANEL, FRONT SIDE FENDER, FRONT STEP GARNISH AND SUNVISOR ASSY	New	1,050.00	900.00
Gross Labour Cost (S\$)			3,630.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >