

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AXA17020368/NRBE2

Date: 30/10/2018

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No : SJQ7855X

Insured Vehicle No :

SHD9810D

Date of Loss: 22/10/2017

Nature of Claim:

TP

Claim No: C0456682

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ7855X**

Make &amp; Model: AUDI A4, 1.8 (A)

Engine No: CDH016288

Reg. Date: 26/05/2009 (Man. Year: 2008)

Chassis No: WAUZZZ8K59A087891

Colour: Black

Odometer: 178055 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size:

245/40 R18

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,590.83	10,464.68	9,126.15	46.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,670.00	2,700.00	1,970.00	42.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,260.83</b>	<b>13,164.68</b>	<b>11,096.15</b>	<b>45.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>10,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>24,260.83</b>	<b>10,500.00</b>	<b>13,760.83</b>	<b>56.72</b>

### INSPECTION

Date of Assignment: 24/10/2017

Date Inspected: 25/10/2017 Inspected At:

Zhong Cheng Enterprise  
Blk 6 Woodlands Road, Yew Tee Industrial  
Estate 399J  
Singapore 678008

Estimated Period of Repair: 7.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2018)
<b>Parts:</b>	143	AUDI A4 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJQ7855X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	<b>*REAR BUMPER UPPER</b> (CONSISTENT)	Damaged	1,423.80 FL	*1,177.00 FL
2	1	<b>*REAR BUMPER SPOILER</b> (CONSISTENT)	Cracked	205.00 FL	*205.00 FL
3	2	<b>*REAR BUMPER SIDE RETAINER</b> (CONSISTENT)	Not Necessary	60.00 FL	*- FL
4	1	<b>*SET REAR BUMPER FASTENERS</b> (CONSISTENT)	Necessary	36.00 FL	*36.00 FL
5	1	<b>*REAR BUMPER TOWING COVER</b> (CONSISTENT)	Necessary	32.00 FL	*32.00 FL
6	1	<b>*REAR CENTRE RETAINER</b> (CONSISTENT)	Distorted	162.00 FL	*162.00 FL
7	1	<b>*REAR REINFORCEMENT</b> (CONSISTENT)	Dented	456.25 FL	*456.25 FL
8	2	<b>*REAR REINFORCEMENT BRACKETS</b> (CONSISTENT)	Dented	306.00 FL	*306.00 FL
9	1	<b>*AIRVENT</b> (CONSISTENT)	Not Necessary	65.25 FL	*- FL
10	1	<b>*BOOTLID</b> (CONSISTENT)	Dented	1,554.00 FL	*1,391.40 FL
11	1	<b>*BOOTLID INNER LOCK</b> (CONSISTENT)	Dented	172.30 FL	*172.30 FL
12	1	<b>*BOOTLID CHROME GARNISH</b> (CONSISTENT)	Not fitted	167.25 FL	*- FL
13	1	<b>*SET BOOTLID CHROME GARNISH CLIPS</b> (CONSISTENT)	Not fitted	60.00 FL	*- FL
14	1	<b>*BOOTLID LOGO EMBLEM A4</b> (CONSISTENT)	Necessary	70.50 FL	*70.50 FL
15	1	<b>*BOOTLID AUDI EMBLEM</b> (CONSISTENT)	Necessary	92.50 FL	*92.50 FL
16	1	<b>*BOOTLID 1.8 EMBLEM</b> (CONSISTENT)	Necessary	67.25 FL	*67.25 FL
17	1	<b>*BOOTLID LAMP (LH/RH)</b> (CONSISTENT)	N/S Scratched	382.00 FL	*191.00 FL
18	2	<b>*SET BOOTLID LAMP FASTENERS</b> (CONSISTENT)	Not Necessary	36.00 FL	*- FL
19	2	<b>*BOOTLID HINDGES GARNISH</b> (CONSISTENT)	Not Necessary	195.00 FL	*- FL
20	2	<b>*BOOTLID SPRING</b> (CONSISTENT)	Not Necessary	157.00 FL	*- FL
21	2	<b>*BOOTLID HINGES</b> (CONSISTENT)	Not Necessary	334.00 FL	*- FL
22	1	<b>*BOOTLID WEATHERSTRIP</b> (CONSISTENT)	Bent	169.00 FL	*169.00 FL
23	1	<b>*BOOTLID HINDGE COVER</b> (CONSISTENT)	Not Necessary	18.00 FL	*- FL
24	1		Dented	47.50 FL	*47.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			<b>*BOOTLID LOCK STRIKER</b> (CONSISTENT)			
25	1		<b>*BOOTLID INNER TRIM BOARD</b> (CONSISTENT)	Cut	205.50 FL	*205.50 FL
26	1		<b>*SET BOOTLID INNER TRIM BOARD FASTENERS</b> (CONSISTENT)	Necessary	36.00 FL	*36.00 FL
27	2		<b>*BOOTLID RUBBER DAMPER</b> (CONSISTENT)	Not Necessary	36.00 FL	*- FL
28	2		<b>*REAR LICENSE PLATE LAMP</b> (CONSISTENT)	Not Necessary	76.00 FL	*- FL
29	2		<b>*TAILLAMP LH/RH</b> (CONSISTENT)	Cracked	790.00 FL	*790.00 FL
30	2		<b>*TAILLAMP LOWER PANEL (LH/RH)</b> (CONSISTENT)	Repair	391.00 FL	*- FL
31	2		<b>*SETS TAILLAMP FASTENERS</b> (CONSISTENT)	Not Necessary	45.00 FL	*- FL
32	2		<b>*TAILLAMP GASKET</b> (CONSISTENT)	Not Necessary	70.00 FL	*- FL
33	1		<b>*REAR END PANEL ASSY COMPLETE</b> (CONSISTENT)	Buckled	1,216.00 FL	*1,216.00 FL
34	1		<b>*REAR END PANEL TOP GARNISH</b> (CONSISTENT)	Cracked	235.00 FL	*235.00 FL
35	1		<b>*SET REAR END PANEL TOP GARNISH FASTENERS</b> (CONSISTENT)	Necessary	32.00 FL	*32.00 FL
36	1		<b>*SPARE TYRE PANEL</b> (CONSISTENT)	Repair	1,412.00 FL	*- FL
37	1		<b>*SPARE TYRE PANEL SIDE EXTENSION RH</b> (CONSISTENT)	Repair	370.00 FL	*- FL
38	1		<b>*SPARE TYRE PANEL BOARD</b> (CONSISTENT)	Not Necessary	297.00 FL	*- FL
39	1		<b>*REAR EXHAUST BRACKET</b> (CONSISTENT)	Not Necessary	63.00 FL	*- FL
40	1		<b>*REAR EXHAUST MUFFLER</b> (CONSISTENT)	Scratched	1,275.00 FL	*1,275.00 FL
41	1		<b>*REAR EXHAUST CHROME TIP</b> (CONSISTENT)	Not Necessary	230.00 FL	*- FL
42	1		<b>*REAR EXHAUST PIPE</b> (CONSISTENT)	Not Necessary	1,272.50 FL	*- FL
43	1		<b>*FRONT BUMPER</b> (CONSISTENT)	Dented	2,890.00 FL	*1,516.80 FL
44	2		<b>*FRONT BUMPER RETAINER</b> (CONSISTENT)	Distorted	210.00 FL	*210.00 FL
45	1		<b>*SET FRONT BUMPER CLIPS</b> (CONSISTENT)	Necessary	38.00 FL	*38.00 FL
46	1		<b>*REAR NUMBER PLATE</b> (CONSISTENT)	Not Necessary	60.00 FS	*- FS
47	1		<b>*END PANEL SEALANT</b> (CONSISTENT)	Necessary	60.00 FS	*60.00 FS
48	1		<b>*REVERSE SENSOR</b> (4PCS)(CONSISTENT)	Damaged-2pcs only	744.00 FS	*372.00 FS
49	1		<b>*FRONT NUMBER PLATE</b> (CONSISTENT)	Dented	60.00 FS	*25.00 FS
50	1		<b>*FRONT BUMPER GRILLE W CHROME</b> (CONSISTENT)	Cracked	2,190.70 FL	*404.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>20,573.30</b>	<b>10,991.40</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	982.47	526.72
<b>Total Parts (\$\$)</b>	<b>19,590.83</b>	<b>10,464.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS ( REAR BUMPER, REAR END PANEL, BOOTLID, TAILLAMP PANEL N/S O/S, REAR FENDER N/S O/S, REAR FENDER INNER PANEL N/S O/S )	New	1,800.00	1,000.00
2	TO CHECK WIRING AND REWIRE	New	80.00	60.00
3	TO REMOVE AND REINSTALL BOOTLID COMPONENTS	New	80.00	60.00
4	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	120.00	80.00
5	TO REMOVE AND REINSTALL REVERSE SENSOR	New	140.00	70.00
6	PROGRAMME SETTING	New	220.00	150.00
7	TO ANTI-RUST	New	160.00	80.00
8	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	1,600.00	1,200.00
9	TO REMOVE & REFIX REAR EXHAUST MUFFLER	New	120.00	0.00
10	TO REMOVE & ALIGN REAR CHASSIS MEMBER	New	350.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,670.00</b>	<b>2,700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >