

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Oct 2017		30 Oct 2017 10:47 Edit Adj Rpt	S\$7,050.00 Edit Estimates	S\$7,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: JEFFREY TOH TUCK FOOK , ID: S0050561G, Tel: +6597826548, Email: HOMECOMS@GMAIL.COM									
Main Claimant: TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K									
Vehicle Reg. No.:	SHD9924J	Date of Loss:	24/10/2017 11:00 - :59 [40 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0457316	Policy/Cover Note No.:	P1522061 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGX1030Y	Policy No. (Claimant):	VPX/P1680520						
		Excess:	S\$0.00						
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Vale Oh - 6880 4897]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/11/2017]								
Driver/Custodian (Insured):	JEFFREY TOH TUCK FOOK (67 / Male) , NRIC: S0050561G, Tel: +6597826548 Email: HOMECOMS@GMAIL.COM								
Adj Asg. Remarks:	ARC								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AXA_SG (02/04/2020): Alert - Adj Mandate Approved (S\$7851.77) - SHD9924J - Claim Handler: Vale Oh - AXA_SG (16/01/2020): FILE REVIEW, PLS WRITE TO TRANSCAB ON LOD-VO - AXA_SG (30/10/2017): New TP Assignment - C0457316/P1522061									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD9924J (C0457316)**
[SGX1030Y]
TP
TRANS-CAB SERVICES PTE LTD
Oct 24 2017 11:00AM
[JEFFREY TOH TUCK FOOK]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Assessment Reports				
			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	31/10/17 19:43	Adjuster Immediate Advice		Load HTM
Photos/Images				
			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	06/03/20 11:37	Chassis Number		Load JPG
2	06/03/20 11:37	Odometer Reading		Load JPG
3	06/03/20 11:37	General View		Load JPG
4	06/03/20 11:37	General View		Load JPG
5	06/03/20 11:37	General View		Load JPG
6	06/03/20 11:37	General View		Load JPG
7	06/03/20 11:37	General View		Load JPG
8	06/03/20 11:37	General View		Load JPG
9	06/03/20 11:37	General View		Load JPG
10	06/03/20 11:37	General View		Load JPG
11	06/03/20 11:37	General View		Load JPG
12	06/03/20 11:37	General View		Load JPG
13	06/03/20 11:37	General View		Load JPG
14	06/03/20 11:37	General View		Load JPG
15	06/03/20 11:37	General View		Load JPG
16	06/03/20 11:37	General View		Load JPG
Documentation				
			1 per page ▼	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail Print
1	30/10/17 09:25	EMAIL_ABS		Load PDF
2	30/10/17 09:25	Estimate_abs		Load PDF
3	30/10/17 09:25	SGX1030Y INSD GIA REPORT_ABS		Load PDF
4	30/10/17 10:35	SHD9924J - TP GIA Report.PDF		Load PDF
5	30/10/17 12:22	CI		Load PDF
6	30/10/17 12:22	Pol Schedule		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	01/11/17 14:11	TP GIA REPORT		Load PDF
2	01/11/17 14:11	TP ESTIMATE- MARKED		Load PDF
3	14/03/18 18:32	LETTER TO OI		Load PDF
4	26/03/20 15:36	LTA SEARCH		Load PDF
5	26/03/20 15:36	RENTAL MILEAGE		Load PDF
6	26/03/20 15:36	RENTAL RECEIPT		Load PDF
7	01/04/20 16:51	TP -Mandate IA		Load PDF
8	04/05/20 17:07	Authorisation to Act		Load PDF
9	04/05/20 17:07	PAYMENT BREAKDOWN – EXPRESS SETTLEMENT FORM		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AXA17020568/KHA3S2**Date:** 04/05/2020REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1522061
Claimant Vehicle No :	SHD9924J	Insured Vehicle No :	SGX1030Y
Date of Loss:	24/10/2017	Nature of Claim:	TP
		Claim No:	C0457316

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9924J	Engine No:	M9R8839C001019
Make & Model:	RENAULT LATITUDE, 2.0 L DCI (A)	Chassis No:	VF1ABL15AUC277523
Reg. Date:	05/06/2014 (Man. Year: 2014)	Odometer:	279225 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 8 mm	Rear Left Side:	Linglong 9 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Linglong 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,796.54	7,682.98	27,113.56	77.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,370.00	1,160.00	10,210.00	89.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,166.54	8,842.98	37,323.56	80.85
Approved Total (Overridden) (S\$)		7,050.00		
(S\$)	46,166.54	7,050.00	39,116.54	84.73
+ GST 7.00/7.00% (S\$)	3,231.66	493.50	2,738.16	84.73
Nett Amount (S\$)	49,398.20	7,543.50	41,854.70	84.73
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$101.46/day) (S\$)		202.92		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		7,851.77		
Global Sum Settlement (S\$)		7,800.00		

INSPECTION

Date of Assignment:	30/10/2017		
Date Inspected:	25/10/2017	Inspected At:	Trans-cab Auto Services Pte Ltd NO. 2 ANG MO KIO ST 63 Singapore 569111
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
Parts:	143	RENAULT LATITUDE 2.0 L DCI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9924J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT (CONSISTENT)	Buckled	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT (CONSISTENT)	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT (CONSISTENT)	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH (CONSISTENT)	Distorted	151.41 FL	*151.41 FL
5	1		*BUMPER SUPPORT FRT (CONSISTENT)	Serviceable	123.88 FL	*- FL
6	1		*BUMPER RETAINER FRT RH (CONSISTENT)	Distorted	150.77 FL	*150.77 FL
7	1		*BUMPER SUPPORT FRT (CONSISTENT)	Serviceable	123.88 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT (CONSISTENT)	Serviceable	472.83 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT (CONSISTENT)	Distorted	266.80 FL	*266.80 FL
10	1		*BUMPER FOG LAMP GRILLE LH (CONSISTENT)	Serviceable	207.21 FL	*- FL
11	1		*BUMPER FOG LAMP GRILLE RH (CONSISTENT)	Serviceable	207.21 FL	*- FL
12	1		*BUMPER BEAM FRT (CONSISTENT)	Repair	914.08 FL	*- FL
13	1		*TOW COVER FRT (CONSISTENT)	Serviceable	28.61 FL	*- FL
14	1		*RADIATOR GRILLE (CONSISTENT)	Cracked	1,707.78 FL	*1,707.78 FL
15	1		*RADIATOR GRILLE BADGE RENUALT (CONSISTENT)	Necessary	225.36 FL	*225.36 FL
16	1		*RADIATOR GRILLE FRAME (CONSISTENT)	Cracked	1,353.75 FL	*1,353.75 FL
17	1		*FRAME FULL SUPPORT PANEL (CONSISTENT)	Cracked	615.90 FL	*615.90 FL
18	1		*FRAME FULL SUPPORT BRACKET (CONSISTENT)	Repair	89.79 FL	-
19	1		*FRONT BRACE PANEL (CONSISTENT)	Repair	177.22 FL	*- FL
20	1		*HORN (CONSISTENT)	Serviceable	314.17 FL	*- FL
21	1		*HORN BRACKET (CONSISTENT)	Repair	40.45 FL	*- FL
22	1		*HEADLAMP LH (CONSISTENT)	Mtg Cracked	1,184.43 FL	*1,184.43 FL
23	1		*HEADLAMP RH (CONSISTENT)	Mtg Cracked	1,184.43 FL	*1,184.43 FL
24	1		*HEADLAMP PANEL FRT LH (CONSISTENT)	Repair	152.15 FL	*- FL
25	1		*HEADLAMP PANEL FRT RH (CONSISTENT)	Repair	152.15 FL	*- FL
26	1		*BONNET (CONSISTENT)	Repair	1,941.63 FL	*- FL
27	1		*BONNET INSULATOR (CONSISTENT)	Serviceable	405.73 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*BONNET STRUT LH (CONSISTENT)	Serviceable	88.61 FL	*- FL
29	1		*BONNET STRUT RH (CONSISTENT)	Serviceable	88.61 FL	*- FL
30	1		*BONNET HINGE LH (CONSISTENT)	Repair	348.31 FL	*- FL
31	1		*BONNET HINGE RH (CONSISTENT)	Repair	348.31 FL	*- FL
32	1		*BONNET LOCK (CONSISTENT)	Distorted	305.48 FL	*305.48 FL
33	1		*BONNET CABLE (CONSISTENT)	Serviceable	119.19 FL	*- FL
34	1		*BONNET CABLE COVER (CONSISTENT)	Serviceable	161.03 FL	*- FL
35	1		*BONNET SEAL OUTER (CONSISTENT)	Serviceable	92.36 FL	*- FL
36	1		*FENDER PANEL FRT LH (CONSISTENT)	Repair	783.83 FL	*- FL
37	1		*FENDER PANEL FRT RH (CONSISTENT)	Repair	783.83 FL	*- FL
38	1		*WHEELARCH FRT LH (CONSISTENT)	Serviceable	278.84 FL	*- FL
39	1		*WHEELARCH FRT RH (CONSISTENT)	Serviceable	278.84 FL	*- FL
40	1		*FENDER BRACKET LOWER LH (CONSISTENT)	Serviceable	15.79 FL	*- FL
41	1		*FENDER BRACKET LOWER RH (CONSISTENT)	Serviceable	15.79 FL	*- FL
42	1		*FENDER INSULATOR LH (CONSISTENT)	Serviceable	130.84 FL	*- FL
43	1		*FENDER INSULATOR RH (CONSISTENT)	Serviceable	130.84 FL	*- FL
44	1		*A/C CONDENSER (CONSISTENT)	Serviceable	2,020.37 FL	*- FL
45	1		*A/C CONDENSER GARNISH LH UPPER (CONSISTENT)	Serviceable	39.67 FL	*- FL
46	1		*A/C CONDENSER GARNISH RH UPPER (CONSISTENT)	Serviceable	39.67 FL	*- FL
47	1		*A/C CONDENSER GARNISH LH (CONSISTENT)	Serviceable	58.81 FL	*- FL
48	1		*A/C CONDENSER GARNISH RH (CONSISTENT)	Serviceable	59.60 FL	*- FL
49	1		*A/C PIPE CONDENSER TO COMPRESSOR (CONSISTENT)	Serviceable	208.39 FL	*- FL
50	1		*A/C PIPE CONDENSER TO EXPANSION VALVE (CONSISTENT)	Serviceable	658.72 FL	*- FL
51	1		*A/C PIPE COMPRESSOR (CONSISTENT)	Serviceable	334.29 FL	*- FL
52	1		*A/C PIPE (CONSISTENT)	Serviceable	658.72 FL	*- FL
53	1		*A/C COMPRESSOR (CONSISTENT)	Serviceable	2,684.61 FL	*- FL
54	1		*AIR COOLER (CONSISTENT)	Serviceable	792.60 FL	*- FL
55	1		*AIR INTERCOOLER HOSE (LONG) (CONSISTENT)	Serviceable	1,014.13 FL	*- FL
56	1		*AIR INTERCOOLER HOSE (SHORT) (CONSISTENT)	Serviceable	375.14 FL	*- FL
57	1		*TRANSMISSION COOLER (CONSISTENT)	Serviceable	1,219.30 FL	*- FL
58	1		*TRANSMISSION COOLER PAD (CONSISTENT)	Serviceable	17.96 FL	*- FL
59	1		*RADIATOR (CONSISTENT)	Serviceable	1,202.20 FL	*- FL
60	2		*RADIATOR STUD UPPER (CONSISTENT)	Serviceable	14.41 FL	*- FL
61	2		*RADIATOR BUSH UPPER (CONSISTENT)	Serviceable	50.12 FL	*- FL
62	2		*RADIATOR MTG LOWER (CONSISTENT)	Serviceable	55.85 FL	*- FL
63	1		*RADIATOR FAN COWLING (CONSISTENT)	Serviceable	820.54 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
64	1		*RADIATOR FAN MOTOR LH (CONSISTENT)	Serviceable	967.36 FL	*- FL
65	1		*RADIATOR FAN MOTOR RH (CONSISTENT)	Serviceable	1,479.46 FL	*- FL
66	1		*RADIATOR TANK (CONSISTENT)	Serviceable	324.62 FL	*- FL
67	1		*RADIATOR HOSE UPPER (CONSISTENT)	Serviceable	240.56 FL	*- FL
68	1		*RADIATOR HOSE LOWER (CONSISTENT)	Serviceable	491.18 FL	*- FL
69	1		*RADIATOR TANK HOSE (CONSISTENT)	Serviceable	61.18 FL	*- FL
70	1		*WINDSCREEN FRT (CONSISTENT)	Serviceable	1,364.06 FL	*- FL
71	1		*ROTARY SWITCH (CONSISTENT)	Serviceable	1,253.11 FL	*- FL
72	1		*SET RADIATOR GRILLE FRAME CLIP (CONSISTENT)	Necessary	52.00 FS	*52.00 FS
73	1		*SET BUMPER CLIP FRT (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
74	1		*BUMPER BRACKET CLIP FRT LH (CONSISTENT)	Not Necessary	12.00 FS	*- FS
75	1		*BUMPER SUPPORT CLIP FRT LH (CONSISTENT)	Not Necessary	10.50 FS	*- FS
76	1		*BUMPER BRACKET CLIP FRT RH (CONSISTENT)	Not Necessary	12.00 FS	*- FS
77	1		*BUMPER SUPPORT CLIP FRT RH (CONSISTENT)	Not Necessary	10.50 FS	*- FS
78	1		*TOW COVER FRT (CONSISTENT)	Serviceable	14.50 FS	*- FS
79	1		*SET RADIATOR GRILLE SCREW (CONSISTENT)	Not Necessary	16.00 FS	*- FS
80	1		*SET BUMPER GRILLE LOWER CLIP (CONSISTENT)	Not Necessary	69.00 FS	*- FS
81	1		*SET FRAME FULL SUPPORT PANEL CLIP (CONSISTENT)	Not Necessary	70.00 FS	*- FS
82	2		*FRAME FULL SUPPORT PANEL NUT (CONSISTENT)	Serviceable	20.00 FS	*- FS
83	2		*FRAME FULL SUPPORT PANEL STUD (CONSISTENT)	Serviceable	30.00 FS	*- FS
84	1		*SET WHEELARCH CLIP FRT LH (CONSISTENT)	Not Necessary	30.50 FS	*- FS
85	1		*SET WHEELARCH CLIP FRT RH (CONSISTENT)	Not Necessary	29.40 FS	*- FS
86	1		*CAP HUB LH FRT (CONSISTENT)	Serviceable	35.00 FS	*- FS
87	1		*RIM LH FRT (CONSISTENT)	Serviceable	385.00 FS	*- FS
88	1		*TYRE LH FRT (CONSISTENT)	Serviceable	330.00 FS	*- FS
89	1		*CAP HUB RH FRT (CONSISTENT)	Serviceable	35.00 FS	*- FS
90	1		*RIM RH FRT (CONSISTENT)	Serviceable	385.00 FS	*- FS
91	1		*TYRE RH FRT (CONSISTENT)	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	38,447.00	8,523.53
- List Item Discount on L Items 10.00/10.00% (\$)	3,650.46	840.55
Total Parts (\$)	34,796.54	7,682.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL PARTS, ADJUST AND REALIGN THE SAME.	New	4,200.00	500.00
2	TOWING FEES.	New	120.00	0.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	4,500.00	440.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
10	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	0.00
11	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	New	380.00	100.00
12	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	New	170.00	50.00
13	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	New	170.00	50.00
14	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00

Gross Labour Cost (\$\$)

11,370.00

1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >