

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT									
SOM	SOMPO INSURANCE SINGAPORE PL			CS3/SMO17020609/	Wbe2				
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date:	03-04-2018					
			Code:	SMO					
1. Policy Particulars :- (THIRD PARTY CLAIM)									
	Insured Veh.	PC 6250A	Veh. Inspected		YM 8287Y				
	Policy No.		Covera	age (\$)	0.00				
	Claim No.	CMTD1703793/AGC	Excess (\$)		0.00				
	Assign From	IRENE HENRY	Assign Date		27/10/2017				
2.	2. Vehicle Particulars & Condition								
	Make & Model	MITSUBISHI FM65FM1RDEA	c.c		7545				
	Engine No.	HIDDEN	Year of Reg.		2008				
	Chassis No.	FM65FMB00010	Colour		RED				
	Odometer	358011 KM	Steering		IN ORDER				
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM				
	General	FAIR							
3. Conditions of Tyres									
		Size	Make		Balance				
	R/H Front Tyre	11 R22.5	LEAD		5 mm				
	L/H Front Tyre	11 R22.5	LEAD		5 mm				
	R/H Rear Tyre	11 R22.5	BRIDGI	ESTONE	4 mm				
	L/H Rear Tyre	11 R22.5	BRIDGI	ESTONE	4 mm				
4.	. Description of Damages								
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT AND REAR PORTION.							
5.	General Information								
	Accident Date	26/10/2017	Inspec	t Date / Time	06/11/2017 ( 12:33 PM )				
	Survey held at TWINCAR AUTOMOTIVE PTE LTD								
	2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921								
		Remarks							
5a.					A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,900-\$9,900				
5a.	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLI	STIMATE WAS NOT PRESENTED 'AS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE	D AT THE STIMATE. S PHOTO	E TIME OF INSPECTIO GRAPHS.					

Report Ref No. CS3/SMO17020609/Wbe2

Inspected By

**Automotive Assessor** 

WILSON TEO CHENG MING

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

\_\_\_\_

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

7 Working Days

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.