

REF: (B1)/LAW17020802/Hghs2

Special Instruction:

ASSIGNMENT (Office)

From (Person): Sorjeet Singh of Alan Shankar. Date/Time: 31-10-2017
Estimated Cost: _____ Bill to: _____

Part by part: \$6335.24

Third Parties:

Claimant:

Surveyor: JAS Appraisal & FormTeam

Workshop: Car Life Auto

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SG 3252P Insured: TBF 1549Y

at Workshop m/s Car Life Auto Tel: 01-75
of Blk 1002 Bukit Merah Lane 3 #01-75

Policy No: BCC-50852-1014-CLA-DC Claim No: SS/107314/317

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____ D.O.A. 08.01.2014

(Client's Record)

SJE

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 20/12/18 Confirmed with ✓ Final Fig 1284100, 6 days (Red \$ 275.74 %; Original 8 days)
Date/Time: 20/12/18 Submit Final Fig 1284100, 6 days (Red \$ 275.74 %; Original 8 days)

Date/Time: 20/12/18 Submit Final Fig 1384100, 6 days (Red \$ 275.74 2%; Original 8 days)

[illegible]

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 20 DEC 2017

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time 26/10/17 File Pass to twinst

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

SG 3052p

Policy Type: OD / TP / TP RES / TL / EVA

Typist

(1) Office Assign Form

[illegible]

(1) Assignment Form

[illegible]

C Damaged Vehicle Photographs Uploaded

--	--

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

✓	
✓	

C Resurvey photo Uploaded

--	--	--	--

Case Handler: [Signature] Date: 20/12/17

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALAN SHANKAR & LIM LLC

Ref : CS1/LAW17020802/qb

151 CHIN SWEE ROAD

#10-07 MANHATTAN HOUSESINGAPORE 169876

Date : 31-10-2017

Code : L138



1. Policy Particulars :- PAPER SURVEY

Insured Veh.	FBF 1549Y	Veh. Inspected	SJG 3252P
Policy No.	BCC.50852.1014.CLA.DC	Coverage (\$)	0.00
Claim No.	SS/10234/317	Excess (\$)	0.00
Assign From	SARJEET SINGH	Assign Date	31/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/01/2014	Inspection Date	31/10/2017
Survey held at	CAR LIFE AUTO ENGINEERING SERVICES BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719		

5a. Remarks

--

Catherine Chong (LKK Auto)

From: Ai Phing (LKKAuto) <aiphing@lkkauto.com>
Sent: Tuesday, 31 October, 2017 12:27 PM
To: Sarjeet Singh; assignments
Cc: bcclaw@singnet.com.sg
Subject: FW: Appointment of LKK Auto Consultants as SJE in MC Suit No. 3529/2017 Alan Shankar & Lim LLC Ref: SS/10234/317 Benedict Chan & Co Ref: BCC.50852.1014.CLA.DC
Attachments: GIA SJG3252P.pdf; GIA FBF 1549Y.pdf; P's Survey Report.pdf; PRI - FormTeam.pdf
Importance: High

Dear Sarjeet,

Thank you for the email.

Dear Assignment Team,

FYNA.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Sarjeet Singh [mailto:sarjeet@asllaw.com.sg]

Sent: Tuesday, 31 October, 2017 12:09 PM

To: Ai Phing (LKKAuto) <aiphing@lkkauto.com>

Cc: bcclaw@singnet.com.sg

Subject: Appointment of LKK Auto Consultants as SJE in MC Suit No. 3529/2017 Alan Shankar & Lim LLC Ref: SS/10234/317 Benedict Chan & Co Ref: BCC.50852.1014.CLA.DC

Importance: High

Dear Ai Phing,

We act for the Defendant [riding FBF 1549Y] and Benedict Chan & Co act for the Plaintiff [driving SJG 3252P] in the above action.

Both parties have agreed and the court has appointed LKK Auto Consultants Pte Ltd as the SJE. We enclose colour copies of the following documents.

- a) Plaintiff's Singapore Accident Report
- b) Defendant's Singapore Accident Report
- c) Plaintiff's survey report on SJG 3252P by JAS Appraisal

d) Defendant's PRI by FormTeam Consultancy Pte Ltd.

Kindly liaise with Mui Choo of Benedict Chan who is copied this email for the inspection of the Plaintiff's vehicle.

We will be grateful if the report can be furnished by 20-11-17 as requested by the court.

Best regards,

Sarjeet Singh
Alan Shankar & Lim LLC
151 Chin Swee Road
#06-10 Manhattan House
Singapore 169876
Tel: 6734 5698
Fax: 6734 5650
Website: www.alanshankar-lim.com

Statement of Confidentiality

The contents of this e-mail message and any attachments are confidential and are intended solely for the addressee. The information may also be legally privileged solicitor and client information and is sent in trust, for the sole purpose of delivery to the intended recipient. If you have received this transmission in error, any use, reproduction or dissemination of this transmission is strictly prohibited and may be unlawful. If you are not the intended recipient, please immediately notify the sender by reply e-mail or phone and delete this message and its attachments, if any.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2014 10:16
Date Of Accident	08/01/2014 16:25
Exact Location Of Accident	MARINA STREET TOWARDS MARINA BAY STATION
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG3252P
Insured/Policyholder	
Name Of Registered Owner	OH CAI LENG
NRIC No	S7416200B

Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3G A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSN3007421300
Cover Note Number	-

Driver

Name of Driver	OH CAI LENG
NRIC No	S7416200B
Date Of Birth	09/05/1974
Occupation	Indoor
Date Of Driving Pass	14/04/1994
Driving Experience	19 Years And 8 Months
Gender	Female
Mobile Number	(Local) +65-96906770
Fax Number	
Contact Number	
E Mail Address	kimmiegoh99@gmail.com
Address	BLK 140 TAMPINES ST 12 #05-444
Postcode	520140
Was driver an employee of the Insured's Company	No

If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Head on collision
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHMENT STATEMENT OF SKETCH PLAN

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBF1549Y
Vehicle Make/Model/Colour	T135 YAMAHA
Details Of Properties	
Name of Driver	WEE KEAT SIONG (HUANG JIXIANG)
NRIC/Passport Number	S7140404H
Contact Number	96617318
Address	BLK 122 JURONG EAST ST 13 #24-41
Postcode	600122
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	


Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan



Describe Circumstances of the Accident

I was driving at normal speed on Marina Street towards Marina Bay station. It is 4 lanes, one way traffic. Suddenly I saw a bike (motor) coming towards me. I stepped on brake but bike hit my car. He was going against the traffic. I called police. LTA officer came. Ambulance came. But motorcyclist was driving and we exchanged details. Then went separate way.

Declaration

I/We declare the foregoing particulars are true in every respect.

8/1/2014 6:10pm.

Signature
Policyholder's Signature / Date & Time

Signature
Driver's Signature (if driver is not the policyholder) / Date & Time

Signature
Witnessed by Reporting Centre Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2014 13:24
Date Of Accident	08/01/2014 16:45
Exact Location Of Accident	ALONG MCE TOWARD RAFFLES BOULEVARD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBF1549Y
Insured/Policyholder	
Name Of Registered Owner	FRIENDSHIP MOTOR CO
Co Reg No	07981100X

Vehicle Particulars

Manufacturer	YAMAHA
Model	T135
Exact Purpose for which vehicle was being used at time of accident	FOR TESTING PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Reporting Only
Vehicle Category	Motorcycle

Insurance Company

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Third Party
Fleet Policy	No
Policy Number	MSD/VMT/13-868570-CA
Cover Note Number	

Driver

Name of Driver	WEE KEAT SIONG
NRIC No	S7140404H
Date Of Birth	30/10/1971
Occupation	Indoor
Date Of Driving Pass	05/11/1988
Driving Experience	25 Years And 2 Months
Gender	Male
Mobile Number	(Local) +65-96617318
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL
Address	BLK 122 JURONG EAST ST 13 #24-41
Postcode	600122
Was driver an employee of the Insured's Company	Yes

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-

-

-

Insurance Company of Driver's Own Vehicle

-

-

-

General Information of the Accident

Type Of Accident

Unknown - REFER TO SKETCH PLAN

Weather Conditions

Clear

Road Surface

Dry

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? Yes

Was any other material or property damaged? Yes

Was there any video captured by Car Camera? No

Details of Police Action

Was the accident reported to the police? No

If Yes, Please state which Police Station

Was notice of intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG MCE TOWARD RAFFLE BOULEVARD AT THE 3RD LANE. WHILE ALONG THE BEND, I REALISED THAT I TRAVELLING THE WRONG RD, THEN I PROCEED TO MAKE AN U-TURN AS I THOUGHT THAT THE RD I TRAVELLING WAS 2 WAYS TRAFFIC. WHILE I WAS ALONG THE EXTREME RIGHT LANE, THERE WAS AN INCOMING VEH(B) TOWARD MY DIRECTION THEN I TRIED TO AVOID BUT UNABLE TO AVOID IT HENCE CAUSED THE COLLISION. NOTE : PLEASE USE THIS MOTOR TRADE POLICY FOR CLAIMING PURPOSE.

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJG3252P

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

GOH LAI LENG

NRIC/Passport Number

S7416200B

Contact Number

96906770

Address

BLK 140 TAMPINES ST 12 #05-444

Postcode

520140

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

WEE KEAT SIONG

Approximate Age

Injuries Sustain

SLIGHTLY INJURED

Injured person in which vehicle?

FBF1549YFRIENDSHIPMO

Were seat belts worn?

Was injured conveyed to hospital by ambulance? No

Address

BLK 122 JURONG EAST ST 13 #24-41


Postcode

600122

ACCIDENT SKETCH PLAN

IMPORTANT NOTICE

- ### Sketch Plan



Describe Circumstances of the Accident

Refer to statement

I/We declare the foregoing particulars are true in every respect.

Witnessed by Reporting Centre
Personnel *al. l. n.*

JAS APPRAISAL SERVICES

22 Sin Ming Lane #06-83 Midview City Singapore 573969

Hand phone No. 98467316

Co. Reg. No. 53202241J

AUTOMOBILE INSPECTION REPORT

Miss Oh Cai Leng
Block 140 #05-444
Tampines Street 12
Singapore 520140

Our Reference : JASTP/C2/105

Date : 18th February 2014

REFERENCE

Assigned By	: Repairers, owner's behalf	Insured Vehicle	: Not Advised
Type of Claim	: Third Party Claim	Policy No.	: Not Advised
Date of Assessment	: 9th January 2014	Claim No	: Not Advised
Date of Inspection	: 9th January 2014	Sum Insured	: Not Advised
Date of Accident	: 8th January 2014	Excess	: Not Advised

Name of Workshop : Car Life Auto Engineering Services
Block 1002 #01-75
Bukit Merah Lane 3
Singapore 159719

PARTICULARS OF DAMAGED VEHICLE

Registration No.	: SJG 3252 P	Gen. Condition	: Good
Make & Model	: Honda Fit 1.3	Body Paintwork	: Good
Year of Registration	: 2008	Air Con	: Fitted
Engine Capacity	: 1339cc	Seat Belt	: Fitted
Engine No.	: L13A4093109	Radio/ CD	: Fitted
Chassis No.	: GE61082903	Steering	: Serviceable
Odometer Reading	: 080276Km	Hand Brake	: Serviceable
Colour	: Black	Foot Brake	: Serviceable

CONDITION OF TYRES

Front o/s tyre	: Yokohama 195/55 R 15 approximately 60%
Front n/s tyre	: Yokohama 195/55 R 15 approximately 60%
Rear o/s tyre	: Yokohama 195/55 R 15 approximately 60%
Rear n/s tyre	: Yokohama 195/55 R 15 approximately 60%

Note : The above percentages denote the remaining estimated life of the tyre thread.

JAS APPRAISAL SERVICES

22 Sin Ming Lane #06-83 Midview City Singapore 573969

Hand phone No. 98467316

Co. Reg. No. 53202241J

Our Reference : JASTP/C2/105

Registration No. : SJG 3252 P

GENERAL REMARKS

At the time of inspection, we noted that this vehicle has sustained impact damages on the front portion.

The vehicle was inspected thoroughly based on the repairer's estimate. We have listed the breakdown as per schedule attached.

Original Quotation	: \$ 9,104.92
Revised Quotation	: \$ 6,335.24 (Part by Part)
Less Excess	: \$ -
Nett Liability	: <u>\$ 6,335.24</u>

Nineteen (19) photographs were taken during our inspection.

Under normal circumstances, the estimated repair period would be approximately eight (8) working days.

In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a '**Without Prejudice**' basis. We hope that this report will be of assistance to you in dealing with this matter.

Should you discover any discrepancy in this report, please kindly notify us within two (2) weeks or this report will be treated as valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/ or other accidents in other legal proceedings.

JAS APPRAISAL SERVICES

22 Sin Ming Lane #06-83 Midview City Singapore 573969

Hand phone No. 98467316

Co. Reg. No. 53202241J

Our Reference JASTP/C2/105

Registration No. SJG 3252 P

QTY	DESCRIPTION	CONDITION/ REMARKS	ORIGINAL QUOTATION	REVISED QUOTATION
-----	-------------	-----------------------	-----------------------	----------------------

LIST PARTS

1 pc	Front bumper	badly dented	\$ 523.50	\$ 523.50
1 pc	Front bumper RH bracket	bent	\$ 22.50	\$ 22.50
1 pc	Front bumper LH bracket	bent	\$ 22.50	\$ 22.50
1 pc	Front bumper reinforcement	bent	\$ 253.90	\$ 253.90
1 pc	Front bumper RH retainer	necessary	\$ 13.25	\$ 13.25
1 pc	Front bumper LH retainer	necessary	\$ 13.25	\$ 13.25
1 pc	Front bumper lower grille	cracked	\$ 95.60	\$ 95.60
1 pc	Front bumper tow hook cover	distorted	\$ 14.60	\$ 14.60
1 pc	Radiator grille	cracked	\$ 137.50	\$ 137.50
1 pc	Radiator grille netting	necessary	\$ 28.00	\$ 28.00 <i>X Not found</i>
1 pc	Headlamp	deep cut	\$ 585.00	\$ 585.00
1 pc	Bonnet	badly dented	\$ 433.80	\$ 433.80
1 pc	Bonnet RH hinge	bent	\$ 31.00	\$ 31.00
1 pc	Bonnet LH hinge	bent	\$ 31.00	\$ 31.00
1 pc	Bonnet rubber	necessary	\$ 18.00	\$ 18.00
1 pc	Bonnet insulator	deformed	\$ 55.00	\$ 55.00
1 pc	Bonnet lock	distorted	\$ 90.60	\$ 90.60
1 pc	Front fender	repairable	\$ 381.40	\$ - <i>R</i>
1 pc	Front wiper panel garnish	deformed	\$ 190.00	\$ 190.00
1 pc	Front wiper blade	cut	\$ 50.60	\$ 50.60
1 pc	Front wiper arm	bent	\$ 56.20	\$ 56.20
1 pc	Front wiper linkage	bent	\$ 29.50	\$ <i>NN</i> 29.50 <i>X No photo</i>
1 pc	Front wiper motor	serviceable	\$ 200.00	\$ -
1 pc	Front windscreen glass	broken	\$ 1,500.00	\$ 1,500.00
1 pc	Front windscreen moulding	necessary	\$ 80.00	\$ 80.00
1 set	Front windscreen clip	necessary	\$ 12.00	\$ 12.00
1 pc	Dashboard top	serviceable	\$ 548.20	\$ -
1 pc	Air con condenser	serviceable	\$ 762.50	\$ -
1 pc	Air con condenser holder	serviceable	\$ 15.00	\$ -
1 pc	Front support panel	repairable	\$ 405.00	\$ - <i>R</i>
1 pc	Bonnet lock brace bracket	bent	\$ 38.00	\$ <i>NN</i> 38.00 <i>X No photo</i>
			<i>422980</i> \$ 6,637.40	\$ 4,325.30
Less 20%			\$ 1,327.48	\$ 865.06
			<i>5383184</i> \$ 5,309.92	\$ 3,460.24

JAS APPRAISAL SERVICES

22 Sin Ming Lane #06-83 Midview City Singapore 573969

Hand phone No. 98467316

Co. Reg. No. 53202241J

Our Reference JASTP/C2/105

Registration No. SJG 3252 P

QTY	DESCRIPTION	CONDITION/ REMARKS	ORIGINAL QUOTATION	REVISED QUOTATION
-----	-------------	-----------------------	-----------------------	----------------------

S/NETT PARTS

1 pc	Front windscreen sealant	necessary	\$ 50.00	\$ 50.00
1 pc	ERP bracket	necessary	\$ 15.00	\$ 15.00
			\$ 65.00	\$ 65.00

LABOUR CHARGES

To remove and check all electrical components, wirings and control unit and test for function. 30

\$ 80.00 \$ 60.00

To remove the affected parts and all relevant fittings and attachments to commence repairs.
Jack up, straighten, cut and weld the above listed parts. Panel beat and reshape the affected area. Replace and realign where necessary.

\$ 1,400.00 \$ 1,050.00 600

To putty and spray painting on accident affected area and to touch up paint work.

\$ 1,000.00 \$ 820.00 800

To apply undercoating on the replaced and repaired portion for rust protection.

\$ 250.00 \$ 220.00 60

To remove and replace front windscreen glass to facilitate repair and to perform water seepage test.

\$ 120.00 \$ 120.00

To remove and refix air con condenser, vacuum clean, refill gas and check for leakages.

\$ 120.00 \$ 60.00

JAS APPRAISAL SERVICES

22 Sin Ming Lane #06-83 Midview City Singapore 573969

Hand phone No. 98467316

Co. Reg. No. 53202241J

Our Reference JASTP/C2/105

Registration No. SJG 3252 P

QTY	DESCRIPTION	CONDITION/ REMARKS	ORIGINAL QUOTATION	REVISED QUOTATION
-----	-------------	-----------------------	-----------------------	----------------------

LABOUR CHARGES

To remove and refix interior fittings, trimmings,
garnish and upholstery to facilitate repair.

\$ 280.00 \$ 220.00 ⁶⁰

To remove and refix dashboard and all other
damaged fittings, check and rectify the affected
components.

\$ 480.00 \$ 260.00 ⁿⁿ
\$ 9,104.92 \$ 6,335.24

1730

The repairers have agreed to undertake repairs at our adjusted amount of \$ 6,335.24 (Six thousand three hundred thirty-five and cents twenty-four only).



David Thor
Automobile Appraiser

\$ 5178.84
4/5 4/100 #

FormTeam Consultancy Pte Ltd (Co.Reg.No:200819260D)

33 Ubi Avenue3 #02-15, Vertex
Singapore 408868
Tel: 6509 1788 Fax: 6509 6221 Email: tomho@fta.com.sg

VEHICLE DAMAGE INSPECTION REPORT

Our File No: RRM14-010047/PRI/CBX/RI/CBX
Date: 15/12/2014

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/13-868570
Claimant Vehicle No:	SJG3252P	Insured Vehicle No:	FBF1549Y
Date of Loss:	08/01/2014	Nature of Claim:	TP
		Claim No:	MSCV/14-000115

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG3252P	Engine No:	L13A4093109
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61082903
Reg. Date:	26/06/2008 (Man. Year: 2008)	Odometer:	92041 km
Colour:	Black		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Kenda 5 mm	Rear Left Side:	Kenda 5 mm
Front Right Side:	Kenda 5 mm	Rear Right Side:	Kenda 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,525.24	3,332.36	192.88	5.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	1,690.00	1,120.00	39.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,335.24	5,022.36	1,312.88	20.72
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	6,335.24	4,000.00	2,335.24	36.86

INSPECTION

Date of Assignment:	10/01/2014	Inspected At:	Car Life Auto Engineering Services (TOWN)
Date Inspected:	10/01/2014, 01/12/2014		BLK 1002 #01-75 BUKIT MERAH LANE 3
Est Repair Period:	6.0 days		Singapore 159719

Adjuster: Chow Bo Xiong

Manager: Frankie

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2014)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	FormTeam Consultancy Pte Ltd/SJG3252P/15/12/2014 18:11	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper	Badly dented	523.50 FL	*523.50 FL
2	1		*Front bumper RH bracket	Bent	22.50 FL	*22.50 FL
3	1		*Front bumper LH bracket	Bent	22.50 FL	*22.50 FL
4	1		*Front bumper reinforcement	Bent	253.90 FL	*253.90 FL
5	1		*Front bumper RH retainer	Necessary	13.25 FL	*13.25 FL
6	1		*Front bumper LH retainer	Necessary	13.25 FL	*13.25 FL
7	1		*Front bumper lower grille	Cracked	95.60 FL	*95.60 FL
8	1		*Front bumper tow hook cover	Distorted	14.60 FL	*14.60 FL
9	1		*Radiator grille	Cracked	137.50 FL	*137.50 FL
10	1		*Radiator grille netting	Not Fitted	28.00 FL	*- FL
11	1		*Headlamp	Deep Cut	585.00 FL	*585.00 FL
12	1		*Bonnet	Badly Dented	433.80 FL	*433.80 FL
13	1		*Bonnet RH hinge	Bent	31.00 FL	*31.00 FL
14	1		*Bonnet LH hinge	Bent	31.00 FL	*31.00 FL
15	1		*Bonnet rubber	Necessary	18.00 FL	*18.00 FL
16	1		*Bonnet insulator	Not Fitted	55.00 FL	*- FL
17	1		*Bonnet lock	Not Replaced	90.60 FL	*- FL
18	1		*Front fender	Repairable	0.00 FL	*- FL
19	1		*Front wiper panel garnish	Deformed	190.00 FL	*190.00 FL
20	1		*Front wiper blade	Cut	50.60 FL	*50.60 FL
21	1		*Front wiper arm	Bent	56.20 FL	*56.20 FL
22	1		*Front wiper linkage	No Photo Show Damage	29.50 FL	*- FL
23	1		*Front wiper motor	Serviceable	0.00 FL	Serviceable
24	1		*Front windscreen glass	Broken	1,500.00 FL	*1,500.00 FL
25	1		*Front windscreen moulding	Necessary	80.00 FL	*80.00 FL
26	1		*Front windscreen clip	Necessary	12.00 FL	*12.00 FL
27	1		*Dashboard top	Serviceable	0.00 FL	Serviceable
28	1		*Air con condenser	Serviceable	0.00 FL	Serviceable
29	1		*Air con condenser holder	Serviceable	0.00 FL	Serviceable
30	1		*Front support panel	Repairable	0.00 FL	*- FL
31	1		*Bonnet lock brace bracket	No Photo Show Damage	38.00 FL	*- FL
32	1		*Front windscreen sealant	Necessary	50.00 FS	*50.00 FS
33	1		*ERP bracket	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 4,390.30 4,149.20

- List Item Discount on L Items 20.00/20.00% (\$\$) 865.06 816.84

Total Parts (\$\$) 3,525.24 3,332.36

FormTeam Consultancy Pte Ltd/SJG3252P/15/12/2014 18:11. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To remove and check all electrical components, wirings and control unit and test for fuction.	New	60.00	30.00
2	To remove the affected parts and all relevant fittings and attachments to commence repairs. Jack up, straighten, cut and weld the above listed parts. Panel beat and reshape the affected area. Replace and realign where necessary.	New	1,050.00	600.00
3	To putty and spray painting on accident affected area and to touch up paint work.	New	820.00	800.00
4	To apply undercoating on the replaced and repaired portion for rust protection.	New	220.00	80.00
5	To remove and replace front windscreen glass to facilitate repair and to perform water seepage test.	New	120.00	120.00
6	To remove and refix air con condenser, vacuum clean, refill gas and check for leakages.	New	60.00	60.00
7	To remove and refix interior fittings, trimmings, garnish and upholstery to facilitate repair.	New	220.00	0.00
8	To remove and refix dashboard and all other damagedx fittings, check and rectify the affected components.	New	260.00	0.00
Gross Labour Cost (\$\$)			2,810.00	1,690.00

FormTeam Consultancy Pte Ltd/SJG3252P/15/12/2014 18:11. Not valid without Reference section.

< END OF ESTIMATES >



Your Ref: SS/10234/317

Date: 26th December 2017

Our Ref: CS1/LAW17020802/T1qbs2

M/s Alan Shankar & Lim LLC

151 Chin Swee Road
#10-07 Manhattan House
Singapore 169876

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SJG 3252P**

INSURED VEHICLE: FBF 1549Y

ACCIDENT DATE: 08/01/2014

We thank you for your instruction on 31/10/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJG 3252P from M/s Jas Appraisal Services.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Singapore Accident Statement of Vehicles SJG 3252P and FBF 1549Y.
- d) Colour damaged vehicle photographs of SJG 3252P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJG 3252P
Make & Model	: Honda Fit 1.3G A
Year of Registration	: 2008
Chassis Number	: GE61082903
Engine Capacity	: 1339 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 3252P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BADLY DENTED	523.50	523.50
1	FRONT BUMPER RH BRACKET	BENT	22.50	22.50
1	FRONT BUMPER LH BRACKET	BENT	22.50	22.50
1	FRONT BUMPER REINFORCEMENT	BENT	253.90	253.90
1	FRONT BUMPER RH RETAINER	NECESSARY	13.25	13.25
1	FRONT BUMPER LH RETAINER	NECESSARY	13.25	13.25
1	FRONT BUMPER LOWER GRILLE	CRACKED	95.60	95.60
1	FRONT BUMPER TOW HOOK COVER	DISTORTED	14.60	14.60
1	RADIATOR GRILLE	CRACKED	137.50	137.50
1	RADIATOR GRILLE NETTING	NOT FITTED	28.00	-
1	HEADLAMP	DEEP CUT	585.00	585.00
1	BONNET	BADLY DENTED	433.80	433.80
1	BONNET RH HINGE	BENT	31.00	31.00
1	BONNET LH HINGE	BENT	31.00	31.00
1	BONNET RUBBER	NECESSARY	18.00	18.00
1	BONNET INSULATOR	DEFORMED	55.00	55.00
1	BONNET LOCK	DISTORTED	90.60	90.60
1	FRONT FENDER	TO REPAIR SEE LABOUR	381.40	-
1	FRONT WIPER PANEL GARNISH	DEFORMED	190.00	190.00
1	FRONT WIPER BLADE	CUT	50.60	50.60
1	FRONT WIPER ARM	BENT	56.20	56.20
1	FRONT WIPER LINKAGE	NOT NECESSARY	29.50	-
1	FRONT WIPER MOTOR	SERVICEABLE	200.00	-
1	FRONT WINDSCREEN GLASS	BROKEN	1,500.00	1,500.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	80.00	80.00
1	SET FRONT WINDSCREEN CLIP	NECESSARY	12.00	12.00
1	DASHBOARD TOP	SERVICEABLE	548.20	-
1	AIR CON CONDENSER	SERVICEABLE	762.50	-
1	AIR CON CONDENSER HOLDER	SERVICEABLE	15.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LA	405.00	-

Report Ref No. CS1/LAW17020802/T1qbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET LOCK BRACE BRACKET	NOT NECESSARY	38.00	-
	LESS 20% DISCOUNT		-1,327.48	-845.96
			5,309.92	3,383.84
	SPECIAL NETT ITEMS			
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	ERP BRACKET (SN)	NECESSARY	15.00	15.00
			65.00	65.00
	LABOUR			
	TO REMOVE AND CHECK ALL ELECTRICAL COMPONENTS, WIRINGS AND CONTROL UNIT AND TEST FOR FUNCTION.		80.00	30.00
	TO REMOVE THE AFFECTED PARTS AND ALL RELEVANT FITTINGS AND ATTACHMENTS TO COMMENCE REPAIRS. JACK UP, STRAIGHTEN, CUT AND WELD THE ABOVE LISTED PARTS. PANEL BEAT AND RESHAPE THE AFFECTED AREA. REPLACE AND REALIGN WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FRONT FENDER AND FRONT SUPPORT PANEL.		1,400.00	600.00
	TO PUTTY AND SPRAY PAINTING ON ACCIDENT AFFECTED AREA AND TO TOUCH UP PAINT WORK.		1,000.00	800.00
	TO APPLY UNDERCOATING ON THE REPLACED AND REPAIRED PORTION FOR RUST PROTECTION.		250.00	60.00
	TO REMOVE AND REPLACE FRONT WINDSCREEN GLASS TO FACILITATE REPAIR AND TO PERFORM WATER SEEPAGE TEST.		120.00	120.00
	TO REMOVE AND REFIX AIR CON CONDENSER, VACUUM CLEAN, REFILL GAS AND CHECK FOR LEAKAGES.		120.00	60.00
	TO REMOVE AND REFIX INTERIOR FITTINGS, TRIMMINGS, GARNISH AND UPHOLSTERY TO FACILITATE REPAIR.		280.00	60.00
	TO REMOVE AND REFIX DASHBOARD AND ALL OTHER DAMAGED FITTINGS, CHECK AND RECTIFY THE AFFECTED COMPONENTS.	NOT NECESSARY	480.00	-
			3,730.00	1,730.00
	GRAND TOTAL		9,104.92	5,178.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,100.00

Report Ref No. CS1/LAW17020802/T1qbs2



Report Ref No. CS1/LAW17020802/T1qbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

A handwritten signature in black ink, appearing to be 'K.K. LAU'.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.