

ASS. REC. BY:

REF:

CS/MS(117020850/Kvb) n2

Special Instruction:

Surveyor
merimenASSIGNMENT (Office)

From (Person): Fievel Tuo of MSCh Date/Time: 01-11-2017 11:27am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YH 98E Insured: GBA 1209Z

at Workshop m/s Cheng Hoo Tel: 6755 6142

of Blk 1079 Yishun Ind Park A # 01-374

Policy No: A28965324MKE Claim No: 535005

Sum Insured: Excess:

Make of Veh: D.O.A. 26.10.2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 01-11-2017 1148am Person Contacted: Sharon Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	YH 98E - CC4 / ALA 17014591 / K263 DOA: 180917
	GBA 1209Z - X
6/12/17	Send preli revised by merimen

ASS. REC. BY:

REF: *MSG/*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s *Cheng I tre*

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *03* days Res: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *YH 98E* Yr Regn: *02 06*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Toy Dyno* C.C. *2986*Colour: *White* A/C: Insured / Std / NI / NASp. Reading: *469467* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JTFU1-354408010387*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *183 R14 X8*R: *155 R12 X 8 (10)*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal. *6* mm R/Bal. *5 5* mmL/Bal. *6* mm L/Bal. *5 5* mmD.O.A. *26/10/17* D.O.I. *4/12/17*Survey held at *✓*Des. of Damages: *Front* / Rear / O/S / N/S / U/C / Rooftop or*Pha o/s*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*1/12 Pke pass to Catherine**22/12 LIR, 8135d Carbur Etdp (Recl 1062-43, 4490)*

RECEIVED 23 FEB 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) *23/2- typist*Days Of Repair: *3*Resurvey No. of Trip: *1*Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

*Merimen*Lump Sum / I.B.I. (\$) *1350/2**300**10**210*

[Signature]

22/2/2018

Survey Department Check List (Case Handler)

Reference No. : CS MSG 170208501 Kvb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 23/2/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17020850/Kvb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 01-11-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 1209Z	Veh. Inspected	YH 98E	
Policy No.	A28965324MKC	Coverage (\$)	0.00	
Claim No.	535005	Excess (\$)	0.00	
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	01/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/10/2017	Inspection Date		
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2017		01 Nov 2017 11:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BUDGETCARS PTE LTD, Co. Reg. No.: 201618239Z								
Main Claimant:	LIM KEE FOO MANUFACTURING PTE LTD, Co. Reg. No.: 200207824E								
Vehicle Reg. No.:	YH98E	Date of Loss:	26/10/2017 10:00 - :59						
Claim Type:	TP / 535005	Policy/Cover Note No.:	A28965324MKC(COMP) (Comprehensive) Coverage: 31/05/2017 - 30/05/2018						
Vehicle Reg. No. (Insured):	GBG1209Z	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/11/2017]								
Driver/Custodian (Insured):	SYED MUHAMMAD MUHAJIMIN BIN SYED NASIR (), NRIC: S9502429G								
Adj Asg. Remarks:	request Kenneth Kong for survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Fievel Foo Wen Yao	Date: 06 Dec 2017

Preliminary Advice

Insured Vehicle No	: GBG1209Z	Accident Date	: 26/10/2017
TP Vehicle No	: YH98E	Assignment Date	: 01/11/2017
Make	: TOYOTA DYNA 150	Est. Duration of Repair	: 3.00
Date of Inspection	: 04/12/2017		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,412.43
Revised Amount	:S\$	1,732.43
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,732.43
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	7824E
Vehicle Details	
Vehicle No.	YH98E
Vehicle to be Exported	Yes
Intended De-registration Date	27 Oct 2017
Vehicle Make	TOYOTA
Vehicle Model	DYNA 150 D
Primary Colour	Blue
Secondary Colour	White
Manufacturing Year	2005
Engine No.	5L5626045
Chassis No.	JTFUF35Y406010387
Maximum Power Output	-
Open Market Value	\$23,912.00
Original Registration Date	15 Feb 2006
First Registration Date	15 Feb 2006
Transfer Count	1
Actual ARF Paid	\$1,196.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	14 Feb 2021
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	5
PQP Paid	\$22,695.00
COE Rebate Amount	\$14,989.00
Total Rebate Amount	\$14,989.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 27 Oct 2017

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

YH98E
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 26/10/2017

Estimate No: ES1791374/WS

Date: 04 Dec 2017

Policy No: DMCV16S017853

Veh Reg No: YH98E

Make/Model: TOYOTA TOYOTA
DYNA 150 D

Chassis No: JTFUF35Y406010387

Engine No: 5L5626045

Reg. Date: 15/02/2006

Estimate Repair Cost to Vehicle No :YH98E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 RH TAIL LAMP	139.10	1 PCS	139.10	✓
2 RH TAIL LAMP PANEL	90.80	1 PCS	90.80	✓
			229.90	
		Less 25%	57.48	172.43
Special Net				
3 REAR SAFETY BAR ASSY	580.00	1 PCS	580.00	✓
4 REAR MAIN STOPPERS	80.00	2 PCS	160.00	✓
			740.00	740.00
Labour				
5 REMOVE AND REFIX REAR SAFETY BAR, RH TAIL LAMP. KNOCK AND REPAIR RH TAIL LAMP PANEL AND REALIGN THE SAME	400.00	1 LA	400.00	300
6 PUTTY AND RESPRAY REAR SAFETY BAR AND BRACKETS	300.00	1 LA	300.00	150
7 TO REPAIR REAR TAILGTE FRAME & REALIGN TAILGATE	800.00	1 LA	800.00	450
			1,500.00	1,500.00
Total			SS 2,412.43	
Add GST @ 7%				168.87
Total Amount Payable				SS 2,581.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

X

YH98E

TP-MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 26/10/2017

Estimate No: ES1791374/WS

Date: 04 Dec 2017

Policy No: DMCV16S017853

Veh Reg No: YH98E

Make/Model: TOYOTA TOYOTA
DYNA 150 D

Chassis No: JTFUF35Y406010387

Engine No: 5L5626045

Reg. Date: 15/02/2006

Estimate Repair Cost to Vehicle No :YH98E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 RH TAIL LAMP	139.10	1 PCS	139.10	✓
2 RH TAIL LAMP PANEL	90.80	1 PCS	90.80	✓
			229.90	
		Less 25%	57.48	172.43
Special Net				
3 REAR SAFETY BAR ASSY	580.00	1 PCS	580.00	✓
4 REAR MAIN STOPPERS	80.00	2 PCS	160.00	
			740.00	740.00
Labour				
5 REMOVE AND REFIX REAR SAFETY BAR, RH TAIL LAMP. KNOCK AND REPAIR RH TAIL LAMP PANEL AND REALIGN THE SAME	400.00	1 LA	400.00	300
6 PUTTY AND RESPRAY REAR SAFETY BAR AND BRACKETS	300.00	1 LA	300.00	150
			700.00	700.00
			Total	S\$ 1,612.43
			Add GST @ 7%	112.87
			Total Amount Payable	S\$ 1,725.30

7 To repair rear tail gate frame and
realign tail gate #800

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020850/KVBN2
Date: 26/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: A28965324MKC (COMP)	
Claimant Vehicle No : YH98E	Insured Vehicle No : GBG1209Z	
Date of Loss: 26/10/2017	Nature of Claim: TP	Claim No: 535005

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YH98E	Engine No: 5L5626045	
Make & Model: TOYOTA DYNA 150, 3.0 D (M)	Chassis No: JTFUF35Y406010387	
Reg. Date: 15/02/2006 (Man. Year: 2005)	Odometer: 469467 km	
Colour: White		
Engine Capacity: 2986 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes	
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 185R14X8	Rear Tyre Size: 155R12X8 (D)	
Front Left Side: Falken 6 mm	Rear Left Side: Falken 5/5 mm	
Front Right Side: Falken 6 mm	Rear Right Side: Falken 5/5 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	912.42	832.42	80.00	8.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	900.00	600.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,412.42	1,732.42	680.00	28.19
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	2,412.42	1,350.00	1,062.42	44.04
+ GST 7.00/7.00% (S\$)	168.87	94.50	74.37	44.04
Nett Amount (S\$)	2,581.29	1,444.50	1,136.79	44.04

INSPECTION

Date of Assignment: 01/11/2017	
Date Inspected: 04/12/2017	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair: 3.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Feb 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YH98E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH TAIL LAMP	Cracked	139.10 FL	*139.10 FL
2	1		*RH TAIL LAMP PANEL	Distorted	90.80 FL	*90.80 FL
3	1		*REAR SAFETY BAR ASSY	Bent	580.00 FS	*580.00 FS
4	1		*REAR MAIN STOPPERS	O/s Dented/Cut	160.00 FS	*80.00 FS
					Sub Total (\$\$)	969.90 889.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	57.48 57.48
					Total Parts (\$\$)	912.42 832.42

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR SAFETY BAR,RH TAIL LAMP,KNOCK AND REPAIR RH TAIL LAMP PANEL AND REALIGN THE SAME	New	400.00	300.00
2	PUTTY AND RESPRAY REAR SAFETY BAR AND BRACKETS	New	300.00	150.00
3	TO REPAIR REAR TAILGATE FRAME & REALIGN TAILGATE	New	800.00	450.00
Gross Labour Cost (\$\$)			1,500.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >