

REF: CS1 / LPC17020854 / C v b s 2

Special Instruction:

ASSIGNMENT (Office)

From (Person): Gerald Poh of LPC Date/Time: 01-11-2017
Estimated Cost: _____ Bill to: _____

Part by Part : \$ 21245.60

Third Parties:

Claimant:

Surveyor: Priority Services

Workshop: ME Solution

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SKI 5148P Insured: WPR 2378

at Workshop m/s mg Solution

Tel:

of 23 Kaki Bukit Ave 4 #02-03

Policy No: _____ Claim No: 16/17/17/VP00/0233021

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25.03.2017

(Client's Record)

D.O.A. 25.03.2017

H.O.D. Enforcement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red S _____ / _____ %; Original 10 days)

Date/Time: 6/12/17 Submit Final Fig LS \$14,300, 9 days (Red \$ 6995.69 33 %; Original days)

Date/Time	Action/Instruction
-----------	--------------------

SKT 5148P - X

WPR 2378 - x

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED JUNE 2017

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

b) Date/Time 6/12-12 File Pass to

2) Date/Time

File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time

File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time

File Return to

Survey Department Check List (Case Handler)

Reference No. : AS1 LPE 17020854 VB
Policy Type: OD / TP / TP RES / TL / EVA

Admin (

Case Handler

Typist

): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No				
C	Regn Month/Year				
N	Vehicle Type				
N	Make & Model				
C	Engine Capacity. (C.C)				
N	Colour				
C	Odometer. (Sp.Reading)				
C	Chassis No				
N	General Condition				
N	Steering				
N	Brake				
N	Modification (Modi)				
C	Tyre Size				
N	Tyre Make				
C	Tyre Balance				
C	Date of Inspection				
N	Survey held				
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 5/12/17
Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS1/LPC17020854/vb	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 01-11-2017	
		Code : LPC2	
1. Policy Particulars :- PAPER SURVEY			
Insured Veh.	WPR 2378	Veh. Inspected	SKT 5148P
Policy No.		Coverage (\$)	0.00
Claim No.	16/17/17/VP00/0233021	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	01/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/03/2017	Inspection Date	01/11/2017
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 16/17/17/VP00/0233021 (Head Office Reference)

25 October 2017

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF SKT5148P

We refer to the above accident.

Kindly assist our Head Office to render your opinion on the adjusted repair costs for the above vehicle and the market value at the time of the loss.

We enclose the following documents :-

- a) Survey report & photos of SKT5148P
- b) GIA report of SKT5148P
- c) Police report of WPR2378

Kindly study the documents and let us have your opinion on the adjusted repair cost within the next 10 days.

You can email your report to ltau@lonpac.com

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIDENT STATEMENT

Date Of Report	27/03/2017 13:50
Date Of Accident	25/03/2017 13:45
Exact Location Of Accident	SECOND LINK TOWARDS MALAYSIA, BEF. MALAYSIA CUSTOM
Country/State of Loss	Malaysia/Johor Darul Takzim

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT5148P
Insured/Policyholder	
Name Of Registered Owner	FOONG TZE KANG (FENG ZHIGANG)
NRIC No	S7811253J
Email Address	lawrence.foong@promatrix.sg
Mobile Phone No	(LOCAL) +65-91992589
Alternative Phone No	Office-91992589
Vehicle Particulars	
Manufacturer	HONDA
Model	HRV 1.5 LX CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	Liberty Insurance Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SI16V08030/VPC/R01 (COMP)
Cover Note Number	
Driver	
Name of Driver	FOONG TZE KANG (FENG ZHIGANG)
NRIC No	S7811253J
Date Of Birth	24/04/1978
Occupation	Indoor
Date Of Driving Pass	23/07/1996
Driving Experience	20 Years And 8 Months
Gender	Male
Mobile Number	(Local) +65-91992589
Fax Number	
Contact Number	Office-91992589
Email Address	lawrence.foong@promatrix.sg

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address



POLIS DIRAJA MALAYSIA REPOt POLIS

(A)

Balai : TRAFIK ISKANDAR PUTERI
 Daerah : ISKANDAR PUTERI
 Kontinjen : JOHOR
 No Repot : TRAFIK IPUTERI/002657/17
 Tarikh : 25/03/2017
 Waktu : 1533 PM
 Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R190317

Butir-butir Penerima Repot

Nama : AHMAD FIKRI BIN SAMSUDIN

No Personel : R195927

Pangkat : KONST/P

Butir-butir Jurubahasa (Jika Ada)

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Pasport : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : FOONG TZE KANG

No K/P (Baru) : ---

No Polis/Tentera : ---

No Pasport : E43742438

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 24/04/1978

Umur : 38 tahun 11 bulan

Keturunan : Cina

Warganegara : Singapore

Pekerjaan : MANAGER

Alamat Tempat Tinggal : BLK 391 BUKIT BATOK WEST AVE 5 #15-426 SINGAPORE 650391, 650391

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 6591992589

Emel : ---

Pengadu Menyatakan:-

PADA 25/03/2017 JAM LEBIH KURANG 1344 PETANG, SAYA MEMANDU MOTOKAR JENIS HONDA HRV NOMBOR SKT5148P DARI SINGAPORE MAHU MENUJU KE TUN AMINAH. PADA KETIKA ITU, APABILA SAYA SAMPAI DI KOMPLEKS SULTAN ABU BAKAR KASTAM, SEMASA SAYA MEMBERHENTIKAN M/KAR SAYA UNTUK MENUNGGU PEMERIKSAAN DARI PIHAK KASTAM. TIBA-TIBA SEBUAH MOTOKAR JENIS PERODUA MYVI NOMBOR WPR2378 DARI ARAH BELAKANG TELAH MELANGGAR BELAKANG M/KAR SAYA LALU M/KAR SAYA MENGELUNSUR KE DEPAN DAN MELANGGAR SEBUAH M/KAR JENIS AUDI Q3 NOMBOR SKH6627E YANG BERADA DI HADAPAN SAYA. SAYA TIDAK MENGALAMI APA-APA KECEDERAAN. KEROSAKAN M/KAR DI BAHAGIAN BELAKANG BUMPER, BONET, SENSOR, BAHAGIAN DEPAN BUMPER, NO PLAT DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI. SEKIAN REPOt SAYA

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

IS Pencetak: Tarikh @ Masa Cetak

: R195927 | 25/03/2017 03:50:17 PM



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK ISKANDAR PUTERI
 Daerah : ISKANDAR PUTERI
 Kontinjen : JOHOR
 No Repot : TRAFIK IPUTERI/002662/17
 Tarikh : 25/03/2017
 Waktu : 1905 PM
 Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R190317
 No Repot Bersangkut : TRAFIK
 IPUTERI/002657/17

Butir-butir Penerima Repot

Nama : AHMAD FIKRI BIN SAMSUDIN

No Personel : R196927

Pangkat : KONST/P

Butir-butir Jurubahasa (Jika Ada)

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : PUNG CHE FOH

No K/P (Baru) : 890405125539

No Polis/Tentera : ---

No Paspot : ---

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 05/04/1989

Umur : 27 tahun 11 bulan

Keturunan : Cina

Warganegara : Malaysia

Pekerjaan : SWASTA

Alamat Tempat Tinggal : C-09-06 BISTARI IMPIAN, JALAN SERANTAU TAMAN DATO ONN, 80350, JOHOR

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 0168480538

Pengadu Menyatakan:-

PADA 25/03/2017 JAM LEBIH KURANG 1344 PETANG, SAYA MEMANDU M/KAR JENIS PERODUA MYVI NOMBOR WPR2378 DARI SINGAPORE MAHU BALIK KE RUMAH DI TAMAN DATO ONN. PADA KETIKA ITU, APABILA SAYA SAMPAI DI KOMPLEKS SULTAN ABU BAKAR KASTAM, SEMASA SAYA MEMBERHENTIKAN M/KAR TIBA-TIBA M/KAR SAYA TELAH MENGELUNSUR KE DEPAN DAN MELANGGAR SEBUAH MOTOKAR JENIS HONDA BRV NOMBOR SKT5148P YANG BERADA DI HADAPAN SAYA. DALAM KEJADIAN ITU, SAYA TIDAK MENGALAMI APA-APA KECEDERAAN. KEROSAKAN M/KAR DI BAHAGIAN DEPAN BUMPER, BONET, SET LAMPU DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI. SEKIAN REPOT SAYA

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

A6028672 | 29/03/2017 02:39:47 PM

POL. SALINAN REPOT
 TRAFIK IPD ISKANDAR PUTERI
 SALINAN YANG DITAMBAH BENAR
 (HANYA UNTUK T. H. T. SIVIL)

SETUA TRAFIK
 TIDAK BOLEH DISALAHKAN
 TIDAK BOLEH DISALAHKAN


RAJAH KASAR KEMALANGAN JALANRAYA

IPTR NO: 02657/17, TARIKH 25/03/2017

LOKASI: KOMPLEKS SULTAN ABU BAKAR

ISKANDAR PUTERI, JOHOR.

(Ukuran Tidak Mengikut Scale)



KENDERAAN TERLIBAT TIADA DI TEMPAT KEJADIAN SEMASA PEMERIKSAAN DIJALANKAN

Tanda Pengenalan :-

- A - -Tepi Sebelah Kiri Jalan
- A1 - -Garis Putih Putus-Putus Pembahagi Lorong,
- A2 - -Garis Putih Putus-Putus Pembahagi Lorong
- A3 - -Pembahagi Jalan
- B - -Arah Ke Malaysia
- C - -Arah Ke Singapore

Ukuran :-

- A ke A1 - 3.4 Meter,
- A1 ke A2 - 3.4 Meter,
- A2 ke A3 - 3.4 Meter,

PEJ. 6
TRAFIK IPD
SALINAN YAS
(HANYA UN)

ISKANDAR PUTERI
KEMERAN
(SIVIL)

(MOHD JURAHAKIM B. JUMAT) SJH 190317
PEN. PEG. PENYIAHAT (TRAFIK)
IPD NUSAJAYA
JOHOR

JOHOR
KEMERAN



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No. TP/0029/17	Date of Report	: 5 April 17
To : Foong Tze Kang (Feng Zhigang)	Date of Request	: 27 March 17
	Report requested by	: Foong Tze Kang (Feng Zhigang)
Block 391, #15-426	Date of Accident	: 25 March 17
Bukit Batok West Avenue 5	Date of Inspection	: 27 March 17
Singapore 650391	Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SKT 5148 P	Odometer Reading	: 33,550 km
Make	: Honda	Carrying Capacity	: 4
Model	: HRV (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2015	Air-Conditioner	: Yes
Colour	: Metallic Black	Wing Mirror	: Yes
Engine Capacity	: 1,497 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: MRHRU1830FP000141	Others	: Nil

TYRE CONDITION

Front Left	: 6mm	Front Right	: 6mm
Make	: Dunlop	Make	: Dunlop
Rear Left	: 6mm	Rear Right	: 6mm
Make	: Dunlop	Make	: Dunlop
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: No
--------------	----------	------------	------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at MG Solution Pte Ltd, 23, Kaki Bukit Avenue 4, (South Wing) #02-03, Singapore 415933.

Follow-up inspection has been conducted.

Point of Impact

At the front and rear portion.

Damages

Front portion: The front bumper, front bumper reinforcement, front grille, headlamps assembly, support panel, etc.

Rear portion: The tailgate, rear bumper, end panel, exhaust silencer, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$21,295.60

Conclusion

The repairer has agreed to undertake repairs at our adjusted amount of \$21,295.60 corresponding to labour charges, spray painting and replacement of parts.

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser



LAWRENCE NG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SKT 5148 P Honda HRV (A)

TP/0029/17

Workshop : MG Solution Pte Ltd

Replacement of Parts	Condition	Repairer's Estimate (S S)	Dist. %	Our Recommendation (S S)	Dist. %
1pc. Tailgate windscreen glass inner seal	Necessary	70.00		20.00	
1tube. Tailgate windscreen glass sealant	Necessary	70.00		40.00	
1set. Tailgate inner trim board clips	Necessary	70.00		30.00	
1set. Rear bumper reverse sensor	Dented / Malfunction	450.00		300.00	200
1pc. Exhaust silencer chrome finisher	Dented	220.00		220.00	150
Total For Parts :-		23,140.00		16,225.60	
Labour Charges :					
To remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, re position & re-align, replacement of parts to the original position including adjustment.		2,200.00		1,800.00 1,400	
Apply rust coating on the replaced & repaired panels.		200.00		90 120.00	
Check wiring & lighting system.		100.00		60.00	
Remove & replace A/C condenser & pipes to assist repairs.		180.00		100.00	
Remove & re-install radiator, hoses & fan assembly to assist repairs.		180.00		80.00	
Remove & re-install tailgate windscreen glass to assist repairs.		200.00		120.00	
Transfer & replace tailgate mechanism to new tailgate.		100.00		70.00	
Remove, re-install & replace rear inner trims, garnishes & boards to assist repairs.		280.00		90 180.00	
Remove & replace exhaust silencer & chrome finisher.		120.00		80.00	
Remove & replace rear bumper reverse sensor.		100.00		60.00	
Spray Painting :					
To putty & spray repaired & replaced body panels.		2,800.00		1,600 2,400.00	
Grand Total :-		29,600.00		21,295.60	

9 days



Your Ref: 16/17/17/VP00/0233021

Date: 08th December 2017

Our Ref: CS1/LPC17020854/Cvbs2

M/s Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SKT 5148P
INSURED VEHICLE: WPR 2378
ACCIDENT DATE: 25/03/2017

We thank you for your instruction on 01/11/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKT 5148P from M/s Priority Services.
- b) Singapore Accident Statement of Vehicles SKT 5148P.
- c) Colour damaged vehicle photographs of SKT 5148P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKT 5148P
Make & Model	: Honda HRV (A)
Year of Registration	: 2015
Chassis Number	: MRHRU1830FP000141
Engine Capacity	: 1497cc
2. We recommend that the repairs of the entire damage require about 9 (Nine) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 5148P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	1,140.00	1,140.00
1	FRONT BUMPER RH SIDE RETAINER	NECESSARY	34.00	34.00
1	FRONT BUMPER LH SIDE RETAINER	NECESSARY	34.00	34.00
1	FRONT BUMPER LOWER GRILLE	REFIT	201.00	-
1	FRONT BUMPER REINFORCEMENT	DENTED	472.00	472.00
1	FRONT GRILLE	CRACKED	405.00	405.00
1	FRONT GRILLE EMBLEM	NECESSARY	75.00	75.00
1	RH HEADLAMP	CRACKED	2,550.00	2,550.00
1	RH HEADLAMP LOWER BRACKET	SERVICEABLE	108.00	-
1	LH HEADLAMP	CRACKED	2,550.00	2,550.00
1	LH HEADLAMP LOWER BRACKET	SERVICEABLE	108.00	-
1	A/C CONDENSER	DENTED	1,445.00	1,445.00
1	RADIATOR	REFIT	1,843.00	-
1	TAILGATE	DENTED	1,760.00	1,760.00
1	TAILGATE 'HR-V' EMBLEM	NECESSARY	56.00	56.00
1	TAILGATE CENTRE EMBLEM	NOT NECESSARY	70.00	-
1	TAILGATE RH LAMP	CRACKED	433.00	433.00
1	TAILGATE LH LAMP	DEFACED / CRACKED	433.00	433.00
1	TAILGATE LOCK	BENT	281.00	281.00
1	TAILGATE LOCK CATCH	BENT	34.00	34.00
1	TAILGATE WEATHERSTRIP	BENT	167.00	167.00
1	TAILGATE INNER TRIM BOARD	CRACKED	455.00	455.00
2	TAILGATE HINGES	SERVICEABLE	231.00	-
1	REAR BUMPER	DENTED	903.00	903.00
1	REAR RH BUMPER	DENTED / CRACKED	433.00	433.00
1	REAR RH BUMPER SIDE RETAINER	NECESSARY	82.00	82.00
1	REAR LH BUMPER	DENTED / CRACKED	433.00	433.00
1	REAR LH BUMPER SIDE RETAINER	NECESSARY	82.00	82.00
1	END PANEL	DENTED	783.00	783.00

Report Ref No. CS1/LPC17020854/Cvbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL INNER GARNISH	DEFORMED	155.00	155.00
1	REAR LH FENDER ARCH MOULDING	REFIT	288.00	-
1	REAR RH FENDER ARCH MOULDING	DEFORMED	288.00	288.00
1	EXHAUST SILENCER	DENTED / BENT	1,118.00	1,118.00
1	DRIVER SEAT FRAME	TO REPAIR SEE LABOUR	2,540.00	-
	LESS 20% DISCOUNT		-	-3,320.20
			21,990.00	13,280.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	70.00	40.00
1	FRONT NUMBER PLATE (SN)	DENTED	80.00	35.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	70.00	30.00
1	BTL RADIATOR COOLANT (SN)	NECESSARY	50.00	25.00
1	TAILGATE WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	70.00	20.00
1	TUBE TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	70.00	40.00
1	SET TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	70.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DENTED / MALFUNCTION	450.00	200.00
1	EXHAUST SILENCER CHROME FINISHER (SN)	DENTED	220.00	150.00
			1,150.00	570.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACE THE ABOVE LISTED PARTS, KNOCK, STRAIGHTEN & RESHAPE, CUT & WELD BODY PANEL PARTS WHERE NECESSARY, RE-POSITION & RE-ALIGN, REPLACEMENT OF PARTS TO THE ORIGINAL POSITION INCLUDING ADJUSTMENT. INCLUSIVE OF THE REPAIR OF DRIVER SEAT FRAME.		2,200.00	1,400.00
	APPLY RUST COATING ON THE REPLACED & REPAIRED PANELS.		200.00	90.00
	CHECK WIRING & LIGHTING SYSTEM.		100.00	60.00
	REMOVE & REPLACE A/C CONDENSER & PIPES TO ASSIST REPAIRS.		180.00	100.00
	REMOVE & RE-INSTALL RADIATOR, HOSES & FAN ASSEMBLY TO ASSIST REPAIRS.		180.00	80.00
	REMOVE & RE-INSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIRS.		200.00	120.00

Report Ref No. CS1/LPC17020854/Cvbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER & REPLACE TAILGATE MECHANISM TO NEW TAILGATE.		100.00	70.00
	REMOVE, RE-INSTALL & REPLACE REAR INNER TRIMS, GARNISHES & BOARDS TO ASSIST REPAIRS.		280.00	90.00
	REMOVE & REPLACE EXHAUST SILENCER & CHROME FINISHER.		120.00	80.00
	REMOVE & REPLACE REAR BUMPER REVERSE SENSOR.		100.00	60.00
	TO PUTTY & SPRAY REPAIRED & REPLACED BODY PANELS.		2,800.00	1,600.00
			6,460.00	3,750.00
GRAND TOTAL			29,600.00	17,600.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,300.00

Report Ref No. CS1/LPC17020854/Cvbs2

HO LEONG CHUAN
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.