

12/20/2017

ASS: REC BY

REF: CS/MSG17020941/Aqbn2

Special Instructions

Surveyor
Menimen

Adrian

ASSIGNMENT (Office)

From (Person): Jasmine Lok of MSIG

Date/Time: 1/11/17 @ 6:20pm

Estimated Cost:

Bill to:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL2862K

Insured: SJY3024L

at Workshop m/s Fong Motors

Tel: 6747 6388

of 1 kaki Bukit Ave 6 # 01-27 / 01-45, 47883

Policy No: B80260134 svp

Claim No: 5347 00

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 28/10/2017

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement

Date/Time: 9:34am @ 2/11/17

Person Contacted: Huck Lee

Vehicle: ☒ IN / ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL2862K-X
	SJY3024L-NA/INC11007070/c2-D.O.A: 13/12/2010
07/11/17 @ 3:40pm	Informed Jasmine, we are pending estimate from repairer.
18/1/18 @ 7:33pm	revised to Jasmine Lok via Menimen.
	US \$ 2500, 5 days CRed to 4847.70, 66%.

REF: MSIG

ASSIGNMENT

From: Date: 02/11/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLL 2862 K

at Workshop this: Fong Motor

of 1 kaki Bukit Ave 6, #01-27, 417883

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum. Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

TP MSIG.

Veh No: SLL2862K Yr Regn: 2017 Feb

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel No: 1496

Colour: white A/C Insured / Std / NI / NA

Sp Reading: 21465 T Radio: Insured / Std / NI / NA

Eng No:

O/No: RU11113923

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 02/11/17.

Survey held at: Fong Motor.

Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Data/Time: File Pass to:

19/11/2017

Data/Time: File Return to:

S:

Report Format:

Lump Sum / I.B. / IS

☐: Preli. Report☐: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp \$☐ Interview \$☐ Tech Insp \$☐ Weekend \$

Survey Fee:

Transporter

Price

Price

Price

TOTAL

200
10

210

MER-TP

2500



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17020941/Aqb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 02-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 3024L	Veh. Inspected	SLL 2862K
Policy No.	B80260134SVP	Coverage (\$)	0.00
Claim No.	534700	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	02/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/10/2017	Inspection Date	02/11/2017
Survey held at	FONG MOTORS 1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Reference No. : CY/MSG/17070941/Argb
Policy Type: OD / TP / TP RES / TL / EVA

Policy Type: OD / TP / TP RES / TL / EVA

Typist

(1) Office Assign Form

C	Reference No.	✓		
C	Customer Code	✓		
N	Assign From	✓		
C	Assign Date	✓		
C	Veh No (Inspected)	✓		
C	Veh No (Insured)	✓		
C	D.O.A	✓		
C	Policy No	✓		
C	Claim No	✓		
C	Insurance Authorisation (CA /REV/REP)			
C	Report Type	✓		
C	Weekend Charges			
N	Survey held at/Repairer	✓		
C	Excess			

(1) Assignment Form

Inspection Form		Inspector's Signature		Inspector's Name	
C	Vehicle No				
C	Regn Month/Year				
N	Vehicle Type				
N	Make & Model				
C	Engine Capacity. (C.C)				
N	Colour				
C	Odometer. (Sp.Reading)				
C	Chassis No				
N	General Condition				
N	Steering				
N	Brake				
N	Modification (Modi)				
C	Tyre Size				
N	Tyre Make				
C	Tyre Balance				
C	Date of Inspection				
N	Survey held				
N	Des.of Damages				

C	Damaged Vehicle Photographs Uploaded
---	--------------------------------------

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

C Resurvey photo Uploaded

Case Handler 18/1/18 Date

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inc Auth'd	Status
Main	30 Oct 2017		01 Nov 2017 18:20 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KATHIRAMALAY KETHEESWARI, ID: S1758120A, Tel: +6597480379		
Main Claimant:	JOHN & ISAAC, Co. Reg. No.: 53319853D		
Vehicle Reg. No.:	SLL2862K	Date of Loss:	28/10/2017 10:00 - :59
Claim Type:	TP / 534700	Policy/Cover Note No.:	B80260134SVP (Comprehensive) Coverage: 19/08/2017 - 18/08/2018
Vehicle Reg. No. (Insured):	SJY3024L	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Fong Motors - Kaki Bukit (HQ) 1 KAKI BUKIT AVE 6 #01-27/01-45, 417883 Kaki Bukit - Tel: 6747 6388		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/11/2017]		
Driver/Custodian (Insured):	SUPPIAH PARAMALINGAM SIVALINGAM (), NRIC: S2671020J, Tel: +6590466874		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. Please request Mr Adrian Ling to survey.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 18 Jan 2018

Preliminary Advice

Insured Vehicle No : SJY3024L
TP Vehicle No : SLL2862K
Make : HONDA VEZEL
Date of Inspection : 02/11/2017
Inspection At : FONG MOTORS - KAKI BUKIT (HQ)
1 KAKI BUKIT AVE 6 #01-27/01-45
SINGAPORE 417883

Accident Date : 28/10/2017
Assignment Date : 01/11/2017
Est. Duration of Repair : 5.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,347.70
Revised Amount	:S\$	3,140.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,140.24
Lump Sum Repair	:S\$	2,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 2 November, 2017 3:40 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SLL 2862K (YOUR REF: 534700)

This mail is associated with :
***SLL2862K (534700)**
[SJY3024L]
TP
JOHN & ISAAC
Oct 28 2017 10:00AM
[KATHIRAMALAY KETHEESWARI]
Fong Motors - Kaki Bukit

Dear Jasmine,

Please be informed that we have inspected the vehicle SLL 2862K on 02/11/2017.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Fong Motors

1, Kaki Bukit Ave 6, #01-45/27, Autobay, Singapore 417883

Vehicle No. ²⁸⁶² SLL2826K
 Make/Model HONDA VEZEL 1.5
 Year :
 Chassis No.

TP MSIG
 Xiao Chen

DATE : 8/11/2017

PARTS LIST

			Unit Price		
1	1 pc	LH REAR DOOR <i>Distorted</i>	\$ 962.60	\$	962.60 ✓
2	1 pc	LH REAR DOOR WEATHER STRIP <i>new</i>	\$ 168.90	\$	168.90 ✓
3	1 pc	LH REAR DOOR STICKER <i>new</i>	\$ 39.30	\$	39.30 ✓
4	1 pc	LH REAR DOOR INNER LOCK <i>new</i>	\$ 282.10	\$	282.10 ✓
5	1 pc	LH REAR DOOR INNER HANDLE <i>new</i>	\$ 94.80	\$	94.80 ✓
6	1 pc	LH REAR DOOR INNER TRIM BOARD <i>new</i>	\$ 479.20	\$	479.20 ✓
7	1 pc	LH REAR DOOR UPPER HINGE <i>new</i>	\$ 78.60	\$	78.60 ✓
8	1 pc	LH REAR DOOR LOWER HINGE <i>new</i>	\$ 78.60	\$	76.00 ✓
9	1 pc	LH REAR DOOR CHECKER	\$ 49.20	\$	472.00 ✓
10		LH REAR DOOR PLASTIC COVER <i>new</i>	\$ 23.20	\$	23.20 ✓
11		LH DOOR CHANNEL <i>new</i>	\$ 44.50	\$	44.50 ✓
12		LH DOOR GLASS CHANNEL <i>new</i>	\$ 73.50	\$	73.50 ✓
		LH DOOR GLASS REGULATOR <i>Damaged</i>	\$ 425.90	\$	425.90 ✓
		LH DOOR GLASS REGULATOR SASH <i>new</i>	\$ 49.90	\$	49.90 ✓
		LH DOOR OUTER GLASS MOULDING <i>new</i>	\$ 112.60	\$	112.60 ✓
		LH DOOR OUTER HANDLE <i>new</i>	\$ 118.60	\$	118.60 ✓
		RH FRONT DOOR <i>Repair</i>	\$ 1,026.60	\$	1,026.60 ✓
		LH REAR FENDER ARCH <i>new</i>	\$ 121.40	\$	121.40 ✓
5PCS		LH REAR FENDER ARCH CLIP <i>new</i>	\$ 4.50	\$	22.50 ✓
		LH LOCKER PANEL ARCH <i>new</i>	\$ 255.50	\$	255.50 ✓
TOTAL PARTS				\$	4,927.70

TO KNOCK AND CHANGE NEW PARTS
 TO SPRAY PAINT LH NEW DOOR, LH FRONT DOOR
 LH REAR FENDER AND DOOR PILLAR
 TO TRANSFER PARTS TO NEW DOOR
 TO CHECK WIRING
 TUFF KOTE

\$ ~~900.00~~ 450
 \$ ~~1,200.00~~ 600
 \$ ~~120.00~~ 80
 \$ ~~100.00~~ 30
 \$ 100.00 x
 \$ 7,347.70

1160

total: 1140.24
 c/s: 2.5k.
 0.5 Pays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

FONG MOTORS

[Signature]

[Signature]
 19/11/18

2.5k
 0.5 Pays

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020941/AQBN2

Date: 19/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B80260134SVP
Claimant Vehicle No :	SLL2862K	Insured Vehicle No :	SJY3024L
Date of Loss:	28/10/2017	Nature of Claim:	TP
		Claim No:	534700

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL2862K	Engine No:	L15B4033892
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11113923
Reg. Date:	20/02/2017 (Man. Year: 2016)	Odometer:	21465 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,927.70	1,980.24	2,947.46	59.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,160.00	1,260.00	52.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,347.70	3,140.24	4,207.46	57.26
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	7,347.70	2,500.00	4,847.70	65.98

INSPECTION

Date of Assignment:	01/11/2017	
Date Inspected:	02/11/2017	Inspected At:
		Fong Motors - Kaki Bukit (HQ)
		1 KAKI BUKIT AVE 6 #01-27/01-45
		Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL2862K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR DOOR	Distorted	962.60 F	*962.60 FL
2	1		*LH REAR DOOR WEATHER STRIP	Necessary	168.90 F	*168.90 FL
3	1		*LH REAR DOOR STICKER	Necessary	39.30 F	*39.30 FL
4	1		*LH REAR DOOR INNER LOCK	Not Necessary	282.10 F	*- FL
5	1		*LH REAR DOOR INNER HANDLE	Not Necessary	94.80 F	*- FL
6	1		*LH REAR DOOR INNER TRIM BOARD	Deformed	479.20 F	*479.20 FL
7	1		*LH REAR DOOR UPPER HINGE	Not Necessary	78.60 F	*- FL
8	1		*LH REAR DOOR LOWER HINGE	Not Necessary	76.00 F	*- FL
9	1		*LH REAR DOOR CHECKER	Not Necessary	472.00 F	*- FL
10	1		*LH REAR DOOR PLASTIC COVER	Not Necessary	23.20 F	*- FL
11	1		*LH DOOR CHANNEL	Not Necessary	44.50 F	*- FL
12	1		*LH DOOR GLASS CHANNEL	Not Necessary	73.50 F	*- FL
13	1		*LH DOOR GLASS REGULATOR	Damaged	425.90 F	*425.90 FL
14	1		*LH DOOR GLASS REGULATOR SASH	Not Necessary	49.90 F	*- FL
15	1		*LH DOOR OUTER GLASS MOULDING	Not Necessary	112.60 F	*- FL
16	1		*LH DOOR OUTER HANDLE	Not Necessary	118.60 F	*- FL
17	1		*RH FRONT DOOR	Repair	1,026.60 F	*- FL
18	1		*LH REAR FENDER ARCH	Cut	121.40 F	*121.40 FL
19	5		*LH REAR FENDER ARCH CLIP	Necessary	22.50 F	*22.50 FL
20	1		*LH ROCKER PANEL ARCH	Cut	255.50 F	*255.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,927.70	2,475.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	495.06
Total Parts (\$\$)	4,927.70	1,980.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK AND CHANGE NEW PARTS	New	900.00	450.00
2	TO SPRAY PAINT LH NEW DOOR,LH FRONT DOOR,LH REAR FENDER AND DOOR PILLAR	New	1,200.00	600.00
3	TO TRANSFER PARTS TO NEW DOOR	New	120.00	80.00
4	TO CHECK WIRING	New	100.00	30.00
5	TUFF KOTE	New	100.00	-
Gross Labour Cost (S\$)			2,420.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >