

ASS. REC. BY:

REF:

CS3 / MS(17021010/SB)⁹²

Special Instruction:

range

Survivor:

Sebastian

ASSIGNMENT (Office)

From (Person):

mesmen

Katherine Wong

of

MSH

Date/Time:

02.11.2017 3:50pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 1984Y

Insured:

SKK 3393H

at Workshop m/s

D motor werkz

Tel:

6734 7260

of

28 0 Woodlands Ind 25 # 01-03

Policy No:

60270344DMA

Claim No:

535220

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

03.11.2017

H.O.D. Endorsement:

Date/Time:

02.11.2017

5:47pm

Person Contacted:

Fion

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJL 1984Y - X

SKK 3393H - X

Dismantle Part: 06.11.2017

After repair: 10.11.2017

25.11.17 5:00pm Email to Katherine Wong thru mesmen.

REF: MSIG

ASSIGNMENT

From:

Date:

3/11/2017

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJL 1984 Y

at Workshop m/s

D Motor Werkz

of 280, Woodlands Ind ES #01-03, 757322

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

3/11/2017 No CIA

Veh No:

SJL 1984 Y

V-Page 2008 Nov 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Suzuki Swift 13M

CC 1328

Colour

Pink

A/C Insured / Std / NI / NA

Sp. Reading

74216

T Radio: Insured / Std / NI / NA

Eng No:

C No:

2 C 115 40061

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/55R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodyear

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.A.

3/11/2017 @ 12.01 pm

Survey held at

D Motor Werkz

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 05 JAN 2018

Date/Time File Pass to?



Prel. Report

11 05-01-2018



Final Report

Date/Time File Return to?

2

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transcription:

Add Fee:



Site Insp. \$



Interview \$



Tech. Insp. \$



Weekend \$

Report Format:

PRC

Lump Sum / I.B.I. \$

TOTAL \$

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG17021010/Sb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 02-11-2017	
			Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKK 3393H	Veh. Inspected	SJL 1984Y	
Policy No.	60270344DMA	Coverage (\$)	0.00	
Claim No.	535220	Excess (\$)	0.00	
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	02/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/10/2017	Inspection Date	03/11/2017	
Survey held at	D MOTORWERKZ PTE LTD 280 WOODLANDS INDUSTRIAL PARK E5 #01-03 SINGAPORE 757322			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2017		02 Nov 2017 15:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	BOK SHI CHIEH, ID: S8110285F		
Main Claimant:	EDDY BIN HENDRA, ID: S85423008		
Vehicle Reg. No.:	SJL1984Y	Date of Loss:	31/10/2017 22:00 - :59
Claim Type:	TP / 535220	Policy/Cover Note No.:	60270344DMA (Comprehensive) Coverage: 27/03/2017 - 26/03/2018
Vehicle Reg. No. (Insured):	SKK3393H	Policy No. (Claimant):	
		Excess:	
Repairer:	D Motorwerkz Pte Ltd (HQ) NO. 280 Woodlands Industrial E5, #01-03 Harvest @ Woodlands, 757322 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/11/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

(1) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Repaired (2) Repainted (3) Repolished (4) Not Contingent (5) Not

Vehicle No: *STL 1984y*

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BT	✓	1
1138	993627	Rear Number Plate Base	BT	✓	1
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper		R	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NRC	✓	30
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	CRK	✓	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	NRC	✓	200
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRK	✓	245
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRK	✓	245
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			
		Labour			400
		Spray Paint			400
		- Bumper			
		- Fender			

No of Items: _____ Assessor: _____

Range: \$1800 - \$2300 @ 3 days.

original copy

4/1/2018

View Sent Message

This mail is associated with :

***SJL1984Y (535220)**
[SKK3393H]

TP
EDDY BIN HENDRA
Oct 31 2017 10:00PM
[BOK SHI CHIEH]
D Motorwerkz Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 25/11/2017 17:06 PM.
To MSI_WCS
Subject Pre-repair Inspection

Dear Katherine,

Refer to your assignment on 02.11.2017 at 3.50PM.

Please be informed that we have inspected the vehicle SJL 1984Y on 03.11.2017 at 12.01PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Nov 2017		02 Nov 2017 15:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		BOK SHI CHIEH, ID: S8110285F							
Main Claimant:		EDDY BIN HENDRA, ID: S8542300B							
Vehicle Reg. No.:		SJL1984Y	Date of Loss:	31/10/2017 22:00 - :59					
Claim Type:		TP / 535220	Policy/Cover Note No.:	60270344DMA (Comprehensive) Coverage: 27/03/2017 - 26/03/2018					
Vehicle Reg. No. (Insured):		SKK3393H	Policy No. (Claimant):						
			Excess:						
Repairer:		D Motorwerkz Pte Ltd (HQ) NO. 280 Woodlands Industrial E5, #01-03 Harvest @ Woodlands, 757322 Woodlands - Tel:							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 03/11/2017]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL1984Y (535220)
[SKK3393H]
TP
EDDY BIN HENDRA
Oct 31 2017 10:00PM
[BOK SHI CHIEH]
D Motorwerkz Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	05/01/18 15:00	General View								Load JPG	☒	
2	05/01/18 15:00	General View								Load JPG	☒	
3	05/01/18 15:00	General View								Load JPG	☒	
4	05/01/18 15:00	General View								Load JPG	☒	
5	05/01/18 15:00	General View								Load JPG	☒	
6	05/01/18 15:00	General View								Load JPG	☒	
7	05/01/18 15:00	General View								Load JPG	☒	
8	05/01/18 15:00	General View								Load JPG	☒	
9	05/01/18 15:00	General View								Load JPG	☒	
10	05/01/18 15:00	General View								Load JPG	☒	
11	05/01/18 15:00	General View								Load JPG	☒	
12	05/01/18 15:00	General View								Load JPG	☒	
13	05/01/18 15:00	General View								Load JPG	☒	
14	05/01/18 15:00	General View								Load JPG	☒	
15	05/01/18 15:00	General View								Load JPG	☒	
16	05/01/18 15:00	General View								Load JPG	☒	
17	05/01/18 15:00	General View								Load JPG	☒	
18	05/01/18 15:00	General View								Load JPG	☒	
19	05/01/18 15:00	General View								Load JPG	☒	
20	05/01/18 15:00	General View								Load JPG	☒	
21	05/01/18 15:00	General View								Load JPG	☒	
22	05/01/18 15:00	General View								Load JPG	☒	
23	05/01/18 15:00	General View								Load JPG	☒	
24	05/01/18 15:00	General View								Load JPG	☒	
25	05/01/18 15:00	General View								Load JPG	☒	
26	05/01/18 15:00	General View								Load JPG	☒	
27	05/01/18 15:00	General View								Load JPG	☒	
28	05/01/18 15:00	General View								Load JPG	☒	
29	05/01/18 15:00	General View								Load JPG	☒	
30	05/01/18 15:00	General View								Load JPG	☒	
31	05/01/18 15:00	General View								Load JPG	☒	
32	05/01/18 15:00	General View								Load JPG	☒	
33	05/01/18 15:00	General View								Load JPG	☒	
34	05/01/18 15:00	General View								Load JPG	☒	
35	05/01/18 15:00	General View								Load JPG	☒	

36	05/01/18 15:00	Odometer Reading	1	Load JPG	☒
37	05/01/18 15:00	General View	1	Load JPG	☒
38	05/01/18 15:00	Chassis Number	1	Load JPG	☒
39	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
40	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
41	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
42	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
43	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
44	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
45	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
46	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
47	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
48	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
49	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
50	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
51	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
52	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
53	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
54	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
55	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
56	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
57	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
58	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
59	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
60	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
61	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
62	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
63	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
64	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
65	05/01/18 15:00	Photographs of Damaged Parts	1	Load JPG	☒
66	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
67	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
68	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
69	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
70	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
71	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
72	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
73	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
74	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
75	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
76	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
77	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
78	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
79	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
80	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
81	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
82	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
83	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
84	05/01/18 15:01	Photo After Spray	1	Load JPG	☒
85	05/01/18 15:01	Photo After Spray	1	Load JPG	☒

86	05/01/18 15:01	Photo After Spray		Load JPG	☒
87	05/01/18 15:01	Photo After Spray		Load JPG	☒
88	05/01/18 15:01	Photo After Spray		Load JPG	☒
89	05/01/18 15:01	Photo After Spray		Load JPG	☒
90	05/01/18 15:01	Photo After Spray		Load JPG	☒
91	05/01/18 15:01	Photo After Spray		Load JPG	☒
92	05/01/18 15:01	Photo After Spray		Load JPG	☒
93	05/01/18 15:01	Photo After Spray		Load JPG	☒
94	05/01/18 15:01	Photo After Spray		Load JPG	☒
95	05/01/18 15:01	Photo After Spray		Load JPG	☒
96	05/01/18 15:01	Photo After Spray		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)




Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021010/SBS2

Date: 12/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 60270344DMA

Claimant Vehicle
No: SJL1984Y

Insured Vehicle No: SKK3393H

Date of Loss: 31/10/2017

Nature of Claim: TP

Claim No: 535220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJL1984Y

Make & Model: SUZUKI SWIFT, 1.3 (M)

Reg. Date: 18/11/2008 (Man. Year: 2008)

Colour: Pink

Engine Capacity: 1328 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: M13A1937596

Chassis No: ZC11S400161

Odometer: 94216 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15

Rear Tyre Size: 195/55R15

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/11/2017

Date Inspected: 03/11/2017 Inspected At:

D Motorwerkz Pte Ltd (HQ)
NO. 280 Woodlands Industrial E5, #01-03
Harvest @ Woodlands
Singapore 757322

Estimated Period of Repair: 0.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00 - \$2,300.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2018)
Parts:	144	SUZUKI SWIFT 1.3 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL1984Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >