

Our Reference : RRM15-123031/RI/FP/cg

PAGE : 6

Your Reference: M436311

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)		
		\$50,650.00	\$30,250.00

REMARKS :

Our recommended Lump Sum Repair Cost is **\$30,250.00** (instead of the submitted repair cost of **\$50,650.00** .In normal circumstances, repairs to the vehicle would take approximately **18 days** to complete. Please find enclosed our note of charges for your kind attention.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FormTeam Consultancy Pte Ltd** for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,

FormTeam Consultancy Pte Ltd

Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser

Our Reference : RRM15-123031/RI/FP/cg
 Your Reference : M436311

PAGE : 4

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
2	Tail Lamp Panel @\$195.98	Dented		391.96	391.96
4	Rear Reverse Sensor @\$326.60	Damaged		1,306.40	1,077.47
	List Items Sub-Total			63,678.39	36,147.56
	Original Less 10%			6,367.84	3,614.76
	Revised Less 10%				
	Discounted Sub-Total			57,310.55	32,532.80
	<u>PARTS REPLACEMENT</u>				
	<u>SPECIAL NETT ITEMS</u>				
6	Front Parking Sensor Holder @\$5.20	Necessary		31.20	31.20
	Front License Plate	Damaged		45.00	45.00
2 set	Front Fender Inner Trim Clip @\$33.00	Necessary		66.00	66.00
4	Rear Reverse Sensor Holder @\$5.20	Necessary		20.80	20.80
	Special Nett Sub-Total			163.00	163.00
	Total Parts Amount			57,473.55	32,695.80

Our Reference : RRM15-123031/RI/FP/cg

PAGE : 2

Your Reference : M436311

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
2	Front Bumper Fog @\$466.38	Broken		932.76	913.50
1	Front Bumper Centre Top Stay	Broken		106.95	106.95
1	Front Bumper Reinforcement	Not Replaced	Slight Damaged	1,497.36	-
1	Front Bumper Upper Impact Absorber	Broken		101.74	101.74
2	Front Bumper Reinforcement Side Bracket @\$71.40	Bent		142.80	142.80
1	Front Fender RH	Not Replaced	Slightly Dented	1,611.19	-
1	Front Fender LH	Not Replaced	Slightly Dented	1,611.19	-
1	Radiator	Broken		1,693.51	1,511.26
1	Radiator Grille	Broken		881.05	734.21
1	Radiator Air Deflector	Broken		181.42	181.42
1	Radiator Fan Blower	Broken		1,579.45	1,416.21
2	Horn @\$178.10	Damaged		356.20	356.20
6	Front Parking Sensor @\$326.60	Damaged		1,959.60	1,616.16
1	Front Parking Sensor Wire	Damaged		481.82	481.82
1	Engine Air Pump	Dented/Damaged		1,787.18	1,787.18
1	Air Pump Molded Hose	Bent		28.50	28.50
1	A/C Condenser	Not Replaced		1,862.00	-
1	Front Support Panel Assy	Dented/Twisted		3,199.57	2,866.31
1	Engine Air Cleaner Housing	Dented/Broken		820.86	782.60
1	Engine Top Cover Plate	Broken		234.56	234.56
1	Air Intake Hose RH	Bent		130.17	130.17
1	Air Intake Hose LH	Bent		130.17	130.17
1	Front License Plate Holder	Deformed		177.41	177.41
1	Guide Pulley	Serviceable		-	-
1	Tightener Pulley	Serviceable		-	-
1	Engine Oil Cooler	Damaged		389.93	389.93
1	Water Pump	Serviceable		-	-
1	Headlamp RH	Broken		2,231.33	1,959.41
1	Headlamp LH	Broken		2,231.33	1,959.41

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

INVOICE

To: Slim Fit (S) Pte Ltd
c/o Blk 3C Woodlands Road
391C/G Yew Tee Industrial Estate
Singapore 677966

Date : 03/11/2015
Invoice No : IV15-11010/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SKQ 796S (Inclusive Of Photographs And Transport Charges) Our reference : CAS/15-11/010	\$1,856.00
Total	\$1,856.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Vehicle No: SKQ 796S

Our ref: CAS/15-11/010

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>					
67	1pc	Rear bumper	Dented/Broken	2,163.74	2,163.74 ✓
68	2pcs	Rear bumper mounting bracket @ \$19.75	Broken	39.50	39.50 ✓
69	1pc	Spare wheel repair kit <i>Photo show no damage</i>	Necessary	255.88	255.88 <i>NH</i>
70	1pc	Spare wheel well	Necessary	591.67	591.67 <i>NH</i>
71	4pcs	Spacer ring @ \$6.66 <i>5161.29</i>	Necessary <i>Photo show</i>	26.64	26.64 <i>NH</i>
72	1pc	Spare wheel well under screening	Dented/Bent	347.51	347.51 ✓
73	2pcs	Rear fender covering @ \$31.50	Torn <i>Photo show</i>	63.00	63.00 <i>NH</i>
74	2pcs	Taillamp @ \$652.07	Cracked/Broken	1,304.14	1,304.14 ✓
5	2pcs	Taillamp panel @ \$195.98 <i>Photo show no damage</i>	Dented	391.96	391.96 <i>NH</i>
76	4pcs	Rear reverse sensor @ \$326.60	Damaged	1,306.40	1,306.40 ✓
				66,858.27	63,678.39
Less 10% <i>39354.62</i> <i>35419.15</i>				(6,685.82)	(6,367.83)
Sub total				60,172.45	57,310.56
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	6pcs	Front parking sensor holder @ \$5.20	Necessary	31.20	31.20 ✓
2	1pc	Front licence plate	Damaged	45.00	45.00 ✓
3	2sets	Rear fender inner trim clip @ \$33.00	Necessary	66.00	66.00 <i>9/16</i>
4	4pcs	Rear reverse sensor holder @ \$5.20 <i>97.00</i>	Necessary	20.80	20.80 ✓
Sub total				60,335.45	57,473.56
<u>LABOUR & MISC. CHARGES</u>					
1		Labour to repair & replace damaged parts <i>mainly bolts and nuts. Rear welding work not required as end panel slightly damaged.</i>		2,500.00	2,200.00 <i>1800/-</i>
2		Spray painting on affected area <i>about 8 panel.</i>		2,400.00	2,000.00 <i>1600/-</i>
3		Remove & refix engine compartment		350.00	250.00 <i>NH</i>
4		Remove & refix exhaust pipe		160.00	140.00 <i>80/-</i>
5		Remove & refix rear trim board & garnish		150.00	120.00 ✓
6		Remove & refix front parking sensor		80.00	60.00 ✓
7		Remove & refix rear reverse sensor		80.00	60.00 ✓
8		Check wiring system		120.00	80.00 <i>60/-</i>
9		To diagnose & reset system after repair		450.00	420.00 ✓
10		Towing		120.00	120.00 ✓
11		Remove, renew air con condenser & refill gas		150.00	140.00 <i>120/-</i>

Constant Appraiser Services


Vehicle No : SKQ 796S

Our ref : CAS/15-11/010

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS</u>			
1	1pc	Bonnet	Dented/Buckled	3,270.18	3,270.18 ✓
2	2pcs	Bonnet hinge @ \$253.10	Bent	506.20	506.20 ✓
3	2pcs	Bonnet upper part catch @ \$102.36	Bent	204.72	204.72 ✓
4	1pc	Bonnet insulation	Distorted	485.75	485.75 ✓
5	1pc	Bonnet front top seal	Necessary	77.44	77.44 ✓
6	1pc	Bonnet Mercedes star	Damaged	107.16	107.16 ✓
7	2pcs	Bonnet spring element @ \$20.37	Bent	40.74	40.74 ✓
	1pc	Bonnet safety hook lever	Bent/Jammed	38.06	38.06 ✓
9	1pc	Bonnet safety hook	Bent	269.95	269.95 ✓
10	2pcs	Bonnet air grille @ \$332.60	Broken	665.20	665.20 ✓
11	1pc	Front bumper	Dented/Broken	2,103.54	2,103.54 ✓
12	1pc	Front bumper lower impact absorber	Broken	84.88	84.88 ✓
13	1pc	Front bumper central grille	Broken	116.25	116.25 ✓
14	1pc	Front licence plate moulding	Deformed	107.37	107.37 ✓
15	1pc	Front bumper center energy-absorbing unit	Broken	106.04	106.04 ✓
16	2pcs	Front bumper fog lamp @ \$466.38	Broken	932.76	932.76 ✓
17	1pc	Front bumper center top stay	Broken	106.95	106.95 ✓
18	1pc	Front bumper reinforcement <i>Photo show not change</i>	Damaged *	1,497.36	1,497.36 ✓ HH
	1pc	Front bumper upper impact absorber	Broken	101.74	101.74 ✓
20	2pcs	Front bumper reinforcement side bracket @ \$71.40	Bent	142.80	142.80 ✓
21	1pc	Front fender RH <i>slight damage</i>	Dented/Buckled t	1,611.19	1,611.19 ✓ R
22	1pc	Front fender LH <i>Photo show not change</i>	Dented/Buckled t	1,611.19	1,611.19 ✓ R
23	1pc	Radiator	Broken	1,693.51	1,693.51 ✓
24	1pc	Radiator grille	Broken	881.05	881.05 ✓
25	1pc	Radiator air deflector	Broken	181.42	181.42 ✓
26	1pc	Radiator fan blower <i>20278.46</i>	Broken	1,579.45	1,579.45 ✓
27	2pcs	Horn @ \$178.10	Damaged	356.20	356.20 ✓
28	6pcs	Front parking sensor @ \$326.60	Damaged	1,959.60	1,959.60 ✓
29	1pc	Front parking sensor wire	Damaged	481.82	481.82 ✓
30	1pc	Engine air pump	Dented/Damaged	1,787.18	1,787.18 ✓
31	1pc	Air pump molded hose	Bent	28.50	28.50 ✓
32	1pc	A/C condenser	Bent/Twisted ✓	1,862.00	1,862.00 ✓

Accident Photo



Page No. : 11
Unable to disclose
NRIC / driving licence

Accident Photo



Accident Photo



Sketch Plan #2 Pg.1

Describe Circumstances of the Accident

Vehicle No: GV 7493R (China)
 Date & Time: 24/09/15 @ 1505 (clear day)
 I followed front unknown mitaxi to slowed down & stopped. My car
 SKD 7965 came from behind & hit onto my vehicle rear portion. No one
 was injured.

Declaration

Note : Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own policy. Please check with your policy for more information.

We declare the foregoing particulars are true in every respect.

HUAT HOCK SUPPLIER

Policyholder's Signature / Date & Time

() Claim Own Policy

Driver's Signature (If driver is not the policyholder) / Date & Time

() Claim Third Party () Claim OD / TP at other workshop

Witnessed by Reporting Centre Personnel

() Reporting Only (AME)

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number SKQ796S

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name


Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo




SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 25/9/15
Policyholder's Signature / Date & Time

 25/9 1020am
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Address 63 JALAN SELAMAT
Postcode 418582
Was driver an employee of the Insured's Company No
If No, Relationship of the Driver with the Insured Spouse
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident Collision- Chain Collision
Weather Conditions Clear
Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No
Was any body injured in the Accident? No
Was any other material or property damaged? Yes
Was there any video captured by Car Camera? No
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? No
If Yes, Please state which Police Station
Was notice of intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

SEE ATTACHED.

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKQ796S
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GV7493R
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number

Accident Photo



Accident Photo

