



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
DIRECT ASIA INSURANCE (SINGAPORE) PL		Ref : CS/DAI17021032/Drbs2	
88 SOUTH BRIDGE ROAD SINGAPORE 058716		Date : 26-12-2017	
		Code : DAI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SJJ 5064L
Policy No.	MT/00353428	Coverage (\$)	0.00
Claim No.	73306	Excess (\$)	600.00
Assign From	ELYN PAN	Assign Date	31/10/2017
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI SANTA FE	c.c	2656
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	KMHS81DR9U421399	Colour	BLACK
Odometer	105806	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/60R18	MICHELIN	5 mm
L/H Front Tyre	235/60R18	MICHELIN	5 mm
R/H Rear Tyre	235/60R18	MICHELIN	5 mm
L/H Rear Tyre	235/60R18	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE CAUGHT FIRE AT ITS ENGINE COMPARTMENT. CAUSE OF FIRE LIKELY DUE TO ELECTRICAL NATURE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/10/2017	Inspection Date	01/11/2017
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		
5a. Remarks			
A)THE MARKET VALUE IS S\$19,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 5064L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ABS PUMP	BURNT	3,500.00	3,500.00
1	ABS WIRE HARNESS	BURNT	5,950.00	5,950.00
	LESS 50% DISCOUNT		-	-4,725.00
			9,450.00	4,725.00
SPECIAL NETT ITEMS				
1	BRAKE OIL (SN)	NECESSARY	50.00	30.00
			50.00	30.00
LABOUR				
	RESET ECU, ABS, SRS AND ETC.		180.00	150.00
	CHECK WIRING FUNCTION.		250.00	150.00
	REMOVE ALL NECESSARY PARTS IN ENGINE COMPARTMENT AND DASHBOARD (IF NECESSARY) TO REPLACE ABS PUMP AND WIRE HARNESS.		1,200.00	800.00
			1,630.00	1,100.00
GRAND TOTAL			11,130.00	5,855.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,850.00
LESS EXCESS				-600.00
NETT LIABILITY				5,250.00

Report Ref No. CS/DAI17021032/Drbs2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.