

CWS

Kenneth

ASSIGNMENT (Office)

From (Person)

Serene Ter

FCI

Date/Time

3.43pm @ 3/11/2017

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

GBG 3324K

Insured

SH 7749K

at Workshop no

K. Kim Hin Auto

Tel

64527018

of 160 Sin Ming Drive #02-20

Policy No

Claim No

D17010161MFSH

Sum Insured

Excess

Make of Veh

D.O.A

28/10/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

(wp)

29.11.2017

H.O.D. Endorsement

Date/Time

4.00pm @ 3/11/17

Person Contacted

Shuman

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction (✓) Estimate

GBG 3324K - X

SH 7749K - CS/FCI15019814/Uqbc2-D.O.A: 18/11/2015

Kenneth confirm \$2726.25 @ 6 days

Red: \$1631.75, 377.

REF: FCI

ASSIGNMENT

From: Date: 29/11/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBG 3324K

at Workshop no: K. Kim Hin Auto

at 160 Sin Ming Drive #02-20

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

30/11 File pass to Catherine

Veh No: GBG 3324K Yr Regn: 07 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp Reading:

Eng No:

C No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In/Car / Jammed / Leaked / Burnt or

Brake: In/Car / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size:

PS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

L/Bal:

D.O.A:

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision

Rear

R/Bal:

L/Bal:

D.O.I:

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 15 MAY 2018

Date/Time File Pass No?



Preli. Report



Final Report

Date/Time File Return No?

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

LUBS OILS:

Photo:

Clean:

Wash:

Taxes:

Total:

Add Fee:



Site Insp: \$



Interview: \$



Reasoning: \$



Clearing: \$

135
50
50
17

252

Report Format:

Lum Sum / L.B. / S.

TP

276.25



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021068/Krb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7749K	Veh. Inspected	GBG 3324K
Policy No.		Coverage (\$)	0.00
Claim No.	D1010161MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	03/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/10/2017	Inspection Date
Survey held at	160 SIN MING DRIVE # 02-20,575722	
Repairer	K KIM HIN AUTOMOTIVE PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	31-10-2017	Our Ref No. D17010161MFSH
Accident Date	28-10-2017	Claim Type. Third Party
Insured Vehicle	SH7749K	Third Party Vehicle. GBG3324K
Survey Location	160 Sin Ming Drive #02-20SIN MING AUTOCITY	
Contact Person.	SHUMAN	
Contact No.	64527018/ 96222116	Fax No. 64583895
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229663)



PRI Documents



Close X

PRI Header Details

Claim No	D17010161MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & K. KIM HI
Workshop Name	K. KIM HIN AUTO PTE LTD (Contact Person : SHUMAN)	Survey Location & Contact Details	160 Sin Ming Drive #02-20SIN MING AUTOCITY Mobile: 96222116 , Phone: 64527018 , Fax: 6458389! EmailId: ADMIN1@KKIMHIN.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. PROVIDED		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7749K	TP Vehicle No	GBG3324K
PRI Recieved Date	02-11-2017 09:00:41 PM	Surveyor Appointed Date	03-11-2017 03:42:57 PM	Surveyor Accept Date	03-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	03-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	9299R
Vehicle Details	
Vehicle No.	GBG3324K
Vehicle to be Exported	No
Intended De-registration Date	01 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	HIACE DX 3.0 A
Primary Colour	Silver
Manufacturing Year	2016
Engine No.	1KD2664273
Chassis No.	KDH2010210031
Maximum Power Output	-
Open Market Value	\$34,199.00
Original Registration Date	24 Jul 2017
First Registration Date	24 Jul 2017
Transfer Count	1
Actual ARF Paid	\$1,710.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	23 Jul 2027
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
PQP Paid	\$19,602.00
COE Rebate Amount	\$19,064.00
Total Rebate Amount	\$19,064.00

The information contained herein is correct as at 01 Nov 2017

OK

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 29276

Vehicle Insured : SH 7749 K
Accident Date : 28-Oct-2017

Date : 06-Nov-2017

Our Ref : 170795 (FIRST) / SHUMAN

PAGE : 1

Not withered
Puting B4 part 6 days

NORDAD COMMERCIAL LEASING PTE LTD
Singapore

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE DX 3.0 A (2017) GBG3324K
=====

- 1 pc rear bumper
- 10 pcs rear bumper clips
- 1 pc o/s rear bumper side bracket
- 1 pc o/s rear body panel
- 1 pc o/s rear rim
- 1 pc o/s rear rim cover
- 1 pc o/s rear wheel bearing
- 1 pc o/s taillamp assy

	CU	400.00	✓
@ S\$ 5.00	M	50.00	✓
	n	30.00	X
	B	1,500.00	✓
		498.00	?
	M	185.00	✓
		125.00	?
	S	36.00	X
		2,824.00	
Less 25% :		-706.00	
		2,118.00	

- 1 pc o/s rear body panel top glass sealant
- 1 pc o/s rear body panel top glass damping seal
- 1 pc o/s rear tyre

M 40.00 sn ✓
M 20.00 sn ✓
320.00 sn ?

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

750.00 *700*

To focus taillamps. To check rear wiring and lighting operation.

50.00 *150*

To remove and refit o/s rear body panel top glass and conduct water leak test.

120.00 *100*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

LKK

Kr

K. Kim Hin AUTO PTE LTD

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

金興(興)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29276

Vehicle Insured : SH 7749 K
Accident Date : 28-Oct-2017

Date : 06-Nov-2017

Our Ref : 170795 (FIRST) / SHUMAN

PAGE : 1

NORDAD COMMERCIAL LEASING PTE LTD
Singapore

NOT WORKING
Resurvey B4 paint 6 days

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE DX 3.0 A (2017) GBG3324K

- 1 pc rear bumper
- 10 pcs rear bumper clips
- 1 pc o/s rear bumper side bracket
- 1 pc o/s rear body panel
- 1 pc o/s rear rim
- 1 pc o/s rear rim cover
- 1 pc o/s rear wheel bearing
- 1 pc o/s taillamp assy

CU 400.00 ✓
@ S\$ 5.00 50.00 ✓
B1 30.00 X
1,500.00 ✓
SN 498.00 XX
185.00 ✓
125.00 XX
36.00 X

2,824.00
Less 25% : -706.00
----- 2,118.00

- 1 pc o/s rear body panel top glass sealant
- 1 pc o/s rear body panel top glass damping seal
- 1 pc o/s rear tyre

nn 40.00 sn ✓
nn 20.00 sn ✓
nn X 320.00 sn X

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

750.00 700

To focus taillamps. To check rear wiring and lighting operation.

50.00 150

To remove and refit o/s rear body panel top glass and conduct water leak test.

nn X 120.00 100 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

金興(襲)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : SH 7749 K

Our Ref : 170795

Page : 2

No. : 29276

To apply undersealing

120.00 301

To dismantle and check rear under-carriage. To replace affected portions.

~ 140.00 X

To conduct rear wheel alignment test.

80.00 601

To putty and respray on affected portions.

600.00 320

Total : S\$ 4,358.00

=====

Singapore Dollars Four Thousand Three Hundred and Fifty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

2135.00
-25%1601.25 s/parts
+ 1125.00 Labour2726.25 ✓ ok




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17021068/Krbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7749K	Veh. Inspected	GBG 3324K	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010161MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	03/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDH2010210031	Colour	SILVER	
Odometer	17369	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	195/80 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	195/80 R15	BRIDGESTONE	7 mm	
L/H Rear Tyre	195/80 R15	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/10/2017	Inspection Date	29/11/2017	
Survey held at	160 SIN MING DRIVE # 02-20,575722			
Repairer	K KIM HIN AUTOMOTIVE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 3324K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CUT	400.00	400.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	O/S REAR BUMPER SIDE BRACKET	TO REPAIR SEE LABOUR	30.00	-
1	O/S REAR BODY PANEL	BENT	1,500.00	1,500.00
1	O/S REAR RIM	SERVICEABLE	498.00	-
1	O/S REAR RIM COVER	DENTED	185.00	185.00
1	O/S REAR WHEEL BEARING	NOT NECESSARY	125.00	-
1	O/S TAILLAMP ASSY	SERVICEABLE	36.00	-
	LESS 25% DISCOUNT		-706.00	-533.75
			2,118.00	1,601.25
SPECIAL NETT ITEMS				
1	O/S REAR BODY PANEL TOP GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
1	O/S REAR BODY PANEL TOP GLASS DAMPING SEAL (SN)	NOT NECESSARY	20.00	-
1	O/S REAR TYRE (SN)	SERVICEABLE	320.00	-
			380.00	-
LABOUR				
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF O/S REAR BUMPER SIDE BRACKET.		750.00	700.00
	TO FOCUS TAILLAMPS.TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	15.00
	TO REMOVE AND REFIT O/S REAR BODY PANEL TOP GLASS AND CONDUCT WATER LEAK TEST.	NOT NECESSARY	120.00	-
	TO APPLY UNDERSEALING.		120.00	30.00
	TO DISMANTLE AND CHECK REAR UNDER-CARRIAGE.TO REPLACE AFFECTED PORTIONS.	NOT NECESSARY	140.00	-
	TO CONDUCT REAR WHEEL ALIGNMENT TEST.		80.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		600.00	320.00
			1,860.00	1,125.00
GRAND TOTAL			4,358.00	2,726.25

Report Ref No. CS/FCI17021068/Krbn2



RECOMMENDED COST OF REPAIRS			2,726.25
-----------------------------	--	--	----------

Report Ref No. CS/FCI17021068/Krbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.