



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 356H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT (CONSISTENT)	BUCKLED	1,259.42	1,259.42
1	BUMPER ABSORBER FRT (CONSISTENT)	SERVICEABLE	394.68	-
1	BUMPER BEAM FRT (CONSISTENT)	TO REPAIR SEE LABOUR	914.08	-
1	BUMPER SPOILER FRT (CONSISTENT)	SERVICEABLE	181.75	-
1	BUMPER GRILLE LOWER FRT (CONSISTENT)	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH (CONSISTENT)	SERVICEABLE	207.22	-
1	BUMPER RETAINER FRT RH (CONSISTENT)	DISTORTED	151.41	151.41
1	BUMPER BRACKET FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	181.75	-
1	HEADLAMP RH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH (CONSISTENT)	BENT	783.83	783.83
1	FENDER INSULATOR RH (CONSISTENT)	SERVICEABLE	130.84	-
1	FENDER BRACKET FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	34.14	-
1	WHEELARCH FRT RH (CONSISTENT)	SERVICEABLE	278.84	-
1	WHEEL HOUSING PANEL FRT RH L70Y(CONSISTENT)	TO REPAIR SEE LABOUR	4,682.09	-
1	LOWER ARM FRT RH (CONSISTENT)	NOT NECESSARY	685.76	-
1	KNUCKLE ARM FRT RH (CONSISTENT)	NOT NECESSARY	846.98	-
1	ABSORBER FRT RH (CONSISTENT)	NOT NECESSARY	360.54	-
1	RADIATOR GRILLE (CONSISTENT)	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'(CONSISTENT)	SERVICEABLE	173.36	-
1	RADIATOR GRILLE FRAME (CONSISTENT)	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL (CONSISTENT)	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	89.79	-
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,941.63	-
1	DOOR MIRROR RH (CONSISTENT)	SERVICEABLE	1,483.40	-
1	DOOR MIRROR GLASS RH (CONSISTENT)	SERVICEABLE	242.33	-

Report Ref No. CC3/ASM17021146/Kps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR MIRROR BACK COVER RH (CONSISTENT)	SERVICEABLE	218.46	-
1	DOOR PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR CHECK FRT RH (CONSISTENT)	SERVICEABLE	194.77	-
1	DOOR FINISHER FRT RH (CONSISTENT)	SERVICEABLE	515.06	-
1	DOOR MOULDING FRT RH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	ROCKER PANEL OUTER RH (CONSISTENT)	TO REPAIR SEE LABOUR	987.49	-
1	DOOR PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-2,866.16	-219.47
			25,795.46	1,975.19
	<u>SPECIAL NETT ITEMS</u>			
1	SET WHEELARCH CLIP FRT RH (SN)(CONSISTENT)	NOT NECESSARY	66.00	-
1	SET FRONT BUMPER CLIP (SN)(CONSISTENT)	NECESSARY	66.00	66.00
1	RIM RH FRT (SN)(CONSISTENT)	SERVICEABLE	385.00	-
1	TYRE RH FRT (SN)(CONSISTENT)	SERVICEABLE	330.00	-
1	DOOR STICKER 'TRANS-CAB' (SN)(CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR STICKER 'CLASSIC' (SN)(CONSISTENT)	NECESSARY	30.00	15.00
1	DOOR STICKER '6555-3333' (SN)(CONSISTENT)	NECESSARY	80.00	60.00
			1,037.00	201.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED .		170.00	20.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BRACKET FRT RH,HEADLAMP PANEL FRT RH,FENDER BRACKET FRT RH,WHEEL HOUSING PANEL FRT RH L70Y,FRAME FULL SUPPORT BRACKET,BONNET,DOOR PANEL FRT RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH, ROCKER PANEL OUTER RH AND DOOR PANEL REAR RH .		2,800.00	500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		3,000.00	1,100.00
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING .	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .		220.00	60.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR .	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS .		170.00	60.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			7,540.00	1,800.00
GRAND TOTAL			34,372.46	3,976.19

RECOMMENDED COST OF REPAIRS				3,976.19
------------------------------------	--	--	--	-----------------

Report Ref No. CC3/ASM17021146/Kps3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.