

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|--|--|--------------------------------------|---------------|-------------------|-------------------------|--|
| ERGO INSURANCE PTE LTD | | | Ref: | CS3/EGI17021337/W | /be2 | |
| 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER D FIVE SINGAPORE 038985 | | | | 18-04-2018 | | |
| | | | Code: | EGI | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | | |
| | Insured Veh. | GBC 1574P | Veh. Ir | spected | SFM 441X | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | GBC1574P/SE/sa | Excess (\$) | | 0.00 | |
| | Assign From | SITI A'THIKAH | Assign Date | | 08/11/2017 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HONDA INTEGRA | c.c | | 1998 | |
| | Engine No. | HIDDEN | Year o | f Reg. | 2006 | |
| | Chassis No. | JHMDC54506S200898 | Colour | | BLACK | |
| | Odometer | 184347 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modifi | cation | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/45Z R17 | CHAME | PIRO HPY | 3 mm | |
| | L/H Front Tyre | 215/45Z R17 | CHAMPIRO HPY | | 3 mm | |
| | R/H Rear Tyre | 215/45Z R17 | CHAMF | PIRO HPY | 4 mm | |
| | L/H Rear Tyre | 215/45Z R17 | CHAME | PIRO HPY | 4 mm | |
| 4. Description of Damages | | | | | | |
| | THE VEHICLE SUS | STAINED DAMAGES AT THE REAR PORTION. | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 07/11/2017 | Inspec | t Date / Time | 08/11/2017 (05:18 PM) | |
| | Survey held at | HAN CAR REPAIRS | | | | |
| | BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718 | | | | | |
| 5a. | a. Remarks | | | | | |
| | AA) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,900-\$4,900 | | | | | |
| 5b. | 5b. Estimate Days of Repair | | | | | |

Report Ref No. CS3/EGI17021337/Wbe2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

5 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.