

ASS. REC. BY: PS

REF: CS/CT217004103 Cgb

Special Instruction:

Survivor: NAZ

ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi of CTZ Date/Time 08-11-2017

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 44654 Insured: SFNSAP

at Workshop m/s EM solution Tel: 64560226

of BLK 17 Sun Ming Rd Est #01-59

Policy No: Claim No SNM 1700121902/9

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 24/2/2017

CA / REV / REP. / REV 24 HRS up 1/3/2017 H.O.D. Endorsement:

Date/Time 28/2/2017 3:35pm Person Contacted: try Vehicle IN/OUT

Date/Time	Action/Instruction (x) Estimate
	<u>SLC 44654</u>
	<u>SFNSAP - MBA/CT217004103/1</u> <u>D.A. - 24/2/2017</u>
	<u>Survey: 1/3/2017; dismantle (1): 2/3/2017; dismantle (2): 3/3/2017</u>
	<u>after repair: 21/3/2017</u>

8/12/17 submit 45 \$ 21700, 14 day. 45 \$ 22400
(Red: 9200, 30/17). (Red: 8500, 28/17).

ASSIGNMENT

From:

Date: 11/1/2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLC 4465H

at Workshop m/s

EM Solution

of

Blk 17 Sin Ming Ind Est #01-39

Insured:

Policy No

Claims No

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? Yes or No

Consistent? Yes or No

days Res. Yes or No

% 3 Val. Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

9/6/17 145pm

PRS

Estimate repair range \$13,000 - \$15,000

Veh No

SLC 4465H

Yr Regn. 13 May 2016

Type M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

HONDA VTEC

Colour

BLU

Sp Reading

8183

Eng No

C/No:

RU111 13564

Gen. Cond

Good Fair / Poor / Burnt

Steering

In order Jammed / Leaked / Burnt or

Brake:

In order Jammed / Leaked / Burnt or

Mod:

Nil / S/Rim STD A/Rim

Tyre Size:

F: 215/60 R16

R: 215/60 R16

BS

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front:

R. Bal

7

mm

L/Bal

7

mm

D.O.A

24/4/2017

Rear:

R. Bal

7

mm

L/Bal

7

mm

D.O.A

1/3/2017

Survey held at

Des. of Damages (Frt)

Rear / O/S / N/S / U/C / Rooftop or

Frt, Rear N/S -

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to?

28/3-2017

Date/Time File Return to?

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee

Transportation:

) S + RS)

) Photos

) Others

TOTAL

Report Format:

PRS

Lump Sum / I.B.I. (\$

6/3/2017.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS3/CTI17004103/gb-1	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 08-11-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFW 59P	Veh. Inspected	SLC 4465H	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM17D01219C02/9	Excess (\$)	0.00	
Assign From	HWANG SHIANG YI	Assign Date	08/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/02/2017	Inspection Date	08/11/2017	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Hwang Shiang Yi <shiangyi.hwang@sg.cntaiping.com>
Sent: Wednesday, 8 November, 2017 3:40 PM
To: assignments@lkkauto.com
Subject: :PAPER SURVEY FOR VEHICLE NO SLC4465H (SNM17D01219C02/9)

Dear Catherine,

We wish to appoint LKK to do the paper re-survey for vehicle no SLC4465H.

Survey report uploaded to Merimen system.

Please acknowledge to receipt of this email.

Thanks & Regards,

Hwang Shiang Yi
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co. Reg. No 200208384E
DID : 6389 6541
Fax : 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Email : shiangyi.hwang@sg.cntaiping.com
Website : www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2017 12:34
Date Of Accident	24/02/2017 15:10
Exact Location Of Accident	HOUGANG AVE 3 TWRDS TAMPINES B/F DEFU LANE 10
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFW59P
Insured/Policyholder	
Name Of Registered Owner	LIAN CHEE BENG
NRIC No	S1129679C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90041323
Alternative Phone No	Others-90041323

Vehicle Particulars

Manufacturer	AUDI
Model	Q5
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSN1618071600
Cover Note Number	

Driver

Name of Driver	LIAN CHEE BENG
NRIC No	S1129679C
Date Of Birth	24/03/1955
Occupation	Indoor
Date Of Driving Pass	04/06/2013
Driving Experience	3 Years And 8 Months
Gender	Male
Mobile Number	(Local) +65-90041323
Fax Number	
Contact Number	Others-90041323
Email Address	NOEMAIL

Address	BLK 114 LENGKONG TIGA #10-175
Postcode	410114
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	Side Swipe- Same Direction
Weather Conditions	Raining
Road Surface	Wet

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC4465H
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Name of Driver	CHENG HENG KWAN
NRIC/Passport Number	S0690639G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan


SKETCH PLAN

VEHICLE NO: SFW 59P
INSURER: Chinn Timpalay
DOA: 24/02/17

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time: [Signature] 27/2/2017
Driver's Signature (if driver is not the policyholder) / Date & Time: [Signature]
Witnessed by Reporting Centre Personnel: [Signature] 28/02/2017



Sketch Plan #2

Describe Circumstances of the Accident

On 24/02/2017 - 3:10pm.

I was travelling along Hargray Ave 3 toward Tampines on the middle lane of 5-lanes road. Somewhere before Detu Lane 10, I was driving on the middle lane, vehicle B was driving on the 3rd lane. Out of sudden, my vehicle skided due to raining weather and my vehicle front right portion collided onto the rear left portion of vehicle B.

Vehicle A - SFW59P

Vehicle B - SLC446SH

[Signature]

Declaration

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own policy. Please check with your policy for more information.

We declare the foregoing particulars are true in every respect.

[Signature] 2 Feb 2017
10:30pm

Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature] 24/02/2017

Witnessed by Reporting Centre Personnel

☒ Claim Own Policy ☐ Claim Third Party ☐ Claim OD / TP at other workshop ☐ Reporting Only

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 64531173, Fax : 64536131.
appraisal & inspection, accident investigation, expert witness

Consultants: Vehicle

Report No: 0076-17-EMAm

18 September 2017

ACCIDENT VEHICLE SURVEY REPORT

Cheng Jenny
Blk 340 Hougang Ave 7 #03-449
Singapore 530340

VEHICLE INFORMATION:

Vehicle Reg No.:	SLC4465H	Odometer:	008183km
Make & Model:	Honda Vezel 1.5X CVT	Colour:	Silver
Chassis number:	RU11113564	Date of accident:	24/02/2017
Year of Regn.:	13/05/2016	Date inspected:	27/02/2017
Repairer at:	EM Solution Pte Ltd	Date inspected (After Repair):	-
	Blk 17 #01-59 Sin Ming Industrial Estate Sector A		
	Singapore 575675		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Dunlop	6mm/Dunlop	215/60R16
Rear:	6mm/Dunlop	6mm/Dunlop	215/60R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front and rear portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy**Parts and Labour Assessment**

Report No: 0076-17-EMAm

Vehicle No: SLC4465H

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Front bonnet	1	buckled	1,020.00	1,020.00
Front bonnet hinge	2	reuse	100.00	0.00 <i>SVC</i>
Front radiator grille	1	fractured	270.00	270.00
Front radiator grille garnish	1	fractured	285.00	285.00
Front radiator grille chrome moulding RH/LH	1	necessary	113.80	113.80
Front radiator grille emblem 'H' logo	1	necessary	28.20	28.20
Front radiator grille support bracket	1	bent	52.00	52.00 <i>X SVC</i>
Front head lamp (HID) RH/LH	2	fractured	3,718.80	3,718.80
Front head lamp lower bracket RH/LH	2	bent	70.00	70.00
Front head lamp clip RH/LH	6	necessary	23.40	23.40
Front bumper	1	squashed	927.50	927.50
Front bumper tow cover	1	deformed	20.00	20.00
Front bumper lower grille	1	fractured	150.00	150.00
Front bumper fog lamp cover RH/LH <i>NN</i>	2 1	deformed	90.00	90.00 <i>45</i>
Front bumper fog lamp RH/LH <i>NN</i>	2 1	fractured	655.40	655.40 <i>327.00</i>
Front bumper lower moulding	1	deformed	146.30	146.30
Front bumper lower diffuser	1	deformed	195.50	195.50
Front bumper side retainer RH/LH	2	necessary	46.00	46.00
Front bumper reinforcement	1	bent	321.00	321.00
Front fender LH	1	buckled	580.00	580.00
Front fender wheel arch garnish RH/LH	2	deformed	306.00	306.00
Front fender inner shield RH/LH	2	deformed	215.80	215.80
Front fender inner shield clip RH/LH	20	necessary	76.00	76.00
Front shock absorber RH/LH	2	bent	742.40	742.40 <i>X NN</i>
Front shock absorber top mounting RH/LH <i>☆</i>	2	necessary	91.80	91.80 <i>X NN</i>
Front knuckle arm RH/LH <i>NN</i>	2 1	bent	700.00	700.00 <i>350</i>
Front knuckle arm bearing RH/LH <i>NN</i>	2 1	dislodged	331.80	331.80 <i>165.90</i>
Front lower arm RH/LH <i>NN</i>	2 1	bent	600.20	600.20 <i>300.10</i>
Front lower arm ball joint RH/LH	2	jammed	226.40	226.40 <i>X NN</i>
Front stabiliser linkage RH/LH <i>NN</i>	2	bent	170.00	170.00 <i>X NN</i>
Rear tailgate	1	bent	1,100.00	1,100.00
Rear tailgate windscreen glass	1	scratched	1,300.00	1,300.00
Rear tailgate windscreen glass moulding	1	necessary	80.00	80.00
Rear tailgate reflector lamp LH	1	warped	240.00	240.00

PAR Automotive Consultancy

Rear tailgate emblem 'Vezel'	1	necessary	65.00	65.00
Rear boot weatherstrip	1	deformed	165.00	165.00
Rear tail lamp LH	1	cracked	460.00	460.00
Rear bumper side LH	1	squashed	195.00	195.00
Rear bumper side retainer LH	1	bent	32.00	32.00
Rear bumper	1	deformed	863.00	863.00
Rear bumper reflector LH	1	fractured	151.00	151.00
Rear end panel	1	buckled	580.00	580.00 XR
Rear spare tyre well panel under shield	1	deformed	190.00	190.00
Rear fender LH	1	buckled	1,211.60	1,211.60
Rear fender quarter garnish LH	1	deformed	561.40	561.40
Rear fender wheel arch garnish LH	1	deformed	212.20	212.20
Rear fender inner shield LH	1	deformed	159.90	159.90
Rear fender inner shield clip LH	10	necessary	38.00	38.00
Rear fender air duct LH	1	deformed	30.30	30.30
Rear fender wheel house panel inner LH	1	buckled	420.00	420.00
Rear fender inner trim LH	1	deformed	831.90	831.90
Rear safety belt LH	1	jammed	262.00	262.00 XNN
Rear suspension axle	1	bent	1,707.90	1,707.90
Rear wheel hub c/w hearing LH	1	dislodged	387.20	387.20
Rear shock absorber RH/LH	1/2	bent	525.20	525.20 26.60
Rear stabiliser bar	1	bent	230.00	230.00
Rear ABS sensor LH	1	shorted	201.60	201.60
Rear undercarriage cover	1	deformed	156.80	156.80
Rear door LH	1	buckled	954.70	954.70
Rear door frame black sticker LH	1	necessary	33.90	33.90
Rear door glass outer moulding LH	1	necessary	54.10	54.10
Rear door inner trim board LH	1	deformed	434.90	434.90 XNN
Rear door inner lock LH	1	jammed	253.30	253.30
Rocker panel garnish LH	1	deformed	225.40	225.40
Rocker panel LH	1	repair	648.00	0.00
Interior floor panel	1	repair	835.00	0.00
Roof lining	1	crumpled	756.00	756.00
Window air bag LH	1	activated	1,428.00	1,428.00
Front passenger safety belt	1	jammed	748.00	748.00 XNN
Front passenger seat air bag	1	activated	1,092.00	1,092.00
Front sport rim RH	1	abraded	944.10	944.10
Rear sport rim LH	1	broken	944.10	944.10

Air bag control unit	1	activated	1,092.00	1,092.00
	<i>Subtotal before discount</i>		35,073.80	33,490.80
	<i>Percentage discount</i>	0% and 20%	0.00	6,698.16
	Sub-total 1		35,073.80	26,792.64
Front bumper clip	10	necessary	35.00	35.00
Front tyre RH/LH	2	abraded	600.00	600.00 XNN
Rear tailgate glass sealant	1	necessary	70.00	70.00
Rear bumper clip	10	necessary	35.00	35.00
Reverse sensor	1	shorted	350.00	300.00
Rear tyre LH @ 80%	1	punctured	300.00	300.00 240
	<i>Subtotal before discount</i>		1,390.00	1,340.00
	<i>Percentage discount</i>	0% and 0%	0.00	0.00
	Sub-total 2		1,390.00	1,340.00
	Parts-total		36,463.80	28,132.64

LABOUR

1. To straighten and panel beating front support panel, front and rear frame members. To cut/weld rear end panel, rear LH fender, LH rocker panel and interior floor panel. To remove and refit above parts.	2,800.00	2,200.00 1,600
2. To putty, re-spray painting and polish affected areas.	2,500.00	2,000.00 1,500
3. To check and rectify wiring system.	120.00	100.00 60
4. To rust proof affected areas.	150.00	120.00 100
5. To remove, refit front RH/LH sport rims/tyres and balancing.	100.00	80.00 30
6. To remove and refit front suspension system.	400.00	350.00 150
7. To remove and refit rear tailgate glass.	150.00	120.00
8. To remove, transfer and refit rear tailgate components.	150.00	100.00 60
9. To remove and refit cushion seats, upholstery, garnish, fittings, etc. to assist repair.	200.00	150.00 80
10. To remove and refit petrol tank to assist repair.	100.00	80.00
11. To remove, refit rear LH sport rim/tyre and balancing.	50.00	40.00 30
12. To remove and refit rear suspension system.	400.00	350.00 250
13. To conduct electronic wheel alignment test.	180.00	150.00 80
14. To remove, transfer and refit rear LH door components.	150.00	100.00 60
15. To remove and refit roof lining.	200.00	150.00 80
16. Towing charges (2 trips).	130.00	130.00 60
	Labour total	7,780.00 6,220.00
	Parts & Labour total	44,243.80 34,352.64

PAR Automotive Consultancy

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :

\$30,900.00

and the recommended number of working days for the repairs is :

18

h

14 days

B J Loi (I Eng, MIMI, AIRTE)

Automotive Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Feb 2017		28 Feb 2017 15:27 Edit Adj Rpt	S\$22,400.00 Edit Estimates	S\$22,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by insurer] Insured: LIAN CHEE BENG, ID: S1129679C Main Claimant: CHENG JENNY, ID: S7306114H Vehicle Reg. No.: SLC4465H Date of Loss: 24/02/2017 15:00 - :59 Claim Type: TP / SNM17D01219C02 Policy/Cover Note No.: DMPCSN1618071600 (Comprehensive) Coverage: 05/04/2016 - 04/04/2017 Vehicle Reg. No. (Insured): SFW59P Policy No. (Claimant): 5080293602 Excess: S\$0.00 Repairer: Em Solution Pte Ltd - Sin Ming (HQ) BLK 17 #01-59 SIN MING INDUSTRIAL ESTATE SECTOR A, 575675 Sin Ming - Tel: 6456 0556 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174] Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel: Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 13/12/2017] Adj Asg. Remarks: PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS AND LET US HAVE YOUR RECOMMENDATION ON COST OF REPAIRS.;				

Claim Documents

*SLC4465H (SNM17D01219C02)
[SFW59P]
TP
CHENG JENNY
Feb 24 2017 3:00PM
[LIAN CHEE BENG]
Em Solution Pte Ltd - Sin Ming

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer	
Assessment Reports				1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	27/02/17 16:40	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	27/02/17 16:37	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/17 17:47	General View		Load JPG	☒
2	15/03/17 17:47	General View		Load JPG	☒
3	15/03/17 17:47	General View		Load JPG	☒
4	15/03/17 17:47	General View		Load JPG	☒
5	15/03/17 17:47	General View		Load JPG	☒
6	15/03/17 17:47	General View		Load JPG	☒
7	15/03/17 17:47	General View		Load JPG	☒
8	15/03/17 17:47	General View		Load JPG	☒
9	15/03/17 17:47	General View		Load JPG	☒
10	15/03/17 17:47	General View		Load JPG	☒
11	15/03/17 17:47	General View		Load JPG	☒
12	15/03/17 17:47	General View		Load JPG	☒
13	15/03/17 17:47	General View		Load JPG	☒
14	15/03/17 17:47	General View		Load JPG	☒
15	15/03/17 17:47	General View		Load JPG	☒
16	15/03/17 17:47	General View		Load JPG	☒
17	15/03/17 17:47	General View		Load JPG	☒
18	15/03/17 17:47	General View		Load JPG	☒
19	15/03/17 17:47	General View		Load JPG	☒

20	15/03/17 17:47	General View		Load JPG	☒
21	15/03/17 17:47	General View		Load JPG	☒
22	15/03/17 17:47	General View		Load JPG	☒
23	15/03/17 17:47	General View		Load JPG	☒
24	15/03/17 17:47	General View		Load JPG	☒
25	15/03/17 17:47	General View		Load JPG	☒
26	15/03/17 17:47	General View		Load JPG	☒
27	15/03/17 17:47	General View		Load JPG	☒
28	15/03/17 17:47	General View		Load JPG	☒
29	15/03/17 17:47	General View		Load JPG	☒
30	15/03/17 17:47	General View		Load JPG	☒
31	15/03/17 17:47	General View		Load JPG	☒
32	15/03/17 17:47	General View		Load JPG	☒
33	15/03/17 17:47	General View		Load JPG	☒
34	15/03/17 17:47	General View		Load JPG	☒
35	15/03/17 17:47	General View		Load JPG	☒
36	15/03/17 17:47	General View		Load JPG	☒
37	15/03/17 17:47	General View		Load JPG	☒
38	15/03/17 17:47	General View		Load JPG	☒
39	15/03/17 17:47	General View		Load JPG	☒
40	15/03/17 17:47	General View		Load JPG	☒
41	15/03/17 17:47	General View		Load JPG	☒
42	15/03/17 17:47	General View		Load JPG	☒
43	15/03/17 17:47	General View		Load JPG	☒
44	15/03/17 17:47	General View		Load JPG	☒
45	15/03/17 17:47	General View		Load JPG	☒
46	15/03/17 17:47	General View		Load JPG	☒
47	15/03/17 17:47	General View		Load JPG	☒
48	15/03/17 17:47	General View		Load JPG	☒
49	15/03/17 17:47	General View		Load JPG	☒
50	15/03/17 17:47	General View		Load JPG	☒
51	15/03/17 17:47	General View		Load JPG	☒
52	15/03/17 17:47	General View		Load JPG	☒
53	15/03/17 17:47	General View		Load JPG	☒
54	15/03/17 17:51	Reinspection Photo		Load JPG	☒
55	15/03/17 17:51	Reinspection Photo		Load JPG	☒
56	15/03/17 17:51	Reinspection Photo		Load JPG	☒
57	15/03/17 17:51	Reinspection Photo		Load JPG	☒
58	15/03/17 17:51	Reinspection Photo		Load JPG	☒
59	15/03/17 17:51	Reinspection Photo		Load JPG	☒
60	15/03/17 17:51	Reinspection Photo		Load JPG	☒
61	15/03/17 17:51	Reinspection Photo		Load JPG	☒
62	15/03/17 17:51	Reinspection Photo		Load JPG	☒
63	15/03/17 17:51	Reinspection Photo		Load JPG	☒
64	15/03/17 17:51	Reinspection Photo		Load JPG	☒
65	15/03/17 17:51	Reinspection Photo		Load JPG	☒
66	15/03/17 17:51	Reinspection Photo		Load JPG	☒
67	15/03/17 17:51	Reinspection Photo		Load JPG	☒
68	15/03/17 17:51	Reinspection Photo		Load JPG	☒
69	15/03/17 17:51	Reinspection Photo		Load JPG	☒
70	15/03/17 17:51	Reinspection Photo		Load JPG	☒

71	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
72	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
73	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
74	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
75	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
76	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
77	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
78	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
79	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
80	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
81	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
82	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
83	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
84	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
85	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
86	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
87	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
88	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
89	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
90	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
91	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
92	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
93	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
94	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
95	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
96	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
97	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
98	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
99	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
100	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
101	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
102	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
103	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
104	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
105	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
106	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
107	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
108	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
109	15/03/17 17:51	Reinspection Photo	1	Load JPG	☒
110	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
111	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
112	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
113	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
114	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
115	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
116	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
117	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
118	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
119	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
120	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒
121	15/03/17 17:52	Reinspection Photo	1	Load JPG	☒

122	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
123	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
124	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
125	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
126	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
127	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
128	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
129	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
130	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
131	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
132	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
133	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
134	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
135	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
136	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
137	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
138	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
139	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
140	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
141	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
142	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
143	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
144	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
145	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
146	15/03/17 17:52	Reinspection Photo	1	Load JPG	✓
147	23/03/17 10:36	Photo After Spray	1	Load JPG	✓
148	23/03/17 10:36	Photo After Spray	1	Load JPG	✓
149	23/03/17 10:36	Photo After Spray	1	Load JPG	✓
150	23/03/17 10:36	Photo After Spray	1	Load JPG	✓
151	23/03/17 10:36	Photo After Spray	1	Load JPG	✓
152	23/03/17 10:36	Photo After Spray	1	Load JPG	✓
153	23/03/17 10:36	Photo After Spray	1	Load JPG	✓
154	23/03/17 10:36	Photo After Spray	1	Load JPG	✓
Documentation				1 per page	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	28/02/17 15:29	E-filed GIA report	1	Load PDF	
2	28/02/17 15:30	CONFIRMATION OF REPAIRER DETAIL	1	Load PDF	
3	08/11/17 15:26	PAPER RE-SURVEY PART 1	1	Load PDF	
4	08/11/17 15:32	PAPER RE-SURVEY PART 2	1	Load PDF	
5	08/11/17 15:33	PAPER RE-SURVEY PART 3	1	Load PDF	
6	08/11/17 15:33	PAPER RE-SURVEY PART 4	1	Load PDF	
7	08/11/17 15:33	PAPER RE-SURVEY PART 5	1	Load PDF	
8	08/11/17 15:34	PAPER RE-SURVEY PART 6	1	Load PDF	
9	08/11/17 15:34	PAPER RE-SURVEY PART 7	1	Load PDF	
10	08/11/17 15:35	PAPER RE-SURVEY PART 8	1	Load PDF	
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	27/02/17 16:39	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
2	27/02/17 16:39	Sketch Plan #2 [Linked Accident Report Documents]	1	Load TIF	
3	27/02/17 16:39	Accident Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
4	27/02/17 16:39	Common Statement [Linked Accident Report Documents]	1	Load TIF	
5	27/02/17 16:39	Common Statement [Linked Accident Report Documents]	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print

1 11/12/17 10:17 Invoice

Load PDF

Linked Accident Report Documents

View Use Viewer

Assessment Reports			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	27/02/17 16:40	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	27/02/17 16:37	Accident Photo		Load JPG
2	27/02/17 16:37	Accident Photo		Load JPG
3	27/02/17 16:37	Accident Photo		Load JPG
4	27/02/17 16:37	Accident Photo		Load JPG
5	27/02/17 16:37	Accident Photo		Load JPG
6	27/02/17 16:37	Accident Photo		Load JPG
7	27/02/17 16:37	Accident Photo		Load JPG
8	27/02/17 16:37	Accident Photo		Load JPG
9	27/02/17 16:37	Accident Photo		Load JPG
10	27/02/17 16:37	Accident Photo		Load JPG
11	27/02/17 16:37	Accident Photo		Load JPG
12	27/02/17 16:37	Accident Photo		Load JPG
Documentation			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	27/02/17 16:39	Sketch Plan		Load TIF
2	27/02/17 16:39	Sketch Plan #2		Load TIF
3	27/02/17 16:39	Accident Sketch Plan		Load TIF
4	27/02/17 16:39	Common Statement		Load TIF
5	27/02/17 16:39	Common Statement		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI17004103/CGBE2-1

Date: 11/12/2017

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1618071600
Claimant Vehicle No :	SLC4465H	Insured Vehicle No :	SFW59P
Date of Loss:	24/02/2017	Nature of Claim:	TP
		Claim No:	SNM17D01219C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC4465H	Engine No:	L15B4033568
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11113564
Reg. Date:	13/05/2016 (Man. Year: 2016)	Odometer:	8183 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	36,463.80	23,665.60	12,798.20	35.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,780.00	4,340.00	3,440.00	44.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,243.80	28,005.60	16,238.20	36.70
Approved Total (Overridden) (S\$)		22,400.00		
Nett Amount (S\$)	44,243.80	22,400.00	21,843.80	49.37

INSPECTION

Date of Assignment:	28/02/2017	
Date Inspected:	01/03/2017	Inspected At:
		Em Solution Pte Ltd - Sin Ming (HQ)
		BLK 17 #01-59 SIN MING INDUSTRIAL
		ESTATE SECTOR A
		Singapore 575675
Estimated Period of Repair:	14.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ashley Chong Chin Yan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2017)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC4465H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,020.00 F	*1,020.00 FL
2	2		*FRONT BONNET HINGE	Serviceable	100.00 F	*- FL
3	1		*FRONT RADIATOR GRILLE	Fractured	270.00 F	*270.00 FL
4	1		*FRONT RADIATOR GRILLE GARNISH	Fractured	285.00 F	*285.00 FL
5	1		*FRONT RADIATOR GRILLE CHROME MOULDING RH / LH	Necessary	113.80 F	*113.80 FL
6	1		*FRONT RADIATOR GRILLE EMBLEM H LOGO	Necessary	28.20 F	*28.20 FL
7	1		*FRONT RADIATOR GRILLE SUPPORT BRACKET	Serviceable	52.00 F	*- FL
8	2		*FRONT HEAD LAMP (HID) RH / LH	Fractured	3,718.80 F	*3,718.80 FL
9	2		*FRONT HEAD LAMP LOWER BRACKET RH / LH	Bent	70.00 F	*70.00 FL
10	6		*FRONT HEAD LAMP CLIP RH / LH	Necessary	23.40 F	*23.40 FL
11	1		*FRONT BUMPER	Squashed	927.50 F	*927.50 FL
12	1		*FRONT BUMPER TOW COVER	Deformed	20.00 F	*20.00 FL
13	1		*FRONT BUMPER LOWER GRILLE	Fractured	150.00 F	*150.00 FL
14	1		*FRONT BUMPER FOG LAMP COVER RH / LH	O/S Deformed/N/S Not Necessary	90.00 F	*45.00 FL
15	1		*FRONT BUMPER FOG LAMP RH / LH	O/S Fractured/N/S Not Necessary	655.40 F	*327.70 FL
16	1		*FRONT BUMPER LOWER MOULDING	Deformed	146.30 F	*146.30 FL
17	1		*FRONT BUMPER LOWER DIFFUSER	Deformed	195.50 F	*195.50 FL
18	2		*FRONT BUMPER SIDE RETAINER RH / LH	Necessary	46.00 F	*46.00 FL
19	1		*FRONT BUMPER REINFORCEMENT	Bent	321.00 F	*321.00 FL
20	1		*FRONT FENDER LH	Buckled	580.00 F	*580.00 FL
21	2		*FRONT FENDER WHEEL ARCH GARNISH RH / LH	Deformed	306.00 F	*306.00 FL
22	2		*FRONT FENDER INNER SHIELD RH / LH	Deformed	215.80 F	*215.80 FL
23	20		*FRONT FENDER INNER SHIELD CLIP RH / LH	Necessary	76.00 F	*76.00 FL
24	2		*FRONT SHOCK ABSORBER RH / LH	Not Necessary	742.40 F	*- FL
25	1		*FRONT KNUCKLE ARM RH / LH	O/S Bent / N/S Not Necessary	700.00 F	*350.00 FL
26	1		*FRONT KNUCKLE ARM BEARING RH / LH	O/S Dislodged/N/S Not Necessary	331.80 F	*165.90 FL
27	1		*FRONT LOWER ARM RH / LH	O/S Bent / N/S Not Necessary	600.20 F	*300.10 FL
28	2		*FRONT LOWER ARM BALL JOINT RH / LH	Not Necessary	226.40 F	*- FL
29	1		*REAR TAILGATE	Bent	1,100.00 F	*1,100.00 FL
30	1		*REAR TAILGATE WINDSCREEN GLASS	Scratched	1,300.00 F	*1,300.00 FL
31	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Necessary	80.00 F	*80.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*REAR TAILGATE REFLECTOR LAMP LH	Warped	240.00 F	*240.00 FL
33	1		*REAR TAILGATE EMBLEM VEZEL	Necessary	65.00 F	*65.00 FL
34	1		*REAR BOOT WEATHERSTRIP	Deformed	165.00 F	*165.00 FL
35	1		*REAR TAIL LAMP LH	Cracked	460.00 F	*460.00 FL
36	1		*REAR BUMPER SIDE LH	Squashed	195.00 F	*195.00 FL
37	1		*REAR BUMPER SIDE RETAINER LH	Bent	32.00 F	*32.00 FL
38	1		*REAR BUMPER	Deformed	863.00 F	*863.00 FL
39	1		*REAR BUMPER REFLECTOR LH	Fractured	151.00 F	*151.00 FL
40	1		*REAR END PANEL	Repair	580.00 F	*- FL
41	1		*REAR SPARE TYRE WELL PANEL UNDER SHIELD	Deformed	190.00 F	*190.00 FL
42	1		*REAR FENDER LH	Buckled	1,211.60 F	*1,211.60 FL
43	1		*REAR FENDER QUARTER GARNISH LH	Deformed	561.40 F	*561.40 FL
44	1		*REAR FENDER WHEEL ARCH GARNISH LH	Deformed	212.20 F	*212.20 FL
45	1		*REAR FENDER INNER SHIELD LH	Deformed	159.90 F	*159.90 FL
46	10		*REAR FENDER INNER SHIELD CLIP LH	Necessary	38.00 F	*38.00 FL
47	1		*REAR FENDER AIR DUCT LH	Deformed	30.30 F	*30.30 FL
48	1		*REAR FENDER WHEEL HOUSE PANEL INNER LH	Buckled	420.00 F	*420.00 FL
49	1		*REAR FENDER INNER TRIM LH	Deformed	831.90 F	*831.90 FL
50	1		*REAR SAFETY BELT LH	Not Necessary	262.00 F	*- FL
51	1		*REAR SUSPENSION AXLE	Bent	1,707.90 F	*1,707.90 FL
52	1		*REAR WHEEL HUB C/W BEARING LH	Dislodged	387.20 F	*387.20 FL
53	1		*REAR SHOCK ABSORBER RH / LH	O/S Not Necessary /N/S	525.20 F	*262.60 FL
54	1		*REAR STABILIZER BAR	Bent	230.00 F	*230.00 FL
55	1		*REAR ABS SENSOR LH	Shorted	201.60 F	*201.60 FL
56	1		*REAR UNDERCARRIAGE COVER	Deformed	156.80 F	*156.80 FL
57	1		*REAR DOOR LH	Buckled	954.70 F	*954.70 FL
58	1		*REAR DOOR FRAME BLACK STICKER LH	Necessary	33.90 F	*33.90 FL
59	1		*REAR DOOR GLASS OUTER MOULDING LH	Necessary	54.10 F	*54.10 FL
60	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	434.90 F	*- FL
61	1		*REAR DOOR INNER LOCK LH	Jammed	253.30 F	*253.30 FL
62	1		*ROCKER PANEL GARNISH LH	Deformed	225.40 F	*225.40 FL
63	1		*ROCKER PANEL LH	Repair	648.00 F	*- FL
64	1		*INTERIOR FLOOR PANEL	Repair	835.00 F	*- FL
65	1		*ROOF LINING	Crumpled	756.00 F	*756.00 FL
66	1		*WINDOW AIR BAG LH	Activated	1,428.00 F	*1,428.00 FL
67	1		*FRONT PASSENGER SAFETY BELT	Not Necessary	748.00 F	*- FL
68	1		*FRONT PASSENGER SEAT AIR BAG	Activated	1,092.00 F	*1,092.00 FL
69	1		*FRONT SPORT RIM RH	Abraded	944.10 F	*944.10 FL
70	1		*REAR SPORT RIM LH	Broken	944.10 F	*944.10 FL
71	1		*AIR BAG CONTROL UNIT	Activated	1,092.00 F	*1,092.00 FL
72	10		*FRONT BUMPER CIP	Necessary	35.00 FS	*35.00 FS
73	2		*FRONT TYRE RH / LH	Not Necessary	600.00 FS	*- FS
74	1		*REAR TAILGATE GLASS SEALANT	Necessary	70.00 FS	*70.00 FS
75	10		*REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
76	1		*REVERSE SENSOR	Shorted	350.00 FS	*300.00 FS
77	1		*REAR TYRE LH (80%)	Punctured	300.00 FS	*240.00 FS
78	2		*FRONT SHOCK ABSORBER TOP MOUNTING RH / LH	Not Necessary	91.80 F	*- FL
79	2		*FRONT STABILISER LINKAGE RH / LH	Not Necessary	170.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **36,463.80** **29,412.00**
 - List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 5,746.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						36,463.80 23,665.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING FRONT SUPPORT PANEL, FRONT AND REAR FRAME MEMBERS. TO CUT / WELD REAR END PANEL, REAR LH FENDER, LH ROCKER PANEL AND INTERIOR FLOOR PANEL. TO REMOVE AND REFIT ABOVE PARTS	New	2,800.00	1,600.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS	New	2,500.00	1,500.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	120.00	60.00
4	TO RUST PROOF AFFECTED AREAS	New	150.00	100.00
5	TO REMOVE, REFIT FRONT RH / LH SPORT RIMS/ TYRES AND BALANCING	New	100.00	30.00
6	TO REMOVE AND REFIT FRONT SUSPENSION SYSTEM	New	400.00	150.00
7	TO REMOVE AND REFIT REAR TAILGATE GLASS	New	150.00	120.00
8	TO REMOVE, TRANSFER AND REFIT REAR TAILGATE COMPONENTS	New	150.00	60.00
9	TO REMOVE AND REFIT CUSHION SEATS, UPHOLSTERY, GARNISH, FITTINGS, ETC. TO ASSIST REPAIR	New	200.00	80.00
10	TO REMOVE AND REFIT PETROL TANK TO ASSIST REPAIR	New	100.00	80.00
11	TO REMOVE, REFIT REAR LH SPORT RIM / TYRE AND BALANCING	New	50.00	30.00
12	TO REMOVE AND REFIT REAR SUSPENSION SYSTEM	New	400.00	250.00
13	TO CONDUCT ELECTRONIC WHEEL ALIGNMENT TEST	New	180.00	80.00
14	TO REMOVE, TRANSFER AND REFIT REAR LH DOOR COMPONENTS	New	150.00	60.00
15	TO REMOVE AND REFIT ROOF LINING	New	200.00	80.00
16	TOWING CHARGES (2 TRIPS)	New	130.00	60.00
Gross Labour Cost (\$\$)			7,780.00	4,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >