Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17021417/UPS3Q2

Date: 27/04/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1926152

Claimant Vehicle No: GBC1208Y Insured Vehicle No: SLM2087B

Date of Loss: 04/11/2017 Nature of Claim: TP Claim No: C0458633

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC1208Y

 Make & Model:
 NISSAN NV200, 1.5 (A)
 Engine No:
 K9KF276D098078

 Reg. Date:
 31/05/2011 (Man. Year: 2010)
 Chassis No:
 JN1YBAM20U0003416

 Colour:
 Silver
 Odometer:
 166522 km

Colour: Silver Engine Capacity: 1461 cc

Engine Capacity: 1461 of Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
Front Left Side: Dunlop 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------------|------------|------------|--------|
| Parts | 840.04 | 815.40 | 24.64 | 2.93 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 685.00 | 505.00 | 180.00 | 26.28 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 1,525.04 | 1,320.40 | 204.64 | 13.42 |
| Approved Total (Overridden) (S\$) | | 1,050.00 | | |
| (S\$) | 1,525.04 | 1,050.00 | 475.04 | 31.15 |
| + GST 7.00/7.00% (S\$) | 106.75 | 73.50 | 33.25 | 31.15 |
| Nett Amount (S\$) | 1,631.79 | 1,123.50 | 508.29 | 31.15 |
| Global Sum S | Settlement (S\$) | 0.00 | | |

INSPECTION

Date of Assignment: 08/11/2017

Date Inspected: 09/11/2017 Inspected At: NPH Auto Service (HQ)

Blk 9005 Tampines Steet 93, #01-

246/254

Singapore 528839

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

| Reference | | | | | |
|---|--|--|--|--|--|
| Part Source: | | (Last Synchronised: 27 Apr 2020) | | | |
| Parts: | N/A | NISSAN NV200 1.5 (A) (Model not available in database) | | | |
| Labour: | Repairer's | (Price-denominated Standard List) | | | |
| Print Code: | e: (Unsubmitted, no print-code for GBC1208Y) | | | | |
| Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | | | | | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | | | | | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-------|--------|--|-------------------|------------|------------|
| 1 | 1 | *REAR BUMPER SIDE RETAINER LH (CONSISTENT) | Not Necessary | 35.20 FL | *-FL |
| 2 | 1 | *REAR LAMP LH (CONSISTENT) | Scratched | 255.60 FN | *255.60 FN |
| 3 | 1 | *REAR BUMPER (CONSISTENT) | Cut | 650.40 FN | *650.40 FN |
| F=Fra | nchise | part. L=ListItemDisc. N=NettItemDisc. | | | |
| | | | Sub Total (S\$) | 941.20 | 906.00 |
| | | - List Item Discount on L Items 30. | 00/30.00% (S\$) | 10.56 | 0.00 |
| | | - Nett Item Discount on N Items 10. | .00/10.00% (S\$) | 90.60 | 90.60 |
| | | 7 | Γotal Parts (S\$) | 840.04 | 815.40 |
| | | Report was unsubmitted during this prin | t-out. | | |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|----------|------------|--------|
| Lab | <u>our Items</u> | | | |
| 1 | REMOVE & INSTALL R/LAMP ,R/BUMPER ,KNOOR/FENDER A RESTRAIGHTEN BODY | CK New | 300.00 | 250.00 |
| 2 | SPRAY PAINTING | New | 280.00 | 230.00 |
| 3 | CHECK WIRING SYSTEM | New | 25.00 | 25.00 |
| 4 | REMOVE & INSTALL REAR BOOT CARPET | New | 80.00 | 0.00 |
| | Gross Labour Cost (S\$) | | 685.00 | 505.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >