

ASS. REC. BY

CJ/FI17021428/Grb02

CWS

GU

ASSIGNMENT OFFICE

Firm Name

Serene Ter

FCI

2:40pm @ 9/11/17

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLE1774A

Insured

SHA 3339D

at Workshop no.

Kah Motor

Tel

6846 5672

of

15 Ubi Road 4

Policy No.

Claim No.

D17 010348 MFSH

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A. 3/11/2017

CA / REV / REP. / REV 24 HRS

1 wks

10/11/17 @ 10 am owner waiting

H.O.D. Endorsement

Date/Time

2:40pm @ 9/11/17

Person Contacted

Steven Chui

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLE1774A X

SHA 3339D - NS / INC / 16021476 / 47 vbn2 - D O A - 30 / 12 / 2017

Sent poli to Serene through email

Signature

REF: FCI

ASSIGNMENT

From:

Date: 10/11/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLE1774 A

at Workshop m/s

Kah Motor

of

15 Ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:


10am @ owner

(Policy Condition)

waiting

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLE1774A

Yr Regn:

12 Jul 2016

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda odyssey cc 2356

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

20893

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHARC 1890 GC205119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

10-11-17

Survey held at

W/S

10:30 AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirm CUP \$14,318.42, 8 days
Red: \$4539.20, 24%

Date/Time. File Pass to?



Preli. Report



Final Report

1) typist

Date/Time. File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Diary

TOTAL

9x15=135

170+135

50

50

110

515

Report Format:

TP

Lump Sum / I.B.I. (\$

14,318.42



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021428/Grb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 3339D	Veh. Inspected	SLE 1774A
Policy No.		Coverage (\$)	0.00
Claim No.	D17010348MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	09/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/11/2017	Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	06-11-2017	Our Ref No. D17010348MFSH
Accident Date	03-11-2017	Claim Type. Third Party
Insured Vehicle	SHA3339D	Third Party Vehicle. SLE1774A
Survey Location	15 UBI ROAD 4	
Contact Person.	STEVEN CHUI	
Contact No.	68413838/ 68413838	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229899)



PRI Documents



Close X

PRI Header Details

Claim No	D17010348MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & KAH MOT
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : STEVEN CHUI)	Survey Location & Contact Details	15 UBI ROAD 4 Mobile: 68413838 , Phone: 68413838 , Fax: 0 EmailId: STEVENCHUI@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3339D	TP Vehicle No	SLE1774A
PRI Recieved Date	07-11-2017 09:51:54 PM	Surveyor Appointed Date	09-11-2017 02:40:03 PM	Surveyor Accept Date	09-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-11-2017	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

[Upload Multiple Documents](#)

File Name

Action

Surveyor Job Remarks

Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010348MFSH

Our Ref: CS/FCI17021428/Grb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 1774A .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10/11/2017 at the premises of M/s KAH MOTOR CO SDN BHD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>18,857.62</u> .
Revised Estimate Amount	: S\$ <u>14,318.42</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at front portion.



Yours faithfully

XING GUO QIANG
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2017 13:38
Date Of Accident	03/11/2017 14:30
Exact Location Of Accident	ALONG JLN ISHAK & LOR MARICAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE1774A
Insured/Policyholder	
Name Of Registered Owner	LIN JIAHUI DAWN
NRIC No	S8409463C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81285850
Alternative Phone No	OFFICE-81285850

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD16V08996/VPC2/R00
Cover Note Number	

Driver

Name of Driver	TAN AI CHENG
NRIC No	S1387324J
Date Of Birth	08/08/1959
Occupation	INDOOR
Date Of Driving Pass	12/04/1978
Driving Experience	39 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92715848
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	8 JALAN ISHAK
Postcode	419332
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA3339D
Vehicle Make/Model/Colour	TAXI
Details Of Properties	
Name of Driver	LIM YEW KIAT
NRIC/Passport Number	S0461806H
Contact Number	96104694
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	4

Details of Witness

Name	
Phone Number	
Email Address	

Vehicle No SZE 1774B**SKETCH PLAN**

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Please continue to Annex E

Sketch Plan Pg. 2

Vehicle No SL61774A

Annex E

Describe Circumstances of the Accident

On 03/11/17 at 1430hrs. I was travelling along Jln. Ishak, suddenly
this vehicle B came out from Lor Meriam. without noticing there is
stopped fire and bang onto my car A.

SL61774A

Declaration

We declare the foregoing particulars are true in every respect.

AS
an



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1387324J

TAN AI CHENG

CHINESE

08 AUG 1958

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

001171556B

001171556B

S1387324J

08 AUG 1958

SINGAPORE


THE HON. MINISTER OF HOME AFFAIRS

Class 3 Motor Cars and Motor Tractors the weight of which (laden) does not exceed 2500 kilograms 12 Apr 1978


NP 428A

Licence No: S1387324J


 S84094630
 DAWN
 1984
 1984



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS:
 CLASS 2
 ALL OTHERS ARE NOT LICENSED TO DRIVE THEM
 1984



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	9463C

Vehicle Details

Vehicle No.	SLE1774A
Vehicle to be Exported	No
Intended De-registration Date	14 Nov 2017
Vehicle Make	HONDA
Vehicle Model	ODYSSEY 2.4 EXV-S CVT SR NAVI RES
Primary Colour	Red
Manufacturing Year	2016
Engine No.	K24W72012325
Chassis No.	JHMRC1890GC205119
Maximum Power Output	129.0 kW (172 bhp)
Open Market Value	\$33,098.00
Original Registration Date	12 Jul 2016
First Registration Date	12 Jul 2016
Transfer Count	0
Actual ARF Paid	\$38,338.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	11 Jul 2026
PARF Rebate Amount	\$28,753.00

Intended COE Rebate Details

COE Expiry Date	11 Jul 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$57,010.00
COE Rebate Amount	\$49,355.00
Total Rebate Amount	\$78,108.00

The information contained herein is correct as at 14 Nov 2017

OK



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Officer: Serene Lee

Claims No: D17010348 MFSH

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLE1774A
Chassis No : JHMRC1890GC205119
Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES
Owner's Name : LIN JIAHUI, DAWN
Ins Policy No. :
Date of Accident : 3/11/2017

Document No. : SQT17004517 Page 1
Date : 6. Nov 2017
Customer No. : WZF002
Svc Advisor :
Engine No : K24W72012325
Date | Time : 6. Nov 2017 8:02:41 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:LIN JIAHUI DAWN OWNER INSURER:LIBERTY ACC DATE:03/11/2017 SURVEYED BY: DATE: REF NO: TP INSURER:FIRST CAPITAL TP VEH:SHA3339D						
BOSUN	SUNDRIES 9 working day X Repeat	1	100.00	X	100.00	7.00	107.00
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BOMISC1	TO RENEW REAR CAR CAMERA	1	350.00	/	350.00	24.50	374.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N) NN	1	180.00	X	180.00	12.60	192.60
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	80	100.00	7.00	107.00
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	180.00	X	180.00	12.60	192.60
BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN (560)	1	4500.00	2240	2800	315.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3600.00	2700	3600.00	252.00	3852.00
BOMISC1	TO RENEW SEONSOR ASSY AMBINET NN	1	350.00	X	350.00	24.50	374.50
Sum Labor					9460.00	662.20	10,122.20
60100-T6A-000ZZ	1 HOOD COMP / buc	1	658.30	/	493.72	34.56	528.28
74141-T6A-010	2 INSULATORHOOD / Dr	1	92.50	/	69.37	4.86	74.23
80050-SP0-000	3 LABELAIR CONDITIONER CAUTION - AC	1	1.80	/	1.35	0.09	1.44
74147-T6A-003	4 SEAL RUBBERH.HOOD / AC	1	12.90	/	9.67	0.68	10.35
74148-T6A-003	SEAL RUBBERL.HOOD X / AC NN	1	12.90	X	9.67	0.68	10.35
60120-T6A-000ZZ	5 HINGE COMPR.HOOD X / BT	1	46.50	/	34.87	2.44	37.31
60170-T6A-000ZZ	6 HINGE COMPL.HOOD X / BT	1	46.50	/	34.87	2.44	37.31
74120-T6A-003	7 LOCK ASSYHOOD / BT	1	104.20	/	78.15	5.47	83.62
80525-T2F-A01	8 SENSOR ASSYAMBIENT X NN	1	42.60	X	31.95	2.24	34.19



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLE1774A
Chassis No : JHMRC1890GC205119
Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES
Owner's Name : LIN JIAHUI, DAWN
Ins Policy No. :
Date of Accident : 3/11/2017

Document No. : SQT17004517 Page 2
Date : 6. Nov 2017
Customer No. : WZF002
Svc Advisor :
Engine No : K24W72012325
Date | Time : 6. Nov 2017 8:02:41 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incl GST
60210-T6A-300ZZ	8 FENDER COMPR.FR. <i>Blue</i>	1	537.80	25	403.35	28.23	431.58
60260-T6A-300ZZ	9 FENDER COMPL.FR.	1	537.80	25	403.35	28.23	431.58
60400-T6A-310ZZ	10 BULKHEAD COMPR.	1	451.80	25	338.85	23.72	362.57
60433-T6D-H00ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE <i>R</i>	1	32.90	X 25	24.67	1.73	26.40
60483-T6D-H00ZZ	SUPPORTL.FR.BULKHEAD UPP SIDE <i>R</i>	1	32.90	X 25	24.67	1.73	26.40
71121-T6A-003	11 BASEFR.GRILLE <i>Cut</i>	1	165.70	25	124.27	8.70	132.97
71122-T6A-003	12 MOLDINGFR.GRILLE <i>CPA</i>	1	258.10	25	193.57	13.55	207.12
75700-TA0-A00	13 EMBLEMFR. <i>MC</i>	1	25.30	25	18.97	1.33	20.30
90301-ST0-003	14 NUTPUSH 3MM <i>MC</i>	2	1.90	25	2.85	0.20	3.05
04711-T6A-900ZZ	15 FACEFR.BUMPER <i>MC</i>	1	686.30	25	514.72	36.03	550.75
71105-T6A-901	16 GRILLEFR.BUMPER LOWER <i>MC</i>	1	65.80	25	49.35	3.45	52.80
71130-T6A-310ZZ	17 BEAM COMP.FR.BUMPER <i>IST</i>	1	291.80	25	218.85	15.32	234.17
71140-T6A-003	BEAMR.FR.BUMPER UPPER <i>NN</i>	1	34.20	X 25	25.65	1.80	27.45
71151-T6A-911	18 BASEMID GRILLE <i>Cut</i>	1	182.80	25	137.10	9.60	146.70
36560-T6A-J01	CAMERA ASSY MVC FR. <i>NN</i>	1	509.90	X 25	382.42	26.77	409.19
36561-T6A-N01	COVER MVC FR.CAMERA <i>NN</i>	1	8.10	X 25	6.07	0.42	6.49
71152-T6A-921	19 UPPER MOLDINGMID GRILLE <i>NN</i>	1	150.60	25	112.95	7.91	120.86
71153-T6A-921	20 MID MOLDINGMID GRILLE <i>Cut</i>	1	144.20	25	108.15	7.57	115.72
71154-T6A-921	21 LOWER MOLDINGR.MID GRILLE <i>Cut</i>	1	38.70	25	29.02	2.03	31.05
71159-T6A-921	22 LOWER MOLDINGL.MID GRILLE <i>Cut</i>	1	38.70	25	29.02	2.03	31.05
71190-T6A-003	BEAML.FR.BUMPER UPPER <i>NN</i>	1	34.20	X 25	25.65	1.80	27.45
71193-T6A-003	23 SPACERR.FR.BUMPER SIDE <i>MC</i>	1	11.60	25	8.70	0.61	9.31
71198-T6A-003	24 SPACERL.FR.BUMPER SIDE <i>MC</i>	1	11.60	25	8.70	0.61	9.31
91505-TM8-003	25 CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
91578-T0A-003	26 CLIPFR.GRILLE	4	2.20	25	6.60	0.46	7.06
33100-T6A-Q11	27 HEADLIGHT ASSYR.WITH LED <i>CPA</i>	1	2237.30	25	1677.97	117.46	1795.43
33150-T6A-Q11	28 HEADLIGHT ASSYL.WITH LED <i>CPA</i>	1	2237.30	25	1677.97	117.46	1795.43
33950-TY0-003	29 LIGHT ASSY FR.FOG <i>CPA</i>	1	261.80	25	196.35	13.74	210.09
33955-T6A-003	30 BRACKETL.FR.FOGLIGHT <i>CPA</i>	1	62.00	25	46.50	3.26	49.76
71109-T6A-921	31 GARNISHL.FR.BUMPER <i>Cut</i>	1	45.20	25	33.90	2.37	36.27

Printed on 7/11/2017 2:51:49 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLE1774A

Chassis No : JHMRC1890GC205119

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : LIN JIAHUI, DAWN

Ins Policy No. :

Date of Accident : 3/11/2017

Document No. : SQT17004517 Page 3

Date : 6. Nov 2017

Customer No. : WZF002

Svc Advisor :

Engine No : K24W72012325

Date | Time : 6. Nov 2017 8:02:41 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
19010-5X6-J02	RADIATOR COMP	1	1320.90	25	990.67	69.35	1060.02
19015-5X6-J01	SHROUD COMP	1	106.30	25	79.72	5.58	85.30
38615-5X6-J01	SHROUD COMP	1	82.10	25	61.57	4.31	65.88
80111-T6A-003	CONDENSER COMP	1	668.60	25	501.45	35.10	536.55
08CLA-P9911LK8	COOLANTANTI-FREEZE	6	23.20	25	104.40	7.31	111.71
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
Sum Item					9397.62	657.85	10,055.47

Survey By

Date & Time

Excess

Status

Signature

Total Amount 18,857.62 1,320.05 20,177.67

Total (Inclusive of GST) 20,177.67

before paint photos
8 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 7/11/2017 2:51:49 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hour Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	Document No.	: SQT17004840	Page	1
Registration No	: SLE1774A	Date	: 28. Nov 2017		
Chassis No	: JHMRC1890GC205119	Customer No.	: WZF002		
Model	: ODYSSEY2.4 EXV-S 16YM NAVI-RES	Svc Advisor	: LIM CHOU SIONG		
Owner's Name	: LIN JIAHUI, DAWN	Engine No	: K24W72012325		
Ins Policy No.	:	Date Time	: 28. Nov 2017 11:03:14 AM		
Date of Accident	: 3/11/2017	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 69440) OWNER: LIN JIAHUI, DAWN OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 3/11/2017 SURVEYED BY: GUO QIANG (L.K.K.) DATE: 10/11/17 REF NO: TP INSURER: FIRST CAPITAL INSURANCE LTD TP VEH: SHA3339D SUPPLEMENTARY LABOUR & PARTS						
71140-T6A-003	BEAMR.FR.BUMPER UPPER / CRA	2	34.20 X 2	25	25.65	1.80	27.45 X 2
71108-T6A-P00	LOWER PLATEFR.BUMPER / CRA	1	144.20	25	108.15	7.57	115.72
74827-SLE-003	CUSHIONHOOD / NCL	2	6.00	25	9.00	0.63	9.63
					Sum Item	142.80	10.00
							152.80

Survey By	_____						
Date & Time	_____						
Excess	_____						
Status	_____						
Signature	_____						
		Total Amount	142.80	10.00			152.80
		Total (Inclusive of GST)					152.80

19256 07

Printed on 28/11/2017 11:08:51 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Page 1/3
28/11/2017
SERVICE PRE-INVOICE

Attn: Guo Qiang (L.K.K.)

GST Reg No.: M200050223
Company Ref. No.: S80FC1380G

8 days.

Customer:	WZF002 / FIRST CAPITAL	Document No:	SVO17072900
Chassis No:	JHMRC1890GC205119	Printed By:	TWLIEW
License No:	SLE1774A	Order Date:	20. November 2017
Mileage:	21377	Order Time:	10:32:48 AM
Engine No:	K24W72012325	Service Advisor:	STEVEN CHUI FOOK SENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount Includ GST
	TP DIRECT SETTLEMENT (J/NO: 69440)						
	OWNER:LIN JIAHUIO DAWN						
	OWNER INSURER:LIBERTY						
	ACC DATE:03/11/2017						
	SURVEYED BY: GUO QIANG						
	DATE: 10/11/17						
	REF NO: D17010348MFSH						
	TP INSURER:FIRST CAPITAL						
	TP VEH:SHA3339D						
60100-T6A-000ZZ	1 HOOD COMP	1	658.30	25	493.72	34.56	528.28
74141-T6A-010	2 INSULATORHOOD	1	92.50	25	69.37	4.86	74.23
80050-SP0-000	3 LABELAIR CONDITIONER CAUTION	1	1.80	25	1.35	0.09	1.44
74147-T6A-003	4 SEAL RUBBER.HOOD	1	12.90	25	9.67	0.68	10.35
74120-T6A-003	5 LOCK ASSYHOOD	1	104.20	25	78.15	5.47	83.62
60210-T6A-300ZZ	6 FENDER COMPR.FR.	1	537.80	25	403.35	28.23	431.58
60280-T6A-300ZZ	7 FENDER COMPL.FR.	1	537.80	25	403.35	28.23	431.58
60400-T6A-310ZZ	8 BULKHEAD COMPR.	1	451.80	25	338.85	23.72	362.57
71121-T6A-003	9 BASEFR.GRILLE	1	165.70	25	124.27	8.70	132.97
75700-TA0-A00	10 EMBLEMFR.	1	25.30	25	18.97	1.33	20.30
90301-ST0-003	11 NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
04711-T6A-900ZZ	12 FACEFR.BUMPER	1	686.30	25	514.72	36.03	550.75
71105-T6A-901	13 GRILLEFR.BUMPER LOWER	1	65.80	25	49.35	3.45	52.80
71130-T6A-306ZZ	14 BEAM COMPR.BUMPER	1	286.10	25	214.57	15.02	229.59
71151-T6A-911	15 BASEMID GRILLE	1	182.80	25	137.10	9.60	146.70
71152-T6A-921	16 UPPER MOLDINGMID GRILLE	1	150.60	25	112.95	7.91	120.86
71153-T6A-921	17 MID MOLDINGMID GRILLE	1	144.20	25	108.15	7.57	115.72
71154-T6A-921	18 LOWER MOLDINGR.MID GRILLE	1	38.70	25	29.02	2.03	31.05
71159-T6A-921	19 LOWER MOLDINGL.MID GRILLE	1	38.70	25	29.02	2.03	31.05
71193-T6A-003	20 SPACERR.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
71198-T6A-003	21 SPACERL.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
91505-TM8-003	22 CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
91578-T0A-003	23 CLIPFR.GRILLE	4	2.20	25	6.60	0.46	7.06
33100-T6A-Q11	24 HEADLIGHT ASSYR.WITH LED	1	2,237.30	25	1,677.97	117.46	1,795.43
33150-T6A-Q11	25 HEADLIGHT ASSYL.WITH LED	1	2,237.30	25	1,677.97	117.46	1,795.43
08CLA-P9911LK8	26 COOLANTANTI-FREEZE	6	23.20	25	104.40	7.31	111.71
BO-NUM-COMP-S	27 NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
71122-T6A-003	28 MOLDINGFR.GRILLE	1	258.10	25	193.57	13.55	207.12
60433-T6D-H00ZZ	29 SUPPORTR.FR.BULKHEAD UPP SIDE	1	32.90	25	24.67	1.73	26.40
60483-T6D-H00ZZ	30 SUPPORTL.FR.BULKHEAD UPP SIDE	1	32.90	25	24.67	1.73	26.40
80111-T6A-003	31 CONDENSER COMP	1	668.60	25	501.45	35.10	536.55
71109-T6A-921	32 GARNISHL.FR.BUMPER	1	45.20	25	33.90	2.37	36.27
71190-T6A-003	33 BEAML.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71140-T6A-003	34 BEAMR.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71108-T6A-P00	35 LOWER PLATEFR.BUMPER	1	144.20	25	108.15	7.57	115.72
33950-TY0-003	36 LIGHT ASSY FR.FOG	1	261.80	25	196.35	13.74	210.09
33955-T6A-003	37 BRACKETL.FR.FOGLIGHT	1	62.00	25	46.50	3.26	49.76
60120-T6A-000ZZ	38 HINGE COMPR.HOOD	1	46.50	25	34.87	2.44	37.31
60170-T6A-000ZZ	39 HINGE COMPL.HOOD	1	46.50	25	34.87	2.44	37.31



SERVICE PRE-INVOICE

***KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / FIRST CAPITAL
Chassis No: JHMRC1890GC205119
License No: SLE1774A
Mileage: 21377
Engine No: K24W72012325

Document No: SVO17072900
Printed By: TWLIEW
Order Date: 20. November 2017
Order Time: 10:32:48 AM
Service Advisor: STEVEN CHUI FOOK SENG

74827-SLE-003	CUSHIONHOOD (A) RCL	2	6.00	25	9.00	0.63	9.63
			SUM PARTS:		7,948.42	556.40	8,504.82
BOSUN	0672	1	30.00		30.00	2.10	32.10
	SUNDRIES						
BOMISC1	EXT-YJ	1	350.00		350.00	24.50	374.50
	TO RENEW REAR CAR CAMERA						
BML01I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT FR LIGHTING MECHANISMS & FOCUS						
	HEADLIGHTS.(N)						
BMC01D	EXT-YJ	1	180.00		180.00	12.60	192.60
	REMOVE & INSTALL RADIATOR WITH FITTINGS.						
	PRESSURE TEST COOLING SYSTEM.(N)						
BMA01D	EXT-YJ	1	230.00	//	230.00	16.10	246.10
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. (A)						
	VACUUM & RECHARGE A/C GAS.(N)						
BKBH01M	EXT-YJ	1	2,800.00		2,800.00	196.00	2,996.00
	CUT OFF & RENEW BULKHEAD.						
	STRAIGHTEN						
	ALIGN CHASSIS & RENEW DAMAGE PARTS.						
BP06R	EXT-YBH	1	2,700.00		2,700.00	189.00	2,889.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)						
SUM LABOUR:					6,370.00	445.90	6,815.90
TOTAL SGD					14,318.42	1,002.30	15,320.72

Total Payable (SGD) 15,320.72

GST Amount is calculated from individual line(s)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Fédération Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17021428/Grbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-01-2018	
			Code : FCI2	
1. Policy Particulars : THIRD PARTY CLAIM				
Insured Veh.	SHA 3339D	Veh. Inspected	SLE 1774A	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010348MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	09/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMRC1890GC205119	Colour	RED	
Odometer	20893	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	DUNLOP	6 mm	
L/H Front Tyre	215/55 R17	DUNLOP	6 mm	
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/11/2017	Inspection Date	10/11/2017	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1774A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	REPEATED	100.00	-
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	HOOD COMP (SN)	BUCKLED	493.72	493.72
1	INSULATOR HOOD (SN)	DEFORMED	69.37	69.37
1	LABELAIR CONDITIONER CAUTION (SN)	NECESSARY	1.35	1.35
1	SEAL RUBBER. HOOD (SN)	NECESSARY	9.67	9.67
1	HINGE COMPR.HOOD (SN)	BENT	34.87	34.87
1	HINGE COMPL.HOOD (SN)	BENT	34.87	34.87
1	LOCK ASSYHOOD (SN)	BENT	78.15	78.15
1	SENSOR ASSYAMBIELT (SN)	NOT NECESSARY	31.95	-
1	FENDER COMPR.FR (SN)	BUCKLED	403.35	403.35
1	FENDER COMPL.FR (SN)	BUCKLED	403.35	403.35
1	BULKHEAD COMPFR (SN)	BUCKLED	338.85	338.85
1	SUPPORTR.FR.BULKHEAD UPP SIDE (SN)	BENT	24.67	24.67
1	SUPPORTL.FR.BULKHEAD UPP SIDE (SN)	BENT	24.67	24.67
1	BASEFR.GRILLE (SN)	CUT	124.27	124.27
1	MOLDINGFR.GRILLE (SN)	CRACKED	193.57	193.57
1	EMBLEMFR (SN)	NECESSARY	18.97	18.97
2	NUTPUSH 3MM (SN)	NECESSARY	2.85	2.85
1	FACEFR.BUMPER (SN)	DEFORMED	514.72	514.72
1	GRILLEFR.BUMPER LOWER (SN)	DEFORMED	49.35	49.35
1	BEAM COMP,FR.BUMPER (SN)	BENT	218.85	214.57
1	BEAMR.FR.BUMPER UPPER (SN)	NOT NECESSARY	25.65	-
1	BASEMID GRILLE (SN)	CUT	137.10	137.10
1	CAMERA ASSYMVC FR (SN)	NOT NECESSARY	382.42	-
1	COVERMVC FR.CAMERA (SN)	NOT NECESSARY	6.07	-
1	UPPER MOLDINGMID GRILLE (SN)	CUT	112.95	112.95
1	MID MOLDINGMID GRILLE (SN)	CUT	108.15	108.15
1	LOWER MOLDINGR.MID GRILLE (SN)	CUT	29.02	29.02
1	LOWER MOLDINGL.MID GRILLE (SN)	CUT	29.02	29.02
1	BEAML.FR.BUMPER UPPER (SN)	NOT NECESSARY	25.65	-

Report Ref No. CS/FCI17021428/Grbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPACERR.FR.BUMPER SIDE (SN)	NECESSARY	8.70	8.70
1	SPACERL.FR.BUMPER SIDE (SN)	NECESSARY	8.70	8.70
14	CLIPBUMPER (SN)	NECESSARY	21.00	21.00
4	CLIPFR.GRILLE (SN)	NECESSARY	6.60	6.60
1	HEADLIGHT ASSYR.WITH LED (SN)	CRACKED	1,677.97	1,677.97
1	HEADLIGHT ASSYL.WITH LED (SN)	CRACKED	1,677.97	1,677.97
1	LIGHT ASSY FR.FOG (SN)	CRACKED	196.35	196.35
1	BRACKETL.FR.FOGLIGHT (SN)	CRACKED	46.50	46.50
1	GARNISHL.FR.BUMPER (SN)	CUT	33.90	33.90
1	RADIATOR COMP (SN)	NOT NECESSARY	990.67	-
1	SHROUD COMP (SN)	NOT NECESSARY	79.72	-
1	SHROUD COMP (SN)	NOT NECESSARY	61.57	-
1	CONDENSER COMP (SN)	CUT	501.45	501.45
6	COOLANT ANTI-FREEZE (SN)	CUT	104.40	104.40
1	NUMBER PLATE WITH CASING (SN)	BENT	45.00	45.00
1	SEAL RUBBERL.HOOD (SN)	NOT NECESSARY	9.67	-
1	BEAMR.FR.BUMPER UPPER (SN) (ADDITIONAL)	CRACKED	25.65	25.65
1	BEAML.FR.BUMPER UPPER (SN) (ADDITIONAL)	CRACKED	25.65	25.65
1	LOWER PLATEFR.BUMPER (SN) (ADDITIONAL)	CRACKED	108.15	108.15
2	CUSHIONHOOD (SN) (ADDITIONAL)	NECESSARY	9.00	9.00
			9,766.07	7,978.42
	LABOUR			
	TO RENEW REAR CAR CAMERA.		350.00	350.00
	REMOVE & RENEW REVERSE SENSOR - 4 PCS.	NOT NECESSARY	180.00	-
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		100.00	80.00
	REMOVE & INSTALL RADIATOR WITH FITTINGS.		180.00	180.00
	CUT OFF & RENEW BULKHEAD. STRAIGHTEN.		4,500.00	2,800.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)		3,600.00	2,700.00
	TO RENEW SENSOR ASSY AMBINET.	NOT NECESSARY	350.00	-
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. (ADDITIONAL)		230.00	230.00
			9,490.00	6,340.00

Report Ref No. CS/FCI17021428/Grbe2



GRAND TOTAL		19,256.07	14,318.42
RECOMMENDED COST OF REPAIRS			14,318.42

Report Ref No. CS/FCI17021428/Grbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.