

ASS REC BY:

REF:

CG3/ALH1701187/Crb-1

Special Instructions:

3AR &amp; Days

Subject:

Richard

ASSIGNMENT (Office)

From (Person):

Jogne

of

ALH

Date/Time:

09-11-2017

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB 7037H

Insured:

SJD 9715Y

at Workshop m/s

Precise Auto

Tel:

6745 7367

of

Bite 1 Kaka Bukit Ave 6 #02-314

Policy No:

Claim No:

541270236586003

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04-06-07

(Client's Record)

CA / REV / REP. / REV 24 HRS (WP)

H.O.D. Endorsement

Date/Time:

15-06-2017 10:29am

Person Contacted:

Anne

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SKB 7037H - NW / ALH1701187 / K4
	SJD 9715Y - X
	Dismantle Part - 16-06-2017
	After repair - 22-06-2017
	Submit L/S \$8000, 7 days
	Red: \$5500, 41%.

RECEIVED 01 DEC 2017

PAS  
RICHARD

REF: A11

# ASSIGNMENT

From: Date: 15062017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB 7137H

at Workshop m/s: Precise Auto

of: B1k 1 Koki Bukit Ane6 #02-34

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKB 7037H Yr Regn: 2011 23/06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: FORD SMAX cc 1999

Colour: WHITE A/C Insured / Std / NI / NA

Sp. Reading: 66810 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WFO SXX GOWS BK 66298

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R17

R: 225/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 04/06 15:20 D.O.I: 15/6 3.30pm

Survey held at: PRECISE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) 24/72017

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$)

☐ : Prel. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS: \$

☐ Photos

☐ Cites

TOTAL:

180

20

200

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17011617/rb-1

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 09-11-2017



Code : AIG

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJD 9715Y	Veh. Inspected	SKB 7037H
Policy No.		Coverage (\$)	0.00
Claim No.	5412703365SG003	Excess (\$)	0.00
Assign From	JOANE	Assign Date	09/11/2017

**2. Vehicle Particulars & Condition**

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	04/06/2017	Inspection Date	09/11/2017
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Catherine Chong (LKK Auto)

---

**From:** Boyogan, Joane <Joane.Boyogan@aig.com>  
**Sent:** Thursday, 9 November, 2017 4:51 PM  
**To:** admin-d@lkkauto.com  
**Cc:** Hsiao Tong (chewht@lkkauto.com)  
**Subject:** #5412703365SG003#027#paper resurvey for SKB7037H  
**Attachments:** 5412703365SG\_tp survey.pdf

Dear Catherine,

Noted that LKK has conducted PRI on third party vehicle SKB7037H

Kindly assist to review enclosed survey report from third party and let us have your recommendation on COR & estimated days to repair

Appreciate if we can have your advice urgently on this matter

Thank you

Regards,

Joane Boyogan  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120  
Tel +64191898 | Fax +68357416  
[joane.boyogan@aig.com](mailto:joane.boyogan@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

### IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

# MOTORCAR (Rear)

SKB 7037 H

NAC	INC	Item	CON	ACC	DB
121	993026	Rear Number Plate			
122	993027	Rear Number Plate Base			
123	993030	Rear Number Plate Garnish			
124	993032	Rear Number Plate Lamp			
125	993033	Rear Bumper	BR	✓	1
126	993035	Rear Bumper Lower			
127	993037	Rear Bumper Lower			
128	993039	Rear Bumper Side RH corner	DB	✓	1
129	993040	Rear Bumper Top Cover			
130	993041	Rear Bumper Top	ML	✓	1
131	993076	Rear Bumper Bracket	RH	BR	✓ 1
132	993088	Rear Bumper Side Retainer	RH	BR	✓ 1
133	993142	Rear Bumper Reinforcement	DB	✓	1
134	993170	Rear Bumper Beam			
135	993171	Rear Bumper Sponge			
136	993199	Rear Bumper Damper			
137	993042	Rear Bumper Protector			
138	993056	Rear Bumper Pad			
139	993029	Rear Bumper Moulding			
140	993044	Rear Bumper Reflector	RH	DB	✓ 1
141	993023	Rear Bumper Lower Spoiler			
142	994023	Reverse Sensor	DM	✓	1
143	993327	Rear End Panel			
144	993339	Rear End Panel Top Garnish			
145	993333	Rear End Panel Inner Trim			
146	993333	Boot Compartment Inner Trim			
147	993351	Rear LH Taillamp			
148	993352	Rear LH Taillamp Garnish			
149	993359	Rear LH Taillamp Panel			
150	993116	Rear RH Taillamp			
151	993353	Rear RH Taillamp Garnish			
152	993359	Rear RH Taillamp Panel			
153	993354	Rear Apron Panel			
154	992853	Bootlid			
155	991328	Bootlid Emblem			
156	990356	Bootlid Handle			
157	990350	Bootlid Moulding			
158	990376	Bootlid Reflector			
159	990222	Bootlid Lamp LH			
160	992139	Bootlid Lamp RH			
161	990243	Bootlid Lock			
162	990377	Bootlid Rubber			
163	990382	Bootlid Hinge			
164	990377	Bootlid Spoiler			
165	994243	Tailgate	DT	R	
166	991323	Tailgate Emblem			
167	994243	Tailgate Outer Handle			
168	994243	Tailgate Moulding	DB	✓	1
169	994243	Tailgate Garnish			
170	994243	Tailgate Reflector			
171	994243	Tailgate Lamp			
172	994243	Tailgate Protector			
173	994276	Tailgate Water Arm			
174	994277	Tailgate Water Blade			
175	994278	Tailgate Water Nozzle			
176	994279	Tailgate Water Motor			
177	994300	Tailgate Glass			
178	994300	Tailgate Glass Rubber			
179	994304	Tailgate Glass Moulding			
180	994307	Tailgate Glass Sealant			
181	994309	Tailgate Lock			
182	994309	Tailgate Rubber			
183	994309	Tailgate Hinge			
184	994309	Tailgate Damper			
185	994309	Tailgate Inner Board			

NAC	INC	Item	CON	ACC	DB
121	993026	Rear Number Plate			
122	993027	Rear Number Plate Base			
123	993030	Rear Number Plate Garnish			
124	993032	Rear Number Plate Lamp			
125	993033	Rear Bumper			
126	993035	Rear Bumper Lower			
127	993037	Rear Bumper Lower			
128	993039	Rear Bumper Side RH corner			
129	993040	Rear Bumper Top Cover			
130	993041	Rear Bumper Top			
131	993076	Rear Bumper Bracket			
132	993088	Rear Bumper Side Retainer			
133	993142	Rear Bumper Reinforcement			
134	993170	Rear Bumper Beam			
135	993171	Rear Bumper Sponge			
136	993199	Rear Bumper Damper			
137	993042	Rear Bumper Protector			
138	993056	Rear Bumper Pad			
139	993029	Rear Bumper Moulding			
140	993044	Rear Bumper Reflector			
141	993023	Rear Bumper Lower Spoiler			
142	994023	Reverse Sensor			
143	993327	Rear End Panel			
144	993339	Rear End Panel Top Garnish			
145	993333	Rear End Panel Inner Trim			
146	993333	Boot Compartment Inner Trim			
147	993351	Rear LH Taillamp			
148	993352	Rear LH Taillamp Garnish			
149	993359	Rear LH Taillamp Panel			
150	993116	Rear RH Taillamp			
151	993353	Rear RH Taillamp Garnish			
152	993359	Rear RH Taillamp Panel			
153	993354	Rear Apron Panel			
154	992853	Bootlid			
155	991328	Bootlid Emblem			
156	990356	Bootlid Handle			
157	990350	Bootlid Moulding			
158	990376	Bootlid Reflector			
159	990222	Bootlid Lamp LH			
160	992139	Bootlid Lamp RH			
161	990243	Bootlid Lock			
162	990377	Bootlid Rubber			
163	990382	Bootlid Hinge			
164	990377	Bootlid Spoiler			
165	994243	Tailgate			
166	991323	Tailgate Emblem			
167	994243	Tailgate Outer Handle			
168	994243	Tailgate Moulding			
169	994243	Tailgate Garnish			
170	994243	Tailgate Reflector			
171	994243	Tailgate Lamp			
172	994243	Tailgate Protector			
173	994276	Tailgate Water Arm			
174	994277	Tailgate Water Blade			
175	994278	Tailgate Water Nozzle			
176	994279	Tailgate Water Motor			
177	994300	Tailgate Glass			
178	994300	Tailgate Glass Rubber			
179	994304	Tailgate Glass Moulding			
180	994307	Tailgate Glass Sealant			
181	994309	Tailgate Lock			
182	994309	Tailgate Rubber			
183	994309	Tailgate Hinge			
184	994309	Tailgate Damper			
185	994309	Tailgate Inner Board			

Rear RH fender NOT changed and door (put in position)

Tailgate deformed NC

hit @ Rear RH corner by white volvo sedan

9 RICHARD

21/2

4 days

21/11/17

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 05/06/2017 19:11  
Date Of Accident 04/06/2017 15:20  
Exact Location Of Accident CARPARKS ENTRANCE OF PUNGGOL WATERWAY POINT  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SKB7037H  
**Insured/Policyholder**  
Name Of Registered Owner JOSEPH ONG  
NRIC No S7519164B  
Email Address JOSEPH.ONG.75@GMAIL.COM  
Mobile Phone No (LOCAL) +65-97424440  
Alternative Phone No OTHERS-97424440

### Vehicle Particulars

Manufacturer FORD  
Model S-MAX 2.0 TITANIUM ECOBOOST  
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company UNITED OVERSEAS INSURANCE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number DHOM120009391500  
Cover Note Number

### Driver

Name of Driver JOSEPH ONG  
NRIC No S7519164B  
Date Of Birth 29/05/1975  
Occupation OUTDOOR  
Date Of Driving Pass 21/07/1998  
Driving Experience 18 YEARS AND 10 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-97424440  
Fax Number  
Contact Number OTHERS-97424440  
Email Address JOSEPH.ONG.75@GMAIL.COM

Approximate Age  
Injuries Sustain SLIGHT  
Injured person in which vehicle? SKB7037H  
Were seat belts worn? YES  
Was injured conveyed to hospital by ambulance?  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name CHUA CHENG CHENG  
Approximate Age  
Injuries Sustain SLIGHT  
Injured person in which vehicle? SKB7037H  
Were seat belts worn? YES  
Was injured conveyed to hospital by ambulance?  
Address  
Postcode

#### DETAILS OF INJURED PERSON 3

Name BESSY CKRE  
Approximate Age  
Injuries Sustain SLIGHT  
Injured person in which vehicle? SKB7037H  
Were seat belts worn? YES  
Was injured conveyed to hospital by ambulance?  
Address  
Postcode

#### DETAILS OF INJURED PERSON 4

Name ONG JOLHE SCRAH  
Approximate Age  
Injuries Sustain SLIGHT  
Injured person in which vehicle? SKB7037H  
Were seat belts worn? YES  
Was injured conveyed to hospital by ambulance?  
Address  
Postcode

#### DETAILS OF INJURED PERSON 5

Name ONG JCRED GABRIEL  
Approximate Age  
Injuries Sustain SLIGHT  
Injured person in which vehicle? SKB7037H  
Were seat belts worn? YES  
Was injured conveyed to hospital by ambulance?  
Address  
Postcode




# Sketch Plan #2


## Describe Circumstances of the Accident


On 04/06/2017 at about 1520 hrs I was stationary at the Park Entrance of Hargrove University Port in vehicle waiting for my going vehicle. Whilst I was waiting to see a few times but I still keep stationary. Whilst I was waiting I saw a car move on while I was just about to wave. Suddenly I felt an impact from behind when I came out my car and I realised that vehicle (SID 97154) collided onto the right portion of my car while car B filtering into the right lane. Hence I wrote below this report to claim vehicle B's insurance for car accident damages to my car and passenger injuries due to this accident.

## Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time  
 5/6/17  
 1-20 PM

Driver's Signature (If driver is not the policyholder) / Date & Time  
 5/6/17 1-20 PM

Witnessed by Reporting Centre Personnel  
 5/6/17

Insurance Co.	AIG Insurance	
Vehicle NO.	2017 TH	Date Of Accident 04/06/17
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input type="checkbox"/> Third Party Claim		



## LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17011617/JBE2

Date: 28/07/2017

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
 Claimant Vehicle No: SKB7037H Insured Vehicle No: SJD9715Y  
 Date of Loss: 04/06/2017 Nature of Claim: TP Claim No: 5412703365SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKB7037H  
 Make & Model: FORD S-MAX, 2.0 Ecoboost Titanium (A) Engine No: BK66298  
 Reg. Date: 23/06/2011 (Man. Year: 2011) Chassis No: WF0SXXGBWSBK66298  
 Colour: White Odometer: 66810 km  
 Engine Capacity: 1999 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 225/50/17 Rear Tyre Size: 225/50/17  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 15/06/2017  
 Date Inspected: 15/06/2017 Inspected At: Precise Auto Service (HQ)  
 No 1 Kaki Bukit Ave 6, #02-34/36  
 Singapore 417883  
 Estimated Period of Repair: 4.0 days

Adjuster: Richard Harjanto

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*-F
2	1		*REAR BUMPER SIDE RH CORNER	Deformed	0.00 F	*-F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
4	1		*REAR BUMPER BRACKET RH	Broken	0.00 F	*-F
5	1		*REAR BUMPER SIDE RETAINER RH	Broken	0.00 F	*-F
6	1		*REAR BUMPER REINFORCEMENT	Deformed	0.00 F	*-F
7	1		*REAR BUMPER REFLECTOR RH	Damaged	0.00 F	*-F
8	1		*REVERSE SENSOR	Damaged	0.00 F	*-F
9	1		*TAILGATE	Repair	0.00 F	*-F
10	1		*TAILGATE MOULDING PANEL	Deformed	0.00 F	*-F
11	1		*REAR EXHAUST RH MUFFLER	* Check	0.00 F	*-F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

PHOTOCOPY

## PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

=====

Accident Date : 04-06-17

OUR REF : SKB 7037H/T/17

## TAX INVOICE

JOSEPH ONG

50 NEWTON ROAD

#18-02

SINGAPORE 307991

Invoice No. : TP1709-006

DATE : 03-09-17

FINAL BILL ON VEH. NO. : SKB 7037H

VEHICLE MODEL : FORD S-MAX

PART BY PART REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

13,500.00

SUB-TOTAL : 13,500.00

ADD GST 7% : 945.00

TOTAL AMOUNT SGD : 14,445.00

This is a computer generated document and requires no signature.

# CHARTERED AUTO ASSESSORS

17 Joo Seng Road #08-129 Joo Seng Heights Singapore 360017 Reg No. 26910200X  
Tel: +65 9631 7008 Fax: +65 6281 9989 Email: charteredauto@gmail.com

Joseph Ong  
50 Newton Road #18-02  
Singapore, 307991

Your Ref : SKB 7037 H  
Our Ref : 201706194/CA  
Date : 12 August, 2017  
Survey : Third Party

## SURVEY REPORT

### PARTICULARS OF VEHICLE

Vehicle No. : SKB 7037 H  
Make : Ford  
Type of Body : 5 Doors MPV  
Year & Model : 2011, S-Max  
Colour : White  
Passenger-cap : 5

Propellant : Petrol, Auto  
Capacity : 2000 cc  
Mileage : 66810  
Engine No : BK66298  
Chassis No : WFOSXXGBWSK66298  
Road Tax : December, 2017

### TYRES CONDITIONS

Front Left	: Pirelli	Worn : 30%	Size : 225/50 R17
Front Right	: Pirelli	Worn : 30%	Size : 225/50 R17
Rear Left	: Pirelli	Worn : 30%	Size : 225/50 R17
Rear Right	: Pirelli	Worn : 30%	Size : 225/50 R17

### PRE-ACCIDENT CONDITION (Static Test Only)

Handbrake : Serviceable  
Footbrake : Serviceable

Steering : Serviceable  
Paintwork : Good

### QUANTUM

Repair Estimate : \$ 17,530.00  
Revised Amount : \$ 13,500.00 (Lump-sum Without Prejudice)

Under normal circumstances, the repair period would be: **twelve ( 12 )** days.  
We **have not** authorised repairs.

Survey Done At : Precise Auto Service  
1 Kaki Bukit Avenue 6, #02-34/36  
Autobay @ Kaki Bukit  
Singapore, 417883

Assignment Date : 15 June, 2017  
Survey Date : 15 June, 2017  
Accident Date : 04 June, 2017  
Assignment Given By : Joseph Ong

Our Ref: 201706194/CA

Vehicle No. SKB 7037 H

Description	Qty	Repair Estimate	Revised Amount	Remarks
Rear bumper fascia	1	950.00	950.00	Torn/Deformed
Rear bumper side o/s	1	320.00	320.00	Torn/Deformed
Rear bumper exhaust guide o/s	1	125.00	125.00	To replace BT
Rear bumper reinforcement	1	1,095.00	1,095.00	Bent
Rear bumper side retainer o/s	1	94.00	94.00	To replace OIS
Rear bumper reflector o/s	1	160.00	160.00	Holder Broken
Rear bumper side retainer rivert o/s	7	48.00	48.00	To replace NIEC
Rear bumper inner centre garnish	1	680.00	680.00	Torn/Deformed
Tailgate assy	1	3,400.00	3,400.00	Bent
Tailgate weatherstrip	1	330.00	330.00	Torn/Deformed
Tailgate lower outer garnish	1	190.00	190.00	Grazed/Deformed
Tailgate lower outer garnish clip	14	84.00	60 84.00	To replace NEC
Tailgate stopper o/s & n/s	2	24.00	24.00	To replace X SJC
Tailgate lock	1	720.00	720.00	Bent
Tailgate ECOBOOST emblem	1	65.00	65.00	To replace 3 NEC
Tailgate FORD badge	1	71.00	71.00	To replace
Tailgate damper o/s	1	230.00	230.00	Bent X SJC
Tailgate inner trimboard	1	640.00	640.00	Torn/Deformed X NN
Tailgate inner trimboard clip	12	72.00	72.00	To replace NEC
Tailgate outer chrome moulding	1	260.00	260.00	Holder Broken X NN
Tailgate lock striker	1	35.00	35.00	Bent X SJC
Tailgate lower outer garnish bracket top & lower	2	52.00	52.00	To replace X NN
Tailgate lower outer garnish bracket rivert	2	18.00	18.00	To replace X NN
Rear windscreen seal	1	120.00	120.00	To replace
Rear windscreen clip	12	72.00	72.00	To replace 3 NEC
Rear windscreen sealant	1	80.00	60 80.00	To replace
Rear end panel top trim	1	175.00	175.00	Torn/Deformed X NN
Rear end panel top trim clip	4	24.00	24.00	To replace NEC
Rear exhaust silencer o/s	1	1,850.00	1,850.00	Bent X NN
Rear exhaust silencer hook o/s	1	48.00	48.00	To replace X NN
Rear fender inner trimboard o/s	1	590.00	590.00	Torn/Deformed X NN
Rear fender inner trimboard clip o/s	8	48.00	48.00	To replace X NN
		12,670.00	12,670.00	
		-	1,267.00	Less 10 %
		12,670.00	11,403.00	
Rear bumper sensor c/w box ( 4 pcs )	S.Nett 1 set	520.00	520.00	Damaged 250
<b>Total Materials Cost :</b>		<b>13,190.00</b>	<b>11,923.00</b>	

Our Ref: 201706194/CA

Vehicle No. SKB 7037 H

Description	Qty	Repair Estimate	Revised Amount	Remarks
Balance brought forward		13,190.00	11,923.00	
To remove/refit wire harness, all related connectors. Check proper function.		120.00	80.00	30
To apply underseal and rust-proofing on the affected areas.		180.00	150.00	50
To remove/refit boot garnishes, speakers, interior garnishes, carpets where necessary.		180.00	150.00	60
To transfer tailgate mechanisms with motor assembly and all attachments.		220.00	180.00	60
To remove/refit rear windscreen glass.		180.00	120.00	
To install four pieces reverse sensors, control unit. Re-connect wires harness. Check function.		250.00	220.00	80
To remove/replace o/s rear exhaust assembly with all attachments, brackets and holders. Straighten and align centre connecting exhaust pipe.		280.00	250.00	X
To putty & spray paint rear bumper, rear bumper side o/s, tailgate, tailgate outer garnish rear panel, o/s rear fender & ect's., inclusive of painting materials.		1,300.00	1,200.00	900
To perform diagnostic checks on control units. Reset to factory specifications		380.00	320.00	150
To remove all damaged parts with all necessary components/attachments. To apply hot-works where necessary, straighten chassis members, repair/reshape dented body panels, in accordance with factory specifications. Replace damaged parts, refit and align into position. Refit all necessary components/attachments.		1,250.00	1,100.00	600
<b>Grand Total:</b>		<b>17,530.00</b>	<b>15,693.00</b>	7 days

#### Summary

Total Material	13,190.00	11,923.00
Total Labour/Painting	4,340.00	3,770.00
Grand Total	17,530.00	15,693.00
Lump-sum Amount		<u>13,500.00</u>



Our Ref: 201706194/CA

Vehicle No. SKB 7037 H

**CAUSE OF DAMAGE**

The vehicle sustained impact to the rear, more to the offside.


**REMARKS**

Having checked the scope of repair works we were satisfied that it was in accordance with the damage sustained. We also checked each item and have indicated its nature of damage. It was our opinion that these items were found damaged beyond repair and require replacement.

We checked the damage carefully and were of the opinion that the vehicle could be repaired.  
We would therefore recommend repairs to be carried out at: **\$ 13,500.00** on a lump-sum basis.

The survey was conducted on a without prejudice basis and we submit this report for your consideration.

CHARTERED AUTO ASSESSORS

---

Tan Chin Suan (Licensed Appraiser)  
AMJML, T Eng (CEB) A.I.M. (U.K)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CS3/AIG17011617/Crbe2-1	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 04-12-2017	
			Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJD 9715Y	Veh. Inspected	SKB 7037H	
Policy No.		Coverage (\$)	0.00	
Claim No.	5412703365SG003	Excess (\$)	0.00	
Assign From	JOANE	Assign Date	09/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	FORD S-MAX	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WF0SXXGBWSBK66298	Colour	WHITE	
Odometer	66810	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	PIRELLI	6 mm	
L/H Front Tyre	225/50 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/06/2017	Inspection Date	15/06/2017	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 7037H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER FASCIA	TORN / DEFORMED	950.00	950.00
1	REAR BUMPER SIDE O/S	TORN / DEFORMED	320.00	320.00
1	REAR BUMPER EXHAUST GUIDE O/S	BENT	125.00	125.00
1	REAR BUMPER REINFORCEMENT	BENT	1,095.00	1,095.00
1	REAR BUMPER SIDE RETAINER O/S	DISTORTED	94.00	94.00
1	REAR BUMPER REFLECTOR O/S	HOLDER BROKEN	160.00	160.00
7	REAR BUMPER SIDE RETAINER RIVERT O/S	NECESSARY	48.00	48.00
1	REAR BUMPER INNER CENTRE GARNISH	TORN / DEFORMED	680.00	680.00
1	TAILGATE ASSY	BENT	3,400.00	3,400.00
1	TAILGATE WEATHERSTRIP	TORN / DEFORMED	330.00	330.00
1	TAILGATE LOWER OUTER GARNISH	GRAZED / DEFORMED	190.00	190.00
14	TAILGATE LOWER OUTER GARNISH CLIP	NECESSARY	84.00	60.00
2	TAILGATE STOPPER O/S & N/S	SERVICEABLE	24.00	-
1	TAILGATE LOCK	BENT	720.00	720.00
1	TAILGATE ECOBOOST EMBLEM	NECESSARY	65.00	65.00
1	TAILGATE FORD BADGE	NECESSARY	71.00	71.00
1	TAILGATE DAMPER O/S	SERVICEABLE	230.00	-
1	TAILGATE INNER TRIMBOARD	NOT NECESSARY	640.00	-
12	TAILGATE INNER TRIMBOARD CLIP	NECESSARY	72.00	72.00
1	TAILGATE OUTER CHROME MOULDING	NOT NECESSARY	260.00	-
1	TAILGATE LOCK STRIKER	SERVICEABLE	35.00	-
2	TAILGATE LOWER OUTER GARNISH BRACKET TOP & LOWER	NOT NECESSARY	52.00	-
2	TAILGATE LOWER OUTER GARNISH BRACKET RIVERT	NOT NECESSARY	18.00	-
1	REAR WINDSCREEN SEAL	NECESSARY	120.00	120.00
12	REAR WINDSCREEN CLIP	NECESSARY	72.00	72.00
1	REAR WINDSCREEN SEALANT	NECESSARY	80.00	60.00
1	REAR END PANEL TOP TRIM	NOT NECESSARY	175.00	-
4	REAR END PANEL TOP TRIM CLIP	NECESSARY	24.00	24.00
1	REAR EXHAUST SILENCER O/S	NOT NECESSARY	1,850.00	-

Report Ref No. CS3/AIG17011617/Crbe2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SILENCER HOOK O/S	NOT NECESSARY	48.00	-
1	REAR FENDER INNER TRIMBOARD O/S	NOT NECESSARY	590.00	-
8	REAR FENDER INNER TRIMBOARD CLIP O/S	NOT NECESSARY	48.00	-
	LESS 10% DISCOUNT		-	-865.60
			12,670.00	7,790.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
4	REAR BUMPER SENSOR C/W BOX	DAMAGED	520.00	250.00
			520.00	250.00
	<b><u>LABOUR</u></b>			
	TO REMOVE / REFIT WIRE HARNESS, ALL RELATED CONNECTORS. CHECK PROPER FUNCTION.		120.00	30.00
	TO APPLY UNDERSEAL AND RUST-PROOFING ON THE AFFECTED AREAS.		180.00	50.00
	TO REMOVE / REFIT BOOT GARNISHES, SPEAKERS, INTERIOR GARNISHES, CARPETS WHERE NECESSARY.		180.00	60.00
	TO TRANSFER TAILGATE MECHANISMS WITH MOTOR ASSEMBLY AND ALL ATTACHMENTS.		220.00	60.00
	TO REMOVE / REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO INSTALL FOUR PIECES REVERSE SENSORS, CONTROL UNIT. RE-CONNECT WIRES HARNESS. CHECK FUNCTION.		250.00	80.00
	TO REMOVE / REPLACE O/S REAR EXHAUST ASSEMBLY WITH ALL ATTACHMENTS, BRACKETS AND HOLDERS. STRAIGHTEN AND ALIGN CENTRE CONNECTING EXHAUST PIPE.	NOT NECESSARY	280.00	-
	TO PUTTY & SPRAY PAINT REAR BUMPER, REAR BUMPER SIDE O/S, TAILGATE, TAILGATE OUTER GARNISH REAR PANEL, O/S REAR FENDER & ETC. INCLUSIVE OF PAINTING MATERIALS.		1,300.00	900.00
	TO PERFORM DIAGNOSTIC CHECKS ON CONTROL UNITS. RESET TO FACTORY SPECIFICATIONS.		380.00	150.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS. TO APPLY HOT-WORKS WHERE NECESSARY, STRAIGHTEN CHASSIS MEMBERS, REPAIR / RESHAPE DENTED BODY PANELS, IN ACCORDANCE WITH FACTORY SPECIFICATIONS. REPLACE DAMAGED PARTS, REFIT AND ALIGN INTO POSITION. REFIT ALL NECESSARY COMPONENTS/ ATTACHMENTS.		1,250.00	600.00
			4,340.00	2,050.00
GRAND TOTAL			17,530.00	10,090.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,000.00

Report Ref No. CS3/AIG17011617/Crbe2-1

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.