



Your Ref: MN.IG.L1.1711361A

Date: 12th December 2017

Our Ref: CS1/LAW17021451/M1tbs2

M/s M Nedumaran & Co

No. 11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

SDL 190Z

INSURED VEHICLE: SKF 5513S

ACCIDENT DATE: 29/12/2016

We thank you for your instruction on 27/10/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDL 190Z from M/s Absolute Appraisal Services Loss Adjusters & Motor Appraisers.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Final Repair Bill of SDL 190Z from M/s Lian Heng Painter Company .
- d) Singapore Accident Statement of Vehicles SDL 190Z and SKF 5513S.
- e) Colour damaged vehicle photographs of SDL 190Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDL 190Z
Make & Model	: Mercedes SLK 280 (A)
Year of Registration	: 2007
Chassis Number	: WDB1714542F174454
Engine Capacity	: 1997 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.