



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDL 190Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH DOOR	DENTED	2,740.00	2,740.00
1	RH DOOR GLASS RUN MOULDING	NOT NECESSARY	157.00	-
1	RH DOOR OUTER HANDLE SIDE	SERVICEABLE	63.00	-
1	RH DOOR KEY INSERT	SERVICEABLE	220.00	-
1	RH DOOR HINGE (TOP)	DISTORTED	125.00	125.00
1	RH DOOR HINGE (LOWER)	DISTORTED	143.00	143.00
1	RH DOOR CHECKER	SERVICEABLE	115.00	-
1	RH DOOR LOCK	DISTORTED	460.00	460.00
1	RH DOOR CATCH	NOT NECESSARY	40.00	-
1	RH DOOR GLASS REGULATOR	BENT	552.00	552.00
1	RH DOOR GLASS REGULATOR MOTOR	MALFUNCTIONED	695.00	695.00
1	RH DOOR SPEAKER	SERVICEABLE	264.00	-
1	RH DOOR CONTROL UNIT	LOOP CRACKED	420.00	420.00
1	RH DOOR BELT WEATHER-STRIP	NECESSARY	123.00	123.00
1	RH DOOR WEATHER-STIP	NECESSARY	255.00	255.00
1	RH DOOR EDGE WEATHER-STRIP	NECESSARY	56.00	56.00
1	RH DOOR TRIM	DEFORMED / CRACKED	985.00	985.00
1	RH STILL PANELLING	DENTED / CUT / CRACKED	720.00	720.00
1	RH STILL PANELLING SEAL	NECESSARY	107.00	107.00
1	RHR FENDER	DENTED	2,300.00	2,300.00
1	RHR SHOCK ABSORBER	NOT NECESSARY	550.00	-
1	RHR WHEEL CARRIER	NOT NECESSARY	1,640.00	-
1	RHR WHEEL FLANGE	NOT NECESSARY	490.00	-
1	RHR WHEEL BEARING	NOT NECESSARY	210.00	-
1	RHR SPRING CONTROL ARM	NOT NECESSARY	470.00	-
1	RHR CAMBER STRUT	NOT NECESSARY	380.00	-
1	RHR STRUT ARM	NOT NECESSARY	275.00	-
1	RHR THRUST ARM	NOT NECESSARY	270.00	-
1	RH DOOR OUTER HANDLE	NOT NECESSARY	465.00	-

Report Ref No. CS1/LAW17021451/M1tbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-968.10
			15,290.00	8,712.90
	<u>SPECIAL NETT ITEMS</u>			
1	RHR SPORT RIM (SN)	DENTED / GRAZED	600.00	600.00
1	RHR TYRE (SN)	NOT NECESSARY	280.00	-
1	JOINT SEALANT (SN)	NECESSARY	60.00	40.00
			940.00	640.00
	<u>LABOUR</u>			
	TO REMOVE & RENEW RHR UNDERCARRIAGES.		300.00	-
	TO RENEW RH SPORT RIM & TYRE.		50.00	20.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO REMOVE & RH DOOR FITTINGS.		150.00	60.00
	TO REMOVE & REFIT REAR TRIMMINGS, REAR CUSHION, ETC.		400.00	100.00
	TO REMOVE & REFIT FUEL TANK.		150.00	80.00
	CHECK LIGHTINGS & WIRINGS.		80.00	30.00
	RUST PROOFING.		200.00	80.00
	TO REMOVE AND RENEW DAMAGED PARTS.		1,500.00	900.00
	TO PUTTY AND RE-SPRAY ALL DAMAGED PARTS.		1,500.00	700.00
			4,450.00	2,050.00
GRAND TOTAL			20,680.00	11,402.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,100.00

Report Ref No. CS1/LAW17021451/M1tbs2

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.