

Surveyor

REF: CSI/LAW17021451/M14052

Special Instruction:

US: \$15250.00

ASSIGNMENT (Office)

From (Person): Irene Lim of M Nedumalan Date/Time: 27-10-2017

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor:

Workshop:

Absolute Appraisal & Furniture

Lian Hong Printer

OD/TP Re-inspection Evaluation

To Inspect Vehicle No:

SDL 190Z

Insured:

SKF 5513S

at Workshop m/s

Lian Hong Printer

Tel:

64535779

of

81k 11 Sda Ming hui est #01-87

Policy No:

BRR/7181/17/nin

Claim No:

MN.IG.LI.1711361A

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29.12.2016

(Client's Record)

SJE

H.O.D. Enforcement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____ days (Red \$ _____ / _____ %; Original 12 days)

Date/Time: 7/12/17 Submit Final Fig 12300, 8 days (Red \$ 2950, 19 %; Original 12 days)

Date/Time	Action/Instruction
	<u>SDL 190Z - CS3/M56/1600/4025/M14052-1</u>
	<u>SKF 5513S - CS/TNC13011533/Kab3</u>
<u>26/2</u>	<u>Re-open to amend report.</u>
<u>26/02/18</u>	<u>Submit LS \$9100.</u>
	<u>1st closed date: 13/12/2017, Reopen by Kim becot has to amend LS to \$9100.</u>
	<u>6/12/2017</u>

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED

\$ 700.00

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

1) Date/Time 7/12/17 File Pass to Typist

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

4) Date/Time _____ File Return to _____

6) Date/Time _____ File Return to _____



LKK Auto Consultancy

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 4060

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDL 190Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH DOOR	DENTED	2,740.00	2,740.00
1	RH DOOR GLASS RUN MOULDING	BENT	157.00	X 157.00
1	RH DOOR OUTER HANDLE SIDE	SERVICEABLE	63.00	-
1	RH DOOR KEY INSERT	SERVICEABLE	220.00	-
1	RH DOOR HINGE (TOP)	DISTORTED	125.00	125.00
1	RH DOOR HINGE (LOWER)	DISTORTED	143.00	143.00
1	RH DOOR CHECKER	SERVICEABLE	115.00	-
1	RH DOOR LOCK	DISTORTED	460.00	460.00
1	RH DOOR CATCH	NOT NECESSARY	40.00	-
1	RH DOOR GLASS REGULATOR	BENT	552.00	552.00
1	RH DOOR GLASS REGULATOR MOTOR	MALFUNCTIONED	695.00	695.00
1	RH DOOR SPEAKER	SERVICEABLE	264.00	-
1	RH DOOR CONTROL UNIT	LOOP CRACKED	420.00	420.00
1	RH DOOR BELT WEATHER-STRIP	NECESSARY	123.00	123.00
1	RH DOOR WEATHER-STIP	NECESSARY	255.00	255.00
1	RH DOOR EDGE WEATHER-STRIP	NECESSARY	56.00	56.00
1	RH DOOR TRIM	DEFORMED / CRACKED	985.00	985.00
1	RH STILL PANELLING	DENTED / CUT / CRACKED	720.00	720.00
1	RH STILL PANELLING SEAL	NECESSARY	107.00	107.00
1	RHR FENDER	DENTED	2,300.00	2,300.00
1	RHR SHOCK ABSORBER	NOT NECESSARY	550.00	-
1	RHR WHEEL CARRIER	DISTORTED	1,640.00	X 1,640.00
1	RHR WHEEL FLANGE	DISTORTED	490.00	X 490.00
1	RHR WHEEL BEARING	DISTORTED	210.00	X 210.00
1	RHR SPRING CONTROL ARM	BENT	470.00	X 470.00
1	RHR CAMBER STRUT	BENT	380.00	X 380.00
1	RHR STRUT ARM	BENT	275.00	X 275.00
1	RHR THRUST ARM	BENT	270.00	X 270.00
1	RH DOOR OUTER HANDLE	NOT NECESSARY	465.00	-
			15,290.00	13,573.00
<u>SPECIAL NETT ITEMS</u>				
1	RHR SPORT RIM (SN)	DENTED / GRAZED	600.00	600.00

Report Ref No. CS1/LAW17021451/M1tbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RHR TYRE (SN)	NOT NECESSARY	280.00	-
1	JOINT SEALANT (SN)	NECESSARY	60.00	40.00
			940.00	640.00
	LABOUR			
	TO REMOVE & RENEW RHR UNDERCARRIAGES.		300.00	X 200.00
	TO RENEW RH SPORT RIM & TYRE.		50.00	20.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO REMOVE & RH DOOR FITTINGS.		150.00	60.00
	TO REMOVE & REFIT REAR TRIMMINGS, REAR CUSHION, ETC.		400.00	100.00
	TO REMOVE & REFIT FUEL TANK.		150.00	80.00
	CHECK LIGHTINGS & WIRINGS.		80.00	30.00
	RUST PROOFING.		200.00	80.00
	TO REMOVE AND RENEW DAMAGED PARTS.		1,500.00	900 1,000.00
	TO PUTTY AND RE-SPRAY ALL DAMAGED PARTS.		1,500.00	700 900.00
			4,450.00	2,550.00
	GRAND TOTAL		20,680.00	16,763.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,300.00

Report Ref No. CS1/LAW17021451/M1tbs2

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.