

ASS. REQ BY

REF CS/FCI17021467/ A76n2

CWS

Adrian

ASSIGNMENT (Office)

From (Person)

Joanne Yong

FCI

Date/Time 5:42pm @ 9/11/17

Estimated Cost

Bill to

OD /  WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SJL 3090M

Insured

SHC 1717Z

at Workshop no.

Kah Motor

Tel

65145687

of 15 Ubi Road 4

Policy No.

Claim No.

D17010433 MFSH

Sum Insured

Excess

Make of Veh:  
(Client's Record)

D.O.A 8/11/2017

13/11/17 @ 10am owner waiting

CA / REV / REP. / REV 24 HRS

'0s'

H.O.D. Endorsement

Date/Time

10/11/17 @ 8:47am

Person Contacted

Mr. Liew

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJL 3090M-X
	SHC1717Z-CC3/EG17011246/A74b372-D.O.A: 7/06/2017
14/11/17 @ 12:09pm	revised to Joanne Yong by email.
	Part by part \$1364.82, 2 days (Red: 458.62:25%)

Summary

ASSIGNMENT

From: \_\_\_\_\_ Date: 13-11-2017

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJL 3090m

at Workshop m/s Kah Motor

of 15 Ubi Rd 4

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Mr. Liew

10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

N/S	O/S

Veh No: SJL3090m. Yr Regn: 2017 / Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic. c.c. 1597

Colour: Grey. A/C: Insured / Std / NI / NA

Sp. Reading: 16300. T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRHFC56506T 001228.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17.  
R: 215/50R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

<u>Front</u>		<u>Rear</u>
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm
L/Bal. <u>96</u> mm		L/Bal. <u>06</u> mm
D.O.A. _____		D.O.I. <u>13/11/17</u>

Survey held at Kah Motor

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>

RECEIVED 18 DEC 2017

Date/Time, File Pass to?  : Preli. Report

1) 13/12 Typset  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: TP

Lump Sum / (B): (\$ 1364.82)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:	<u>100</u>
Transportation:	<u>50</u>
_____ \$ + RS _____ \$	
Photos	<u>15</u>
Others	
TOTAL	<u>165</u>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021467/Atb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 10-11-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1717Z	Veh. Inspected	SJL 3090M
Policy No.		Coverage (\$)	0.00
Claim No.	D17010433MFSH	Excess (\$)	0.00
Assign From	CWS ( JOANNE YONG)	Assign Date	10/11/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	08/11/2017	Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

<b>Date</b>	08-11-2017	<b>Our Ref No.</b> D17010433MFSH
<b>Accident Date</b>	08-11-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC1717Z	<b>Third Party Vehicle.</b> SJL3090M
<b>Survey Location</b>	15 UBI ROAD 4	
<b>Contact Person.</b>	TW LIEW	
<b>Contact No.</b>	65145687/ 0	<b>Fax No.</b> 67480770
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	KAH MOTOR CO SDN BHD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JOANNEY	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229998)



PRI Documents



Close X

## PRI Header Details

<b>Claim No</b>	D17010433MFSH	<b>Policy No</b>	D-15072701MFSH	<b>Claimant S.No &amp; Name</b>	1 & KAH MOTOC
<b>Workshop Name</b>	KAH MOTOR CO SDN BHD (Contact Person : TW LIEW)	<b>Survey Location &amp; Contact Details</b>	15 UBI ROAD 4 <b>Mobile:</b> 0 , <b>Phone:</b> 65145687 , <b>Fax:</b> 67480770 <b>EmailId:</b> TWLIEW@HONDA.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	DIRECT SETTLEMENT:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHC1717Z	<b>TP Vehicle No</b>	SJL3090M
<b>PRI Recieved Date</b>	08-11-2017 10:13:13 PM	<b>Surveyor Appointed Date</b>	09-11-2017 05:41:08 PM	<b>Surveyor Accept Date</b>	10-11-2017 0:

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	10-11-2017	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 14 November, 2017 12:09 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17010433MFSH/1  
**Attachments:** CSFCI17021467Atb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SJL 3090M.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Friday, 10 November, 2017 9:48 AM

**To:** 'Claim Workflow System' <[cwsmotorclaims@first-insurance.com.sg](mailto:cwsmotorclaims@first-insurance.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: SURVEY ASSESSMENT - D17010433MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

**Sent:** Thursday, 9 November, 2017 5:41 PM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [JOANNEYONG@FIRST-INSURANCE.COM.SG](mailto:JOANNEYONG@FIRST-INSURANCE.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D17010433MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010433MFSH

Date: 14 November 2017

Our Ref: CS/FCI17021467/Atb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SJL 3090M**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/11/2017 at the premises of M/s KAH MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,823.44</u>
Revised Estimate Amount	: S\$ <u>1,364.82</u>
"Check" Items Amount	: S\$ <u>10.50</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

ADRIAN LING WAI PING  
*B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI*  
Licensed Appraiser



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

13/11/17 @ 10.00 am

<b>Customer</b>	: FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	<b>Document No.</b>	: SQT17004562	<b>Page</b>	1
<b>Registration No</b>	: SJL3090M	<b>Date</b>	: 8. Nov 2017	<b>Customer No.</b>	: WZF002
<b>Chassis No</b>	: MRHFC5650GT001228	<b>Svc Advisor</b>	: LIEW THYE WEI	<b>Engine No</b>	: R16B21601527
<b>Model</b>	: CIVIC 1.6 VTI YM2016	<b>Date   Time</b>	: 8. Nov 2017 12:33:40 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: LEE XUAN DUN JOSEPH	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 8/11/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: LEE XUAN DUN JOSEPH OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 8/11/17 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAPITAL INSURANCE TP VEH: SHC1717Z						
71500-TEC-Q00ZZ	FACE ASSYRR.BUMPER <i>rehd</i>	1	617.20	25	462.90	32.40 ✓	495.30
71502-TEX-Y00	GARNISHRR.BUMPER LOWER <i>rehd</i>	1	34.50	25	25.87	1.81 ✓	27.68
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE <i>lt</i>	1	7.40	25	5.55	0.39 ✓	5.94
71593-TEA-T01	SPACERR.RR.BUMPER SIDE ?	1	11.50	25	8.62	0.60 x?	9.22 <i>mm</i>
91505-TM8-003	CLIPBUMPER <i>re</i>	7	2.00	25	10.50	0.74 ✓	11.24
					<b>Sum Item</b>	<b>513.44</b>	<b>35.94</b>
BOSUN	SUNDRIES	1	30.00		10 30.00	2.10 10.70	32.10 <i>re</i>
BA02R	REMOVE & REFIX REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40 ✓	128.40
BKB02R	REMOVE & RENEW RR BUMPER.	1	560.00		280 560.00	39.20 277.6	599.20
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	600.00		450 600.00	42.00 481.00	642.00
					<b>Sum Labor</b>	<b>1310.00</b>	<b>91.70</b>
							<b>1,401.70</b>

Survey By: Adrian Lij  
Date & Time: 13/11/17 10 a.m.  
Excess: \_\_\_\_\_  
Status: re authorized  
Signature: [Signature]

Printed on 8/11/2017 4:44:41 PM

This is a computer generated invoice. No signature is required.  
Part prices are subjected to change without notice.  
The above estimated cost of repair do not include any unforeseen damages.  
GST Amount is calculated from individual line(s)

02 Day

<b>Total Amount</b>	1,823.44	127.64	1,951.08
<b>Total (inclusive of GST)</b>			<b>1,951.08</b>

LKK Auto Consultants hence notify the Rep

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_





**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

©

16/11/2017

# SERVICE PRE-INVOICE

GST Reg No.: M200050223

Attn: Adrain Ling (L.k.k.) Company Ref. No.: S60FC1380G

2 days.

Customer: WZF002 / FIRST CAPITAL  
 Chassis No: MRHFC5650GT001228  
 License No: SJL3090M  
 Mileage: 16353  
 Engine No: R16B21601527

Document No: SVO17071752  
 Printed By: CSLIM  
 Order Date: 14. November 2017  
 Order Time: 10:47:28 AM  
 Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 69417) OWNER: LEE XUAN DUN JOSEPH OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 8/11/17 SURVEYED BY: ADRAIN LING DATE: 13/11/17 @ 10AM. REF NO: D17010433 MFSH TP INSURER: FIRST CAPITAL INSURANCE TP VEH: SHC1717Z						
71500-TEC-Q00ZZ	FACE ASSYRR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISHRR.BUMPER LOWER	1	34.50	25	25.87	1.81	27.68
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	1	7.40	25	5.55	0.39	5.94
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
	<b>SUM PARTS:</b>				<b>504.82</b>	<b>35.34</b>	<b>540.16</b>
BOSUN	0672	1	10.00		10.00	0.70	10.70
	SUNDRIES						
BA02R	EXT-YJ	1	120.00		120.00	8.40	128.40
	REMOVE & REFIX REVERSE SENSORS-4 PCS (N)						
BKBU02R	EXT-YJ	1	280.00		280.00	19.60	299.60
	REMOVE & RENEW RR BUMPER.						
BP01R	EXT-YBH	1	450.00		450.00	31.50	481.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(1P)						
	<b>SUM LABOUR:</b>				<b>860.00</b>	<b>60.20</b>	<b>920.20</b>
	<b>TOTAL SGD</b>				<b>1,364.82</b>	<b>95.54</b>	<b>1,460.36</b>
	<b>Total Payable (SGD)</b>						<b>1,460.36</b>

GST Amount is calculated from individual line(s)




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021467/Atbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 1717Z	Veh. Inspected	SJL 3090M
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17010433MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	09/11/2017
2. Vehicle Particulars & Condition			
Make & Model	HONDA CIVIC	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MRHFC5650GT001228	Colour	GREY
Odometer	16300	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/50 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/50 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/11/2017	Inspection Date	13/11/2017
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 3090M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FACE ASSYRR BUMPER (SN)	DEFORMED	462.90	462.90
1	GARNISHRR BUMPER LOWER (SN)	DEFORMED	25.87	25.87
1	GARNISHR RR BUMPER SIDE (SN)	CUT	5.55	5.55
1	SPACERRR.RR BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
7	CLIPBUMPER (SN)	NECESSARY	10.50	10.50
1	SUNDRIES (SN)	NECESSARY	30.00	10.00
			543.44	514.82
<b>LABOUR</b>				
REMOVE & REFIX REVERSE SENSORS-4 PCS.			120.00	120.00
REMOVE & RENEW RR BUMPER.			560.00	280.00
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.			600.00	450.00
			1,280.00	850.00
<b>GRAND TOTAL</b>			<b>1,823.44</b>	<b>1,364.82</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,364.82</b>

Report Ref No. CS/FCI17021467/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.