

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS3/MSG17014972/WQBS2-1  
**Date:** 24/11/2017

**REFERENCE**

**Handling Insurer:** MSIG Insurance (Singapore) Pte. Ltd. **Policy No:** B28842070MKC  
**Claimant Vehicle No :** SFW512Y **Insured Vehicle No :** YP4636J  
**Date of Loss:** 31/07/2017 **Nature of Claim:** TP **Claim No:** 525208

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

**Reg No:** SFW512Y  
**Make & Model:** TOYOTA COROLLA, 1.5 AXIO (A) **Engine No:** 1NZC806395  
**Reg. Date:** 30/11/2007 (Man. Year: 2007) **Chassis No:** NZE1416057490  
**Colour:** Dark Blue **Odometer:** 127856 km  
**Engine Capacity:** 1496 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (\$\$):** Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

**General Condition:** Good **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

**CONDITION OF TYRES**

**Front Tyre Size:** 185/70R14 **Rear Tyre Size:** 185/70R14  
**Front Left Side:** Yokohama 6 mm **Rear Left Side:** Yokohama 6 mm  
**Front Right Side:** Yokohama 6 mm **Rear Right Side:** Yokohama 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,377.01	2,390.86	3,986.15	62.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	1,350.00	1,860.00	57.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,587.01</b>	<b>3,740.86</b>	<b>5,846.15</b>	<b>60.98</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,000.00</b>		
<b>(\$\$)</b>	9,587.01	3,000.00	6,587.01	68.71
<b>+ GST 7.00/7.00% (\$\$)</b>	671.09	210.00	461.09	68.71
<b>Nett Amount (\$\$)</b>	<b>10,258.10</b>	<b>3,210.00</b>	<b>7,048.10</b>	<b>68.71</b>

**INSPECTION**

**Date of Assignment:** 02/08/2017  
**Date Inspected:** 03/08/2017 **Inspected At:** 17 KIM CHUAN TERRECE  
 Repairer: Hock Cheong Automec Pte Ltd (Aljunied)  
 611 Aljunied Road  
 Singapore 389830

**Estimated Period of Repair:** 5.0 days**Adjuster:** Richard Harjanto**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Nov 2017)
<b>Parts:</b>	143	TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFW512Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Dented	481.85 FL	*481.85 FL
2	2	*REAR BUMPER SIDE RETAINER LH/RH	Necessary	243.20 FL	*130.00 FL
3	2	*REAR BUMPER CORNER RETAINER LH/RH	Necessary	244.20 FL	*150.00 FL
4	8	*REAR BUMPER RETAINING CLIP	Necessary	103.20 FL	*60.00 FL
5	1	*REAR END PANEL	Repair	581.25 FL	*- FL
6	1	*REAR END PANEL GARNISH	Distorted	59.60 FL	*59.60 FL
7	4	*REAR END PANEL GARNISH CLIP	Necessary	51.60 FL	*20.00 FL
8	2	*TAILLAMP ASSY LH/RH	Dented / Deformed	562.50 FL	*562.50 FL
9	2	*TAILLAMP BASE PANEL LH/RH	Repair	323.70 FL	*- FL
10	2	*TAILLAMP SIDE CLIP	Necessary	25.80 FL	*25.80 FL
11	1	*SPARE TYRE PANEL	Repair	972.25 FL	*- FL
12	1	*SPARE TYRE PANEL TOP BOARD	Not Necessary	789.10 FL	*- FL
13	1	*REAR BOOT LID	Dented	781.25 FL	*690.00 FL
14	1	*REAR BOOT LID OUTER GARNISH	Dented	289.90 FL	*289.90 FL
15	2	*REAR BOOT LID OUTER GARNISH CLIP	Necessary	25.80 FL	*25.80 FL
16	1	*REAR BOOT LID TOYOTA LOGO	Necessary	45.70 FL	*45.70 FL
17	1	*REAR BOOT LID AXIO EMBLEM	Necessary	61.10 FL	*45.00 FL
18	1	*REAR BOOT LID X EMBLEM	Necessary	53.70 FL	*35.00 FL
19	1	*REAR BOOT LID INNER LOCK	Bent	181.25 FL	*90.00 FL
20	1	*REAR BOOT LID INNER LOCK LOWER STRIKER	Repair	43.70 FL	*- FL
21	1	*REAR BOOT WEATHERSTRIP	Torn	281.60 FL	*210.00 FL
22	2	*REAR BOOT LID HINGE LH/RH	Repair	363.00 FL	*- FL
23	1	*REAR BOOT LID UNDERSIDE COVER	Reuse	235.10 FL	*- FL
24	10	*REAR BOOT LID UNDERSIDE COVER CLIP	Not Necessary	129.00 FL	*- FL
25	1	*SET REAR PARKING SENSOR	Shorted	280.00 FS	*200.00 FS
26	1	*SET REAR PARKING CAMERA	Not Necessary	580.00 FS	*- FS
27	1	*SET REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
28	1	*REAR END PANEL JOINT / SEAM GUM	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,109.35</b>	<b>3,121.15</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>1,732.34</b>	<b>730.29</b>
<b>Total Parts (\$)</b>	<b>6,377.01</b>	<b>2,390.86</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY ANTI-RUST UNDERSEAL FOR THE AFFECTED PARTS AND AREAS.	New	200.00	60.00
2	TO INSTALL REAR PARKING SENSORS AND TUNE SENSING DISTANCE.	New	120.00	60.00
3	TO CHECK WIRING.	New	40.00	30.00
4	TO INSTALL REAR PARKING CAMERA AND CHECK FUNCTIONS.	New	150.00	0.00
5	LABOUR CHARGES TO REMOVE AND REPLACE DAMAGED PARTS AND NECESSARY ITEMS; TO CUT OUT AND WELD DAMAGED BODY PANELS; TO KNOCK, STRAIGHTEN AND ALIGN AFFECTED AREAS.	New	1,200.00	600.00
6	SPRAY PAINTING OF THE REAR BUMPER, REAR END PANEL, SPARE TYRE PANEL, REAR BOOT LID & HINGES, TAILLAMP BASE PANELS AND NECESSARY AREAS.	New	1,500.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,210.00</b>	<b>1,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >