

REF: CS/FWD17021716 / Gqbn2

Special Instruction:

US: \$ 9900.00

Third Parties:

Claimant:

Surveyor: CL Appraiser

Workshop: Hock 'matures

From (Person): Jara Li of FWD Date/Time: 09.11.2017

Estimated Cost: _____ Bill to: _____

$$\text{OD}(\overline{\text{TP Re-inspection}}) / \text{Evaluation}$$

To Inspect Vehicle No: SJL 2332Y Insured: STF 2333Z
at Workshop m/s Hock Motors Tel: 6846 9707 (Kelvin)
of Blk 1 Kaki Bukit Ave 6 #02-38

Policy No: _____ Claim No: 12017 00006387

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 03-10-2017
(Client's Record) _____

16.11.2017 (Thursday) @ 10am

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red S _____/_____%; Original ⁹_____ days)

Date/Time: 11/2/17 Submit Final Fig 6600, 8 days (Red S 3300, 33%; Original 9 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add

Transport

Photos

Others

Total

1) Date/Time 11/12/17 File Pass to tyrist

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time File Pass to

6) Date/Time _____ File Return to _____

Summary

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$21K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SIL2332Y

Yr Regn: 19 Nov 2008

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C

1799

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

228081

T/Radio:

Insured / Std / NI / NA

Eng/No:

JHMFED 163095200923

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45ZR17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

D.O.I.

16-11-17

Survey held at

w/s

1. AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) 11/12/2017

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.A. (\$)

TR
6600

Days Of Repair:

8

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

[Signature]

11/12/2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS/FWD17021716/qb

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 14-11-2017



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SFF 2333Z	Veh. Inspected	SJL 2332Y
Policy No.		Coverage (\$)	0.00
Claim No.	1201700006387	Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	09/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/10/2017	Inspection Date	16/11/2017
Survey held at	HOCK MOTORS WORKSHOP NO.1 KAKI BUKIT AVE 6 #02-38 AUTOBAY @KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

21/05/2014

OE Rebate for Registered Vehicle

ulars

Business

0760W

Vehicle No.	SJL2332Y
Vehicle to be Exported	No
Intended De-registration Date	16 Nov 2017
Vehicle Make	HONDA
Vehicle Model	HONDA CIVIC 1.8L 5AT
Primary Colour	Black
Manufacturing Year	2008
Engine No.	R18A14005200
Chassis No.	JHMFD16309S200923
Maximum Power Output	103.0 kW (138 bhp)
Open Market Value	\$23,035.00
Original Registration Date	19 Nov 2008
First Registration Date	19 Nov 2008
Transfer Count	2
Actual ARF Paid	\$23,035.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	18 Nov 2018
PARF Rebate Amount	\$12,669.00
Intended COE Rebate Details	
COE Expiry Date	18 Nov 2018
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$8,301.00
COE Rebate Amount	\$834.00
Total Rebate Amount	\$13,503.00

The information contained herein is correct as at 16 Nov 2017

OK

Catherine Chong (LKK Auto)

From: clara.li@fwd.com
Sent: Thursday, 9 November, 2017 5:14 PM
To: assignments@lkkauto.com; admin-d@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com
Subject: RE: [Request for Re-inspection] Our Ref: CY.9308A.17 (HMW)AC/hh Your Ref: 1201700006387
Attachments: TP GIA & Survey Report.pdf; SFF2333Z (03.10.2017) 1201700006387.zip

Hi LKK team,

Attached are the supporting documents.

Please acknowledge receipt.

Thank you.

Regards,
Clara

From: Clara Li Zirong - SGUser
Sent: Thursday, 9 November, 2017 5:02 PM
To: 'Helen'
Cc: Belliana - SGUser; assignments@lkkauto.com; sur@lkkauto.com; 'Catherine Chong (LKK Auto)'; admin-a@lkkauto.com
Subject: RE: [Request for Re-inspection] Our Ref: CY.9308A.17 (HMW)AC/hh Your Ref: 1201700006387

WITHOUT PREJUDICE

Hi Helen,

We refer to your email on even date.

Our appointed surveyor, LKK Auto Consultants Pte Ltd will be attending the re-inspection and confirming on the arrangement below.

Thank you.

Hi LKK team,

Please refer to the email below and confirm with Helen on the arrangement.

Thank you.

Kind Regards
Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	--	--	--

From: Helen [<mailto:helen@yoga-legal.com>]

Sent: Thursday, 9 November, 2017 4:46 PM

To: Clara Li Zirong - SGUser

Cc: Belliana - SGUser

Subject: RE: [Request for Re-inspection] Our Ref: CY.9308A.17 (HMW)AC/hh Your Ref: 1201700006387

Hi! Clara

Our client's vehicle (SJL2332Y) will be available for **re-inspection on Thursday, 16th November 2017 @ 10.00 a.m.** at our client's workshop:-

M/s. Hock Motors Workshop
1 Kaki Bukit Avenue 6 #02-38
AutoBay @ Kaki Bukit
Singapore 417883
Person to contact: Kelvin @ 68469707

Kindly confirm the appointment and let us have the name of the surveyor who will be conducting the re-inspection.

Thank you!

Regards

Helen Han
Secretary

M/s C. YOGARAJAH LLC
883 North Bridge Road
#19-05 Southbank
Singapore 198785
Tel : (65) 6292 5838
Fax : (65) 6292 5938
Email : helen@yoga-legal.com

Important Note: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6292 5838, if you have received this message in error. Thank you

From: clara.li@fwd.com [mailto:clara.li@fwd.com]

Sent: Tuesday, 7 November, 2017 3:54 PM

To: helen@yoga-legal.com

Cc: belliana@fwd.com

Subject: [Request for Re-inspection] Your Ref: CY.9308A.17 (HMW)AC/hh Our Ref: 1201700006387

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Helen,

We acknowledge receipt of your Letter of Demand dated 30 October 2017.

We noted that there was no request made to us to conduct Pre-Repair Survey prior to the repairs and hence the PRS never took place.

Please note there is a breach of NIMA protocol for the above matter in pursuant to Clause 2 and 4 of Appendix C, Pre-action Protocol for Non-Injury Motor Accident Cases.

As such, we would want to conduct a physical re-inspection of your client's vehicle, SJL2332Y, kindly assist with the necessary arrangement and revert to us at least 5 working days in advance.

We reserve our rights on cost for this matter.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
---	--	--	---

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT

MSME17131039 / SMR Motor Pte Ltd - KMD BMD
ENTRY DATE & TIME: 04/10/2017 16:12

Heck motors

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/10/2017 16:12
Date Of Accident 03/10/2017 19:05
Exact Location Of Accident SERANGOON NORTH AVE 4
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJL2332Y
Insured/Policyholder
Name Of Registered Owner LOVE LIVE EXPLORE
Co Reg No 53350760W
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-97992949

Vehicle Particulars

Manufacturer HONDA
Model CIVIC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5086493886

Cover Note Number

Driver

Name of Driver POH DEBRA HITOMI
NRIC No S8890079J
Date Of Birth 11/05/1988
Occupation INDOOR
Date Of Driving Pass 25/10/2010
Driving Experience 6 YEARS AND 11 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-87821411
Fax Number
Contact Number
Email Address NOEMAIL

Address BLK 520 SERANGOON NORTH AVE 4 #02-184
 Postcode 550520
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG SERANGOON NORTH AVE 4. SUDDENLY, VEHICLE B (SFF2333Z) DASHED OUT FROM THE RIGHT CAR PARK AND HIT ONTO MY VEHICLE RIGHT PORTION AND THEN HIT ONTO VEHICLE C (SLH3772B).

Attachments

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFF2333Z
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver NG TIONG WEE
 NRIC/Passport Number
 Contact Number 91822228
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLH3772B

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Name of Driver

NRIC/Passport Number

Contact Number

98310319

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

POH DEBRA HITOMI

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJL2332Y

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insured or the companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested persons.
7. By the completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

A. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information or details that may be provided by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to other persons who have insured vehicle(s) involved in the accident (all insured(s) who have insured vehicle(s) involved in this accident, and/or collectively referred to as the "Insurers"), the Insurers' law/yer/firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, records or notices to the relevant parties, where applicable, of certain personal data about me to bring about delivery of the same as well as on the external cover of documents, etc. packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' law/yer/firm, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law/yer/firm), which may be situated outside of Singapore, for one or more of the above Purposes.

4/10/17
LOVE LIVE EXPLORE
CA Reg No: 53360760W

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Roadside Personnel

Sketch Plan

car park

Sketch Plan diagram showing a car park area with a car labeled 'A' and a car labeled 'B' involved in an accident. A witness is indicated by a downward arrow. The diagram is divided into sections by a vertical line and a horizontal line. The car park is labeled 'car park' and the accident area is labeled 'A' and 'B'.

Here more

Sketch Plan #2 Pg. 1

Description of the Accident

I was driving along Jorgensen North Ave &
 suddenly vehicle B (SPP 3332) dropped out
 from the right car park and hit on to my
 vehicle right pocket and then again and hit
 on to vehicle C (SH 372B)

[Faint, mostly illegible text from the reverse side of the page is visible through the paper.]

[Faint text, possibly a signature or date.]

[Handwritten signature]
 4/10/17
LOVE LIVE EXPLORE
 Co Reg No: 53350780W

[Handwritten signature]

CL APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Love Live Explore
C/o: Hock Motors Workshop
No.1 Kaki Bukit Ave 6 #02-02
AutoBay, Singapore 417883

Invoice No: CL/17744

Ref No: HM/10/1701/TP

Date: 19 October 2017

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SJL 2332 Y
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL S\$ 796.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

LCL APPRAISER PTE LTD

47A Edgefield Plains #13-16 Singapore 828714
Hp: 90688689 Email: clappraiser@yahoo.com
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Love Live Explore
C/o: Hock Motors Workshop
No.1 Kaki Bukit Ave 6 #02-02
AutoBay, Singapore 417883

Date : 19 October 2017
Our ref : HM/10/1701/TP

Accident Date : 03 October 2017
Inspection Date : 05 October 2017
Repairer Name : Hock Motors Workshop
No.1 Kaki Bukit Ave 6 #02-02
AutoBay, Singapore 417883

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SJL 2332 Y
Make / Model : Honda Civic
Chassis No : JHMFD16309S200923
Engine No : R18A14005200

Year / Capacity : 2008 / 1799 cc
Colour : Black
Mileage : 225131

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Achilles	215/45 R17	5 mm	Sport
Front Offside	: Achilles	215/45 R17	5 mm	Sport
Rear Nearside	: Achilles	215/45 R17	5 mm	Sport
Rear Offside	: Achilles	215/45 R17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front portion.
(Details refer to the photographs attached)

Enclosed number of photographs: **101** copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 9,900.00** on a contractual basis.

Under normal circumstances, the repair period would be about 9 (Nine) working days.

ECL APPRAISER PTE LTD

Vehicle Registration No: SJL 2332 Y

Our Ref No: HM/10/1701/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front bonnet	Damage	\$ 637.80	\$ X 637.80 <i>Repair</i>
1	Front bonnet rubber	Necessary	\$ 21.50	\$ X 21.50 <i>NN</i>
2	Front headlamps	O/S Damage	\$ 2,165.60	\$ 1,082.80
2	Front headlamp lower brackets	O/S Damage	\$ 117.60	\$ 58.80
1	Front grille base	Damage	\$ 224.60	\$ 224.60
1	Front grille chrome moulding	Necessary	\$ 142.60	\$ 142.60
1	Front grille logo	Necessary	\$ 85.10	\$ 85.10
1	Front bumper	Damage	\$ 701.00	\$ 701.00
1	Front bumper o/s fog lamp	Damage	\$ 303.80	\$ 303.80
1	Front bumper o/s fog lamp cover	Damage	\$ 46.70	\$ 46.70
1	Front bumper reinforcement	Damage	\$ 295.40	\$ 295.40
2	Front bumper side retainers	Necessary	\$ 62.60	\$ 62.60
1	Front number plate granish	Damage	\$ 96.00	\$ X 96.00 <i>NN</i>
2	Front fenders	O/S Damage	\$ 1,189.60	\$ 594.80
1	Front o/s fender quarter glass moulding	Necessary	\$ 41.00	\$ 41.00
1	Front o/s fender stay	Damage	\$ 31.60	\$ X 31.60 <i>NN</i>
1	Front o/s fender inner shield	Damage	\$ 94.80	\$ 94.80
1	Front o/s fender inner panel	Damage	\$ 537.60	\$ X 537.60 <i>Repair</i>
1	Air con condenser	Damage	\$ 781.60	\$ 781.60
1	Air con liquid pipe	Necessary	\$ 190.80	\$ X 190.80 <i>NN</i>
1	Front o/s door	Repair	\$ 1,023.80	
1	Front o/s wheel hub	Damage	\$ 176.90	\$ 176.90
1	Front o/s wheel bearing	Necessary	\$ 109.00	\$ 109.00
1	Front o/s shock absorber	Damage	\$ 514.00	\$ 514.00 <i>458.9</i>
1	Front o/s knuckle arm	Damage	\$ 257.00	\$ 257.00
1	Front o/s lower arm	Damage	\$ 278.50	\$ 278.50
1	Power steering rack	Intact	\$ 1,670.90	
1	Front o/s drive shaft	Damage	\$ 993.20	\$ 993.20 <i>NN</i>
1	Engine undercover	Damage	\$ 142.20	\$ X 142.20 <i>NN</i>
			\$ 12,932.80	\$ 8,501.70 <i>6789.1</i>
Less 20%			\$ 2,586.56	\$ 1,700.34
Total Cost - List Items			\$ 10,346.24	\$ 6,801.36

5631.28

CL APPRAISER PTE LTD

Vehicle Registration No: SJL 2332 Y

Our Ref No: HM/10/1701/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
List Items Total c/f			\$ 10,346.24	\$ 6,801.36

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	Necessary	\$ 45.00	\$ 45.00 30
1	Front number plate	Damage	\$ 50.00	\$ 50.00 20
1	Front o/s fender inner shield clip (1 set)	Necessary	\$ 35.00	\$ 35.00 /
1	Front o/s tyre (Depreciation)	Damage	\$ 280.00	\$ 140.00 /
1	Sport rim (1 set)	Damage	\$ 1,500.00	\$ 1,500.00 375
1	Engine undercover clip (1 set)	Necessary	\$ 45.00	\$ 45.00 20
Total Cost - Special Nett items			\$ 1,955.00	\$ 1,815.00 600

Total cost of parts

\$ 12,301.24 \$ 8,616.36

LCL APPRAISER PTE LTD

Vehicle Registration No: SJL 2332 Y

Our Ref No: HM/10/1701/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 12,301.24	\$ 8,616.36

LABOUR

- | | | | |
|---|--|-------------|-----------------------------|
| 1 | To check wiring , lighting and resetting headlamps focussing. | \$ 80.00 | \$ 50.00 30 |
| 2 | To remove and refit front undercarriage. | \$ 600.00 | \$ 450.00 200 |
| 3 | To conduct wheel alignment. | \$ 150.00 | \$ 120.00 60 |
| 4 | To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door. | \$ 150.00 | \$ 120.00 60 |
| 5 | To apply undercoating on repaired and replaced panel. | \$ 200.00 | \$ 150.00 80 |
| 6 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,800.00 | \$ 1,500.00 800 |
| 7 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. | \$ 1,600.00 | \$ 1,320.00 1000 |

2230

GRAND TOTAL

\$ 16,881.24 \$ 12,326.36

8261.28
20% 660e

C L APPRAISER PTE LTD

Vehicle Registration No: SJL 2332 Y

Our Ref No: HM/10/1701/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 9,900.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS/FWD17021716/Gqbn2

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 12-12-2017



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SFF 2333Z	Veh. Inspected	SJL 2332Y
Policy No.		Coverage (\$)	0.00
Claim No.	1201700006387	Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	09/11/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMFD16309S200923	Colour	BLACK
Odometer	228081	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 ZR17	ACHILLES	5 mm
L/H Front Tyre	215/45 ZR17	ACHILLES	5 mm
R/H Rear Tyre	215/45 ZR17	ACHILLES	5 mm
L/H Rear Tyre	215/45 ZR17	ACHILLES	5 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	03/10/2017	Inspection Date	16/11/2017
Survey held at	HOCK MOTORS WORKSHOP NO.1 KAKI BUKIT AVE 6 #02-38 AUTOBAY @KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 2332Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	REPAIRED SEE LABOUR	637.80	-
1	FRONT BONNET RUBBER	NOT NECESSARY	21.50	-
2	FRONT HEADLAMPS	O/S REPLACED	2,165.60	1,082.80
2	FRONT HEADLAMP LOWER BRACKETS	O/S REPLACED	117.60	58.80
1	FRONT GRILLE BASE	REPLACED	224.60	224.60
1	FRONT GRILLE CHROME MOULDING	REPLACED	142.60	142.60
1	FRONT GRILLE LOGO	REPLACED	85.10	85.10
1	FRONT BUMPER	REPLACED	701.00	701.00
1	FRONT BUMPER O/S FOG LAMP	REPLACED	303.80	303.80
1	FRONT BUMPER O/S FOG LAMP COVER	REPLACED	46.70	46.70
1	FRONT BUMPER REINFORCEMENT	REPLACED	295.40	295.40
2	FRONT BUMPER SIDE RETAINERS	REPLACED	62.60	62.60
1	FRONT NUMBER PLATE GARNISH	NOT NECESSARY	96.00	-
2	FRONT FENDERS	O/S REPLACED	1,189.60	594.80
1	FRONT O/S FENDER QUARTER GLASS MOULDING	REPLACED	41.00	41.00
1	FRONT O/S FENDER STAY	NOT NECESSARY	31.60	-
1	FRONT O/S FENDER INNER SHIELD	REPLACED	94.80	94.80
1	FRONT O/S FENDER INNER PANEL	REPAIRED SEE LABOUR	537.60	-
1	AIR CON CONDENSER	REPLACED	781.60	781.60
1	AIR CON LIQUID PIPE	NOT NECESSARY	190.80	-
1	FRONT O/S DOOR	REPAIRED SEE LABOUR	1,023.80	-
1	FRONT O/S WHEEL HUB	REPLACED	176.90	176.90
1	FRONT O/S WHEEL BEARING	REPLACED	109.00	109.00
1	FRONT O/S SHOCK ABSORBER	REPLACED	514.00	458.90
1	FRONT O/S KNUCKLE ARM	REPLACED	257.00	257.00
1	FRONT O/S LOWER ARM	REPLACED	278.50	278.50
1	POWER STEERING RACK	NOT NECESSARY	1,670.90	-
1	FRONT O/S DRIVE SHAFT	REPLACED	993.20	993.20
1	ENGINE UNDERCOVER	NOT NECESSARY	142.20	-

Report Ref No. CS/FWD17021716/Gqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-2,586.56	-1,357.82
			10,346.24	5,431.28
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	REPLACED	45.00	30.00
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET FRONT O/S FENDER INNER SHIELD CLIP (SN)	REPLACED	35.00	35.00
1	FRONT O/S TYRE (DEPRECIATION)(SN)	REPLACED	280.00	140.00
1	SET SPORT RIM (SN)	REPLACED	1,500.00	375.00
1	SET ENGINE UNDERCOVER CLIP (SN)	REPLACED	45.00	20.00
			1,955.00	600.00
	<u>LABOUR</u>			
	TO CHECK WIRING,LIGHTING AND RESETTNG HEADLAMPS FOCUSING.		80.00	30.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		600.00	200.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS,TRANSFER ALL FITTINGS TO NEW DOOR.		150.00	60.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		200.00	80.00
	TO PROVIDE LABOUR CHARGES,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS,REPAIR INCLUDING CUT AND WELD;RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRONT BONNET,FRONT O/S FENDER INNER PANEL AND FRONT O/S DOOR.		1,800.00	800.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS,REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,600.00	1,000.00
	-		-	-
	-		-	-
	-		-	-
			4,580.00	2,230.00
	GRAND TOTAL		16,881.24	8,261.28

Report Ref No. CS/FWD17021716/Gqbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,600.00
---	--	--	----------

Report Ref No. CS/FWD17021716/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.