

ASS: REC BY:

REF:

C3/MSG17021808/A9b2

Special Instructions

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Monica Chung

of

MSIG

Date/Time

15/11/17 @ 9:11 am

Estimated Cost:

Bill to:

OD: ☒ WS: ☐ TP RES: ☐ OD RES: ☐ EVA: ☐ INV: ☐ MV: ☐ CS

To Inspect Vehicle No:

SLL 34022

Insured:

SKK 46485

at Workshop m/s

MG solution

Tel:

91886931

of

23 Kaki Bukit Ave 4 # 02-03B, 415 933

Policy No:

80437845ATT

Claim No:

536707

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

13/11/2017

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement

Date/Time:

9:15 am @ 15/11/17

Person Contacted:

Ms. Heng

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction

(☒ Estimate

SLL 34022 - KA/MSG17021808/13

O.A: 13/11/17

SKK 46485 - X

16/11/17 @ 10:20 am Informed Monica Chung, we are pending estimate from repairer.

19/11/17 @ 2:36 pm Revised to Monica Chung via Messenger.

LS \$3800, 6 days (Red & 5331.08, 58%)

REF: MSIG

ASSIGNMENT

From: _____ Date: 15/11/17

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLL 3402 Z

at Workshop m/s MG solution

of 23 kaki Bukit Ave 4 #02-03B, 415933

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLL 3402 Z Yr Regn: 2017 Feb

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis- C.C. 1598

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 14956 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053REH 104560315

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17.

R: 215/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 15/11/17.

Survey held at: MG solution.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MSIG.

RECEIVED 13 DEC 2017.

Date/Time, File Pass to?

☐

Preli. Report

1) 19/12 typist

☐

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format:

Lump Sum / I.B.T. (\$)

MER-TP

3800

>00

10

>10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17021808/Aqb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-11-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 4648S	Veh. Inspected	SLL 3402Z
Policy No.	80437845ATT	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	15/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/11/2017	Inspection Date	15/11/2017
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/17071808/Asb
 Policy Type: OD / TP / TP RES / TL / EVA

SLL 34027

Case Handler

Typist

Admin (Chen): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Adrian)

Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

Chen 19/12/17

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	14 Nov 2017		15 Nov 2017 09:11 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ONG CHEE PENG, ID: S7730973Z		
Main Claimant:	TAN LAY SIONG ANTHONY (CHEN LIXIANG ANTHONY), ID: S71400371		
Vehicle Reg. No.:	SLL3402Z	Date of Loss:	13/11/2017 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	80437845ATT (Comprehensive) Coverage: 21/07/2017 - 20/07/2018
Vehicle Reg. No. (Insured):	SKK4648S	Policy No. (Claimant):	
		Excess:	
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/11/2017]		
Adj Asg. Remarks:	pls assign to Adrian Ling		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 19 Dec 2017

Preliminary Advice

Insured Vehicle No	: SKK4648S	Accident Date	: 13/11/2017
TP Vehicle No	: SLL3402Z	Assignment Date	: 15/11/2017
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 6
Date of Inspection	: 15/11/2017		
Inspection At	: MG SOLUTION		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,131.08
Revised Amount	:S\$	4,741.53
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,741.53
Lump Sum Repair	:S\$	3,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 16 November, 2017 10:20 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SLL 3402Z (YOUR REF: 536707)

This mail is associated with :

***SLL3402Z (536707)**

[SKK4648S]

TP

TAN LAY SIONG ANTHONY (CHEN LIXIANG ANTHONY)

Nov 13 2017 12:00AM

[ONG CHEE PENG]

MG Solution Pte Ltd

Dear Monica,

Please be informed that we have inspected the vehicle SLL 3402Z on 15/11/2017.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
Co. Reg. No.: 201427944N

vehicle in

SLL 34022

Date: 14/11/2017

To: MSIG INSURANCE (SINGAPORE) PTE LTD By Fax & Email
Tel: 6827 7000
Fax: 6225 7402
Email: claims@sg.msig-asia.com
Attn: Motor Claims Department

Dear Sir,

Re: Accident involving motor vehicle Nos. SLL 34022 and SKK 46485 along
P1E towards Tuns before Blk Ext. on 13/11/2017

We are instructed by TAN LAY SIOM ANTHONY (Name of Claimant) to notify you of a road traffic accident on the above mentioned. A copy of the Singapore Accident Statement / Traffic Police Report filed is enclosed.

As a result of the accident, our client's / customer's vehicle has been damaged. Before our client / we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you or your insurer would like to conduct a **Pre- Repair Survey** of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client / we shall proceed to repair the vehicle without further reference to you.

Thank you

Yours faithfully



MS. HENG YOKE HONG
HP: 9188 6931

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed Surveyor: _____
(Name & Signature)

Date & Time of Inspection: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/11/2017 16:14
Date Of Accident	13/11/2017 09:15
Exact Location Of Accident	PIE TWDS TUAS B4 BKE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL3402Z
Insured/Policyholder	
Name Of Registered Owner	TAN LAY SIONG ANTHONY(CHEN LIXIANG ANTHONY)
NRIC No	S7140037I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81181771
Alternative Phone No	OTHERS-81181771

Vehicle Particulars

Manufacturer	TOYOTA
Model	CORROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100500997-00000
Cover Note Number	

Driver

Name of Driver	SEONG YEE PING(XIANG YIPING)
NRIC No	S7401391J
Date Of Birth	19/01/1974
Occupation	INDOOR
Date Of Driving Pass	25/07/2001
Driving Experience	16 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90623056
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 4 FLORA DRIVE #07-57
Postcode	507026
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK4648S
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	SEONG YEE PING(XIANG YIPING)
------	------------------------------



Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	SLL3402Z
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	
Postcode	


SKETCH PLAN

[illegible]

8-1

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/11/2017 at about 0912 hrs at along PIE towards Tuas before BKE exit. I was travelling on the Lane 2 and when my front vehicle slow down and stop due to heavy traffic hence I follow suit. Suddenly I heard a loud bang from behind and when I alighted, I realised that it was Vehicle (B) who hit onto my Rear Portion of my Vehicle (A) causing damages to my vehicle. I have 2 passengers inside my vehicle.

(A) SLL 3402 Z

(B) SKK 4648 S

DECLARATION

I/We declare that the above information is true and correct.

FOR DRIVER/ACCUSED
DATE: 11/11/17

Signature
11/11/17
DATE: 11/11/17

Signature 14/11/17
14/11/17
DATE: 14/11/17

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: MSIG INSURANCE (SINGAPORE) PTE LTD	DATE	: 14/11/2017
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLL3402Z		MROS3REH104560315
MODEL	: TOYOTA COROLLA ALTIS 1.6 A		
CHASSIS NO			Xiao Chan
<u>ACCIDENT DETAILS</u>		DATE	: 13-Nov-17
		TIME	: 12:00HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Buckle</i>	1	\$ 788.20	\$ 788.20
2	BOOTLID LOGO <i>Neu</i>	1	\$ 72.00	\$ 72.00
3	BOOTLID 'COROLLA' EMBLEM <i>Neu</i>	1	\$ 75.00	\$ 75.00
4	BOOTLID 'ALTIS' EMBLEM <i>Neu</i>	1	\$ 69.20	\$ 69.20
5	BOOTLID REFLECTOR <i>Neu Neu</i>	2	\$ 150.20	\$ 300.40
6	BOOTLID TOP LOCK <i>Peng</i>	1	\$ 350.00	\$ 350.00
7	BOOTLID LOWER CATCH <i>Not Neu</i>	1	\$ 87.00	\$ 87.00
8	BOOTLID INSULATOR <i>Neu</i>	1	\$ 312.00	\$ 312.00
9	BOOTLID WEATHER STRIP <i>Cut</i>	1	\$ 255.30	\$ 255.30
10	BOOTLID HINGE <i>Neu</i>	2	\$ 122.30	\$ 244.60
11	REAR BUMPER <i>Deformed</i>	1	\$ 522.30	\$ 522.30
12	REAR BUMPER SIDE RETAINER <i>Neu</i>	2	\$ 101.00	\$ 202.00
13	REAR BUMPER REFLECTOR <i>Neu</i>	2	\$ 75.30	\$ 150.60
14	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 460.00	\$ 460.00
15	REAR BUMPER REINFORCEMENT SPONGE <i>Neu</i>	1	\$ 130.00	\$ 130.00
16	TAIL LAMP <i>LH Cracked</i>	2	\$ 389.20	\$ 778.40
17	TAIL LAMP LOWER BRACKET <i>Neu Neu</i>	2	\$ 62.00	\$ 124.00
18	TAIL LAMP PANEL <i>Neu Neu</i>	2	\$ 387.20	\$ 774.40

19	REAR FENDER INNER TRIM <i>new</i>	2	\$ 355.20	\$ 710.40	+
20	REAR FENDER AIR VENT <i>new</i>	2	\$ 155.90	\$ 311.80	+
21	REAR END PANEL <i>Dented</i>	1	\$ 655.20	\$ 655.20	581.20
22	REAR END PANEL TOP GARNISH <i>Crushed</i>	1	\$ 255.30	\$ 255.30	✓

3868.7

2901.52

TOTAL PRICE \$ 7,628.10

LESS 25% \$ 1,907.03

SUB TOTAL PRICE \$ 5,721.08

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	BOOTLID SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
3	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
4	TAILLAMP PANEL SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
6	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 60.00	✓
8	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	✓

320

TOTAL \$ 550.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,200.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,000.00	600	
3	TUFF COAT	\$180.00	40	
4	TO CONDUCT WATER LEAKAGE TEST	\$250.00	*	
5	WIRING CHECK	\$150.00	30	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50	

1520

TOTAL

\$2,860.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,271.08

TOTAL LABOUR COST : \$ 2,860.00

TOTAL REPAIR COST : \$ 9,131.08

9221.07

Adrian L
15/11/17.
h/s 0629p
Total: 4741.52
h/s: 3.8K ✓

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17021808/AQBN2

Date: 20/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80437845ATT
Claimant Vehicle No :	SLL3402Z	Insured Vehicle No :	SKK4648S
Date of Loss:	13/11/2017	Nature of Claim:	TP
		Claim No:	536707

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL3402Z	Engine No:	1ZRY339887
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104560315
Reg. Date:	22/02/2017 (Man. Year: 2016)	Odometer:	14956 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,361.07	3,221.52	3,139.55	49.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	1,520.00	1,340.00	46.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,221.07	4,741.52	4,479.55	48.58
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	9,221.07	3,800.00	5,421.07	58.79

INSPECTION

Date of Assignment:	15/11/2017	
Date Inspected:	15/11/2017 Inspected At:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2017)	
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLL3402Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Buckled	788.20 FL	*788.20 FL
2	1	*BOOTLID LOGO	Necessary	72.00 FL	*72.00 FL
3	1	*BOOTLID COROLLA EMBLEM	Necessary	75.00 FL	*75.00 FL
4	1	*BOOTLID ALTIS EMBLEM	Necessary	69.20 FL	*69.20 FL
5	2	*BOOTLID REFLECTOR	Not Necessary	300.40 FL	*- FL
6	1	*BOOTLID TOP LOCK	Damaged	350.00 FL	*281.00 FL
7	1	*BOOTLID LOWER CATCH	Not Necessary	87.00 FL	*- FL
8	1	*BOOTLID INSULATOR	Not Necessary	312.00 FL	*- FL
9	1	*BOOTLID WEATHER STRIP	Cut	255.30 FL	*255.30 FL
10	2	*BOOTLID HINGE	Not Necessary	244.60 FL	*- FL
11	1	*REAR BUMPER	Deformed	522.30 FL	*522.30 FL
12	2	*REAR BUMPER SIDE RETAINER	Necessary	202.00 FL	*202.00 FL
13	2	*REAR BUMPER REFLECTOR	Not Necessary	150.60 FL	*- FL
14	1	*REAR BUMPER REINFORCEMENT	Bent	460.00 FL	*378.00 FL
15	1	*REAR BUMPER REINFORCEMENT SPONGE	Not Necessary	130.00 FL	*- FL
16	1	*TAIL LAMP	N/s Cracked	778.40 FL	*389.20 FL
17	2	*TAIL LAMP LOWER BRACKET	Not Necessary	124.00 FL	*- FL
18	2	*TAIL LAMP PANEL	Not Necessary	774.40 FL	*- FL
19	2	*REAR FENDER INNER TRIM	Not Necessary	710.40 FL	*- FL
20	2	*REAR FENDER AIR VENT	Not Necessary	311.80 FL	*- FL
21	1	*REAR END PANEL	Dented	655.20 FL	*581.20 FL
22	1	*REAR END PANEL TOP GARNISH	Cracked	255.30 FL	*255.30 FL
23	1	*REAR BUMPER PLATE	Not Necessary	50.00 FS	*- FS
24	1	*BOOTLID SEALANT	Not Necessary	80.00 FS	*- FS
25	1	*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
26	1	*TAILLAMP PANEL SEALANT LH	Not Necessary	80.00 FS	*- FS
27	1	*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	20.00 FS	*- FS
28	1	*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
29	1	*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
30	1	*REVERSE SENSOR	Damaged	220.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,268.10	4,188.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,907.03	967.18
Total Parts (\$\$)	6,361.07	3,221.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	600.00
3	TUFF COAT	New	180.00	40.00
4	TO CONDUCT WATER LEAKAGE TEST	New	250.00	-
5	WIRING CHECK	New	150.00	30.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
Gross Labour Cost (\$\$)			2,860.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >