

REF: CSI/LAW17021942/Avbsz

Special Instructions:

From (Person): Linda Phua of Linda Phua Law Date/Time: 16-11-2017  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

45: \$ 21200.00

Third Parties:

Claimant:

Surveyor: PAR Automotive & FarmTeam

Workshop: N-51 Automotive

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: GBD 8118Y  
at Workshop m/s N-5, G.D.S. Insured: SKA 9188m

at Workshop m/s N-51 Automotive Insured: SRK 418  
of 2 K. 1. 211 Tel: 6812 0051

of 2 Kaki Bukit Ave 2 # 01-17

Policy No: \_\_\_\_\_ Claim No: LP/NTUC/2017-0307

Sum Insured: \_\_\_\_\_ Claim No: LP/N10C/2017-0307  
Make of Motor: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record) \_\_\_\_\_ D.O.A. 08-01-2016

(Client's Record) \_\_\_\_\_ D.O.A. \_\_\_\_\_ 08-01-2016 \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_  
 Date/Time: \_\_\_\_\_ H.O.D. Endorsement/Date: \_\_\_\_\_

Date/Time: 11/12/17 Confirmed with 184825 Final Fig 184825, 13 days (Red \$ 13 / 13 %; Original 13 days)

Date/Time: 11/12/17 Submit Final Fig 18 \$9350, 12 days (Red \$ 11850 / 55 %; Original 13 days)

[illegible]

RECEIVED 11 DEC 2017

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

|  |  |
|--|--|
| Para(2) : Comments on consistency of damages (Parts Not Consistent : NC) |  |
|--|--|

Para(3) : Nett Value

Market Value : \_\_\_\_\_

Salvage Value :

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

Fee Charged:

Basic &amp; Acid

Transport

## Photos

Others

Total

Date: \_\_\_\_\_

350

1) Date/Time 11/12- typst File Pass to

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

2) Date/Time

4) Date/Time

6) Date/Time

File Return to

File Return to

File Return to



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LINDA PHUA LAW PRACTICE

Ref : CS1/LAW17021942/Avb

20 HAVELOCK ROAD  
#02-45 CENTRAL SQUARE  
SINGAPORE 059765

Date : 16-11-2017



Code : L153

## 1. Policy Particulars :- PAPER SURVEY

|              |                   |                |            |
|--------------|-------------------|----------------|------------|
| Insured Veh. | SKQ 9188M         | Veh. Inspected | GBD 8118Y  |
| Policy No.   |                   | Coverage (\$)  | 0.00       |
| Claim No.    | LP/NTUC/2017-0307 | Excess (\$)    | 0.00       |
| Assign From  | LINDA PHUA        | Assign Date    | 16/11/2017 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 08/01/2016  | Inspection Date | 16/11/2017 |
| Survey held at | N-51 AUTOMOTIVE PL<br>2 KAKI BUKIT AVE 2<br>#01-17 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                 |            |

## 5a. Remarks

|  |
|--|
|  |
|--|

## Catherine Chong (LKK Auto)

---

**From:** Linda Phua <linda@lindaphualaw.com>  
**Sent:** Wednesday, 29 November, 2017 11:56 AM  
**To:** Catherine Chong (LKK Auto)  
**Subject:** RE: SJE Assignment - new case - LP/NTUC/2017-0307- Vehicle GBD 8118 Y -  
**Importance:** High

Hi Catherine

1. For this matter, kindly be informed that we had adjourned the hearing two times and explained to the court that our first email to you apparently was not received by you.
2. You requested for the documents to be couriered to you and that was made only on 10.11.2017.
3. The court had adjourned our hearing to the 15 Dec 2017 and had also ordered that the SJE report must be ready and released by 15 Dec 2017.
4. Can you please request Adrian Ling to expedite this matter?

Regards  
Linda Phua



**LINDA PHUA LAW PRACTICE  
COMMISSIONER FOR OATHS**

E: [linda@lindaphualaw.com](mailto:linda@lindaphualaw.com)

T: +65 6534 7388 F: +65 6534 8911 M: 9777 2781

20 Havelock Road, Central Square #02-45 Singapore 059765

Website: [www.lindaphualaw.com](http://www.lindaphualaw.com)

**LINDA PHUA LAW PRACTICE (UEN 53313522B) DO NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FAX OR EMAIL.**

This document is confidential and privileged. If you have received this transmission in error, please notify the sender immediately by reply e-mail and then delete this message. You should not copy or use it for any purpose or disclose its contents to any other person.

## Linda Phua

---

**From:** Catherine Chong (LKK Auto) <admin-d@lkkauto.com>  
**Sent:** Friday, 10 November 2017 4:57 PM  
**To:** Linda Phua  
**Cc:** 'assignments'  
**Subject:** RE: SJE ASsignment - new case - LP/NTUC/2017-0307- Vehicle GBD 8118 Y -

Dear Linda,

Ok.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Linda Phua [mailto:[linda@lindaphualaw.com](mailto:linda@lindaphualaw.com)]  
**Sent:** Friday, 10 November, 2017 4:51 PM  
**To:** Catherine Chong (LKK Auto) <admin-d@lkkauto.com>  
**Cc:** 'assignments' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: SJE ASsignment - new case - LP/NTUC/2017-0307- Vehicle GBD 8118 Y -

Hi Catherine

I am on leave today to Tuesday. I will arrange for documents to be couriered to your office next Wednesday.

Attention to you?

LINDA PHUA LAW PRACTICE  
t :6534 7388 f: 6534 8911  
m: 97772781

20 Havelock Road , Central Square #02-45 Singapore 059765

LINDA PHUA LAW PRACTICE (UEN 53313522B) do not accept service of documents or notice of proceedings by fax or email.

This document is confidential and privileged. If you have received this transmission in error, please notify this sender immediately by reply email and then delete the message. You should not copy or use for any purpose or disclose to any other person.

On 10 Nov 2017 4:46 pm, "Catherine Chong (LKK Auto)" <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)> wrote:

Dear Linda,

Thank you for your email.

Can provide us documents for this SJE by hand.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Linda Phua [<mailto:linda@lindaphualaw.com>]

**Sent:** Monday, 6 November, 2017 11:00 AM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Subject:** FW: SJE ASsignment - new case - LP/NTUC/2017-0307- Vehicle GBD 8118 Y -

Dear Catherine

1. I refer to this matter and our conversation this morning. Please refer to my email sent to you on the 25.10.2017.
2. I have removed the attachments from this email. The court had adjourned the matter to 24.11.2017 for us to produce the SJE report. Can you look into this assignment ?

Regards

Linda Phua



**LINDA PHUA LAW PRACTICE**

**COMMISSIONER FOR OATHS**

E: [linda@lindaphualaw.com](mailto:linda@lindaphualaw.com)

T: +65 6534 7388 F: +65 6534 8911 M: 9777 2781

20 Havelock Road, Central Square #02-45 Singapore 059765

Website: [www.lindaphualaw.com](http://www.lindaphualaw.com)

**LINDA PHUA LAW PRACTICE (UEN 53313522B) DO NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FAX OR EMAIL.**

**This document is confidential and privileged. If you have received this transmission in error, please notify the sender immediately by reply e-mail and then delete this message. You should not copy or use it for any purpose or disclose its contents to any other person.**

**From:** Linda Phua

**Sent:** Wednesday, 25 October 2017 5:31 PM

**To:** 'assignments@lkkauto.com' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Subject:** SJE ASsignment - new case - LP/NTUC/2017-0307- Vehicle GBD 8118 Y - Part 1 /2 of emails

Dear Sirs

1. I act for NTUC Income Insurance Co-Op Ltd. Please be informed that a suit has been commenced by the owner of GBD 8118 Y. Parties have not been able to come to an agreement on the claim for cost of repairs.
2. The court had appointed your Adrian Ling as the Single Joint Expert for this matter.
3. We attach a copy of the following documents: -

3.

- a. FormTEam SR
- b. SAS of SKQ 9188 M and
- c. SAS of GBD 8118 Y

4. The survey report of PART Automotive will be sent in 2/2 of my emails.

Regards

Linda Phua



**LINDA PHUA LAW PRACTICE**

**COMMISSIONER FOR OATHS**

E: [linda@lindaphualaw.com](mailto:linda@lindaphualaw.com)

T: +65 6534 7388 F: +65 6534 8911 M: 9777 2781

20 Havelock Road, Central Square #02-45 Singapore 059765

Website: [www.lindaphualaw.com](http://www.lindaphualaw.com)

**LINDA PHUA LAW PRACTICE (UEN 53313522B) DO NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FAX OR EMAIL.**

**This document is confidential and privileged. If you have received this transmission in error, please notify the sender immediately by reply e-mail and then delete this message. You should not copy or use it for any purpose or disclose its contents to any other person.**



# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

NEO & CHIEONG ENGINEERING SERVICES  
1017 YISHUN INDUSTRIAL PARK A #01-240  
SINGAPORE 768759

Contact : 82226811

## TAX INVOICE

Date : 31/03/2016  
Date in : 08/01/2016  
Vehicle Num. : GBD8118Y  
Make/Model : TOYOTA HIACE 3.0 DX A-2015  
Chassis/Eng# : KDII2015017850/1KD2511702  
Accident Date : 08/01/2016  
Claim No : CLM13343  
Reference : JAN-19/2016  
Policy No. : 5072454173 (25/06/2016)

LUMPSUM REPAIR BILL  
AS PER SURVEYOR REPORT  
REF : 0164-16-N51 DATED 28/03/2016  
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$  
21,200.00

|           |                       |           |
|-----------|-----------------------|-----------|
| E. & O.E. | Sub S\$ :             | 21,200.00 |
|           | Add GST ( 7 % ) S\$ : | 1,484.00  |
|           | Total Amount S\$ :    | 22,684.00 |



for N-51 AUTOMOTIVE PTE LTD



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                   |
|----------------------------|-------------------|
| Date Of Report             | 08/01/2016 14:41  |
| Date Of Accident           | 08/01/2016 12:00  |
| Exact Location Of Accident | Jalan Bukit Merah |
| Country/State of Loss      | Singapore         |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKQ9188M             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | KENG ANN ENGINEERING |
| Co Reg No                   | 43802600D            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             |                      |
| Alternative Phone No        | Office-98348089      |

### Vehicle Particulars

|  |             |
|--|-------------|
| Manufacturer   | TOYOTA      |
| Model  | HARRIER     |
| Exact Purpose for which vehicle was being used at time of accident           | Leisure     |
| Are you claiming under your own insurance policy for repair to your vehicle? | Yes         |
| If No, Please state action to be taken                                       |             |
| Vehicle Category   | Private Car |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC Income Insurance Co-operative Ltd |
| Type Of Coverage          | Comprehensive                          |
| Fleet Policy              | No                                     |
| Policy Number             | 5068154106-01                          |
| Cover Note Number         |  |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | LIM KENG ANN          |
| NRIC No              | S1582659B             |
| Date Of Birth        | 18/11/1963            |
| Occupation           | Indoor                |
| Date Of Driving Pass | 05/01/1981            |
| Driving Experience   | 35 Years And 0 Months |
| Gender               | Male                  |
| Mobile Number        | (Local) +65-98348089  |
| Fax Number           |                       |
| Contact Number       |                       |
| EMail Address        | NOEMAIL               |

#### Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address

#### DETAILS OF INJURED PERSON 1

Name UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SH8382C

Were seat belts worn? Yes

Was injured conveyed to hospital by ambulance? Yes

Address

Postcode

## Sketch Plan Pg.2

### Describe Circumstances of the Accident

#### Brief Details.

On 08/01/2016 at about 1200hrs, I was travelling in my car registration number SKQ9188M along Jalan Bukit Merah towards Queensway and I was on the second lane of three lanes. While driving, my handphone rang and I was distracted by the sound, I turn and look at my handphone. When I turn my head back to the front, it was too late for me to react and my car hit a van GBD8118Y in front of me. The lorry swerve to the left and my car kept moving forward and hit a taxi SH8382C. The taxi driver was conveyed to hospital.

#### Declaration

I/We declare the foregoing particulars are true in every respect.



08-01-16 14:36

Policyholder's Signature / Date & Time

08-01-16 14:36

Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)  
Customer Care Executive  
Motor Service Centre

Witnessed by Reporting Centre Personnel

## Police Report



**SINGAPORE  
POLICE FORCE**



7701 30102 0074

2 of 2

Police Station Of Origin:  
Queenstown N.P.C  
3 Queensway #01-03 SINGAPORE 149073  
Tel No: 1800-4718999

Report No: T231601352077

## CONTINUATION OF REPORT

## Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

## Driver

|                                   |                |  |                                 |
|-----------------------------------|----------------|--|---------------------------------|
| Name                              | LIM KENG ANN   | ID No.                                 | S1552659B                       |
| Related Vehicle                   | SKQ9188M (Car) | Contact No.                            | 99349069                        |
| Hospital/Clinic                   | N.L.           | Class of Driving Licence & Expiry Date | Class: 3<br>Date of Expiry: NIL |
| Date Treatment                    | NIL            | Date Discharge                         | NIL                             |
| No. of Days granted Medical Leave | N.L.           | Degree of Injury                       | NIL                             |

## Brief Details.

On 08/01/2016 at about 1200hrs, I was travelling in my car registration number SKQ9188M along Jalan Bukit Merah towards Queensway and I was on the second lane of three lanes. While driving, my handphone rang and I was distracted by the sound. I turn and look at my handphone. When I turn my head back to the front, it was too late for me to react and my car hit a van G3D81 18Y in front of me. The lorry swerve to the left and my car kept moving forward and hit a taxi SH5382C. The taxi driver was conveyed to hospital.

Accident Photo



Accident Photo



Accident Photo





# FormTeam Consultancy Pte Ltd

No.33, Ubi Ave 3  
#02-15, Vertex  
Singapore 408868

Tel: (65) 6509 1788  
Fax: (65) 6509 6221

Email: [motorsurvey@fta.com.sg](mailto:motorsurvey@fta.com.sg)

Co.Reg No: 200819280D

GST Reg No: 200819280D

Our Reference : RRN16-051548/RI/CBX/cg  
Your Reference: MT/CA/TP/009/0887268-002/RD/PJT  
Date : 05-Jul-2016

Motor Claims Department  
NTUC Income Insurance Co-Operative Limited  
73 Bras Basah Road  
#05-01 NTUC Trade Union House  
Singapore 189556

Attention : Ms Rajeswary

Dear Sir/Mdm,

## **RE-INSPECTION OF VEHICLE NO . GBD 8118Y**

Pursuant to your instructions on 13 May 2016, we have conducted a reinspection of the above vehicle at 2 Kaki Bukit Ave 2 #01-17/18 S'417921 on 23 Jun 2016.


We recommend a repair cost of **\$8,550.00** (see report) based on lump sum repair and the estimated duration of repairs would take **13 days**.

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

**FormTeam Consultancy Pte Ltd**  
Adjusters & Surveyors (Licensed Appraiser)



Chow Bo Xiong  
Automobile Appraiser

(Email : [chowbx@fta.com.sg](mailto:chowbx@fta.com.sg))

Encl. Re-inspection Report

# FormTeam Consultancy Pte Ltd

PAGE : 2

Our Reference : RRN16-051548/RI/CBX/cg

Your Reference : MT/CA/TP/009/0887268-002/RD/PJT

| QTY | DESCRIPTION                              | CONDITION            | REMARKS | SUBMITTED | REVISED  |
|-----|--|----------------------|---------|-----------|----------|
| 1   | Rear LH Tail Lamp Apron Garnish          | Not Consistent       |         | 103.30    | -        |
| 1   | Rear LH Tail Lamp Apron Garnish Retainer | Not Consistent       |         | 38.40     | -        |
| 1   | Rear LH Tail Lamp Back Rubber Gasket     | Not Consistent       |         | 25.80     | -        |
| 2   | Rear LH Tail Lamp Clips                  | Not Consistent       |         | 13.00     | -        |
| 1   | Rear LH Tail Lamp Inner Panel            | Repair               |         | -         | -        |
| 1   | Rear RH Chassis Frame                    | Repair               |         | -         | -        |
| 1   | Rear RH Fender                           | Not Replaced         |         | 1,832.40  | -        |
| 1   | Rear RH Fender Glass Moulding            | Necessary            |         | 189.10    | 189.10   |
| 1   | Rear RH Fender Inner Air Vent            | Warped               |         | 33.60     | 33.60    |
| 1   | Rear RH Fender Inner Cardboard           | No Photo Show Damage |         | 151.20    | -        |
| 1   | Rear RH Fender Inner Panel               | Repair               |         | -         | -        |
| 1   | Rear RH Fender Sliding Door Rail         | Repair               |         | -         | -        |
| 1   | Rear RH Fender Sliding Door Rail Garnish | Reuse                |         | -         | -        |
| 1   | Rear RH Tail Lamp (G L)                  | Broken               |         | 397.50    | 397.50   |
| 1   | Rear RH Tail Lamp Apron Garnish          | Buckled              |         | 103.30    | 103.30   |
| 1   | Rear RH Tail Lamp Apron Garnish Retainer | Necessary            |         | 38.40     | 38.40    |
| 1   | Rear RH Tail Lamp Back Rubber Gasket     | Necessary            |         | 25.80     | 25.80    |
| 2   | Rear RH Tail Lamp Clips                  | Necessary            |         | 13.00     | 13.00    |
| 1   | Rear RH Tail Lamp Inner Panel            | Buckled              |         | 542.30    | 542.30   |
| 1   | Rear Tailgate                            | Buckled              |         | 1,755.30  | 1,755.30 |
| 1   | Rear Tailgate 'Hiace' Emblem             | Necessary            |         | 33.10     | 33.10    |
| 1   | Rear Tailgate 'Logo' Emblem              | Necessary            |         | 77.30     | 77.30    |
| 2   | Rear Tailgate Damper L/R                 | LH Not Consistent    |         | 575.40    | 287.70   |
| 2   | Rear Tailgate Hinges L/R                 | Not Replaced         |         | 137.80    | -        |
| 1   | Rear Tailgate Inner Cardboard            | Fractured            |         | 178.30    | 178.30   |
| 1   | Rear Tailgate Inner Handle               | Reuse                |         | -         | -        |
| 1   | Rear Tailgate Inner Lock Handle          | Reuse                |         | -         | -        |
| 1   | Rear Tailgate Inner Lock Handle Garnish  | Reuse                |         | -         | -        |

# FormTeam Consultancy Pte Ltd

PAGE : 4

Our Reference : RRN16-051548/RI/CBX/cg

Your Reference : MT/CA/TP/009/0887268-002/RD/PJT

| QTY                    | DESCRIPTION                                  | CONDITION      | REMARKS | SUBMITTED | REVISED  |
|------------------------|--|----------------|---------|-----------|----------|
| 1 set                  | Rear RH Fender Inner Cardboard Clips         | Necessary      |         | 30.00     | 30.00    |
| 1                      | Rear RH Fender Inner Upholstery Wooden Board | Fractured      |         | 500.00    | 500.00   |
| 1                      | Rear RH Tail Lamp 'Brake' Bulb               | Fused          |         | 12.00     | 12.00    |
| 1                      | Rear RH Tail Lamp 'Reverse' Bulb             | Fused          |         | 12.00     | 12.00    |
| 1                      | Rear RH Tail Lamp 'Signal' Bulb              | Fused          |         | 12.00     | 12.00    |
| 1                      | Rear Tailgate '1250KG Max Weight' Sticker    | Not Fitted     |         | 35.00     | -        |
| 1                      | Rear Tailgate '70Km/h' Sticker               | Necessary      |         | 15.00     | 15.00    |
| 1                      | Rear Tailgate '8 Pax' Sticker                | Not Fitted     |         | 15.00     | -        |
| 1                      | Rear Tailgate Camera Recorder                | Not Consistent |         | 800.00    | -        |
| 1 set                  | Rear Tailgate Inner Cardboard Clips          | Necessary      |         | 30.00     | 30.00    |
| 1                      | Rear Tailgate Number Plate                   | Bent           |         | 25.00     | 20.00    |
| 1                      | Rear Tailgate Number Plate Holder            | Bent           |         | 50.00     | 25.00    |
| 1                      | Rear Tailgate Reverse Camera                 | Not Consistent |         | 800.00    | -        |
| 1                      | Rear Tailgate Windscreen Sealant             | Necessary      |         | 100.00    | 60.00    |
| 1                      | Spare Tyre                                   | Reuse          |         | -         | -        |
| Special Nett Sub-Total |  |                |         | 11,636.00 | 926.00   |
| Total Parts Amount     |  |                |         | 20,359.40 | 7,327.18 |

# FormTeam Consultancy Pte Ltd

PAGE : 6

Our Reference : RRN16-051548/RI/CBX/cg

Your Reference: MT/CA/TP/009/0887268-002/RD/PJT

| QTY | DESCRIPTION                               | SUBMITTED   | REVISED    |
|-----|---|-------------|------------|
|     | Our Recommended Repair Cost (see remarks) | \$21,200.00 | \$8,550.00 |


## REMARKS :


Our recommended Lump Sum Repair Cost is **\$8,550.00** (instead of the submitted repair cost of **\$21,200.00** .In normal circumstances, repairs to the vehicle would take approximately **13 days** to complete. Please find enclosed our note of charges for your kind attention.

## Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FormTeam Consultancy Pte Ltd** for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,  
**FormTeam Consultancy Pte Ltd**

  
Frankie Pang  
AMSAE(AUST), AMIRTE, AMSOE,  
MASPACI, MSAAA  
Licensed Appraiser

  
Chow Bo Xiong  
Automobile Appraiser

# PAR Automotive Consultancy

Regn No 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel : 645 31173, Fax : 645 36131.

Report No: 0164-16-N51

28 March 2016

Neo & Cheong Engineering Svs  
1017 Yishun Ind Park A #01-240  
Singapore 768759

**INVOICE No.** 0164-16-N51


**Vehicle No.** GBD8118Y

| <u>S/NO.</u>                | <u>SERVICES RENDERED</u>   | <u>Amount due</u>        |
|-----------------------------|--|--------------------------|
| 1                           | Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection). | \$1,054.00               |
| <b>Total amount payable</b> |  | <b><u>\$1,054.00</u></b> |

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



# PAR Automotive Consultancy

## Parts and Labour Assessment

### PARTS

| Description of part                                       | Qty | Condition | Repairer's estimate | Our adjustment |
|---|-----|-----------|---------------------|----------------|
| REAR BUMPER   | 1   | squashed  | 327.90              | 327.90 ✓       |
| REAR BUMPER INNER STEP PANEL                              | 1   | distorted | 260.00              | 260.00 ✓       |
| REAR BUMPER LOWER BRACKET                                 | 4   | bent      | 98.40               | 98.40 ✓        |
| REAR BUMPER SIDE RETAINER L/R                             | 2   | necessary | 49.30               | 49.30 ✓        |
| REAR END INNER PANEL                                      | 1   | buckled   | 999.50              | 999.50 ✓       |
| REAR END OUTER PANEL                                      | 1   | buckled   | 436.40              | 436.40 ✓       |
| REAR END PANEL INNER TOP ALUMINIUM GARNISH                | 1   | deformed  | 103.80              | 103.80 ✓       |
| REAR END PANEL INNER TOP ALUMINIUM GARNISH CLIPS          | 6   | necessary | 39.00               | 39.00 ✓        |
| REAR END PANEL INNER TOP ALUMINIUM GARNISH SIDE COVER L/R | 2   | deformed  | 23.00               | 23.00 ✓        |
| REAR EXHAUST GASKET                                       | 1   | necessary | 88.90               | 88.90 ✓        |
| REAR EXHAUST PIPE   | 1   | bent      | 871.20              | 871.20 ✓       |
| REAR EXHAUST RUBBER MOUNTING                              | 1   | distorted | 39.50               | 39.50 ✓        |
| REAR FLOOR PANEL  | 1   | repair    | 1,889.50            | 0.00 ✗         |
| REAR LH TAILLAMP (G L)                                    | 1   | fractured | 397.50              | 397.50 ✓       |
| REAR LH TAILLAMP APRON GARNISH                            | 1   | warped    | 103.30              | 103.30 ✗       |
| REAR LH TAILLAMP APRON GARNISH RETAINER                   | 1   | necessary | 38.40               | 38.40 ✗        |
| REAR LH TAILLAMP BACK RUBBER GASKET                       | 1   | necessary | 25.80               | 25.80 ✓        |
| REAR LH TAILLAMP CLIPS                                    | 2   | necessary | 13.00               | 13.00 ✓        |
| REAR LH TAILLAMP INNER PANEL                              | 1   | repair    | 542.30              | 0.00 ✗         |
| REAR RH CHASSIS FRAME                                     | 1   | repair    | 792.80              | 0.00 ✗         |
| REAR RH FENDER <i>Reps</i>                                | 1   | buckled   | 1,832.40            | 1,832.40 ✗     |
| REAR RH FENDER GLASS MOULDING                             | 1   | necessary | 189.10              | 189.10 ✓       |
| REAR RH FENDER INNER AIR VENT                             | 1   | warped    | 33.60               | 33.60 ✓        |
| REAR RH FENDER INNER CARDBOARD                            | 1   | fractured | 151.20              | 151.20 ✓       |
| REAR RH FENDER INNER PANEL                                | 1   | repair    | 1,114.70            | 0.00 ✗         |
| REAR RH FENDER SLIDING DOOR RAIL                          | 1   | repair    | 490.00              | 0.00 ✗         |
| REAR RH FENDER SLIDING DOOR RAIL GARNISH                  | 1   | reuse     | 76.40               | 0.00 ✗         |
| REAR RH TAILLAMP (G L)                                    | 1   | broken    | 397.50              | 397.50 ✓       |
| REAR RH TAILLAMP APRON GARNISH                            | 1   | buckled   | 103.30              | 103.30 ✓       |
| REAR RH TAILLAMP APRON GARNISH RETAINER                   | 1   | necessary | 38.40               | 38.40 ✓        |
| REAR RH TAILLAMP BACK RUBBER GASKET                       | 1   | necessary | 25.80               | 25.80 ✓        |
| REAR RH TAILLAMP CLIPS                                    | 2   | necessary | 13.00               | 13.00 ✓        |
| REAR RH TAILLAMP INNER PANEL                              | 1   | buckled   | 542.30              | 542.30 ✓       |
| REAR TAILGATE   | 1   | buckled   | 1,755.30            | 1,755.30 ✓     |
| REAR TAILGATE 'HIACE' EMBLEM                              | 1   | necessary | 33.10               | 33.10 ✓        |
| REAR TAILGATE 'LOGO' EMBLEM                               | 1   | necessary | 77.30               | 77.30 ✓        |
| REAR TAILGATE DAMPER L/R                                  | 2   | bent      | 575.40              | 575.40 ✓       |
| REAR TAILGATE HINGES L/R <i>no new</i>                    | 2   | bent      | 137.80              | 137.80 ✗       |
| REAR TAILGATE INNER CARDBOARD                             | 1   | fractured | 178.30              | 178.30 ✓       |
| REAR TAILGATE INNER HANDLE                                | 1   | reuse     | 95.00               | 0.00 ✗         |
| REAR TAILGATE INNER LOCK HANDLE                           | 1   | reuse     | 67.40               | 0.00 ✗         |

SPARE TYRE

1316

|                          |       |              |              |
|--------------------------|-------|--------------|--------------|
| 1                        | reuse | 280.00       | 0.00         |
| Subtotal before discount |       | SS 11,916.00 | SS 11,636.00 |
| Sub-total 2              |       | SS 11,916.00 | SS 11,636.00 |
| Parts-total              |       | SS 25,158.08 | SS 20,359.40 |

## LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

150.00 80.00 ✓

To remove, reinstall fender glass

150.00 120.00 60 ✓

To remove and refit rear windscreen(to FR)

150.00 120.00 ✓

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

140.00 100.00 80 ✓

Dismantle and testing of sound system

550.00 550.00 ✓

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

1,750.00 1,250.00 1000 ✓

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

160.00 120.00 80 ✓

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

2,000.00 1,760.00 1300 ✓

To mount vehicle on to Car 'O' Liner.

3350

400.00 400.00 ✓

To apply anti-rust chemical on repaired and replaced panel.

120.00 120.00 80 ✓

|                      |              |              |
|----------------------|--------------|--------------|
| Labour Total         | SS 5,570.00  | SS 4,620.00  |
| Parts & Labour Total | SS 30,728.08 | SS 24,979.40 |

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 21,200.00

and the recommended number of working days for the repairs is within 13 day(s).

BJ LOI (I Eng, MIML AIRTE)  
Automotive Appraiser

total: 11723.57

1/2: 9350

12 Days.



Your Ref: LP/NTUC/2017-0307

Date: 11<sup>th</sup> December 2017

Our Ref: CS1/LAW17021942/Avbs2

**M/s Linda Phua Law Practice**

20 Havelock Road  
#02-45 Central Square  
Singapore 059765

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
GBD 8118Y  
INSURED VEHICLE: SKQ 9188M  
ACCIDENT DATE: 08/01/2016**

We thank you for your instruction on 16/11/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBD 8118Y from M/s FormTeam Consultancy Pte Ltd.
- b) Survey report by PAR Automotive Consultancy with colour photographs.
- c) Singapore Accident Statement of Vehicles SKQ 9188M.
- d) Colour damaged vehicle photographs of GBD 8118Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

|                      |                         |
|----------------------|-------------------------|
| Registration Number  | : GBD 8118Y             |
| Make & Model         | : Toyota Hiace 3.0 DX A |
| Year of Registration | : 2015                  |
| Chassis Number       | : KDH2015017850         |
2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 8118Y

| Qty                         | Description of Parts                                      | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |   |                      |                           |                   |
| 1                           | REAR BUMPER   | SQUASHED             | 327.90                    | 327.90            |
| 1                           | REAR BUMPER INNER STEP PANEL                              | DISTORTED            | 260.00                    | 260.00            |
| 4                           | REAR BUMPER LOWER BRACKET                                 | BENT                 | 98.40                     | 98.40             |
| 2                           | REAR BUMPER SIDE RETAINER L/R                             | NECESSARY            | 49.30                     | 49.30             |
| 1                           | REAR END INNER PANEL                                      | BUCKLED              | 999.50                    | 999.50            |
| 1                           | REAR END OUTER PANEL                                      | BUCKLED              | 436.40                    | 436.40            |
| 1                           | REAR END PANEL INNER TOP ALUMINIUM GARNISH                | DEFORMED             | 103.80                    | 103.80            |
| 6                           | REAR END PANEL INNER TOP ALUMINIUM GARNISH CLIPS          | NECESSARY            | 39.00                     | 39.00             |
| 2                           | REAR END PANEL INNER TOP ALUMINIUM GARNISH SIDE COVER L/R | DEFORMED             | 23.00                     | 23.00             |
| 1                           | REAR EXHAUST GASKET                                       | NECESSARY            | 88.90                     | 88.90             |
| 1                           | REAR EXHAUST PIPE   | BENT                 | 871.20                    | 871.20            |
| 1                           | REAR EXHAUST RUBBER MOUNTING                              | DISTORTED            | 39.50                     | 39.50             |
| 1                           | REAR FLOOR PANEL  | TO REPAIR SEE LABOUR | 1,889.50                  | -                 |
| 1                           | REAR LH TAILLAMP (G L)                                    | FRACTURED            | 397.50                    | 397.50            |
| 1                           | REAR LH HEADLAMP APRON GARNISH                            | NOT NECESSARY        | 103.30                    | -                 |
| 1                           | REAR LH HEADLAMP APRON GARNISH RETAINER                   | NOT NECESSARY        | 38.40                     | -                 |
| 1                           | REAR LH TAILLAMP BACK RUBBER GASKET                       | NECESSARY            | 25.80                     | 25.80             |
| 2                           | REAR LH TAILLAMP CLIPS                                    | NECESSARY            | 13.00                     | 13.00             |
| 1                           | REAR LH TAILLAMP INNER PANEL                              | TO REPAIR SEE LABOUR | 542.30                    | -                 |
| 1                           | REAR RH CHASSIS FRAME                                     | TO REPAIR SEE LABOUR | 792.80                    | -                 |
| 1                           | REAR RH FENDER  | TO REPAIR SEE LABOUR | 1,832.40                  | -                 |
| 1                           | REAR RH FENDER GLASS MOULDING                             | NECESSARY            | 189.10                    | 189.10            |
| 1                           | REAR RH FENDER INNER AIR VENT                             | WARPED               | 33.60                     | 33.60             |
| 1                           | REAR RH FENDER INNER CARDBOARD                            | FRACTURED            | 151.20                    | 151.20            |
| 1                           | REAR RH FENDER INNER PANEL                                | TO REPAIR SEE LABOUR | 1,114.70                  | -                 |
| 1                           | REAR RH FENDER SLIDING DOOR RAIL                          | TO REPAIR SEE LABOUR | 490.00                    | -                 |

Report Ref No. CS1/LAW17021942/Avbs2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts                          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
| 1   | REAR RH FENDER SLIDING DOOR RAIL GARNISH      | REUSE         | 76.40                     | -                 |
| 1   | REAR RH TAILLAMP (G L)                        | BROKEN        | 397.50                    | 397.50            |
| 1   | REAR RH TAILLAMP APRON GARNISH                | BUCKLED       | 103.30                    | 103.30            |
| 1   | REAR RH TAILLAMP APRON GARNISH RETAINER       | NECESSARY     | 38.40                     | 38.40             |
| 1   | REAR RH TAILLAMP BACK RUBBER GASKET           | NECESSARY     | 25.80                     | 25.80             |
| 2   | REAR RH TAILLAMP CLIPS                        | NECESSARY     | 13.00                     | 13.00             |
| 1   | REAR RH TAILLAMP INNER PANEL                  | BUCKLED       | 542.30                    | 542.30            |
| 1   | REAR TAILGATE                                 | BUCKLED       | 1,755.30                  | 1,755.30          |
| 1   | REAR TAILGATE 'HIACE' EMBLEM                  | NECESSARY     | 33.10                     | 33.10             |
| 1   | REAR TAILGATE 'LOGO' EMBLEM                   | NECESSARY     | 77.30                     | 77.30             |
| 2   | REAR TAILGATE DAMPER L/R                      | BENT          | 575.40                    | 575.40            |
| 2   | REAR TAILGATE HINGES L/R                      | NOT NECESSARY | 137.80                    | -                 |
| 1   | REAR TAILGATE INNER CARDBOARD                 | FRACTURED     | 178.30                    | 178.30            |
| 1   | REAR TAILGATE INNER HANDLE                    | REUSE         | 95.00                     | -                 |
| 1   | REAR TAILGATE INNER LOCK HANDLE               | REUSE         | 67.40                     | -                 |
| 1   | REAR TAILGATE INNER LOCK HANDLE GARNISH       | REUSE         | 77.30                     | -                 |
| 2   | REAR TAILGATE INNER LOCK HANDLE GARNISH CLIPS | NECESSARY     | 13.00                     | 13.00             |
| 1   | REAR TAILGATE MECHANISM LOCK                  | BENT          | 262.30                    | 262.30            |
| 1   | REAR TAILGATE MIRROR ARM WITH GLASS           | REUSE         | 469.10                    | -                 |
| 2   | REAR TAILGATE NUMBER PLATE LAMP L/R           | FRACTURED     | 224.20                    | 224.20            |
| 1   | REAR TAILGATE OUTER GARNISH                   | WARPED        | 136.70                    | 136.70            |
| 4   | REAR TAILGATE OUTER GARNISH CLIPS             | NECESSARY     | 26.00                     | 26.00             |
| 1   | REAR TAILGATE OUTER KEY LOCK                  | REUSE         | 75.80                     | -                 |
| 1   | REAR TAILGATE OUTER LOCK HANDLE               | NOT NECESSARY | 109.20                    | -                 |
| 2   | REAR TAILGATE SIDE RUBBER SEAL L/R            | NECESSARY     | 51.40                     | 51.40             |
| 1   | REAR TAILGATE THIRD BRAKE LAMP                | REUSE         | 183.30                    | -                 |
| 1   | REAR TAILGATE WEATHERSTRIP                    | DEFORMED      | 387.60                    | 387.60            |
| 1   | REAR TAILGATE WINDSCREEN MOULDING             | NECESSARY     | 115.00                    | 115.00            |
| 1   | SET REAR TAILGATE WIRE HARNESS                | REUSE         | 151.30                    | -                 |
| 1   | SPARE TYRE BRACKET                            | BENT          | 278.50                    | 278.50            |
| 1   | SET SPARE TYRE SCREW LOCK                     | BENT          | 28.60                     | 28.60             |
|     | LESS 25% DISCOUNT                             |               | -4,414.02                 | -2,352.53         |
|     |   |               | 13,242.08                 | 7,057.57          |

Report Ref No. CS1/LAW17021942/Avbs2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty  | Description of Parts  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--|---|---------------|---------------------------|-------------------|
| <b><u>SPECIAL NETT ITEMS</u></b>   |   |               |                           |                   |
| 1  | REAR 2 CHANNEL AMPLIFIER (SN)                                 | NOT NECESSARY | 2,800.00                  | -                 |
| 1  | REAR 4 CHANNEL AMPLIFIER (SN)                                 | NOT NECESSARY | 3,400.00                  | -                 |
| 1  | SET REAR BUMPER CLIPS (SN)                                    | NECESSARY     | 30.00                     | 30.00             |
| 1  | SET REAR BUMPER REVERSE SENSOR (SN)                           | SHORTED       | 350.00                    | 220.00            |
| 1  | REAR FLOOR PANEL INNER TOP UPHOLSTERY WOODEN BOARD (SN)       | FRACTURED     | 800.00                    | 350.00            |
| 1  | RR FLOOR PANEL INNER TOP UPHOLSTERY WOODEN BOX (SN)           | NOT NECESSARY | 120.00                    | -                 |
| 1  | REAR FLOOR PANEL INSULATOR MAT (SN)                           | NOT NECESSARY | 350.00                    | -                 |
| 1  | REAR INTERIOR L.E.D DISPLAY WOODEN AND ACRYLIC TOP BOARD (SN) | NOT NECESSARY | 1,250.00                  | -                 |
| 1  | REAR RH FENDER GLASS SEALANT (SN)                             | NECESSARY     | 100.00                    | 60.00             |
| 1  | SET REAR RH FENDER INNER CARDBOARD CLIPS (SN)                 | NECESSARY     | 30.00                     | 30.00             |
| 1  | REAR RH FENDER INNER UPHOLSTERY WOODEN BOARD (SN)             | NOT NECESSARY | 500.00                    | -                 |
| 1  | REAR RH TAILLAMP 'BRAKE' BULB (SN)                            | FUSED         | 12.00                     | 12.00             |
| 1  | REAR RH TAILLAMP 'REVERSE' BULB (SN)                          | FUSED         | 12.00                     | 12.00             |
| 1  | REAR RH TAILLAMP 'SIGNAL' BULB (SN)                           | FUSED         | 12.00                     | 12.00             |
| 1  | REAR TAILGATE '1250KG MAX WEIGHT' STICKER (SN)                | NECESSARY     | 35.00                     | 35.00             |
| 1  | REAR TAILGATE '70KM/H' STICKER (SN)                           | NECESSARY     | 15.00                     | 15.00             |
| 1  | REAR TAILGATE '8PAX' STICKER (SN)                             | NECESSARY     | 15.00                     | 15.00             |
| 1  | REAR TAILGATE CAMERA RECORDER (SN)                            | NOT NECESSARY | 800.00                    | -                 |
| 1  | SET REAR TAILGATE INNER CARDBOARD CLIPS (SN)                  | NECESSARY     | 30.00                     | 30.00             |
| 1  | REAR TAILGATE NUMBER PLATE (SN)                               | BENT          | 25.00                     | 25.00             |
| 1  | REAR TAILGATE NUMBER PLATE HOLDER (SN)                        | BENT          | 50.00                     | 30.00             |
| 1  | REAR TAILGATE REVERSE CAMERA (SN)                             | SHORTED       | 800.00                    | 380.00            |
| 1  | REAR TAILGATE WINDSCREEN SEALANT (SN)                         | NECESSARY     | 100.00                    | 60.00             |
| 1  | SPARE TYRE (SN)   | REUSE         | 280.00                    | -                 |
|  |   |               | 11,916.00                 | 1,316.00          |
| <b><u>LABOUR</u></b>   |   |               |                           |                   |
| TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR. |   |               | 150.00                    | 80.00             |
| TO REMOVE, REINSTALL FENDER GLASS.   |   |               | 150.00                    | 60.00             |

Report Ref No. CS1/LAW17021942/Avbs2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

| Qty   | Description of Parts   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
|   | TO REMOVE AND REFIT REAR WINDSCREEN (TO FR)  |               | 150.00                    | 120.00            |
|   | TO REMOVE , REINSTALL ROOF TOP TRIM  |               | 140.00                    | 80.00             |
|   | UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)   |               |                           |                   |
|   | DISMANTLE AND TESTING OF SOUND SYSTEM.   |               | 550.00                    | 550.00            |
|   | TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.   |               | 1,750.00                  | 1,000.00          |
|   | TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.  |               | 160.00                    | 80.00             |
|   | TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, REAR LH TAILLAMP INNER PANEL, REAR RH CHASSIS FRAME, REAR RH FENDER, REAR RH FENDER INNER PANEL AND REAR RH FENDER SLIDING DOOR RAIL. |               | 2,000.00                  | 1,300.00          |
|   | TO MOUNT VEHICLE ON TO CAR 'O' LINER.  | NOT NECESSARY | 400.00                    | -                 |
|   | TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.  |               | 120.00                    | 80.00             |
|   |  |               | 5,570.00                  | 3,350.00          |
| <b>GRAND TOTAL</b>  |  |               | <b>30,728.08</b>          | <b>11,723.57</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |  |               |                           | <b>9,350.00</b>   |

Report Ref No. CS1/LAW17021942/Avbs2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.