

PAR Automotive Consultancy

Annex A: Page 2
Report No: 0164-16-N51-GBD8118Y

REAR TAILGATE INNER LOCK HANDLE GARNISH
REAR TAILGATE INNER LOCK HANDLE GARNISH CLIPS
REAR TAILGATE MECHANISM LOCK
REAR TAILGATE MIRROR ARM WITH GLASS
REAR TAILGATE NUMBER PLATE LAMP L/R
REAR TAILGATE OUTER GARNISH
REAR TAILGATE OUTER GARNISH CLIPS
REAR TAILGATE OUTER KEY LOCK
REAR TAILGATE OUTER LOCK HANDLE *HE NEW*
REAR TAILGATE SIDE RUBBER SEAL L/R
REAR TAILGATE THIRD BRAKE LAMP
REAR TAILGATE WEATHERSTRIP
REAR TAILGATE WINDSCREEN MOULDING
REAR TAILGATE WIRE HARNESS - SET
SPARE TYRE BRACKET
SPARE TYRE SCREW LOCK - SET

1	reuse	77.30	0.00 X
2	necessary	13.00	13.00 ✓
1	bent	262.30	262.30 ✓
1	reuse	469.10	0.00 X
2	fractured	224.20	224.20 ✓
1	warped	136.70	136.70 ✓
4	necessary	26.00	26.00 ✓
1	reuse	75.80	0.00 X
1	distorted	109.20	109.20 X
2	necessary	51.40	51.40 ✓
1	reuse	183.30	0.00 X
1	deformed	387.60	387.60 ✓
1	necessary	115.00	115.00 ✓
1	reuse	151.30	0.00 X
1	bent	278.50	278.50 ✓
1	bent	28.60	28.60 ✓

Percentage discount 25% and 25%

Subtotal before discount S\$ 17,656.10 S\$ 11,631.20
S\$ 4,414.03 S\$ 2,907.80

Sub-total 1 S\$ 13,242.08 S\$ 8,723.40

REAR 2 CHANNEL AMPLIFIER } *HE NEW*
REAR 4 CHANNEL AMPLIFIER
REAR BUMPER CLIPS - SET
REAR BUMPER REVERSE SENSOR - SET
REAR FLOOR PANEL INNER TOP UPHOLSTERY
WOODEN BOARD
RR FLOOR PANEL INNER TOP UPHOLSTERY WOODEN
BOX *HE NEW*
REAR FLOOR PANEL INSULATOR MAT *HE NEW*
REAR INTERIOR L.E.D DISPLAY WOODEN AND
ACRYLIC TOP BOARD *HE NEW*
REAR RH FENDER GLASS SEALANT
REAR RH FENDER INNER CARDBOARD CLIPS - SET
REAR RH FENDER INNER UPHOLSTERY WOODEN
BOARD *HE NEW*
REAR RH TAILLAMP 'BRAKE' BULB
REAR RH TAILLAMP 'REVERSE' BULB
REAR RH TAILLAMP 'SIGNAL' BULB
REAR TAILGATE '1250KG MAX WEIGHT' STICKER
REAR TAILGATE '70KM/H' STICKER
REAR TAILGATE '8PAX' STICKER
REAR TAILGATE CAMERA RECORDER *HE NEW*
REAR TAILGATE INNER CARDBOARD CLIPS - SET
REAR TAILGATE NUMBER PLATE
REAR TAILGATE NUMBER PLATE HOLDER
REAR TAILGATE REVERSE CAMERA
REAR TAILGATE WINDSCREEN SEALANT

1	shorted	2,800.00	2,800.00 X
1	shorted	3,400.00	3,400.00 X
1	necessary	30.00	30.00 ✓
1	shorted	350.00	350.00 220
1	fractured	800.00	800.00 350
1	fractured	120.00	120.00 X
1	necessary	350.00	350.00 X
1	fractured	1,250.00	1,250.00 X
1	necessary	100.00	100.00 60
1	necessary	30.00	30.00 ✓
1	fractured	500.00	500.00 X
1	fused	12.00	12.00 ✓
1	fused	12.00	12.00 ✓
1	fused	12.00	12.00 ✓
1	necessary	35.00	35.00 ✓
1	necessary	15.00	15.00 ✓
1	necessary	15.00	15.00 ✓
1	shorted	800.00	800.00 X
1	necessary	30.00	30.00 ✓
1	bent	25.00	25.00 ✓
1	bent	50.00	50.00 30
1	shorted	800.00	800.00 380
1	necessary	100.00	100.00 60

PAR Automotive Consultancy

Regn No 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173. Fax : 645 36131

Report No: 0164-16-N51

28 March 2016

ACCIDENT VEHICLE SURVEY REPORT

Neo & Cheong Engineering Svs
1017 Yishun Ind Park A #01-240
Singapore 768759

VEHICLE INFORMATION:

Vehicle Reg No.:	GBD8118Y	Odometer:	18905km
Make & Model:	Toyota Hiace 3.0 DX A	Colour:	White
Chassis number:	KDH2015017850	Date of accident:	08/01/2016
Year of Regn.:	26/06/2015	Date inspected:	11/01/2016
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Bridgestone	5mm/Bridgestone	225/45R18
Rear:	5mm/Michelin	5mm/Michelin	245/40ZR18

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

FormTeam Consultancy Pte Ltd

Vehicle No: GBD 8118Y

Workshop: N-51 Automotive Pte Ltd

Accident Date: 8 January 2016

No. 33 Ubi Ave 3
#02-15 Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: motorsurvey@fta.com.sg
www.fta.com.sg

Co. Reg No: 200819280D

GST Reg. No: 200819280D



FormTeam Consultancy Pte Ltd

PAGE : 5

Our Reference : RRN16-051548/RI/CBX/cg

Your Reference: MT/CA/TP/009/0887268-002/RD/PJT

QTY	DESCRIPTION	SUBMITTED	REVISED
	LABOUR & MISC		
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00	80.00
2	To remove, reinstall fender glass.	120.00	120.00
3	To remove and refit rear windscreen. (to FR)	120.00	120.00
4	To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100.00	100.00
5	Dismantle and testing of sound system.	550.00	550.00
6	To re-spray painting on the rear boot lid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,250.00	800.00
7	To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	120.00	60.00
8	To provide labour, workmanship to change the above damaged body parts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. (including all repair parts)	1,760.00	1,400.00
9	To mount vehicle on to Car 'O' Liner. (not necessary)	400.00	-
10	To apply anti-rust chemical on repaired and replaced panel.	120.00	120.00
	Total Labour Amount	4,620.00	3,350.00
	Total Parts and Labour	24,979.40	10,677.18

FormTeam Consultancy Pte Ltd

PAGE : 3

Our Reference : RRN16-051548/RI/CBX/cg

Your Reference : MT/CA/TP/009/0887268-002/RD/PJT

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
2	Rear Tailgate Inner Lock Handle	Necessary		13.00	13.00
	Garnish Clips				
1	Rear Tailgate Mechanism Lock	Bent		262.30	262.30
1	Rear Tailgate Mirror Arm With Glass	Reuse		-	-
2	Rear Tailgate No. Plate Lamp L/R	Fractured		224.20	224.20
1	Rear Tailgate Outer Garnish	Warped		136.70	136.70
4	Rear Tailgate Outer Garnish Clips	Necessary		26.00	26.00
1	Rear Tailgate Outer Key Lock	Reuse		-	-
1	Rear Tailgate Outer Lock Handle	Not Consistent		109.20	-
2	Rear Tailgate Side Rubber Seal L/R	Necessary		51.40	51.40
1	Rear Tailgate Third Brake Lamp	Reuse		-	-
1	Rear Tailgate Weatherstrip	Deformed		387.60	387.60
1	Rear Tailgate Windscreen Moulding	Necessary		115.00	115.00
1 set	Rear Tailgate Wire Harness	Reuse		-	-
1	Spare Tyre Bracket	Bent		278.50	278.50
1 set	Spare Tyre Screw Lock	Bent		28.60	28.60
	List Items Sub-Total			11,631.20	8,534.90
	Original Less 25%			2,907.80	2,133.73
	Revised Less 25%				
	Discounted Sub-Total			8,723.40	6,401.17
	PARTS REPLACEMENT				
	SPECIAL NETT ITEMS				
1	Rear 2 Channel Amplifier	Not Consistent		2,800.00	-
1	Rear 4 Channel Amplifier	Not Consistent		3,400.00	-
1 set	Rear Bumper Clips	Necessary		30.00	30.00
1 set	Rear Bumper Reverse Sensor	Not Fitted		350.00	-
1	Rear Floor Panel Inner Top Upholstery Wooden Board	Not Consistent		800.00	-
1	Rear Floor Panel Inner Top Upholstery Wooden Box	Fractured		120.00	120.00
1	Rear Floor Panel Insulator Mat	Not Necessary		350.00	-
1	Rear Interior L.E.D Display Wooden And Acrylic Top Board	No Photo Show Damage		1,250.00	-
1	Rear RH Fender Glass Sealant	Necessary		100.00	60.00

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

PAGE : 1

Our Reference : RRN16-051548/RI/CBX/cg

Your Reference : MT/CA/TP/009/0887268-002/RD/PJT

Date : 05-Jul-2016

Attention : Ms Rajeswary

TO : Motor Claims Department
NTUC Income Insurance Co-Operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Dear Sir/Madam,

Vehicle No : GBD 8118Y
Model : Toyota Hiace
Mileage : 37570 km
Chassis No : KDH2015017850
Workshop : M/S N-51 Automotive Pte Ltd

Pursuant to your instructions on **13 May 2016**, we have conducted a reinspection of the above vehicle at **2 Kaki Bukit Ave 2 #01-17/18 S'417921** on **23 Jun 2016**.

We are pleased to submit hereunder our adjustment which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	<u>PARTS REPLACEMENT-LIST ITEMS</u>				
1	Rear Bumper	Squashed		327.90	327.90
1	Rear Bumper Inner Step Panel	Distorted		260.00	260.00
4	Rear Bumper Lower Bracket	Bent		98.40	98.40
2	Rear Bumper Side Retainer L/R	Necessary		49.30	49.30
1	Rear End Inner Panel	Buckled		999.50	999.50
1	Rear End Outer Panel	Buckled		436.40	436.40
1	Rear End Panel Inner Top Aluminium Garnish	Deformed		103.80	103.80
6	Rear End Panel Inner Top Aluminium Garnish Clips	Necessary		39.00	39.00
2	Rear End Panel Inner Top Aluminium Garnish Side Cover L/R	Deformed		23.00	23.00
1	Rear Exhaust Gasket	Necessary		88.90	88.90
1	Rear Exhaust Pipe	Bent		871.20	871.20
1	Rear Exhaust Rubber Mounting	Distorted		39.50	39.50
1	Rear Floor Panel	Repair		-	-
1	Rear LH Tail Lamp (G L)	Not Consistent		397.50	-

Accident Photo



Accident Photo



Accident Photo



Police Report



SINGAPORE
POLICE FORCE



T-201601052074

Police Station Of Origin:
Queensway N.P.C.
3 Queensway #01-03 SINGAPORE 149073
Tel No. 1900-7718999

3 of 3

Report No. T-201601052074

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate in this report. If you don't have the certificate with you now, please fax a copy to 65/74885 stating the report number as reference.

Signature Of Officer Recording The Report

D /

MUHAMMAD ASSYARIFF B N OMAR

Signature Of Interpreter

Not applicable

Officer In Charge Of Case

TP / GIT /

YEO CHUN JIAN

Contact No.: 65176213

Authentication Stamp

NOTE:

Singapore Police Force

Signature Of Informant

Date/Time:

05/01/2015 13:57

Classification Of Case

Police Report



**SINGAPORE
POLICE FORCE**



T2016010800054

1-43

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 140073
Tel No: 1800-4719999

Report No: T2016010800054

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/01/2016 13:57	Vice Report No.: D2016010800054	Station Diary No.: 25
Informant's Particulars		
Name of Informant: LIM KENG ANN		Address: APT BLK 567 HOUGANG STREET 51 #10-67 SINGAPORE 530567
ID Type / ID No.: NRIC NO / S15828593	Contact No.: Home/Office:	Mobile: 98348080
Nationality: SINGAPORE CITIZEN		Email:
Sex: Male	Age: 52	Date of Birth: 18/11/1963
Type of Informant: Driver		Institution / School Name:
Race: Chinese	Language: English	
Occupation: Employment agent/Labour contractor	Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 08/01/2016 12:00	Type of Location: Straight Road
Location: Along Road 1 JALAN BUKIT MERAH				
ALONG JALAN BUKIT MERAH TOWARDS QUEENSWAY				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control:	Traffic Volume:		
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
GBD8118Y	Van				Slightly Damaged	0
SH6382C	Car				Slightly Damaged	0
SK09186M	Car				Slightly Damaged	0

Sketch Plan Pg.1

NTUC Income Motor Service Centre

Vehicle No: SKQ9188M Report Date & Start Time: 08-01-16 / 14:36

Report No: MT/

D.O.A: 8/1/16

Make / Model: Toyota Harrier

Reporting Type: OD

End Time: /

Time: 1200 hrs.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



08-01-16 / 14:36

Policyholder's Signature / Date & Time

[Signature]

08-01-16 / 14:36

Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

[Signature]

Witnessed by Reporting Centre Personnel

Sketch Plan

Jalan Bukit Merah

Vehicle A: SKQ9188M

Vehicle B: GBD8118Y

Vehicle C: SH8382C

Address	Blk 567 #10-67 Hougang Street 51
Postcode	530567
Was driver an employee of the Insured's Company	Yes
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Chain Collision
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name	Queenstown N.p.c
Police Station Address	ROAD: 3 QUEENSWAY #01-03 , POSTCODE: 149073 , COUNTRY: Singapore
Police Station Contact	TEL NO: 1800-4719999 - FAX NO:
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

Refer to Police Report	
Are accident photos available for attachment?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD8118Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SH8382C
Vehicle Make/Model/Colour	

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 9200B

Vehicle Details

Vehicle No.: GBD8118Y

Vehicle to be Exported: No

Intended De-registration Date: 08 Jan 2016

Vehicle Make: TOYOTA

Vehicle Model: HIACE 3.0 DX A

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 1KD2511702

Chassis No.: KDH2015017850

Maximum Power Output: -

Open Market Value: \$29,544.00

Original Registration Date: 26 Jun 2015

First Registration Date: 26 Jun 2015

Transfer Count: 0

Actual ARF Paid: \$1,478.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 Jun 2025

COE Category: C - Goods Vehicle & Bus

Period(Years): 10

PQP Paid: \$50,370.00

COE Rebate Amount: \$47,669.00

Total Rebate Amount: \$47,669.00

The information contained herein is correct as at 08 Jan 2016

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate this Website](#) | [Rate this e-Service](#)