

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: LP/NTUC/2017-0307 Date: 11th December 2017

Our Ref: CS1/LAW17021942/Avbs2

M/s Linda Phua Law Practice 20 Havelock Road #02-45 Central Square Singapore 059765

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

GBD 8118Y

INSURED VEHICLE: SKQ 9188M ACCIDENT DATE: 08/01/2016

We thank you for your instruction on 16/11/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBD 8118Y from M/s FormTeam Consultancy Pte Ltd.
- b) Survey report by PAR Automotive Consultancy with colour photographs.
- Singapore Accident Statement of Vehicles SKQ 9188M.
- d) Colour damaged vehicle photographs of GBD 8118Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: GBD 8118Y

Make & Model

: Toyota Hiace 3.0 DX A

Year of Registration

: 2015

Chassis Number

: KDH2015017850

- We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.