

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/11/2017 12:08
Date Of Accident	13/11/2017 14:10
Exact Location Of Accident	JUNCTION OF LORONG 1 & LORONG 6 TOA PAYOH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU8287T
Insured/Policyholder	
Name Of Registered Owner	SUNDARI D/O JEYARAMAN
NRIC No	S7635134A
Email Address	SCORPIONETTE8@YAHOO.COM
Mobile Phone No	(LOCAL) +65-81635441
Alternative Phone No	OTHERS-81635441

Vehicle Particulars

Manufacturer	BMW
Model	520I AUTO ABS AIRBAG 2WD XENON HEADLAMP
Exact Purpose for which vehicle was being used at time of accident	PTE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3028861706
Cover Note Number	

Driver

Name of Driver	SUNDARI D/O JEYARAMAN
NRIC No	S7635134A
Date Of Birth	08/11/1976
Occupation	INDOOR
Date Of Driving Pass	24/02/1997
Driving Experience	20 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81635441
Fax Number	
Contact Number	OTHERS-81635441
Email Address	SCORPIONETTE8@YAHOO.COM

**JIN AUTO SERVICES PTE
LTD
BLK 14 #01-412 DEFU
LANE 10
SINGAPORE 539195
539195**

**Claim Reference: SGU 8287T
Assessment Number: JA000091
Version: JINAUTO1/2
Date Calculated: 17/11/2017 02:42**

**Full Report - V1
Registration: SGU8287T
Printed: 27/11/2017 10:21**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	JOUIS SEOW	Date of Incident:	13/11/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SGU 8287T	Estimated Repair Time:	7 day(s)
Policy Number:	DMPCSN3028861706	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

*Not Affected
a/s
EXCESS N/C*

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	5 Series
Sub Model:	520 I
Model Sheet Number:	145 01
Registration:	SGU8287T
Registration Month:	September
Registration Year:	2008
VIN Number:	WBANT12030CX29413
Manufacture Year:	2008
Odometer:	157507
Colour:	Other
Engine Number:	A6471171N46B20BE
Fuel Level:	%

Model Specs

FROM 09/2008	BUSINESS EDITION
DIP/FOLD MIRROR	XENON HEADLAMPS
DAKOTA LEATHER TRIM	COMFORT FRONT SEATS
FRONT ACTIVE SEATS	FRONT COMFORT SEATS
2.0 LTR 125 KW	6-SPEED AUTOMATIC
ACTIVE STEERING	DYNAMIC DRIVE
TYRES 225/50 WR 17	WHEELS 7.5J X 17 ALU
ALIGNMENT W/LOADING	SPORTS SUSPENSION
4-DOOR	RAD GRILLE CHROME
PARK DISTANCE CONT	CHROME LINE
TWO COAT METALLIC	PREPARE OFF VEHICLE
PARTS PAINTED	

*4 days
Tehongto Affirming on 27/11/17*

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Fair	Severity of Impact:	
Steering:	Satisfactory	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	16/11/2017
Place of Inspection:			
Pre-Accident Damage:			
Tyres Condition:	Fair	Tread Depth RHF:	
Tread Depth LHF:		Tread Depth RHR:	
Tread Depth LHR:		Direction of Impact:	
Damage Areas:			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JIN AUTO SERVICES PTE LTD

Claim Reference: SGU 8287T

Assessment Number: JA000091



Version: JINAUTO1/2

Date Calculated: 17/11/2017 02:42

Full Report - V1

Registration: SGU8287T

Printed: 27/11/2017 10:21



Addresses

Cost Summary

Total Labour	\$870.93
Total Paint/Material	\$205.13
Total Parts	\$4,813.45
Total of Additional Costs	\$82.00
Excess:	TBA
Grand Total Exc GST:	\$5,971.51
7 % GST:	\$418.01
Grand Total Inc GST:	\$6,389.52

Repair Information

LABOUR

Time Basis 12 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
41 35 000)	R + R R/F WING	17.0	65.17
	INCLUDES: R + R BUMPER, INDICATOR AND WHEELHOUSE COVER		
	DOES NOT INCLUDE: R + R SILL MOULDING		
51 11 551	R + R FRONT BUMPER CARRIER	3.0	11.50
51 11 592	RENEW FRONT BUMPER COVER (FRONT BUMPER REMOVED)	9.0	34.50
66 20 610	ADD/WORK PARK DISTANCE CONTROL	4.0	15.33
51 11 701	RENEW L/F BUMPER BRACKET (REMOVED)	1.0	3.83
51 11 701	RENEW R/F BUMPER BRACKET (REMOVED)	1.0	3.83
63 12 522)	R + R RIGHT HEADLAMP	5.0	19.17
63 12 524	RENEW R/HEADLAMP (REMOVED)	3.0	11.50
51 71 947	R + R RIGHT SILL RAIL	7.0	26.83
51 47 500	R + R FRONT ASSEMBLY PROTECTION	2.0	7.67
0471	REPAIR BONNET <i>n/c</i>	30.0* X	115.00 X

LABOUR COST

Total Work Units	82.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	6.8HRS	\$314.33
Labour Markup (0.0 %)		\$0.00
Paint Labour	12.1HRS	\$556.60
Total Labour	18.9HRS	\$870.93

JIN AUTO SERVICES PTE LTD

Claim Reference: SGU 8287T

Assessment Number: JA000091

Version: JINAUTO1/2

Date Calculated: 17/11/2017 02:42

Full Report - V1

Registration: SGU8287T

Printed: 27/11/2017 10:21

NOTE TIME BASIS = 12 WU / HOUR

PAINT WORK

Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

WU

Cost Price (\$)

- TWO COAT METALLIC
- PREPARE OFF VEHICLE
- PARTS PAINTED

742	R/F WING NEW PART PAINTING	10.0	
1017	FRONT PANEL SURFACE PAINT	4.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	17.0	
634	R/WASHER NOZZLE TRIMREPAIR PAINT PLASTIC	9.0	
471	BONNET REPAIR PAINTING >50%	48.0	X

LABOUR COST - PAINT

TIME(PAINT)

- Preparation Main Work Plastic
- Preparation Main Work Metal
- Preparation Work Multi Layer Paint

Total Work Units (10WU/HR)

Total Paintwork Labour

MATERIAL COST - PAINT

- New Part Painting
- Material-Constant Main Work Metal
- Surface-/Blend Paint
- Repair Painting
- Repair Painting Plastic
- Material-Const Main Work Plastic
- Total Excluding Pearlescent Uplift
- Pearlescent Uplift @ 0.0%
- Total Paint Material Cost

88.0	
8.0	
25.0	
0.0	
121.0	
12.1HRS	\$556.60
	Cost Price
	\$19.61
	\$28.60
	\$3.74
	\$82.56
	\$57.92
	\$12.70
	\$205.13
	\$0.00
	\$205.13

PARTS

Price Valid: 01/10/2017

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER COVER	51 11 0 420 276		0%	910.00F
313	1	FRT TOWING EYE COVER	51 11 0 430 601		0%	30.00F
317	1	L/F BUMPER BRACKET	51 11 7 178 077		0%	20.00FX
318	1	R/F BUMPER BRACKET	51 11 7 178 078		0%	20.00F
336	1	FRONT BUMPER SUPPORT	51 11 7 178 080		0%	520.00F
340	1	R/F IMPACT DAMPER	51 11 7 178 082	Sponge	0%	54.00F
416	1	R/F GRILLE	51 13 7 065 702		0%	110.00F
562	1	RIGHT HEADLAMP ASSY	63 12 7 177 754		0%	1,750.00F
632	1	R/WASHER JET CARRIER	51 11 7 060 586		0%	95.00F
634	1	R/WASHER NOZZLE TRIM	51 11 0 149 266		0%	30.00F
638	1	R/F FOG LAMP	63 17 7 177 712		0%	180.00FX
742	1	R/F WING	41 35 7 111 430		0%	650.00FX
842	1	R/F WHEELHOUSE COVER	51 71 7 033 750		0%	120.00FX
f: OEM Parts		Sub Total				\$4,489.00
g: Original		Mark Up From Cost		(5 %)		\$224.45
h: Secondhand		Sundry Parts		(Fixed)		\$100.00
p: Parallel		Total Parts				\$4,813.45
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER
NB - USING HISTORICAL REFERENCE PRICES

Extras

Description Betterment Price

JIN AUTO SERVICES PTE LTD**Claim Reference: SGU 8287T****Assessment Number: JA000091****Version: JINAUTO1/2****Date Calculated: 17/11/2017 02:42****Full Report - V1****Registration: SGU8287T****Printed: 27/11/2017 10:21**NUMBERPLATE
AUDATEX FEESPECIALIST
SPECIALIST

0%

Total Extras*11* \$40.00 *X*
\$42.00
\$82.00**Final Calculation****Total Parts****\$4,813.45****Labour**

Total Panel/Mechanical

\$314.33 *130.33*

Total Paintwork

\$556.60 *289.60*

Labour Markup (0.0 %)

\$0.00

Total Labour**\$870.93****Additional Costs**

Corr Prot Materials External

\$0.00

Corr Prot Materials Internal

\$0.00

Cost of Specialist

\$82.00

Total of Additional Costs**\$82.00****Total Paint/Material Costs***102.96* **\$205.13****Grand Total Excludes GST****\$5,971.51**

GST @ 7 %

\$418.01**Grand Total Includes GST****\$6,389.52****Assessment Notes**

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER**

079909

**Claim Reference: SNM17D06599C01
Assessment Number: JA000091
Version: JINAUTO1/2
Date Calculated: 28/11/2017 04:52**

**Full Report - V1
Registration: SGU8287T
Printed: 28/11/2017 12:52**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	13/11/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM17D06599C01	Estimated Repair Time:	7 day(s)
Policy Number:	DMPCSN3028861706	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	5 Series
Sub Model:	520 I
Model Sheet Number:	145 01
Registration:	SGU8287T
Registration Month:	September
Registration Year:	2008
VIN Number:	WBANT12030CX29413
Manufacture Year:	2008
Odometer:	157507
Colour:	Other
Engine Number:	A6471171N46B20BE
Fuel Level:	%

Model Specs

FROM 09/2008	BUSINESS EDITION
DIP/FOLD MIRROR	XENON HEADLAMPS
DAKOTA LEATHER TRIM	COMFORT FRONT SEATS
FRONT ACTIVE SEATS	FRONT COMFORT SEATS
2.0 LTR 125 KW	6-SPEED AUTOMATIC
ACTIVE STEERING	DYNAMIC DRIVE
TYRES 225/50 WR 17	WHEELS 7.5J X 17 ALU
ALIGNMENT W/LOADING	SPORTS SUSPENSION
4-DOOR	RAD GRILLE CHROME
PARK DISTANCE CONT	CHROME LINE
TWO COAT METALLIC	PREPARE OFF VEHICLE
PARTS PAINTED	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Fair	Severity of Impact:	
Steering:	Satisfactory	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	16/11/2017
Place of Inspection:			
Pre-Accident Damage:			
Tyres Condition:	Fair	Tread Depth RHF:	
Tread Depth LHF:		Tread Depth RHR:	
Tread Depth LHR:		Direction of Impact:	
Damage Areas:			

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D06599C01

Full Report - V1



Assessment Number: JA000091

Registration: SGU8287T

Version: JINAUTO1/2

Printed: 28/11/2017 12:52

Date Calculated: 28/11/2017 04:52



Addresses

Cost Summary

Total Labour	\$420.13
Total Paint/Material	\$102.96
Total Parts	\$3,983.95
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$4,549.04
7 % GST:	\$318.43
Grand Total Inc GST:	\$4,867.47

Repair Information

LABOUR

Time Basis 12 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	ADD/TIME FOR MAIN WORK	2.0	7.67
51 11 656	R + R FRONT BUMPER	5.0	19.17
51 11 551	R + R FRONT BUMPER CARRIER	3.0	11.50
51 11 592	RENEW FRONT BUMPER COVER (FRONT BUMPER REMOVED)	9.0	34.50
66 20 610	ADD/WORK PARK DISTANCE CONTROL	4.0	15.33
51 11 701	RENEW R/F BUMPER BRACKET (REMOVED)	1.0	3.83
63 12 522)	R + R RIGHT HEADLAMP	5.0	19.17
63 12 524	RENEW R/HEADLAMP (REMOVED)	3.0	11.50
51 47 500	R + R FRONT ASSEMBLY PROTECTION	2.0	7.67

LABOUR COST

Total Work Units	34.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	2.8HRS	\$130.33
Labour Markup	(0.0 %)	\$0.00
Paint Labour	6.3HRS	\$289.80
Total Labour	9.1HRS	\$420.13

NOTE TIME BASIS = 12 WU / HOUR

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number Description

- TWO COAT METALLIC
- PREPARE OFF VEHICLE

WU Cost Price (\$)

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D06599C01

Full Report - V1

Assessment Number: JA000091

Registration: SGU8287T

Version: JINAUTO1/2

Printed: 28/11/2017 12:52

Date Calculated: 28/11/2017 04:52

	- PARTS PAINTED		
1017	FRONT PANEL SURFACE PAINT	4.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	17.0	
634	R/WASHER NOZZLE TRIMREPAIR PAINT PLASTIC	9.0	
LABOUR COST - PAINT			
	TIME(PAINT)	30.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	63.0	
	Total Paintwork Labour	6.3HRS	\$289.80
MATERIAL COST - PAINT			Cost Price
	Surface-/Blend Paint		\$3.74
	Repair Painting Plastic		\$57.92
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$102.96
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$102.96

PARTS

					Price Valid: 01/10/2017	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER COVER	51 11 0 420 276		0%	910.00F
336	1	FRONT BUMPER SUPPORT	51 11 7 178 080		0%	520.00F
313	1	FRT TOWING EYE COVER	51 11 0 430 601		0%	30.00F
318	1	R/F BUMPER BRACKET	51 11 7 178 078		0%	20.00F
638	1	R/F FOG LAMP	63 17 7 177 712		0%	180.00F
416	1	R/F GRILLE	51 13 7 065 702		0%	110.00F
340	1	R/F IMPACT DAMPER	51 11 7 178 082	Sponge	0%	54.00F
632	1	R/WASHER JET CARRIER	51 11 7 060 586		0%	95.00F
634	1	R/WASHER NOZZLE TRIM	51 11 0 149 266		0%	30.00F
562	1	RIGHT HEADLAMP ASSY	63 12 7 177 754		0%	1,750.00F
f: OEM Parts		Sub Total				\$3,699.00
g: Original		Mark Up From Cost (5 %)				\$184.95
h: Secondhand		Sundry Parts (Fixed)				\$100.00
p: Parallel		Total Parts				\$3,983.95
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER
NB - USING HISTORICAL REFERENCE PRICES

Extras

Description	Betterment	Price
AUDATEXFEE	0%	\$42.00
SPECIALIST		
Total Extras		\$42.00

Final Calculation

Total Parts		\$3,983.95
Labour		
Total Panel/Mechanical	\$130.33	
Total Paintwork	\$289.80	
Labour Markup (0.0 %)	\$0.00	
Total Labour		\$420.13
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	

Audatex System Using Manufacturer Times

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D06599C01

Full Report - V1

Assessment Number: JA000091

Registration: SGU8287T

Version: JINAUTO1/2

Printed: 28/11/2017 12:52

Date Calculated: 28/11/2017 04:52

Cost of Specialist	\$42.00	
Total of Additional Costs		\$42.00
Total Paint/Material Costs		\$102.96
Grand Total Excludes GST		<u>\$4,549.04</u>
GST @ 7 %		\$318.43
Grand Total Includes GST		<u>\$4,867.47</u>

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2017 Sendback Est	17 Nov 2017 11:27 S\$5,971.51	17 Nov 2017 12:22 Edit Adj Rpt	S\$3,510.59 Edit Estimates	S\$3,510.59 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SUNDARI D/O JEYARAMAN , ID: S7635134A		
Vehicle Reg. No.:	SGU8287T	Date of Loss:	13/11/2017 14:00 - :59 [109 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM17D06599C01	Policy/Cover Note No.:	DMPCSN3028861706 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/11/2017]		
Driver/Custodian:	SUNDARI D/O JEYARAMAN (41 / Male), NRIC: S7635134A		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (29/11/2017): Alert - Adj Mandate Approved (S\$4549.00) - SGU8287T - Claim Handler: Chong Boon ...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

SGU8287T (SNM17D06599C01)

OD

Nov 13 2017 2:00PM

[SUNDARI D/O JEYARAMAN]

Jin Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#) ▼

Assessment Reports

 1 per page ▼ ☒

No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	17/11/17 11:27	Repairer Estimates	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/11/17 14:44	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

 3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 13:23	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
2	27/11/17 13:23	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
3	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	27/11/17 13:23	General View	1	Load JPG	<input checked="" type="checkbox"/>

Documentation

 1 per page ▼ ☒

Assessment Reports				✓
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail Print
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail Print
1	16/11/17 13:04	E-filed GIA report	i	Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/11/17 14:47	ADJUSTED ESTIMATE	i	Load PDF
2	17/04/18 10:50	REPAIRER INFORM OWNER SOLD THE VEHICLE	i	Load PDF
3	19/06/18 11:13	SGU8287T AMEND GIA	i	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI17021963/URBS2**Date:** 29/06/2018**REFERENCE****Insured/Claimant:** SUNDARI D/O JEYARAMAN
Date of Loss: 13/11/2017**Policy No:** DMPCSN3028861706
Nature of Claim: OD**Claim No:** SNM17D06599C01**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SGU8287T
Make & Model: BMW 520I, 2.0 AT D/AB 2WD 4DR HID NAV (A)
Reg. Date: 17/09/2008 (Man. Year: 2008)
Colour: Grey
Engine Capacity: 1995 cc
Market Value/New Car Price: S\$31,000.00
Sum Insured (S\$): **Market Value/New Car Price****Engine No:** A6471171N46B20BE
Chassis No: WBANT12030CX29413
Odometer: 158040 km**CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Good **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 225/55 R16 **Rear Tyre Size:** 225/55 R16
Front Left Side: Pirelli 5 mm **Rear Left Side:** Goodyear 5 mm
Front Right Side: Pirelli 5 mm **Rear Right Side:** Goodyear 5 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,895.45	2,987.50	1,907.95	38.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,076.06	523.09	552.97	51.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,971.51	3,510.59	2,460.92	41.21
+ GST 7.00/7.00% (S\$)	418.01	245.74	172.27	41.21
Nett Amount (S\$)	6,389.52	3,756.33	2,633.19	41.21

INSPECTION**Date of Assignment:** 17/11/2017 **Present Location:** Jin Auto Services Pte Ltd (Defu)
Date Inspected: 27/11/2017 **Inspected At:** Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195
Estimated Period of Repair: 4.0 days**Adjuster:** MARCUS CHUA**Manager:** Janice Lee Si Hua*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jun 2018)

Parts: 143 BMW 520I 2.0 AT D/AB 2WD 4DR HID NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGU8287T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER COVER (WCP)	Distorted	910.00 F	*910.00 F
2	1	NA	*FRONT BUMPER SUPPORT (WCP)	Repair	520.00 F	*- F
3	1	NA	*FRT TOWING EYE COVER (WCP)	Torn	30.00 F	*30.00 F
4	1	NA	*L/F BUMPER BRACKET (WCP)	Not Necessary	20.00 F	*- F
5	1	NA	*R/F BUMPER BRACKET (WCP)	Necessary	20.00 F	*20.00 F
6	1	NA	*R/F FOG LAMP (WCP)	Not Necessary	180.00 F	*- F
7	1	NA	*R/F GRILLE (WCP)	Not Necessary	110.00 F	*- F
8	1	NA	*R/F IMPACT DAMPER (WCP)	Not Necessary	54.00 F	*- F
9	1	NA	*R/F WHEELHOUSE COVER (WCP)	Not Necessary	120.00 F	*- F
10	1	NA	*R/F WING (WCP)	Repair	650.00 F	*- F
11	1	NA	*R/WASHER JET CARRIER (WCP)	Not Necessary	95.00 F	*- F
12	1	NA	*R/WASHER NOZZLE TRIM (WCP)	Not Necessary	30.00 F	*- F
13	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Cracked	1,750.00 F	*1,750.00 F
14	1	NA	*SPECIALIST AUDATEXFEE		42.00 FS	*42.00 FS
15	1	NA	*SPECIALIST NUMBERPLATE	Not Necessary	40.00 FS	*- FS
16	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,671.00	2,852.00
+ Margin on L,N Items 5.00/5.00% (S\$)	224.45	135.50
Total Parts (S\$)	4,895.45	2,987.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	556.60	289.80
2	Total Paint Materials	New	205.13	102.96
3	Total Panel/Mechanical Labour	New	314.33	130.33
Gross Labour Cost (\$\$)			1,076.06	523.09

Report was unsubmitted during this print-out.

< END OF ESTIMATES >