

ASS. REC BY

REF CS/FCI17022016/Grbn2

Repairer wants GR

Sat/Client

GR

ASSIGNMENT / Officer

CWS

From (Person)

May chua

FCI

Date/Time 3:41pm @ 17/11/17

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

FBL 6847Y

Insured

SHD 4130R

at Workshop m/t

AHM Performance

Tel

97907538

of 1 kaki Bukit Ave 6 #02-46 417883

Policy No

Claim No

D17010542MFSH

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

9/11/2017

CA / REV / REP / REV 24 HRS

'wp'

20/11/2017

H.O.D. Endorsement

Date/Time 5:13pm @ 17/11/17

Person Contacted

AH Hong

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FBL 6847Y - X

SHD 4130R - X

Sent preliminary revised to May through email.

REF: FCL

ASSIGNMENT

From: Date: 20-11-2017

Estimated Cost:

QD TP WS TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBL 6847Y

at Workshop no:

AHM Performance

at:

Blk 1 Kaki Bukit Ave 6 #02-46

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAO Accident Report: Consistent? : Yes or No

GVA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Vehicle:

FBL6847Y

Page: 24 Jan 2017

Type: M/Car / M/C/Bus / Van / Lorry / Taxi / Prime Mover:

Truck / Trailer or

Make:

Honda CB190R cc 184

Colour:

Black

A/C Insured / Std / NI / NA

So Reading:

9172

T-Radio Insured / Std / NI / NA

Eng No:

C No:

LWBPC L100G-1011290

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Incl / Jammed / Leaked / Burnt or

Brake: Incl / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size:

F:

110/70 R17

R:

140 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CST

Front:

Rear:

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

mm

L/Bal:

D/OA:

D/OA:

20-11-17

Survey held at:

w/s

12pm

Des. of Damages: Fnt / Rear / OS / US / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

13/12 Finalised \$ 2892.8 with Hony.

Red: \$ 622.20, 19%

15/12/2017

RECEIVED 15 DEC 2017

Date/Time File Passed:



: Prel. Report

typist



: Final Report

Date/Time File Returned:

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Fuel:

Phone:

Total:

Total:

Add Fee:



Site Insp:

\$



Intercept:

\$



Tech Insp:

\$



Misc:

\$

Report Format:

TP

Lump / LB / S:

2592.80

130

50

50

91

321



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022016/Grb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4130R	Veh. Inspected	FBL 6847Y
Policy No.		Coverage (\$)	0.00
Claim No.	D17010542MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	17/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/11/2017	Inspection Date
Survey held at	AHM PERFORMANCE BLK 1 KAKI BUKIT AVE 6 #02-46 SINGAPORE 417883	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	13-11-2017	Our Ref No. D17010542MFSH
Accident Date	09-11-2017	Claim Type. Third Party
Insured Vehicle	SHD4130R	Third Party Vehicle. FBL6847Y
Survey Location	1 Kaki Bukit Avenue 6 #02-46	
Contact Person.	MR AH HONG	
Contact No.	68461884/ 97907538	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AHM PERFORMANCE	Attention. NIL
Cc : TP Solicitor	LEGAL OPTIONS LLC	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230136)



PRI Documents



Close



PRI Header Details

Claim No	D17010542MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & LEGAL OP
Workshop Name	AHM PERFORMANCE (Contact Person : MR AH HONG)	Survey Location & Contact Details	1 Kaki Bukit Avenue 6 #02-46 Mobile: 97907538 , Phone: 68461884 , Fax: 0 EmailId: CRYSTAL@LEGALOPTIONS.BIZ		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4130R	TP Vehicle No	FBL6847Y
PRI Recieved Date	16-11-2017 07:50:11 PM	Surveyor Appointed Date	17-11-2017 03:40:31 PM	Surveyor Accept Date	17-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	17-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010542MFSH

Our Ref: CS/FCI17022016/Grb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBL 6847Y .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/11/2017 at the premises of M/s AHM PERFORMANCE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 3,077.00 .
Revised Estimate Amount	: S\$ 2,407.00 .
"Check" Items Amount	: S\$ 550.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the n/s and o/s body.



Yours faithfully

XING GUO QIANG
Automotive Assessor

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Wednesday, November 29, 2017 12:15 PM
To: 'Claim Workflow System'; MAYCHUA@FIRST-INSURANCE.COM.SG
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D17010542MFSH/1
Attachments: FBL 6847Y.pdf

Dear May,

Enclosed preliminary revised **FBL 6847Y**.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, November 17, 2017 5:15 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010542MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Friday, 17 November, 2017 3:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; MAYCHUA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010542MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

1709

1784

10% : 1605.46

2.55.6

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	9277G

Vehicle Details

Vehicle No.	FBL6847Y
Vehicle to be Exported	No
Intended De-registration Date	21 Nov 2017
Vehicle Make	HONDA
Vehicle Model	CB190R MANUAL
Primary Colour	Black
Manufacturing Year	2016
Engine No.	WH161FMK16L01270
Chassis No.	LWBPCL100G1011290
Maximum Power Output	-
Open Market Value	\$3,450.00
Original Registration Date	24 Jan 2017
First Registration Date	24 Jan 2017
Transfer Count	1
Actual ARF Paid	\$518.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	23 Jan 2027
COE Category	D - Motorcycle
COE Period(Years)	10
QP Paid	\$6,052.00
COE Rebate Amount	\$5,550.00
Total Rebate Amount	\$5,550.00

The information contained herein is correct as at 21 Nov 2017

OK

MALOSSI

ENGINES AND SPECIAL PARTS

Auto Consultants hence notify
 Repairer the following:
 - Repairer must be notified after spray painting
 - Supply damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
data
 Acknowledged by Repairer
 Signature: _____
 Date: 16-11-17



PBL 68H7Y

'black'

03190R

front murguard

890 / / Cut

Headlamp

8585 / / Scr.

front signal "L"

8115 / / Cut

clutch lever

828 / / Cut

handle bar "L"

8165 / / BT

handle balancer "L"

818 / / Cut

mirror "L"

855 / / Cut

~~in unit~~

in bracket

828 / / BT

Fuel tank cover "L"

8210 / / CMA

Gear pedal

875 / / BT

front footrest "L"

895 / / Cut

side stand

845 X Repair.

main stand

875 X Repair

Rear box

8180 / / Cut

2472

Exhaust pipe

8550 / / Cut

10% : 224.8

Exhaust cover

865 / / CMA

2592.8

LH side cover

875 / / Cut

Tow

845 40.

labour

8400 150.

left side cover 'Black'

868 / / Cut

in unit "net price"

8160 (SN) / / Cut

in cover

818 (SN) / / Cut

part by part ~~2468.6~~

~~ump~~ ~~1650~~

left inner shroud 870 / CMA

Guo Giang - 8288 0282

2011/17 2Days. After repair photos.

3215

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022016/Grbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-12-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4130R	Veh. Inspected	FBL 6847Y	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010542MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	17/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB190R	c.c	184	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	LWBPCL100G1011290	Colour	BLACK	
Odometer	9172	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70 R17	CST	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R17	CST	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/11/2017	Inspection Date	20/11/2017	
Survey held at	AHM PERFORMANCE BLK 1 KAKI BUKIT AVE 6 #02-46 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 6847Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT MUDGUARD	CUT	90.00	90.00
1	HEADLAMP	SCRATCHED	585.00	585.00
1	FRONT SIGNAL "L"	CUT	115.00	115.00
1	CLUTCH LEVER	CUT	28.00	28.00
1	HANDLE BAR "L"	BENT	165.00	165.00
1	HANDLE BALANCER "L"	CUT	18.00	18.00
1	MIRROR "L"	CUT	55.00	55.00
1	IU BRACKET	BENT	28.00	28.00
1	FUEL TANL COVER "L"	CRACKED	210.00	210.00
1	REAR PEDAL	BENT	75.00	75.00
1	FRONT FOOTREST "L"	CUT	95.00	95.00
1	SIDE STAND	TO REPAIR SEE LABOUR	45.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	75.00	-
1	REAR BOX	CUT	180.00	180.00
1	EXHAUST PIPE	CUT	550.00	550.00
1	EXHAUST COVER	CRACKED	65.00	65.00
1	LH SIDE COVER	CRACKED	75.00	75.00
1	LEFT SIDE COVER "BLACK"	CUT	68.00	68.00
1	LEFT INNER SHROUD	CRACKED	70.00	70.00
	LESS 10% DISCOUNT		-	-247.20
			2,592.00	2,224.80
SPECIAL NETT ITEMS				
1	IU UNIT (SN)	CUT	160.00	160.00
1	IU COVER (SN)	CUT	18.00	18.00
			178.00	178.00
LABOUR				
	TOW.		45.00	40.00

Report Ref No. CS/FCI17022016/Grbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR INCLUSIVE OF THE REPAIR OF SIDE STAND AND MAIN STAND.		400.00	150.00
			445.00	190.00
GRAND TOTAL			3,215.00	2,592.80
RECOMMENDED COST OF REPAIRS				2,592.80

Report Ref No. CS/FCI17022016/Grbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.