

ASS. REC. BY:

REF:

TP / CS / TP17022042 / Kvb2

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJY 7168D Yr Regn: 09, 10

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis c.c. 1598

Colour: M. Green A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NR053722E106177633

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 2/11/17

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 15/11/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

D/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/11 File pass to Carhome, better floor

SJY 7168D - X

7/12 11/12 891302 email (Ref 8133.97, 477)

RECEIVED 8 7 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 7/12 - typist

Days Of Repair: 11

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: TP

Lump Sum / I.B.I.: (\$ 9150)

Survey Fee:

Transportation:

\$ - RS \$

Photos

Others

TOTAL

TX15=105

170+

50

50

58

80

513

# Survey Department Check List (Case Handler)

Reference No.: CS/TP170 22042/Kvb  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin ( ): Case handler to make sure all Information created by the assignment team are ACCURATE.

## (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor ( ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp. Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des. of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 3/12/17  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ESTEEM PERFORMANCE PL \*

Ref : CS/TP17022042/Kvb

BLK 5033, #01-259, ANG MO KIO INDUSTRIAL  
PARK 2, SINGAPORE 569536

Date : 20-11-2017



Code : TP053

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SJY 7168D
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	20/11/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	02/11/2017	Inspection Date	15/11/2017
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

## 5a. Remarks

--	--

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	13/11/2017 18:22
Date Of Accident	02/11/2017 18:05
Exact Location Of Accident	AIRPORT RD BEFORE TPE/KPE ENTRANCE TWDS TAMPINES
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SJY7168D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66039399

**Vehicle Particulars**

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

**Insurance Company**

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD16V16658/VPZ/R02
Cover Note Number	

**Driver**

Name of Driver	ROSLAN BIN MAULOD
NRIC No	S1668763D
Date Of Birth	31/05/1964
Occupation	OUTDOOR
Date Of Driving Pass	06/03/1989
Driving Experience	28 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91547385
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 223C COMPASSVALE WALK #03-667
Postcode	543223
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	BGV3621 (PRIVATE CAR)
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER AS ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	BGV3621
Vehicle Make/Model/Colour	TOYOTA CAMRY
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature

Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan \*



7/7



Describe Circumstance of the Accident \*

- Traffic was heavy on Airport Road (towards KPE/TPE entrance towards Tampines).
- SKB 3405E was stopping to join the queue before the entrance & I also stopped behind her.
- Suddenly the car behind me, a BGV3621 banged onto me which make my car banged the car SKB 3405E.
- No injuries were sustained to me & the other car exchanged particulars while the Malaysian registered car driver called TP.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

\*

*[Signature]* 09/11/17-  
0130

Driver's Signature (if driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre Personnel

6/7



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SJY 7168 D

Parts	(a) Cost / List Price Items	\$ 15,493.42
	Plus/Less 25%	\$ 3,873.36
	Total of Cost / List	\$ 11,620.07
	(b) Nett Price Items	
	Less	
	Total of Nett Item	
	(c) Special Nett Items	\$ 335.00
Total Parts Cost		\$ 11,955.07
Labour		\$ 5,150.00
Total		\$ 17,105.07

Not Authorized  
11 Sep 8 91501  
Resurvey After Repair

17239.23  
17,283.97

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : UKC  
Survey conducted on : 15/11/17 at

### Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 11 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Se

Date: 15/11/17





# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : SJY 7168 D  
Make & Model : TOYOTA ALTIS  
Chassis No : MR053ZEE106177633

Submit By : Carmen Lim  
Year Manufacture : 2010  
Engine No. :   
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>B<sub>1</sub></i>	1	\$45.00	S.N	✓
2	Bonnet <i>B<sub>1</sub></i>	1	\$788.01		✓
3	Bonnet lock <i>D<sub>1</sub></i>	1	\$101.70		✓
4	Bonnet hinge LH <i>B<sub>1</sub></i>	1	\$61.64		✓
5	Bonnet hinge RH <i>B<sub>1</sub></i>	1	\$61.64		✓
6	Headlamp LH <i>P<sub>1</sub></i>	1	\$495.20		✗
7	Headlamp RH <i>J<sub>1</sub></i>	1	\$495.20		✗
8	Front grille <i>C<sub>1</sub></i>	1	\$342.60		✓
9	Front grille logo <i>M<sub>1</sub></i>	1	\$66.07		✓
10	Front support panel (complete) <i>B<sub>1</sub></i>	1	\$727.30		✓
11	Brace panel <i>B<sub>1</sub></i>	1	\$125.70		✓
12	Condenser <i>J<sub>1</sub></i>	1	\$1,289.24		✗
13	Condenser fan motor <i>J<sub>1</sub></i>	1	\$250.20		✗
14	Condenser fan blade <i>J<sub>1</sub></i>	1	\$148.50		✗
15	Condenser fan cowling <i>J<sub>1</sub></i>	1	\$205.01		✗
16	Radiator <i>1/2001 C<sub>1</sub></i>	1	\$1,681.96		✓
17	Coolant <i>M<sub>1</sub></i>	1	\$45.00	S.N	25 J <sub>1</sub>
18	Front bumper <i>B<sub>1</sub></i>	1	\$457.21		✓
19	Front bumper clip <i>M<sub>1</sub></i>	10	\$40.00		✓
20	Front bumper reinforcement <i>B<sub>1</sub></i>	1	\$359.31		✓
21	Front bumper side retainer LH <i>D<sub>1</sub></i>	1	\$65.33		✓
22	Front bumper side retainer RH <i>D<sub>1</sub></i>	1	\$65.33		✓
23	Front bumper bracket LH <i>R</i>	1	\$44.17		✗

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. :  
 Make & Model :  
 Chassis No :

**SJY 7168 D**

TOYOTA ALTIS

MR053ZEE106177633

Submit By :  
 Year Manufacture :  
 Engine No. :  
**Cost / List**

**Carmen Lim**

2010

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Front bumper bracket RH <i>R</i>	1	\$44.17		<i>X</i>
25	Front bumper lower grille <i>Di</i>	1	\$152.81		<i>2</i>
26	LH front fender <i>R</i>	1	\$386.28		<i>X</i>
27	LH front fender undershield <i>Sn</i>	1	\$185.20		<i>X</i>
28	LH front fender undershield clip <i>nn</i>	8	\$28.00		<i>X</i>
29	RH front fender <i>R</i>	1	\$386.28		<i>X</i>
30	RH front fender undershield <i>Sn</i>	1	\$185.20		<i>X</i>
31	RH front fender undershield clip <i>nn</i>	8	\$28.00		<i>X</i>
32	Reverse sensor <i>short</i>	2	\$200.00	S.N	<i>✓</i>
33	Rear number plate <i>Det</i>	1	\$45.00	S.N	<i>✓</i>
34	Rear No.plate lamp LH <i>Sn</i>	1	\$57.20		<i>X</i>
35	Rear No.plate lamp RH <i>Sn</i>	1	\$57.20		<i>X</i>
36	Rear bumper <i>Ry</i>	1	\$564.00		<i>✓</i>
37	Rear bumper clip <i>nn</i>	10	\$40.00		<i>✓</i>
38	Rear bumper side retainer LH <i>Di</i>	1	\$57.80		<i>✓</i>
39	Rear bumper side retainer RH <i>Di</i>	1	\$57.80		<i>✓</i>
40	Rear bumper bracket LH <i>Ry</i>	1	\$103.70		<i>✓</i>
41	Rear bumper bracket RH <i>Ry</i>	1	\$103.70		<i>✓</i>
42	Rear bumper sponge <i>CM</i>	1	\$144.67		<i>✓</i>
43	Rear bumper reflector LH <i>Sn</i>	1	\$67.76		<i>X</i>
44	Rear bumper reflector RH <i>Sn</i>	1	\$67.76		<i>X</i>
45	Bootlid <i>Ry</i>	1	\$859.60		<i>✓</i>
46	Bootlid lock <i>Det</i>	1	\$116.80		<i>✓</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. :  
 Make & Model :  
 Chassis No. :

**SJY 7168 D**

TOYOTA ALTIS  
 MR053ZEE106177633

Submit By :  
 Year Manufacture :  
 Engine No. :

**Carmen Lim**  
 2010

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Bootlid hinge LH <i>R</i>	1	\$96.60		X
48	Bootlid hinge RH <i>R</i>	1	\$96.60		X
49	Bootlid emblem <i>RM</i>	1	\$44.17		✓
50	Wording "1.6" <i>RM</i>	1	\$45.60		✓
51	Wording "ALTIS" <i>RM</i>	1	\$48.19		✓
52	Wording "COROLLA" <i>RM</i>	1	\$41.23		✓
53	Bootlid chrome <i>Pullway Box</i>	1	\$223.21		✓
54	Bootlid reflector LH <i>CM</i>	1	\$222.95		✓
55	Bootlid reflector RH <i>CM</i>	1	\$222.95		✓
56	Tail end panel <i>B</i>	1	\$580.60		✓
57	Tail end panel garnish <i>RM</i>	1	\$252.70		✓
58	Tail end panel garnish clip <i>RM</i>	8	\$28.00		✓
59	Boot weatherstrip <i>CM</i>	1	\$184.70	<i>92.35</i>	<i>50% RM</i>
60	Tail lamp LH <i>CM</i>	1	\$350.66		✓
61	Tail lamp RH <i>CM</i>	1	\$350.66		✓
62	Spare tyre well panel <i>R</i>	1	\$780.15		X
63	Spare tyre board <i>Return</i>	1	\$359.20		✓
64					
65					
66					
67					
68					
69		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
 Company Reg No. 200005485N / GST No. 20-0005485-N



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Labour

Vehicle No. : **SJY 7168 D** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA ALTIS** Year of Manufacture : **2010**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,REAR BUMPER,BOOTLID, END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,800.00	1400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,REAR BUMPER,BOOTLID, END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$2,400.00	1600
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
5	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100
6	To tuff coat.	\$300.00	120
7	To transfer boot mechanism to new boot	\$120.00	50
8	Towing	\$60.00	✓
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

**ESTEEM PERFORMANCE PTE LTD**

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

**Spare Parts**

Vehicle No. :

Make &amp; Model :

Chassis No. :

**SJY 7168 D**

TOYOTA ALTIS

MR053ZEE106177633

Submit By :

Year Manufacture :

Engine No. :

Cost / List

**CARMEN LIM**

2010

**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Engine under cover <i>C/D</i>	1	\$178.90		✓
2		1			
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ESTEEM PERFORMANCE PL \*

Ref : CS/TP17022042/Kvbn2

BLK 5033, #01-259, ANG MO KIO INDUSTRIAL  
PARK 2, SINGAPORE 569536

Date : 14-12-2017



ON BEHALF OF GOLDBELL CAR RENTAL PTE LTD Code : TP053

## Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	Veh. Inspected	SJY 7168D
	Policy No.	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	15/11/2017

## Vehicle Particulars & Condition

2.	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	MR053ZEE106177633	Colour	METALLIC GREEN
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		

## Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	4 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	4 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	3 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	3 mm

## Description of Damages

4.	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
----	--

## General Information

5.	Accident Date	02/11/2017	Inspection Date	15/11/2017
	Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

## Remarks

5a.	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
-----	---

## Estimate Days of Repair

5b.	ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-----	-------------------------------------	-----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 7168D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BONNET	BENT	788.01	788.01
1	BONNET LOCK	DISTORTED	101.70	101.70
1	BONNET HINGE LH	BENT	61.64	61.64
1	BONNET HINGE RH	BENT	61.64	61.64
1	HEADLAMP LH	SERVICEABLE	495.20	-
1	HEADLAMP RH	SERVICEABLE	495.20	-
1	FRONT GRILLE	CRACKED	342.60	342.60
1	FRONT GRILLE LOGO	NECESSARY	66.07	66.07
1	FRONT SUPPORT PANEL (COMPLETE)	BENT	727.30	727.30
1	BRACE PANEL	BENT	125.70	125.70
1	CONDENSER	SERVICEABLE	1,289.24	-
1	CONDENSER FAN MOTOR	SERVICEABLE	250.20	-
1	CONDENSER FAN BLADE	SERVICEABLE	148.50	-
1	CONDENSER FAN COWLING	SERVICEABLE	205.01	-
1	RADIATOR	HOUSING CRACKED	1,681.96	1,681.96
1	FRONT BUMPER	BENT	457.21	457.21
10	FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPER REINFORCEMENT	BENT	359.31	359.31
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	65.33	65.33
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	65.33	65.33
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	44.17	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	44.17	-
1	FRONT BUMPER LOWER GRILLE	MISSING	152.81	152.81
1	LH FRONT FENDER	TO REPAIR SEE LABOUR	386.28	-
1	LH FRONT FENDER UNDERSHIELD	SERVICEABLE	185.20	-
8	LH FRONT FENDER UNDERSHIELD CLIP	NOT NECESSARY	28.00	-
1	RH FRONT FENDER	TO REPAIR SEE LABOUR	386.28	-
1	RH FRONT FENDER UNDERSHIELD	SERVICEABLE	185.20	-
8	RH FRONT FENDER UNDERSHIELD CLIP	NOT NECESSARY	28.00	-
1	REAR NO PLATE LAMP LH	SERVICEABLE	57.20	-

Report Ref No. CS/TP17022042/Kvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NO PLATE LAMP RH	SERVICEABLE	57.20	-
1	REAR BUMPER	BENT	564.00	564.00
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	57.80	57.80
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	57.80	57.80
1	REAR BUMPER BRACKET LH	BENT	103.70	103.70
1	REAR BUMPER BRACKET RH	BENT	103.70	103.70
1	REAR BUMPER SPONGE	CRACKED	144.67	144.67
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	67.76	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	67.76	-
1	BOOTLID	BENT	859.60	859.60
1	BOOTLID LOCK	DENTED	116.80	116.80
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	96.60	-
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	96.60	-
1	BOOTLID EMBLEM	NECESSARY	44.17	44.17
1	WORDING "1.6"	NECESSARY	45.60	45.60
1	WORDING "ALTIS"	NECESSARY	48.19	48.19
1	WORDING "COROLLA"	NECESSARY	41.23	41.23
1	BOOTLID CHROME	DENTED / WARPED	223.21	223.21
1	BOOTLID REFLECTOR LH	CRACKED	222.95	222.95
1	BOOTLID REFLECTOR RH	CUT	222.95	222.95
1	TAIL END PANEL	BENT	580.60	580.60
1	TAIL END PANEL GARNISH	DENTED	252.70	252.70
8	TAIL END PANEL GARNISH CLIP	NECESSARY	28.00	28.00
1	TAIL LAMP LH	CRACKED	350.66	350.66
1	TAIL LAMP RH	CRACKED	350.66	350.66
1	SPARE TYRE WELL PANEL	TO REPAIR SEE LABOUR	780.15	-
1	SPARE TYRE BOARD	DEFORMED	359.20	359.20
1	ENGINE UNDER COVER	CRACKED	178.90	178.90
	LESS 25% DISCOUNT		-3,871.91	-2,523.43
			11,615.71	7,570.27
1	BOOT WEATHERSTRIP (50%)(SN)	CUT	184.70	92.35

Report Ref No. CS/TP17022042/Kvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-46.18	-
			138.52	92.35
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	BENT	45.00	45.00
1	COOLANT (SN)	NECESSARY	45.00	25.00
2	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	REAR NUMBER PLATE (SN)	DENTED	45.00	45.00
			335.00	315.00
	<b><u>LABOUR</u></b>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER,BONNET,SUPPORT PANEL,LHF FENDER,RHF FENDER,REAR BUMPER,BOOTLID,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER).INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET LH,FRONT BUMPER BRACKET RH,LH FRONT FENDER,RH FRONT FENDER,BOOTLID HINGE LH,BOOTLID HINGE RH AND SPARE TYRE WELL PANEL.		1,800.00	1,400.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,BONNET,SUPPORT PANEL,LHF FENDER,RHF FENDER,REAR BUMPER,BOOTLID,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER).		2,400.00	1,600.00
	TO CHECK WIRING & FOCUS HEADLAMP.		50.00	40.00
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD.		150.00	60.00
	TO REMOVE & REFIT RADIATOR,CONDENSER TO ASSIST WORK LOAD,TO TOP UP A/C GAS		150.00	100.00
	TO TUFF COAT.		300.00	120.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	50.00
	TOWING.		60.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
	-		-	-
	-		-	-
	-		-	-
			5,150.00	3,450.00
	<b>GRAND TOTAL</b>		<b>17,239.23</b>	<b>11,427.62</b>

Report Ref No. CS/TP17022042/Kvbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,150.00
---	--	--	----------

Report Ref No. CS/TP17022042/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.