LIU'S BROTHER AUTO ENGINEERING WORKSHOP

Invoice/Ref No: GBC75U170223

*U-U	ROBNO: 53291793J, Tel: 6741-1730 / 731, Fax: 6744-5746. Email: husbro@ymail.com	Es	timate
Customer Name: Address:	AXA Insurance Singapore Pte Ltd Motor Claims Department 8 Shenton Way #27-01 AXA Tower Singapore 068811	Date: Vehicle No: Model/Make: 5M/T ABS 2DR	15-11-17 GBC75U Nissan Cabstar 3.0 2WD Turbo
Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1 2 3	Rear Power Gate "U" Panel Power Gate "Triangle" Cover Pillar "Eubres" Garnish Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs To putty & spray painting & including touch up paint on accident affected areas	\$ 800.00 \$ 180.00 \$ 300.00 \$ 800.00 \$ 400.00	sn 8 sn 8 sn 7 - 460
	Total Parts & Labour of estimate for damaged vehicle Total amount in Part By Part / Lump Sum Basis for repaired vehicle SDLS: Wat Aulw (1) wh	\$ 2,480.00	\$
	NOT Arthornal Male /11/17 Why phio Alle P/P A	M/s Liu's Brot	ther Auto Engrg W
	2 A LKK Auto Consultants pence potify		

P1050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: