

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/074/2017
DATE : 14-NOV-2017

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL :
FAX :

OWNER'S NAME : ISHIWATA TADAYOSHI
ADDRESS : APT BLK 618 JURONG WEST STREET 65
#14-424
S(640618)
TELEPHONE NO : 98475115

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100478696-01
VEHICLE NO : SLF1541A
MODEL CODE : BS9BKLC
MODEL/YEAR : OUTBACK 2.5I-S AWD CVT
ENGINE NO : FB25Y357538
CHASSIS NO : JF2BS9KC2GG039245
MILEAGE : 1 KM
DATE IN : 14/11/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 14/11/2017

Print Date : 14/11/2017
Print Time : 20:01:45

Tanjik 9749 5749
'WP'

22/11/17 C 1445

Resurvey before paint

sure@lkkauto.com

5-6 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLF1541A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO SUPPLY AND REPLACE BUMPER ASSY, TAILGATE, REAR BUMPER BEAM AND REAR UNDERGUARD 580	3480.00	\$ 1740.
2	ZZ/002	TO SPRAY REAR BUMPER, REAR TAILGATE AND REAR BUMPER BEAM 440	1320.00	880.
3	ZZ/003	TRANSFER TAILGATE MECHANISM	200.00	X
4	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	150.00	✓
5	ZZ/005	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	200.00	X
6	ZZ/006	REMOVE & INSTALL REAR WINDSCREEN	400.00	X
7	ZZ/007	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	350.00	✓
8	ZZ/008	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	250.00	X
9	ZZ/009	SUNDRIES	100.00	50.
TOTAL LABOUR CHARGES			6450.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLF1541A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	SKIRT COMPL R OBK	52401AL0319P	338.00	?		
2	BUMPER FACE R OBKFHI	57704AL130	773.00	de		
3	BEAM COMPL R OBK EU	57719AL020	515.00	?		
4	COVER HOOK R OBK FHI	57731AL390W6	15.00	Rp		
5	REAR RESIN UNDER GUARD OBK	57734AL050			351.00	de
6	PANEL COMPL R GATE	60809AL0109P	1394.90	Rp		
7	GLASS ASSY R G	63019AL140	2419.56	x		
8	RUBBER DAM GLS	63232AL020	9.40	x		
9	SEAL GLS RG B	63242AL010	6.00	x		
10	WSTR DR R GATE	63516AL000	145.10	?		
11	GARNISH	91111AL000NN	341.90	x		
12	PROTECTOR-REAR GARNISH	91713AG040	18.60	x		
13	PROTECTOR UPR	91713AL000	29.00	?		
14	PROTECTOR LWR SD	91713AL150	4.00	?		
15	PROTECTOR SD A	91713AL160	4.00	?		
16	PROTECTOR SD	91713SG020	16.00	?		
17	PROTECTOR LWR	91713VA040	4.00	?		
18	ORNAMENT F 6KA	93013AL000	94.00	net		
19	ORNAMENT R OBK 6KA	93033AL040	94.00	net		
20	LETTER MK "OUTBACK"	93079AL000	66.00	net		
21	LETTER MK HOYO	93079AL020	94.00	net		
SUB TOTAL			6381.46	0.00	351.00	0.00
LESS DISCOUNT (NETT-20 %)			1276.29	0.00	0.00	0.00
GRAND TOTAL			5105.17	0.00	351.00	0.00
OVERALL TOTAL			5456.17			

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

		DAMAGED PARTS & PRICES			

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT S/LIST REMARKS
		-----	-----	-----	-----
			-----	-----	-----

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLF1541A

TOTAL LABOUR CHARGES	6450.00
TOTAL SPARE PARTS CHARGES	5456.17

GRAND TOTAL	11906.17 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.