

ASS. REC. BY:

REF: CS/CTU7022156/Rcd302 Special Instruction:

Supervisor:

Rasul

ASSIGNMENT (Office)

From (Person): Joel Tan of CTL Date/Time: 21.11.2017 11:30am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCM 794M Insured: SJF 52493
at Workshop m/s Hua Hong Tel: 6661 9695 / ~~6960 9690~~
of 257 Sungai Kudat St 1

Policy No: DM11CSN 1558631601 Claim No: 3NM1700654202/9

Sum Insured: Excess:

Make of Veh: D.O.A. 13.11.2017
(Client's Record)

CA / REV / REP. / REV 24 HRS up. H.O.D. Endorsement:

Date/Time: 21.11.2017 11:30am Person Contacted: Mrs. Tan Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SCM 794M - X
	SJF 52493 - X

06/1/17
SurreyVIC

Fane

REF:

04741

COT XP124: 2021/APR

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SCM 794M

at Workshop m/s Hua Hong

of 250 Summer Knap ST 1

Insured: CTI/HP

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. of Market Value: 27K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCM 794M Yr Reg: 1996 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 318IA/4DR c.c. 1596

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 184108 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA CA8 2040 AA 695 33

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/11/17 D.O.I. 21/11/17

Survey held at Hua Hong

Des. of Damages: FR / REAR / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

repair limit 11K
29/5/17 5:31pm Confirmed LR \$11,000 and 14 days with Ashley. (Ref 6891.68, 386)

RECEIVED 3 APR 2019

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 14

Resurvey No. of Trip: 1

Survey Fee	200
Transportation	
Site Insp (\$)	
Interview (\$)	
Tech. Invs (\$)	
Weekend (\$)	
Photos	
Others	
TOTAL	200

Add Fee: : Site Insp (\$ _____)) S + RS _____

: Interview (\$ _____)) Photos

: Tech. Invs (\$ _____)) Others

: Weekend (\$ _____))

Report Format: TP

Lump Sum / I.B.I: (\$ 11,000)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17022156/R1rb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-11-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 5249S	Veh. Inspected	SCM 794M
Policy No.	DMHCSN1558631601	Coverage (\$)	0.00
Claim No.	SNM17D06542C02/9	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	21/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/11/2017	Inspection Date	21/11/2017
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Nov 2017 Sendback Est	17 Nov 2017 15:20 S\$17,707.93	21 Nov 2017 11:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS				
Insured:	UNKNOWN, ID: 526904741, Tel: +6593820271			
Main Claimant:	NEOL CHIEW SIN MENG, ID: 526904741			
Vehicle Reg. No.:	SCM794M	Date of Loss:	13/11/2017 08:00 - :59	
Claim Type:	TP / SNM17D06542C02/9	Policy/Cover Note No.:	DMHCSN1558631601	
Vehicle Reg. No. (Insured):	SJF5249S	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1, 729332 Sungei Kadut - Tel: 6760 8815 / 6760 0539			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/11/2017]			
Driver/Custodian (Insured):	UNKNOWN (/ Male), NRIC: 526904741, Tel: +6593820271			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS				
			View All	Search Tasks
			Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 29 March 2019 5:31 PM
To: 'Ashley Tan'
Subject: RE: Finalisation for Vehicle No. SCM794M

Dear Ashley,

As spoken, confirm at limit repair \$11,000/-.

Repair days 14

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Friday, 29 March 2019 5:27 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: Finalisation for Vehicle No. SCM794M

Dear Denise

Confirm lump sum \$11,450?

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9690 | M. 9816 4151 | F. 6661 9699
Follow us @ huahong.com.sg



From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Friday, 29 March 2019 4:56 PM
To: Ashley Tan <ashley@huahong.com.sg>
Subject: RE: Finalisation for Vehicle No. SCM794M

Dear Ashley,

I've done the adjustment.

Rasul (LKKAuto)

From: Ashley Tan <ashley@huahong.com.sg>
Sent: Wednesday, 9 January, 2019 1:35 PM
To: Rasul (LKKAuto)
Subject: RE: Finalisation for Vehicle No. SCM794M

Hi Rasul

Checked items:-

Front Spoiler Filled
Front Trim
Inner Air Guide LH/RH
Front Upper Air Duct
Front Crossmember
Aux Fan
Fan Shroud

Supplementary items:-

Front Bumper Undercover
Front Inner Shield LH ✕

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9690 | M. 9816 4151 | F. 6661 9699
Follow us @ huahong.com.sg



From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Friday, 21 December 2018 10:01 AM
To: Ashley Tan <ashley@huahong.com.sg>
Subject: RE: Finalisation for Vehicle No. SCM794M

Hi Ashley,

Can you name the damage item parts?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK



Save the Earth. Print only when necessary.

From: Ashley Tan [mailto:ashley@huahong.com.sg]
Sent: Monday, 17 December, 2018 2:35 PM
To: Rasul (LKKAuto)
Cc: Janice Lee (LKKAuto); SUR
Subject: Finalisation for Vehicle No. SCM794M

Dear all

Please refer to the files attached for:-

- After paint
- Checked items
- Supplementary items

Supplementary created in Merimen.

Please confirm lump sum finalisation.

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9690 | M. 9816 4151 | F. 6661 9699
Follow us @ huahong.com.sg



Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Wednesday, 22 November, 2017 9:47 AM
To: 'ashley@huahong.com.sg'
Cc: Janice Lee (LKKAuto)
Subject: SCM 794M doa : 13/11/2017

Hi Ashely,

The NETT amount repair limit for this vehicle is 11K
Kindly let Ms Tan know

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type	Singapore NRIC	
Owner ID	04741	
Vehicle Details		
Vehicle No.	SCM794M	
Vehicle to be Exported	Yes	
Intended De-registration Date	14 Nov 2017	
Vehicle Make	B.M.W.	
Vehicle Model	316IA/4DR	
Primary Colour	Silver	
Manufacturing Year	1996	
Engine No.	06498432164E2	
Chassis No.	WBACA82040AA69533	
Maximum Power Output	-	
Open Market Value	\$27,645.00	
Original Registration Date	01 Jul 1996	
First Registration Date	01 Jul 1996	
Transfer Count	4	
Actual ARF Paid	\$41,468.00	
Intended PARF Rebate Details		
PARF Eligibility	Forfeited	
PARF Eligibility Expiry Date	-	
PARF Rebate Amount	\$0.00	
Intended COE Rebate Details		
COE Expiry Date	30 Apr 2021	27,000
COE Category	A - Car (1600cc & below)	15,997
COE Period(Years)	5	<u>11,003</u>
PQP Paid	\$23,039.00	
COE Rebate Amount	\$15,997.00	
Total Rebate Amount	\$15,997.00	
Message		
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.		

The information contained herein is correct as at 14 Nov 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2017 13:40
Date Of Accident	13/11/2017 08:45
Exact Location Of Accident	ALONG AYE TOWARDS CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCM794M
Insured/Policyholder	
Name Of Registered Owner	NEOL CHIEW SIN MENG
NRIC No	S2690474I
Email Address	NOELCHIEW@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98411305
Alternative Phone No	OTHERS-98411305

Vehicle Particulars

Manufacturer	BMW
Model	316IA/4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5087562299
Cover Note Number	

Driver

Name of Driver	NEOL CHIEW SIN MENG
NRIC No	S2690474I
Date Of Birth	16/12/1967
Occupation	INDOOR
Date Of Driving Pass	16/03/1990
Driving Experience	27 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98411305
Fax Number	
Contact Number	OTHERS-98411305
EEmail Address	NOELCHIEW@HOTMAIL.COM

Address	BLK 658 HOUGANG AVENUE 8 #07-435
Postcode	530658
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF5249S
Vehicle Make/Model/Colour	HYUNDAI / BLUE
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLR7539E
Vehicle Make/Model/Colour	TOYOTA

Details Of Properties

Name of Driver	NG KIAN PENG
NRIC/Passport Number	S7019276D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Yong
NRIC/FIN No.:

Claim Reference:
 Assessment Number: HHTP1799
 Version: HUAHON01/1
 Date Calculated: 17/11/2017 07:21

Full Report - V1
 Registration: SCM794M
 Printed: 17/11/2017 15:22

MATERIAL COST - PAINT	Cost Price
Total Excluding Pearlescent Uplift	\$241.87
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$241.87

PARTS

Price Valid: 01/10/2017

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRT SPOILER FILLERED	51 11 2 233 839		0%	CR? 1,040.00*
303	1	BUMPER COVER	51 11 2 233 870		0%	DE 152.00*
321	1	L/F OUT BUMPER BRKT	51 11 2 233 845		0%	neu 18.00*
322	1	R/F BUMPER OUT BRKT	51 11 2 233 846		0%	neu 18.00*
415	1	L/F GRILLE	51 13 8 195 151		0%	Bro 92.00*
416	1	R/F GRILLE	51 13 8 195 152		0%	Bro 92.00*
431	1	GRILLE BADGE	51 14 8 132 375		0%	neu 68.00*
471	1	BONNET	41 61 8 135 343		0%	neu 1,300.00*
475	1	LEFT BONNET HINGE	41 61 8 135 069		0%	neu 55.00*
476	1	RIGHT BONNET HINGE	41 61 8 135 070		0%	neu 55.00*
492	1	L/BONNET LOCK	51 23 1 977 635		0%	neu 35.00*
493	1	R/BONNET LOCK	51 23 1 977 636		0%	neu 35.00*
524	1	BONNET SEAL	51 23 8 207 821		0%	neu 78.00*
561	1	LEFT HEADLAMP ASSY	63 12 8 363 083		0%	Bro 1,100.00*
562	1	RIGHT HEADLAMP ASSY	63 12 8 363 084		0%	CRA 1,100.00*
638	1	R/F FOG LAMP	63 17 8 357 390		0%	CRA 258.00*
677	1	L/F INDICATOR	63 13 8 353 277		0%	SCA 78.00*
678	1	R/F INDICATOR	63 13 8 353 278		0%	SCA 78.00*
950	1	FRONT TRIM	41 33 8 225 981		0%	CRA? 310.00*
977	1	L/INNER AIR GUIDE	51 71 8 156 247		0%	CRA? 68.00*
978	1	R/INNER AIR GUIDE	51 71 8 156 248		0%	CRA? 68.00*
981	1	FRONT UPPER AIR DUCT	51 71 8 119 045		0%	CRA? 85.00*
1001	1	FRONT CROSSMEMBER	41 13 8 132 178		0%	neu 465.00*
1009	1	FRONT PANEL	41 13 8 122 560		0%	neu 520.00*
2583	1	REAR BUMPER COVER	51 12 8 222 447		0%	SCA 885.00*
2586	1	LWR BUMPER CVR TRIM	51 12 1 977 384		0%	SCA 320.00*
2610	1	REAR CTR BUMPER TRIM	51 12 8 146 093		0%	SCA 78.00*
2611	1	L/R SIDE MOULDING	51 12 8 135 487		0%	SCA 58.00*
2612	1	R/R SIDE MOULDING	51 12 8 135 488		0%	SCA 58.00*
2643	1	REAR BUMPER CARRIER	51 12 8 146 015		0%	XAN? 262.00*
2647	1	REAR BUMPER INSERT	51 12 1 960 721		0%	XAN? 116.00*
2931	1	BOOTLID/TAILGATE	41 62 8 119 706		0%	neu 1,100.15*
2944	1	BOOT/TAILGATE SEAL	51 71 1 977 050		0%	neu 95.00*
3011	1	REAR BADGE	51 14 8 132 375		0%	neu 68.00*
3021	1	REAR MODEL BADGE	51 14 8 108 831		0%	neu 52.00*
4449	1	FRONT AIR BAFFLE	51 71 1 977 046		0%	XSL? 140.00*
4465	1	CONDENSER	64 53 8 390 271		0%	XSL? 500.00*
4469	1	AUX FAN	64 50 8 364 093		0%	CRA 800.00*
4479	1	FRONT FAN SHROUD	17 11 1 723 029		0%	XSL 120.00*
7479	1	POWER STRG OIL TANK	32 41 6 851 217		0%	XAN? 98.00*
7761	1	RADIATOR	17 11 1 728 907		0%	XAN? 820.00*
7767	1	FAN SHROUD	17 11 1 723 067		0%	CRA? 120.00*
7793	1	BLOWER	11 52 1 723 363		0%	XSL? 165.00*
7801	1	FAN CLUTCH	11 52 1 740 962		0%	XSL? 135.00*
8888	1	GEARBOX OIL COOLER	17 20 1 728 770		0%	XSL? 850.00*

Hua Hong Pte Ltd

Claim Reference:
 Assessment Number: HHTP1799
 Version: HUAHON01/1
 Date Calculated: 17/11/2017 07:21

Full Report - V1
 Registration: SCM794M
 Printed: 17/11/2017 15:22

1000	1	BUMPER SCREW X10	Renew	0%	<i>Renew</i> 50.00*
1000	1	BONNET LOCK CATCH X2	Renew	0%	<i>PA</i> 110.00*
1000	1	BONNET INSULATOR	Renew	0%	<i>TX</i> 420.00*
1000	1	BONNET INSULA CLIP	Renew	0%	<i>Renew</i> 50.00*
f: OEM Parts			Sub Total		\$14,638.15
g: Original			Mark Up From Cost	(5 %)	\$731.91
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$15,470.06
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE SPECIALIST	0%	\$42.00
FRT/REAR NO PALTE SPECIALIST		<i>Nec</i> \$70.00
AIR CON GAS SPECIALIST	0%	<i>Nec</i> \$50.00
RADIATOR COOLANT SPECIALIST		<i>Nec</i> \$20.00
P/STEERING OIL 2L SPECIALIST	0%	<i>Nec</i> \$20.00
Total Extras		\$202.00

Final Calculation

Total Parts		\$15,470.06
Labour		
Total Panel/Mechanical	\$1,019.67	<i>750.67</i>
Total Paintwork	\$724.50	
Corr Prot Internal 13 WU	\$49.83	
Total Labour		\$1,794.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$202.00	
Total of Additional Costs		\$202.00
Total Paint/Material Costs		\$241.87
Grand Total Excludes GST		\$17,707.93 <i>17,891.68</i>
GST @ 7 %		\$1,239.56
Grand Total Includes GST		\$18,947.49

Assessment Notes

Resin
 Hp 90010088
 14 days
 HS
 21/11/17 P1320
 Resin after repair
 23/11/17

12049.63

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 17 Dec 2018)**Parts:** 143 BMW 316I 1.6 AT D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hua Hong Pte Ltd/SCM794M/17/12/2018 14:28**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bumper Undercover	0.00	0.00	CRA *175.00 F ✓
2	1		*Front Inner Shield LH	0.00	0.00	NN *160.00 F X
Sub Total (S\$)						335.00
+ Margin on L,N Items 5.00% (S\$)						16.75
Total Parts (S\$)						351.75

F=Franchise part.

Hua Hong Pte Ltd/SCM794M/17/12/2018 14:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Hua Hong Pte Ltd
Blk 4, 393H Woodlands
Road,
Yew Tee Industrial Estate
Singapore, 678016

Claim Reference:
Assessment Number: HHTP1799
Version: HUAHON01/1
Date Calculated: 13/03/2019 05:40

Full Report - V1
Registration: SCM794M
Printed: 13/03/2019 13:40

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	hua Hong	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	5087562299	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	3 Series
Sub Model:	316 I
Model Sheet Number:	124 03
Registration:	SCM794M
Registration Month:	
Registration Year:	
VIN Number:	WBACA82040AA69533
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

AIR CONDITIONING	FRONT FOG LAMP HELLA
REPEATER LAMP YELLOW	5-SPEED AUTOMATIC
M-TECH FRONT SPOILER	TWO COAT METALLIC
PREPARE OFF VEHICLE	



Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/11/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Claim Reference:
 Assessment Number: HHTTP1799
 Version: HUAHON01/1
 Date Calculated: 13/03/2019 05:40

Full Report - V1
 Registration: SCM794M
 Printed: 13/03/2019 13:40



Addresses

Cost Summary

Total Labour	\$1,794.00
Total Paint/Material	\$241.87
Total Parts	\$15,821.81
Total of Additional Costs	\$202.00
Excess:	TBA
Grand Total Exc GST:	\$18,059.68
7 % GST:	\$1,264.18
Grand Total Inc GST:	\$19,323.86

Repair Information

LABOUR

Time Basis 12 WU = 1 HR. Price/CL 1 = \$46.00/HR
 Price/Dent = \$0.00/HR

Repair /

Guide Number Repair Details

	WU	Cost Price (\$)
97 00 000/KN RUST PROOFING/UNDERBODY SEALANT		
97 35 020 POST TREATMENT BOTH FRONT SIDE PANELS	8.0	30.67
97 33 510 METAL FINISH FRONT-END TRIM AND FRONT-END PANEL (ASSEMBLY OPERATION)	2.0	7.67
97 61 510 INJECT PROTECTIVE WAX TO BONNET CAVITY (ASSEMBLY OPERATION)	2.0	7.67
97 62 510 INJECT PROTECTIVE WAX TO TAILGATE CAVITY (ASSEMBLY OPERATION)	1.0	3.83
41 33 001 R + R FRONT PANEL CPL INCLUDES: R + R FRONT BUMPER, IMPACT DAMPER, RADIATOR, INNER WHEELHOUSE COVER, HEADLAMP AND FLASHER LAMP R + R PARTIALLY WIRING HARNESS	50.0	191.67
64 50 701 ADDITIONAL WORK FOR SPECIAL EQUIPMENT	16.0	61.33
NO NUMBER ADD/WORK R + R FRONT FOG LAMPS	2.0	7.67
51 11 592 REMOVE/REFIT FRONT BUMPER BAR TRIM (WITH FRONT BUMPER BAR REMOVED)	6.0	23.00
51 11 701 R + R L/FRT BUMPER BRACKET	2.0	7.67
51 11 701 R + R R/FRT BUMPER BRACKET	2.0	7.67
63 10 514 ALIGN FRONT FOG LAMPS	2.0	7.67
41 61 000 R + R BONNET	6.0	23.00
41 61 501 REPLACE BONNET (WITH BONNET REMOVED)	6.0	23.00
41 61 545 RENEW L/BONNET HINGE	1.0	3.83
41 61 545 RENEW R/BONNET HINGE	1.0	3.83
51 12 500 R + R REAR BUMPER	4.0	15.33
51 12 501 REPLACE REAR BUMPER BAR	5.0	19.17

Hua Hong Pte Ltd

Claim Reference:
 Assessment Number: HHTTP1799
 Version: HUAHON01/1
 Date Calculated: 13/03/2019 05:40

Full Report - V1
 Registration: SCM794M
 Printed: 13/03/2019 13:40

	(WITH BUMPER BAR REMOVED)		
63 21 680)	R + R L/TAIL LAMP	2.0	7.67
63 21 680)	R + R R/TAIL LAMP	2.0	7.67
63 21 680)	R + R TAIL LAMP	1.0	3.83
51 71 860	R + R TAILGATE GASKET	1.0	3.83
41 62 000	R + R TAILGATE	9.0	34.50
	INCLUDES: R + R TAILGATE WIRING HARNESS		
41 62 501	REPLACE TAILGATE (WITH TAILGATE REMOVED)	4.0	15.33
17 40 000	R + R ADDITIONAL RADIATOR FAN	7.0	26.83
17 40 550	R + R FAN WHEEL	1.0	3.83
17 40 560	R + R RADIATOR SHROUD	3.0	11.50
64 53 550	R + R AIR CONDITIONING CONDENSER	8.0	30.67
17 11 506	RENEW RADIATOR (REMOVED)	1.0	3.83
11 52 020	R + R FAN CLUTCH	4.0	15.33
0741	REPAIR L/F WING	20.0*	76.67
0742	REPAIR R/F WING	20.0*	76.67
1217	REPAIR L/F CHASSIS LEG-FRT	20.0*	76.67
1218	REPAIR R/F CHASSIS LEG-FRT	20.0*	76.67
2711	REPAIR REAR PANEL	40.0*	153.33
LABOUR COST			
	Total Work Units	279.0	
	Corrosion Protection		
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	1.1HRS	49.83
	Sub Total	23.3HRS	\$1,069.50
	Paint Labour	15.8HRS	\$724.50
	Total Labour	39.0HRS	\$1,794.00

NOTE TIME BASIS = 12 WU / HOUR

PAINT WORK		Time Basis 12 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
99 68 529	FRONT SPOILER PAINTING STAGE 2	16.0	
LE 0303	FRT BUMPER AIR GRILLPAINTING STAGE 2	6.0	
99 33 519)	FRONT PANEL PAINTING STAGE 2	5.0	
99 61 539	BONNET PAINTING STAGE 3	37.0	
99 35 529	L/F WING PAINTING STAGE 3	13.0	
99 35 529	R/F WING PAINTING STAGE 3	13.0	
99 33 537	FRONT TRIM PAINTING STAGE 3	7.0	
99 69 539	REAR BUMPER PAINTING STAGE 3	26.0	
99 34 529	REAR PANEL PAINTING STAGE 3	14.0	
99 62 539	BOOTLID/TAILGATE PAINTING STAGE 3	20.0	
L 1217	L/F CHASSIS LEG END PAINTING STAGE 1	3.0	
L 1218	R/ENGINE CARRIER ENDPAINING STAGE 1	3.0	
99 99 000	ADD/TIME FOR MAIN WORK	26.0	
LABOUR COST - PAINT			
	TIME(PAINT)	0.0	
	Total Work Units (12WU/HR)	189.0	
	Total Paintwork Labour	15.8HRS	\$724.50

Claim Reference:

Assessment Number: HHTTP1799

Version: HUAHON01/1

Date Calculated: 13/03/2019 05:40

Full Report - V1

Registration: SCM794M

Printed: 13/03/2019 13:40

MATERIAL COST - PAINT

Total Excluding Pearlescent Uplift

Pearlescent Uplift @ 0.0%

Total Paint Material Cost

Cost Price

\$241.87

\$0.00

\$241.87

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/05/2018	
					Bet.	Price (\$)
283	1	FRT SPOILER FILLERED	51 11 2 233 839		0%	1,040.00*
303	1	BUMPER COVER	51 11 2 233 870		0%	152.00*
321	1	L/F OUT BUMPER BRKT	51 11 2 233 845		0%	18.00*
322	1	R/F BUMPER OUT BRKT	51 11 2 233 846		0%	18.00*
415	1	L/F GRILLE	51 13 8 195 151		0%	92.00*
416	1	R/F GRILLE	51 13 8 195 152		0%	92.00*
431	1	GRILLE BADGE	51 14 8 132 375		0%	68.00*
471	1	BONNET	41 61 8 135 343		0%	1,300.00*
475	1	LEFT BONNET HINGE	41 61 8 135 069		0%	55.00*
476	1	RIGHT BONNET HINGE	41 61 8 135 070		0%	55.00*
492	1	L/BONNET LOCK	51 23 1 977 635		0%	35.00*
493	1	R/BONNET LOCK	51 23 1 977 636		0%	35.00*
524	1	BONNET SEAL	51 23 8 207 821		0%	78.00*
561	1	LEFT HEADLAMP ASSY	63 12 8 363 083		0%	1,100.00*
562	1	RIGHT HEADLAMP ASSY	63 12 8 363 084		0%	1,100.00*
638	1	R/F FOG LAMP	63 17 8 357 390		0%	258.00*
677	1	L/F INDICATOR	63 13 8 353 277		0%	78.00*
678	1	R/F INDICATOR	63 13 8 353 278		0%	78.00*
843	1	L/F SIDE PANEL COVER	51 71 8 151 561		0%	160.00*
950	1	FRONT TRIM	41 33 8 225 981		0%	310.00*
977	1	L/INNER AIR GUIDE	51 71 8 156 247		0%	68.00*
978	1	R/INNER AIR GUIDE	51 71 8 156 248		0%	68.00*
981	1	FRONT UPPER AIR DUCT	51 71 8 119 045		0%	85.00*
1001	1	FRONT CROSSMEMBER	41 13 8 132 178		0%	465.00*
1009	1	FRONT PANEL	41 13 8 122 560		0%	520.00*
2583	1	REAR BUMPER COVER	51 12 8 222 447		0%	885.00*
2586	1	LWR BUMPER CVR TRIM	51 12 1 977 384		0%	320.00*
2610	1	REAR CTR BUMPER TRIM	51 12 8 146 093		0%	78.00*
2611	1	L/R SIDE MOULDING	51 12 8 135 487		0%	58.00*
2612	1	R/R SIDE MOULDING	51 12 8 135 488		0%	58.00*
2643	1	REAR BUMPER CARRIER	51 12 8 146 015		0%	262.00*
2647	1	REAR BUMPER INSERT	51 12 1 960 721		0%	116.00*
2931	1	BOOTLID/TAILGATE	41 62 8 119 706		0%	1,100.15*
2944	1	BOOT/TAILGATE SEAL	51 71 1 977 050		0%	95.00*
3011	1	REAR BADGE	51 14 8 132 375		0%	68.00*
3021	1	REAR MODEL BADGE	51 14 8 108 831		0%	52.00*
4449	1	FRONT AIR BAFFLE	51 71 1 977 046		0%	140.00*
4465	1	CONDENSER	64 53 8 390 271		0%	500.00*
4469	1	AUX FAN	64 50 8 364 093		0%	800.00*
4479	1	FRONT FAN SHROUD	17 11 1 723 029		0%	120.00*
7479	1	POWER STRG OIL TANK	32 41 6 851 217		0%	98.00*
7761	1	RADIATOR	17 11 1 728 907		0%	820.00*
7767	1	FAN SHROUD	17 11 1 723 067		0%	120.00*
7793	1	BLOWER	11 52 1 723 363		0%	165.00*
7801	1	FAN CLUTCH	11 52 1 740 962		0%	135.00*

Hua Hong Pte Ltd

Claim Reference:
 Assessment Number: HHTTP1799
 Version: HUAHON01/1
 Date Calculated: 13/03/2019 05:40

Full Report - V1
 Registration: SCM794M
 Printed: 13/03/2019 13:40

8888	1	GEARBOX OIL COOLER	17 20 1 728 770	0%	850.00*
1000	1	BUMPER SCREW X10	Renew	0%	50.00*
1000	1	BONNET LOCK CATCH X2	Renew	0%	110.00*
1000	1	BONNET INSULATOR	Renew	0%	420.00*
1000	1	BONNET INSULA CLIP	Renew	0%	50.00*
1000	1	FRT BUMP UNDER COVER	Renew	0%	175.00* CA ✓
f: OEM Parts				Sub Total	\$14,973.15
g: Original				Mark Up From Cost (5 %)	\$748.66
h: Secondhand				Sundry Parts (Fixed)	\$100.00
p: Parallel				Total Parts	\$15,821.81
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE SPECIALIST	0%	\$42.00
FRT/REAR NO PALTE SPECIALIST		\$70.00
AIR CON GAS SPECIALIST	0%	\$50.00
RADIATOR COOLANT SPECIALIST		\$20.00
P/STEERING OIL 2L SPECIALIST	0%	\$20.00
Total Extras		\$202.00

Final Calculation

Total Parts		\$15,821.81
Labour		
Total Panel/Mechanical	\$1,019.67	
Total Paintwork	\$724.50	
Corr Prot Internal 13 WU	\$49.83	
Total Labour		\$1,794.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$202.00	
Total of Additional Costs		\$202.00
Total Paint/Material Costs		\$241.87
Grand Total Excludes GST		\$18,059.68
GST @ 7 %		\$1,264.18
Grand Total Includes GST		\$19,323.86

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: HHTP1799
Version: LKKAUTOC/3
Date Calculated: 29/03/2019 08:54

Full Report - V1
Registration: SCM794M
Printed: 29/03/2019 16:54

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	5087562299	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	3 Series
Sub Model:	316 I
Model Sheet Number:	124 03
Registration:	SCM794M
Registration Month:	
Registration Year:	
VIN Number:	WBACA82040AA69533
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

AIR CONDITIONING	FRONT FOG LAMP HELLA
REPEATER LAMP YELLOW	5-SPEED AUTOMATIC
M-TECH FRONT SPOILER	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/11/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Addresses

Cost Summary

Total Labour	\$1,725.00
Total Paint/Material	\$241.87
Total Parts	\$12,172.01
Total of Additional Costs	\$202.00
Excess:	TBA
Grand Total Exc GST:	\$14,340.88
7 % GST:	\$1,003.86
Grand Total Inc GST:	\$15,344.74

Repair Information

LABOUR

Time Basis 12 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
97 00 000/KN	RUST PROOFING/UNDERBODY SEALANT		
97 35 020	POST TREATMENT BOTH FRONT SIDE PANELS	8.0	30.67
97 33 510	METAL FINISH FRONT-END TRIM AND FRONT-END PANEL (ASSEMBLY OPERATION)	2.0	7.67
97 61 510	INJECT PROTECTIVE WAX TO BONNET CAVITY (ASSEMBLY OPERATION)	2.0	7.67
97 62 510	INJECT PROTECTIVE WAX TO TAILGATE CAVITY (ASSEMBLY OPERATION)	1.0	3.83
41 33 001	R + R FRONT PANEL CPL INCLUDES: R + R FRONT BUMPER, IMPACT DAMPER, RADIATOR, INNER WHEELHOUSE COVER, HEADLAMP AND FLASHER LAMP	50.0	191.67
64 50 701	R + R PARTIALLY WIRING HARNESS ADDITIONAL WORK FOR SPECIAL EQUIPMENT	16.0	61.33
NO NUMBER	ADD/WORK R + R FRONT FOG LAMPS	2.0	7.67
51 11 592	REMOVE/REFIT FRONT BUMPER BAR TRIM (WITH FRONT BUMPER BAR REMOVED)	6.0	23.00
51 11 701	R + R L/FRT BUMPER BRACKET	2.0	7.67
51 11 701	R + R R/FRT BUMPER BRACKET	2.0	7.67
63 10 514	ALIGN FRONT FOG LAMPS	2.0	7.67
41 61 000	R + R BONNET	6.0	23.00
41 61 501	REPLACE BONNET (WITH BONNET REMOVED)	6.0	23.00
51 12 500	R + R REAR BUMPER	4.0	15.33
51 12 657	RENEW REAR BUMPER COVER	5.0	19.17
63 21 680)	R + R L/TAIL LAMP	2.0	7.67
63 21 680)	R + R R/TAIL LAMP	2.0	7.67

Claim Reference:

Full Report - V1

Assessment Number: HHTP1799

Registration: SCM794M

Version: LKKAUTOC/3

Printed: 29/03/2019 16:54

Date Calculated: 29/03/2019 08:54

63 21 680)	R + R TAIL LAMP	1.0	3.83
51 71 860	R + R TAILGATE GASKET	1.0	3.83
41 62 000	R + R TAILGATE	9.0	34.50
	INCLUDES: R + R TAILGATE WIRING HARNESS		
41 62 501	REPLACE TAILGATE (WITH TAILGATE REMOVED)	4.0	15.33
17 40 000	R + R ADDITIONAL RADIATOR FAN	7.0	26.83
17 40 550	R + R FAN WHEEL	1.0	3.83
0741	REPAIR L/F WING	20.0*	76.67
0742	REPAIR R/F WING	20.0*	76.67
1217	REPAIR L/F CHASSIS LEG-FRT	20.0*	76.67
1218	REPAIR R/F CHASSIS LEG-FRT	20.0*	76.67
2711	REPAIR REAR PANEL	40.0*	153.33
LABOUR COST			
	Total Work Units	261.0	
	Corrosion Protection		
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	1.1HRS	49.83
	Sub Total	21.8HRS	\$1,000.50
	Paint Labour	15.8HRS	\$724.50
	Total Labour	37.5HRS	\$1,725.00

NOTE TIME BASIS = 12 WU / HOUR

PAINT WORK		Time Basis 12 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
99 68 529	FRONT SPOILER PAINTING STAGE 2	16.0	
LE 0303	FRT BUMPER AIR GRILLPAINTING STAGE 2	6.0	
99 33 519)	FRONT PANEL PAINTING STAGE 2	5.0	
99 61 539	BONNET PAINTING STAGE 3	37.0	
99 35 529	L/F WING PAINTING STAGE 3	13.0	
99 35 529	R/F WING PAINTING STAGE 3	13.0	
99 33 537	FRONT TRIM PAINTING STAGE 3	7.0	
99 69 539	REAR BUMPER PAINTING STAGE 3	26.0	
99 34 529	REAR PANEL PAINTING STAGE 3	14.0	
99 62 539	BOOTLID/TAILGATE PAINTING STAGE 3	20.0	
L 1217	L/F CHASSIS LEG END PAINTING STAGE 1	3.0	
L 1218	R/ENGINE CARRIER ENDPAINING STAGE 1	3.0	
99 99 000	ADD/TIME FOR MAIN WORK	26.0	
LABOUR COST - PAINT			
	TIME(PAINT)	0.0	
	Total Work Units (12WU/HR)	189.0	
	Total Paintwork Labour	15.8HRS	\$724.50
MATERIAL COST - PAINT			Cost Price
	Total Excluding Pearlescent Uplift		\$241.87
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$241.87

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/05/2018	Bet.	Price (\$)
------------------	------------	--------------------	--------------------	-----------------	--------------------------------	-------------	-------------------

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: HHTP1799

Registration: SCM794M

Version: LKKAUTOC/3

Printed: 29/03/2019 16:54

Date Calculated: 29/03/2019 08:54

283	1	FRT SPOILER FILLERED	51 11 2 233 839	0%	1,040.00*
303	1	BUMPER COVER	51 11 2 233 870	0%	152.00*
321	1	L/F OUT BUMPER BRKT	51 11 2 233 845	0%	18.00*
322	1	R/F BUMPER OUT BRKT	51 11 2 233 846	0%	18.00*
415	1	L/F GRILLE	51 13 8 195 151	0%	92.00*
416	1	R/F GRILLE	51 13 8 195 152	0%	92.00*
431	1	GRILLE BADGE	51 14 8 132 375	0%	68.00*
471	1	BONNET	41 61 8 135 343	0%	1,300.00*
492	1	L/BONNET LOCK	51 23 1 977 635	0%	35.00*
493	1	R/BONNET LOCK	51 23 1 977 636	0%	35.00*
524	1	BONNET SEAL	51 23 8 207 821	0%	78.00*
561	1	LEFT HEADLAMP ASSY	63 12 8 363 083	0%	1,100.00*
562	1	RIGHT HEADLAMP ASSY	63 12 8 363 084	0%	1,100.00*
638	1	R/F FOG LAMP	63 17 8 357 390	0%	258.00*
677	1	L/F INDICATOR	63 13 8 353 277	0%	78.00*
678	1	R/F INDICATOR	63 13 8 353 278	0%	78.00*
950	1	FRONT TRIM	41 33 8 225 981	0%	310.00*
977	1	L/INNER AIR GUIDE	51 71 8 156 247	0%	68.00*
978	1	R/INNER AIR GUIDE	51 71 8 156 248	0%	68.00*
981	1	FRONT UPPER AIR DUCT	51 71 8 119 045	0%	85.00*
1001	1	FRONT CROSSMEMBER	41 13 8 132 178	0%	465.00*
1009	1	FRONT PANEL	41 13 8 122 560	0%	520.00*
2583	1	REAR BUMPER COVER	51 12 8 222 447	0%	885.00*
2586	1	LWR BUMPER CVR TRIM	51 12 1 977 384	0%	320.00*
2610	1	REAR CTR BUMPER TRIM	51 12 8 146 093	0%	78.00*
2611	1	L/R SIDE MOULDING	51 12 8 135 487	0%	58.00*
2612	1	R/R SIDE MOULDING	51 12 8 135 488	0%	58.00*
2931	1	BOOTLID/TAILGATE	41 62 8 119 706	0%	1,100.15*
2944	1	BOOT/TAILGATE SEAL	51 71 1 977 050	0%	95.00*
3011	1	REAR BADGE	51 14 8 132 375	0%	68.00*
3021	1	REAR MODEL BADGE	51 14 8 108 831	0%	52.00*
4469	1	AUX FAN	64 50 8 364 093	0%	800.00*
7767	1	FAN SHROUD	17 11 1 723 067	0%	120.00*
1000	1	BUMPER SCREW X10	Renew	0%	50.00*
1000	1	BONNET LOCK CATCH X2	Renew	0%	110.00*
1000	1	BONNET INSULATOR	Renew	0%	420.00*
1000	1	BONNET INSULA CLIP	Renew	0%	50.00*
1000	1	FRT BUMP UNDER COVER	Renew	0%	175.00*

f: OEM Parts
g: Original
h: Secondhand
p: Parallel
x: Exchange

Sub Total		\$11,497.15
Mark Up From Cost	(5 %)	\$574.86
Sundry Parts	(Fixed)	\$100.00
Total Parts		\$12,172.01

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE SPECIALIST	0%	\$42.00
FRT/REAR NO PALTE SPECIALIST		\$70.00
AIR CON GAS SPECIALIST	0%	\$50.00
RADIATOR COOLANT SPECIALIST		\$20.00
P/STEERING OIL 2L SPECIALIST	0%	\$20.00
Total Extras		\$202.00

Claim Reference:

Full Report - V1

Assessment Number: HHTP1799

Registration: SCM794M

Version: LKKAUTOC/3

Printed: 29/03/2019 16:54

Date Calculated: 29/03/2019 08:54

Final Calculation

Total Parts		\$12,172.01
Labour		
Total Panel/Mechanical	\$950.67	
Total Paintwork	\$724.50	
Corr Prot Internal 13 WU	\$49.83	
Total Labour		\$1,725.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$202.00	
Total of Additional Costs		\$202.00
Total Paint/Material Costs		\$241.87
Grand Total Excludes GST		\$14,340.88
GST @ 7 %		\$1,003.86
Grand Total Includes GST		\$15,344.74

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Nov 2017 Sendback Est	17 Nov 2017 15:20 S\$17,707.93	21 Nov 2017 11:27 Edit Adj Rpt	S\$11,000.00 Edit Estimates	S\$11,000.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	17 Dec 2018 14:24	17 Dec 2018 14:28 S\$351.75	17 Dec 2018 14:28			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	UNKNOWN, ID: S2690474], Tel: +6593820271								
Main Claimant:	NEOL CHIEW SIN MENG, ID: S26904741								
Vehicle Reg. No.:	SCM794M	Date of Loss:	13/11/2017 08:00 - :59 [256 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM17D06542C02/9	Policy/Cover Note No.:	DMHCSN1558631601						
Vehicle Reg. No. (Insured):	SJF5249S	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1, 729332 Sungei Kadut - Tel: 6760 8815 / 6760 0539								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/11/2017]								
Driver/Custodian (Insured):	UNKNOWN (/ Male), NRIC: S2690474], Tel: +6593820271 Email:								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
• CHINA_TAIPING (09/02/2018): Alert - Adj Mandate Approved (S\$0.00) - SCM794M - Claim Handler: Joel Goh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SCM794M (SNM17D06542C02/9)
[SJF5249S]
TP
NEOL CHIEW SIN MENG
Nov 13 2017 8:00AM
[UNKNOWN]
Hua Hong Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)		Thumbnail	Print			
1	17/11/17 15:20	Repairer Estimates	1	Load HTM				
2	17/12/18 14:28	Repairer Estimates Suppl. #1	1	Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
2	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
3	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
4	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
5	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
6	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
7	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
8	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
9	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
10	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
11	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
12	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
13	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
14	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
15	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
16	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
17	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
18	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
19	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
20	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
21	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
22	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
23	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
24	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
25	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
26	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
27	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
28	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
29	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
30	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
31	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
32	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			
33	03/04/19 11:04	General View	1	Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
34	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
68	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
69	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
70	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
71	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
72	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
73	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
74	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
75	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
76	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
77	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
78	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
79	03/04/19 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
80	03/04/19 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
81	03/04/19 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
82	03/04/19 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
83	03/04/19 11:04	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
84	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
85	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
86	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
87	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
88	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
89	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
90	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
91	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
92	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
93	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
94	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
95	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
96	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
97	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
98	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
99	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
100	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
101	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
102	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
103	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
104	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
105	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
106	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
107	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
108	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
109	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
110	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
111	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
112	03/04/19 11:04	General View		<input checked="" type="checkbox"/>
113	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
114	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
115	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
116	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
117	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
118	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
119	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
120	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
121	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
122	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
123	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
124	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
125	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
126	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
127	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
128	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
129	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
130	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
131	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
132	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
133	03/04/19 11:07	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
134	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
147	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
148	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
149	03/04/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	14/11/17 13:31	Singapore Accident Statement	 Load PDF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/02/18 15:15	REPORT OF SCM794M	 Load PDF	
2	09/02/18 15:15	REPORT OF SLR7539E	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/19 14:34	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117022156/R1CD3E2

Date: 03/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN1558631601
 Claimant Vehicle No: SCM794M Insured Vehicle No: SJF5249S
 Date of Loss: 13/11/2017 Nature of Claim: TP Claim No: SNM17D06542C02/9

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCM794M**
 Make & Model: BMW 316i, 1.6 AT D/AB 4DR (A) Engine No: 06498432164E2
 Reg. Date: 01/07/1996 (Man. Year: 1996) Chassis No: WBACA82040AA69533
 Colour: Blue Odometer: 184108 km
 Engine Capacity: 1596 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	15,721.81	12,072.01	3,649.80	23.21	
Miscellaneous Items	302.00	302.00	0.00	0.00	
Labour	2,035.87	1,966.87	69.00	3.39	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	18,059.68	14,340.88	3,718.80	20.59	
Approved Total (Overridden) (S\$)		11,000.00			
	(S\$)	18,059.68	11,000.00	7,059.68	39.09
	+ GST 7.00/7.00% (S\$)	1,264.18	770.00	494.18	39.09
	Nett Amount (S\$)	19,323.86	11,770.00	7,553.86	39.09

INSPECTION

Date of Assignment: 21/11/2017 Present Location: Hua Hong Pte Ltd (Sungei Kadut)
 Date Inspected: 21/11/2017 Inspected At: Hua Hong Pte Ltd (Sungei Kadut)
 25D Sungei Kadut Street 1
 Singapore 729332

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
Parts: 143	BMW 316i 1.6 AT D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCM794M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AUX FAN (WCP)	Cracked	800.00 F	*800.00 F
2	1	NA	*BLOWER (WCP)	Serviceable	165.00 F	*- F
3	1	NA	*BONNET (WCP)	Buckled	1,300.00 F	*1,300.00 F
4	1	NA	*BONNET INSULA CLIP (WCP)	Necessary	50.00 F	*50.00 F
5	1	NA	*BONNET INSULATOR (WCP)	Deformed	420.00 F	*420.00 F
6	1	NA	*BONNET LOCK CATCH X2 (WCP)	Bent	110.00 F	*110.00 F
7	1	NA	*BONNET SEAL (WCP)	Necessary	78.00 F	*78.00 F
8	1	NA	*BOOT/TAILGATE SEAL (WCP)	Necessary	95.00 F	*95.00 F
9	1	NA	*BOOTLID/TAILGATE (WCP)	Bent	1,100.15 F	*1,100.15 F
10	1	NA	*BUMPER COVER (WCP)	Deformed	152.00 F	*152.00 F
11	1	NA	*BUMPER SCREW X10 (WCP)	Necessary	50.00 F	*50.00 F
12	1	NA	*CONDENSER (WCP)	Serviceable	500.00 F	*- F
13	1	NA	*FAN CLUTCH (WCP)	Serviceable	135.00 F	*- F
14	1	NA	*FAN SHROUD (WCP)	Cracked	120.00 F	*120.00 F
15	1	NA	*FRONT AIR BAFFLE (WCP)	Serviceable	140.00 F	*- F
16	1	NA	*FRONT CROSSMEMBER (WCP)	Bent	465.00 F	*465.00 F
17	1	NA	*FRONT FAN SHROUD (WCP)	Serviceable	120.00 F	*- F
18	1	NA	*FRONT PANEL (WCP)	Bent	520.00 F	*520.00 F
19	1	NA	*FRONT TRIM (WCP)	Cracked	310.00 F	*310.00 F
20	1	NA	*FRONT UPPER AIR DUCT (WCP)	Cracked	85.00 F	*85.00 F
21	1	NA	*FRT SPOILER FILLERED (WCP)	Cracked	1,040.00 F	*1,040.00 F
22	1	NA	*GEARBOX OIL COOLER (WCP)	Serviceable	850.00 F	*- F
23	1	NA	*GRILLE BADGE (WCP)	Necessary	68.00 F	*68.00 F
24	1	NA		Bent	35.00 F	*35.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*L/BONNET LOCK (WCP)			
25	1	NA	*L/F GRILLE (WCP)	Broken	92.00 F	*92.00 F
26	1	NA	*L/F INDICATOR (WCP)	Scratched	78.00 F	*78.00 F
27	1	NA	*L/F OUT BUMPER BRKT (WCP)	Necessary	18.00 F	*18.00 F
28	1	NA	*L/INNER AIR GUIDE (WCP)	Cracked	68.00 F	*68.00 F
29	1	NA	*L/R SIDE MOULDING (WCP)	Scratched	58.00 F	*58.00 F
30	1	NA	*LEFT BONNET HINGE (WCP)	Not Necessary	55.00 F	*- F
31	1	NA	*LEFT HEADLAMP ASSY (WCP)	Broken	1,100.00 F	*1,100.00 F
32	1	NA	*LWR BUMPER CVR TRIM (WCP)	Scratched	320.00 F	*320.00 F
33	1	NA	*POWER STRG OIL TANK (WCP)	Serviceable	98.00 F	*- F
34	1	NA	*R/BONNET LOCK (WCP)	Bent	35.00 F	*35.00 F
35	1	NA	*R/F BUMPER OUT BRKT (WCP)	Necessary	18.00 F	*18.00 F
36	1	NA	*R/F FOG LAMP (WCP)	Cracked	258.00 F	*258.00 F
37	1	NA	*R/F GRILLE (WCP)	Broken	92.00 F	*92.00 F
38	1	NA	*R/F INDICATOR (WCP)	Scratched	78.00 F	*78.00 F
39	1	NA	*R/INNER AIR GUIDE (WCP)	Cracked	68.00 F	*68.00 F
40	1	NA	*R/R SIDE MOULDING (WCP)	Scratched	58.00 F	*58.00 F
41	1	NA	*RADIATOR (WCP)	Serviceable	820.00 F	*- F
42	1	NA	*REAR BADGE (WCP)	Necessary	68.00 F	*68.00 F
43	1	NA	*REAR BUMPER CARRIER (WCP)	Not Necessary	262.00 F	*- F
44	1	NA	*REAR BUMPER COVER (WCP)	Scratched	885.00 F	*885.00 F
45	1	NA	*REAR BUMPER INSERT (WCP)	Not Necessary	116.00 F	*- F
46	1	NA	*REAR CTR BUMPER TRIM (WCP)	Scratched	78.00 F	*78.00 F
47	1	NA	*REAR MODEL BADGE (WCP)	Necessary	52.00 F	*52.00 F
48	1	NA	*RIGHT BONNET HINGE (WCP)	Not Necessary	55.00 F	*- F
49	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Cracked	1,100.00 F	*1,100.00 F
Supplementary #1						
50	1		*Front Bumper Undercover (WCP)	Cracked	175.00 F	*175.00 F
51	1		*Front Inner Shield LH (WCP)	Not Necessary	160.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	14,973.15	11,497.15
+ Margin on L,N Items 5.00/5.00% (\$\$)	748.66	574.86
Total Parts (\$\$)	15,721.81	12,072.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AIR CON GAS (NECESSARY)	50.00	50.00
2	1	AUDATEX FEE	42.00	42.00
3	1	FRT/REAR NO PLATE (NECESSARY)	70.00	70.00
4	1	P/STEERING OIL 2L (NECESSARY)	20.00	20.00
5	1	RADIATOR COOLANT (NECESSARY)	20.00	20.00
6	1	SUNDRY (NECESSARY)	100.00	100.00
Sub Total (S\$)			302.00	302.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	724.50	724.50
2	Total Paint Materials	New	241.87	241.87
3	Total Panel/Mechanical Labour	New	1,069.50	1,000.50
Gross Labour Cost (S\$)			2,035.87	1,966.87

Report was unsubmitted during this print-out.

< END OF ESTIMATES >