

Torque 5 Pte Ltd (Co.Reg.No:201313221G)

No. 8 Kaki Bukit Ave 4,, #01-50
Singapore 415875

Tel: 64524457 Fax: 64524584 Email: sam.chang@torque5.com

INSURER: **FWD Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00000521	Date of Loss:	17/11/2017
Vehicle Reg. No.:	SDX29293	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHUA YEW THYE		

Make/Model: HONDA CIVIC, 1.8 L (A)
 Vehicle Colour: BLACK
 Engine No: R18A13023170
 Odometer: 241126 KM

Vehicle Reg. Date: 20/02/2008

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) 0

Present Location: TORQUE 5 PTE LTD (KAKI BUKIT)

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Amount

6,457.50

130.00

3,980.00

0.00

0.00

Gross Total (S\$)**10,567.50****+ GST 7.00% (S\$)**

739.73

Nett Amount (S\$)**11,307.23****COST OF CLAIMS**

Parts
 Miscellaneous Items
 Labour
 Paintwork Labour
 Towing

This claim is handled by: **STEPHANIE TEO**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

Gao Qi'ang.

21/11/17

Not Authorized

Excess: \$600

* Beyond
 economical
 repairs *

* informed
 Clara (FWD)
 on
 21/11/17 @
 9-30 am

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2017)
Parts:	143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDX2929J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET / Bue	0.00	0.00	*400.00 F
2	1		*BONNET HINGE (LH) = BT	0.00	0.00	*33.00 F
3	1		*BONNET HINGE (RH)	0.00	0.00	*33.00 F
4	1		*BONNET INNER RUBBER = Tm	0.00	0.00	*13.50 F
5	1		*BONNET OUTER RUBBER	0.00	0.00	-
6	1		*BONNET INSULATOR - RL	0.00	0.00	*55.00 F
7	10		*BONNET INSULATOR CLIP - RL	0.00	0.00	*35.00 F
8	1		*BONNET LOCK - BT	0.00	0.00	*65.00 F
9	1		*FRONT NUMBER PLATE GARNISH - RL	0.00	0.00	*25.00 F
10	1		*FRONT GRILLE ASSY - CR	0.00	0.00	*175.00 F
11	10		*FRONT GRILLE ASSY CLIP - MC	0.00	0.00	*35.00 F
12	1		*FRONT GRILLE LOGO - MC	0.00	0.00	*20.00 F
13	1		*FRONT BUMPER - RL	0.00	0.00	*350.00 F
14	10		*FRONT BUMPER CLIP - MC	0.00	0.00	*35.00 F
15	1		*FRONT BUMPER RETAINER (LH) = YMC	0.00	0.00	*12.00 F
16	1		*FRONT BUMPER RETAINER (RH)	0.00	0.00	*12.00 F
17	1		*FRONT BUMPER BRACKET (LH)	0.00	0.00	*20.00 F
18	1		*FRONT BUMPER BRACKET (RH)	0.00	0.00	*20.00 F
19	1		*FRONT BUMPER REINFORCEMENT - BT	0.00	0.00	*180.00 F
20	1		*FRONT BUMPER FOG LAMP (LH) ?	0.00	0.00	*200.00 F
21	1		*FRONT BUMPER FOG LAMP (RH) ?	0.00	0.00	*200.00 F
22	1		*FRONT BUMPER FOG LAMP GARNISH (LH) ?	0.00	0.00	*20.00 F
23	1		*FRONT BUMPER FOG LAMP GARNISH (RH) ?	0.00	0.00	*20.00 F
24	1		*FRONT BUMPER LOWER GRILLE - RL	0.00	0.00	-
25	1		*FRONT BUMPER UNDERCOVER	0.00	0.00	*50.00 F
26	10		*FRONT BUMPER UNDERCOVER CLIP ?	0.00	0.00	*35.00 F
27	1		*HEAD LAMP (LH) = YCR	0.00	0.00	*550.00 F
28	1		*HEAD LAMP (RH)	0.00	0.00	*550.00 F
29	2		*HEAD LAMP CLIP (LH) = YMC	0.00	0.00	*7.00 F
30	2		*HEAD LAMP CLIP (RH)	0.00	0.00	*7.00 F
31	1		*FRONT FENDER (LH) X Y repair	0.00	0.00	*350.00 F
32	1		*FRONT FENDER (RH) X	0.00	0.00	*350.00 F
33	1		*FRONT FENDER COWLING (LH) X Y NN	0.00	0.00	*70.00 F
34	1		*FRONT FENDER COWLING (RH) X	0.00	0.00	*70.00 F
35	10		*FRONT FENDER COWLING CLIP (LH) X	0.00	0.00	*35.00 F
36	10		*FRONT FENDER COWLING CLIP (RH) X	0.00	0.00	*35.00 F
37	1		*FRONT FENDER INNER PANEL (LH) X Y NN	0.00	0.00	*100.00 F
38	1		*FRONT FENDER INNER PANEL (RH) X	0.00	0.00	*100.00 F
39	1		*FRONT FENDER TRIANGULAR GLASS MOULDING X NN	0.00	0.00	*32.00 F
40	1		*SUPPORT PANEL - BT	0.00	0.00	*380.00 F
41	1		*CONDENSOR = YBT	0.00	0.00	*570.00 F
42	1		*RADIATOR	0.00	0.00	*750.00 F
43	1		*HORN X NN	0.00	0.00	*40.00 F
44	1		*LIQUID PIPE	0.00	0.00	*130.00 F
45	1		*DISCHARGE PIPE X Y ?	0.00	0.00	*146.00 F
46	1		*SUCTION PIPE	0.00	0.00	*80.00 F
47	1		*WASHER TANK	0.00	0.00	*62.00 F

F=Franchise part.

Total Parts (\$)**6,457.50**

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT FENDER TRIANGULAR GLASS SEALANT X NN	80.00
2	1	FRONT NUMBER PLATE CBT	50.00
Sub Total (\$)			130.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO R&R ACCIDENT AFFECTED AREAS	New 600	1,800.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	New 1000	1,500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREAS	New 60	90.00
4	TO R&R AIRCON CONDENSOR & REFILL GAS	New 100	150.00
5	TO CHECK WIRING LAYOUT & HEAD LAMP FOCUS	New 30	80.00
6	TO R&R ENGINE PARTS & ATTACHMENT	New NN X	150.00
7	TO R&R TRIANGLE GLASS	New NN X	150.00
8	TO CHECK WATER SEEPAGE	New NN X	60.00
Gross Labour Cost (\$)			3,980.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5 Days.

lump sum repair.