

ASS. REC. BY:

REF:

CS/FCL17022183/Kabnz

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): CWS Eileen Lee of FCL Date/Time: 21-11-2017 233pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 5150B Insured: SHA 1218Hat Workshop m/s Trans Cab Tel: 6297 6666of No. 2 AMK St 63Policy No: _____ Claim No: D17010778MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17-11-2017
(Client's Record)CA / REV / REP. / REV 24 HRS 1091

H.O.D. Endorsement: _____

Date/Time: 21-11-2017 2.52pm Person Contacted: Candy Vehicle: IN LOU

Date/Time	Action/Instruction (✓) Estimate	
	SHD 5150B - CS- / 924 16000658 / Kabzy	DCA: 08012011
	SHA 1218H - CS / FCL16001662 / Mlvb2	DCA: 22012016



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022183/Ktb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1218H	Veh. Inspected	SHD 5150B
Policy No.		Coverage (\$)	0.00
Claim No.	D17010778MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	21/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/11/2017	Inspection Date	21/11/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	20-11-2017	Our Ref No.	D17010778MFSH
Accident Date	17-11-2017	Claim Type.	Third Party
Insured Vehicle	SHA1218H	Third Party Vehicle.	SHD5150B
Survey Location	NO. 2 ANG MO KIO STREET 63		
Contact Person.	CANDY KONG		
Contact No.	62876666/ 62876666	Fax No.	62877764
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230415)

PRI Documents

Close X

PRI Header Details

Claim No	D17010778MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & TR PTE LTI
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 62876666 , Phone: 62876666 , Fax: EmailId: CANDY.KONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1218H	TP Vehicle No	SHD51
PRI Recieved Date	21-11-2017 02:14:26 PM	Surveyor Appointed Date	21-11-2017 02:33:21 PM	Surveyor Accept Date	21-11-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	21-11-2017	Upload Survey Report *:	
------------------------------------	---	-----------------------------	------------	--------------------------------	---

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	3878K
Vehicle Details	
Vehicle No.	SHD5150B
Vehicle to be Exported	Yes
Intended De-registration Date	20 Nov 2017
Vehicle Make	CHEVROLET
Vehicle Model	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour	Red
Manufacturing Year	2011
Engine No.	Z20S1455295K
Chassis No.	KL1LA69RJBB094349
Maximum Power Output	110.0 kW (147 bhp)
Open Market Value	\$14,281.00
Original Registration Date	30 Apr 2012
First Registration Date	30 Apr 2012
Transfer Count	0
Actual ARF Paid	\$14,281.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	29 Apr 2020
PARF Rebate Amount	\$9,996.00
Intended COE Rebate Details	
COE Expiry Date	29 Apr 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	8
PQP Paid	\$42,384.00
COE Rebate Amount	\$12,935.00
Total Rebate Amount	\$22,931.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Nov 2017

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 5150B -**AAD1711-213***Not Authored**Clipy 84350/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD5150B - CANDY**KL1LA69RJBB094349****CHEVROLET****EPICA 2.0****17.11.2017****FCIL****PART****LIST**

1	1	Rear Bumper	\$	<i>R</i>	1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>R</i>	239.94	✓
3	1	Rear Bumper Centre Absorber	\$	<i>CM</i>	260.00	✓
4	1	Rear Bumper Side Retainer RH	\$	<i>S</i>	68.76	X
5	1	Rear Bumper Side Retainer LH	\$	<i>S</i>	68.76	X
6	1	Rear Bumper Reflectors RH	\$	<i>S</i>	119.74	X
7	1	Rear Bumper Reflectors LH	\$	<i>R</i>	119.74	✓
8	1	Rear Bumper Tow Hook Cover	\$	<i>S</i>	93.00	X
9	1	Rear Luggage Floor Panel	\$	<i>R</i>	973.00	X
10	1	Rear Luggage Floor Panel Insulator	\$	<i>S</i>	63.50	X
11	1	Rear Luggage Floor Panel Trim Board	\$	<i>S</i>	378.00	X
12	1	Rear End Panel Outer	\$	<i>R</i>	623.76	✓
13	1	Rear End Panel Inner Trim	\$	<i>R</i>	263.84	X
14	1	Bootlid	\$	<i>R</i>	973.00	✓
15	1	Bootlid inner trim board	\$	<i>S</i>	400.00	X
16	1	Bootlid Weatherstrip	<i>172.14</i> \$	<i>D</i>	344.28	<i>50.62</i>
17	1	Bootlid Lock - Top	\$	<i>R</i>	466.56	X
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>R</i>	120.62	✓
19	1	Bootlid Logo	\$	<i>R</i>	138.84	✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>R</i>	119.84	✓
21	1	Bootlid Reflector Centre	\$	<i>S</i>	217.97	X
22	1	Bootlid Reflector RH	\$	<i>S</i>	128.40	X
23	1	Bootlid Reflector LH	\$	<i>S</i>	128.40	X
24	1	Bootlid Hinge RH	\$	<i>R</i>	120.00	X
25	1	Bootlid Hinge LH	\$	<i>R</i>	120.00	X
26	1	Rear Tail Lamp RH	\$	<i>S</i>	479.30	X
27	1	Rear Tail Lamp Panel RH	\$	<i>R</i>	359.00	X
28	1	Rear Tail Lamp LH	\$	<i>S</i>	479.30	X
29	1	Rear Tail Lamp Panel LH	\$	<i>R</i>	359.00	X
30	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i>	1,110.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-213

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 5150B -

31	1	Rear Fender RH	\$	<i>R</i> 1,145.00 X
32	1	Rear Fender Inner Trim RH	\$	<i>Sm</i> 418.44 X
33	1	Rear Fender LH	\$	<i>R</i> 1,145.00 X
34	1	Rear Fender Inner Trim LH	\$	<i>Sm</i> 418.44 X

TOTAL	\$	13,665.43
10%	\$	1,366.54
	\$	12,298.89

Specical Nett

1	1Set	Licence Plate With Holder	\$	<i>Sm</i> 60.00 X
2	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 X
3	1Set	Rear Bumper Parking Sensor	\$	<i>Ncl</i> 300.00 ✓
4	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 44.00 ✓
5	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00 X
6	1Set	Rear Fender Inner Trim Clip RH	\$	<i>nn</i> 30.00 X
7	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00 X
8	1	Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00 ✓
9	1	Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 30.00 ✓
10	1	Rear Exhaust Mounting	\$	<i>Sm</i> 10.00 X
11	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00 X
12	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00 X
13	1	Spare Tyre	\$	<i>Sm</i> 180.00 X
14	1	Spare Wheel Rim	\$	<i>Sm</i> 126.74 X

TOTAL	\$	1,090.74
TOTAL PARTS	\$	13,389.63

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 5,400.00 *600*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *600*

Putty And Spray Painting Of The Affected
Portion.

\$ 5,350.00 *600*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-213**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 5150B -

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	601
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	nn 170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
To transfer of boot fittings and conduct water seepage test.	\$	170.00	601
Towing fees	\$	nn 120.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
	\$	12,830.00	
TOTAL	\$	26,219.63	

Repair Days**20 Days**

5 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022183/Ktbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1218H	Veh. Inspected	SHD 5150B	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010778MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	21/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET EPICA (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KL1LA69RJBB094349	Colour	WHITE / RED	
Odometer	557270	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GITI	9 mm	
L/H Front Tyre	195/65 R15	GITI	9 mm	
R/H Rear Tyre	195/65 R15	GREMAX	4 mm	
L/H Rear Tyre	195/65 R15	GREMAX	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/11/2017	Inspection Date	21/11/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5150B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BENT	1,202.00	1,202.00
1	REAR BUMPER BEAM	BENT	239.94	239.94
1	REAR BUMPER CENTRE ABSORBER	CRACKED	260.00	260.00
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	68.76	-
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	119.74	-
1	REAR BUMPER REFLECTORS LH	BROKEN	119.74	119.74
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	973.00	-
1	REAR LUGGAGE FLOOR PANEL INSULATOR	SERVICEABLE	63.50	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	REAR END PANEL OUTER	BENT	623.76	623.76
1	REAR END PANEL INNER TRIM	SERVICEABLE	263.84	-
1	BOOTLID	BENT	973.00	973.00
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID LOCK-TOP	TO REPAIR SEE LABOUR	466.56	-
1	BOOTLID "CHEVROLET" BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID "EPICA LT" BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	SERVICEABLE	128.40	-
1	BOOTLID REFLECTOR LH	SERVICEABLE	128.40	-
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	120.00	-
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	120.00	-
1	REAR TAIL LAMP RH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	359.00	-
1	REAR TAIL LAMP LH	SERVICEABLE	479.30	-

Report Ref No. CS/FCI17022183/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	359.00	-
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	TO REPAIR SEE LABOUR	1,110.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
	LESS 10% DISCOUNT		-1,332.11	-379.78
			11,989.04	3,417.96
1	BOOTLID WEATHERSTRIP (50%)(SN)	DISTORTED / CUT	344.28	172.14
	LESS 10% DISCOUNT		-34.43	-
			309.85	172.14
<u>SPECIAL NETT ITEMS</u>				
1	SET LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	60.00	-
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	DENTED	300.00	300.00
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	44.00	44.00
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	10.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE (SN)	SERVICEABLE	180.00	-
1	SPARE WHEEL RIM (SN)	SERVICEABLE	126.74	-
			1,090.74	404.00

Report Ref No. CS/FCI17022183/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR LUGGAGE FLOOR PANEL,BOOTLID LOCK-TOP,BOOTLID HINGE RH,BOOTLID HINGE LH,REAR TAIL LAMP PANEL RH,REAR TAIL LAMP PANEL LH,REAR EXHAUST BOX (MUFFLER A-EXH,RR),REAR FENDER RH AND REAR FENDER LH.		5,400.00	600.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		5,350.00	600.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	-		-	-
	-		-	-
	-		-	-
			12,830.00	1,460.00
	GRAND TOTAL		26,219.63	5,454.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,350.00

Report Ref No. CS/FCI17022183/Ktbn2



Report Ref No. CS/FCI17022183/Ktbn2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.